

LBA AUTOMOTIVE PTE.LTD

NO 1 KAKI BUKIT AVE 6 #02-47

AUTOBAY SINGAPORE 417883

Tel : 6509 5521 / 65095524 Fax : 6509 5523

The Motor Claims Dept.

M/S EQ INSURANCE CO.LTD

22 GEMMILL LANE

SINGAPORE 069257

SKL8900G

ESTIMATE

DATE : 12.12.2017
VEHICLE NO : PC2372H
MAKE/MODEL : TOYOTA HIACE
ACC DATE : 15.11.2017

PARTICULAR		UNIT PRICE	AMOUNT	
QTY		S\$		S\$
<u>LIST PRICE</u>				
1	1 REAR TAILLAMP RH	325.50	SCN	325.50 ✓
2	1 REAR TAILLAMP LOWER APRON GARNISH RH	166.15	n	166.15 x
3	1 REAR TAILLAMP LOWER APRON GARNISH HOLDER RH	65.10	n	65.10 x
4	1 REAR BUMPER	517.10	cut	517.10 ✓
5	2 REAR BUMPER SIDE HOLDER RH/LH	66.10	n	132.20 x
				1,206.05
			LESS 25%	301.51
				904.54

842.6
631.95

SPECIAL NETT ITEMS

1	1 (SET) REAR BUMPER CLIP	35.00	ner	35.00 ✓
---	--------------------------	-------	-----	---------

LABOUR CHARGES :

1	TO KNOCK OUT DENT AND REPLACE ACCIDENT PARTS	380	400.00
2	TO SPRAY PAINTING ON ACCIDENT PORTION	380	400.00
3	TO CHECK WIRING		20.00 ✓
4	TO REMOVE, REFIX REVERSE SENSOR	50	80.00
TOTAL:			900.00

not Admit
n/s 1200/2
3 dy.
12/12/17

ESTIMATE PARTS AND LABOUR GRAND TOTAL : \$ 1,839.54

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: