

Messrs Grab Rentals Pte Ltd

Estimate To Repair

Vehicle No :

Chassis No :

Toyota Prius Hybrid 1.8 CVT

SLS2174B

JTDKB3FU803569871

*Not Authorized
make
2/5/17 9500/17
12/12/17
10 day.*

Third Party Insurer :

AIG

Insured's Veh No :

SLE4260X

Date of accident :

10.12.2017

Date : 11.12.2017

reg: LKK Marcus

12-12-2017 0925 hrs

Pages : 1 of 3

S/No	Quantity	Description	Unit price	Amount
LIST ITEMS				
1	1 pc	tailgate lid <i>20d500</i>	\$ 929.60	\$ 929.60
2	1 pc	tailgate lid prius badge <i>nee</i>	\$ 46.30	\$ 46.30
3	1 pc	tailgate lid hybrid badge <i>nee</i>	\$ 52.90	\$ 52.90
4	1 pc	tailgate lid centre emblem badge <i>nee</i>	\$ 46.30	\$ 46.30
5	1 pc	tailgate lid lock top <i>7w1</i>	\$ 452.10	\$ 452.10
	1 pc	tailgate lid lock striker bottom <i>17</i>	\$ 25.30	\$ 25.30
7	1 pc	tailgate lid weatherstirp <i>7w1</i>	\$ 360.70	\$ 360.70
8	1 pc	tailgate lid inner trimboard <i>11</i>	\$ 251.50	\$ 251.50
9	2 pc	tailgate lid rubber stopper <i>17</i>	\$ 18.60	\$ 37.20
10	2 pc	tailgate lid side catch <i>17</i>	\$ 22.60	\$ 45.20
11	2 pc	tailgate lid side catch latch <i>17</i>	\$ 24.30	\$ 48.60
12	1 pc	tailgate lid keyless sensor <i>17</i>	\$ 6.00	\$ 6.00
13	1 pc	tailgate lid rear view glass weatherstirp <i>nee</i>	\$ 35.00	\$ 35.00
14	2 pc	tailgate lid rear windshield glass side weatherstirp <i>17</i>		\$ -
15	1 pc	rear licence plate garnish <i>000</i>	\$ 891.20	\$ 891.20
16	2 pc	rear licence plate lamp <i>17</i>	\$ 63.70	\$ 127.40
17	1 pc	rear end panel <i>30d500</i>	\$ 629.80	\$ 629.80
18	1 pc	rear end panel inner trim <i>7w1</i>	\$ 162.90	\$ 162.90
19	1 pc	rear bumper upper <i>0.5</i>	\$ 423.90	\$ 423.90
20	1 pc	rear bumper lower <i>0.5</i>	\$ 552.30	\$ 552.30
21	2 pc	rear bumper side <i>0.5 70.1</i>	\$ 392.70	\$ 785.40
22	1 pc	rear bumper reinforcement <i>nee</i>	\$ 318.30	\$ 318.30
23	12 pc	rear bumper clips <i>nee</i>	\$ 4.30	\$ 51.60
24	1 pc	o/s rear bumper end splashshield cover <i>0.5</i>	\$ 89.80	\$ 89.80
25	2 pc	rear bumper side retainer <i>0.5 2nd</i>	\$ 112.70	\$ 225.40
26	2 pc	rear bumper screw spacer <i>17</i>	\$ 4.30	\$ 8.60
27	2 pc	rear bumper LED lamp <i>0.5 1st</i>	\$ 486.80	\$ 973.60
28	1 pc	rear bumper tow cover <i>70.1</i>	\$ 14.80	\$ 14.80
29	1 pc	rear bumper lower splashshield cover centre <i>0.5</i>	\$ 222.60	\$ 222.60
30	1 pc	o/s rear bumper lower splashshield cover side <i>17</i>		\$ -
31	10 pc	rear bumper lower splashshield cover clips <i>nee</i>	\$ 4.30	\$ 43.00
32	2 pc	rear LED lamp <i>0.5 1st</i>	\$ 433.70	\$ 867.40
33	4 pc	rear LED lamp clips holder <i>17</i>	\$ 4.30	\$ 17.20
34	1 pc	o/s rear fender <i>2</i>		\$ -
35	1 pc	o/s rear fender air vent <i>17</i>	\$ 65.00	\$ 65.00
Balance C/F				\$ 7,089.70

6745

Please conduct the survey at

Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216

Messrs Grab Rentals Pte Ltd

Date : 11.12.2017

Estimate To Repair Toyota Prius Hybrid 1.8 CVT
Vehicle No : SLS2174B
Chassis No : JTDKB3FU803569871

Pages : 2 of 3

S/No	Quantity	Description	Unit price	Amount
		Balance B/F		\$ 7,089.70
		LIST ITEMS		
36	2 pc	head lamp n/s one	\$ 3,079.60	\$ 6,159.20
37	1 pc	n/s head lamp panel	\$ 85.00	\$ 85.00
	1 pc	n/s front bumper tow cover	\$ 28.10	\$ 28.10
39	1 pc	front bumper upper weatherstirp	\$ 34.40	\$ 34.40
40	3 pc	front bumper upper weatherstirp clips	\$ 4.30	\$ 12.90
41	1 pc	front bumper reinforcement	\$ 691.10	\$ 691.10
42	1 pc	front bumper absorber foam	\$ 70.30	\$ 70.30
43	1 pc	front bumper lower beam	\$ 238.50	\$ 238.50
44	1 pc	front bumper lower beam garnish		\$ -
45	2 pc	front bumper side retainer	\$ 76.90	\$ 153.80
46	1 pc	n/s front bumper LED lamp	\$ 910.20	\$ 910.20
47	1 pc	front bumper lower centre air grille	\$ 165.00	\$ 165.00
48	1 pc	front bumper upper centre air grille	\$ 335.60	\$ 335.60
49	1 pc	front bumper emblem badge	\$ 87.10	\$ 87.10
50	2 pc	front bumper air guide	\$ 54.00	\$ 108.00
51	6 pc	front bumper air guide clips	\$ 4.30	\$ 25.80
52	1 pc	front bumper lower splashshield cover	\$ 180.10	\$ 180.10
53	6 pc	front bumper lower splashshield cover clips	\$ 4.30	\$ 25.80
54	1 pc	battery cover		\$ -
55	1 pc	battery tray		\$ -
56	1 pc	radiator assy	\$ 1,841.00	\$ 1,841.00
57	1 pc	radiator barce panel	\$ 76.20	\$ 76.20
58	1 pc	radiator fan shroud	\$ 219.30	\$ 219.30
59	1 pc	radiator bottom garnish	\$ 169.70	\$ 169.70
60	1 pc	horn high tone	\$ 112.80	\$ 112.80
61	1 pc	horn lowe tone	\$ 112.80	\$ 112.80
62	1 pc	air con condensor	\$ 1,303.60	\$ 1,303.60
				\$ 20,236.00
		Less 25%		\$ 5,059.00
				\$ 15,177.00
		Balance C/F		\$ 15,177.00

111028
832687 43535

Please conduct the survey at

Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216

Messrs Grab Rentals Pte Ltd

Date : 11.12.2017

Estimate To Repair Toyota Prius Hybrid 1.8 CVT
Vehicle No : SLS2174B
Chassis No : JTDKB3FU803569871

Pages : 3 of 3

S/No	Quantity	Description	Unit price	Amount
		Balance B/F		\$ 15,177.00
		SPECIAL NETT ITEMS		
63	1 pc	tailgate lid rear view glass sealant 40	\$ 100.00	\$ 100.00
64	1 pc	tailgate lid rear view glass sponge 30	\$ 60.00	\$ 60.00
	1 pc	tailgate lid rear windshield glass sealant 40	\$ 180.00	\$ 180.00
66	1 pc	tailgate lid rear windshield glass sponge 30	\$ 100.00	\$ 100.00
67	1 pc	rear licence plate	\$ 80.00	\$ 80.00
68	1 set	rear bumper parking sensor 200	\$ 450.00	\$ 450.00
69	1 pc	battery	\$ -	\$ -
70	1 pc	radiator coolant	\$ 30.00	\$ 30.00
				\$ 1,000.00
				340
		LABOUR & MISC. CHARGES		
1		To check electrical lighting concerned.	30	\$ 60.00
2		To reinstall of rear bumper parking sensor.	50	\$ 150.00
		To place vehicle on jig bench to obtain cross and parallel measurement and correct to manufacturer specification with hydraulic pneumatic jack.	11X	\$ 550.00
4		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	80	\$ 150.00
5		To drop rear exhaust box and renew the same.	60	\$ 180.00
6		To rust-proofing of the affected areas.	100	\$ 280.00
7		To remove and refit rear windscreen glass.	120	\$ 180.00
8		To remove and refit rear view glass.	100	\$ 100.00
9		To transfer of tailgate fittings, fixture and perform waterseepage test.	80	\$ 150.00
10		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	1200	\$ 2,200.00
11		Putty and spray painting of the affected portion.	1400	\$ 1,600.00
				\$ 5,600.00
				3220
				1188687
		Grand Total		\$ 21,777.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

Please conduct the survey at

Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216