

Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

CHOO SUAN PHOCK
BLK 245 KIM KEAT LINK #03-131
SINGAPORE 310245

Attention : THE OWNER
Contact : 96951039

Estimate : ES006225

Date : 11/12/2017
Vehicle Num : SKG5279M
Make/Model : BMW 520IA-2012
Chassis/Eng# : WBAXG12000DX48332/A0460146N2
Accident Date : 10/12/2017
Claim No :
Reference :
Policy No :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	BOOT LID <i>As ✓</i>		
2.	2	BOOT LID HINGES <i>R</i>		
3.	1	BOOT LID LOCK <i>?</i>		
4.	1	BMW LOGO <i>As ✓</i>		
5.	1	520I EMBLEM <i>As ✓</i>		
6.	2	BOOT LID REFLECTOR <i>As ✓</i>		
7.	1	BOOT WEATHERSTRIP <i>?</i>		
8.	2	TAIL LAMP <i>As ✓</i>		
9.	4	TAIL LAMP CLIP <i>As ✓</i>		
10.	2	TAIL LAMP SIDE GARNISH <i>As ✓</i>		
11.	1	REAR END PANEL <i>As ✓</i>		
12.	1	REAR END PANEL TOP GARNISH <i>?</i>		
13.	6	REAR END PANEL TOP GARNISH CLIP <i>?</i>		
14.	1	REAR FLOOR PANEL <i>?</i>		
15.	1	REAR FLOOR PANEL INNER TOP GARNISH <i>?</i>		
16.	1	REAR FLOOR PANEL LOWER UNDER COVER <i>As ✓</i>		
17.	1	REAR FLOOR PANEL SIDE UNDER COVER R/H <i>?</i>		
18.	1	REAR BUMPER <i>As ✓</i>		
19.	1	REAR BUMPER REINFORCEMENT <i>As ✓</i>		
20.	1	REAR BUMPER CENTRE GARNISH <i>As ✓</i>		
21.	1	REAR BUMPER REINFORCEMENT TOP GARNISH <i>?</i>		
22.	6	REAR BUMPER CLIP <i>As ✓</i>		
23.	2	REAR BUMPER BRACKET <i>?</i>		
24.	2	REAR BUMPER SIDE RETAINER <i>As ✓</i>		
25.	1	REAR BUMPER TOW COVER <i>As ✓</i>		
26.	2	REAR BUMPER REFLECTOR <i>As ✓</i>		
27.	1	REAR BUMPER SPONGE <i>As ✓</i>		
28.	4 2	REVERSE SENSOR <i>As ✓</i>	280.00	1,120.00
29.	2	REVERSE SENSOR HOLDER <i>?</i>		

CONTINUE / ...

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature



Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

CHOO SUAN PHOCK
BLK 245 KIM KEAT LINK #03-131
SINGAPORE 310245

Attention : THE OWNER
Contact : 96951039

Estimate : ES006225

Date : 11/12/2017
Vehicle Num. : SKG5279M
Make/Model : BMW 520IA-2012
Chassis/Eng# : WBAXG12000DX48332/A0460146N2
Accident Date : 10/12/2017
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
30.	1	REAR EXHAUST SILENCER BOX ?		
31.	1	REAR EXHAUST HEATER SHIELD ?		
32.	1	REAR EXHAUST MOUNTING ?		
33.	1	REAR EXHAUST BRACKET RX		
34.	2	REAR EXHAUST CHROME PIPE RI-		
35.	1	REAR FLOOR TOP BOARD ?		
36.	2	FRONT SEAT HEAD RESTRAINT ?		
37.	1	AIR BAG ECU ASSY ?		
38.	2	FRONT SEAT BELT ?		
39.	2	FRONT SEAT BELT BRACKET ?		
40.	1	FRONT BUMPER RI-		
41.	1	FRONT BUMPER REINFORCEMENT ?		
42.	2	FRONT BUMPER BRACKET RX		
43.	6	FRONT BUMPER CLIP RI-		
44.	1	FRONT BUMPER LOWER GRILLE CENTER CR1-		
45.	1	BMW LOGO RI-		
46.	2	RADIATOR GRILLE BASE RI/CR1+		
47.	2	RADIATOR GRILLE CHROME RI/CR1+		
48.	1	FRONT BUMPER SPONGE RIX		
49.	1	HEADLAMP L/H CR1-		
50.	1	FRONT BUMPER LOWER GRILLE L/H ?		
51.	1	FRONT AIR DUCT COWLING ?		
52.	2	FRONT BUMPER SENSOR (CENTRE) ?		
List TotalS\$:				1,120.00
5.00% Discount S\$:				56.00
				1,064.00
SPECIAL NETT ITEMS :				
1.	1	FRONT NUMBER PLATE		25.00

CONTINUE / ...



Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

CHOO SUAN PHOCK
BLK 245 KIM KEAT LINK #03-131
SINGAPORE 310245

Attention : THE OWNER
Contact : 96951039

Estimate : ES006225

Date : 11/12/2017
Vehicle Num : SKG5279M
Make/Model : BMW 520IA-2012
Chassis/Eng# : WBAXG12000DX48332/A0460146N2
Accident Date : 10/12/2017
Claim No :
Reference :
Policy No :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

2.	1	FRONT NUMBER PLATE HOLDER		33.00
----	---	---------------------------	--	-------

Special Nett Total S\$:

LABOUR :

CHANGE TAIL LAMP AND CHECK LIGHTING
REMOVE & REINSTALL EXHAUST SILENCER BOX & EXHAUST PIPE
REMOVE & REINSTALL SRS SYSTEM COMPONENTS
COMPUTER DIAGNOSE AND INITIALIZATION OF ECU MODULE
CHANGE HEAD LAMP & DO LIGHT BEAM LEVEL ADAPTATION
TO CUT OFF REAR END PANEL, REAR FLOOR PANEL, KNOCK AND
STRAIGHTEN REAR CHASSIS FRAMES, AND CHANGE ALL
NECESSARY PARTS
TO KNOCK AND STRAIGHTEN FRONT SUPPORT MOUNTING, FRONT
CHASSIS FRAMES, AND CHANGE ALL NECESSARY PARTS
RUST PROOFING TREATMENT
SPRAY PAINT FRONT & REAR DAMAGED AREA

Labour Total S\$:

1000 1,500.00

900.00

180.00

1100 1,600.00

5,255.00

SingDollars : Six Thousand Three Hundred Seventy-Seven Only

Total S\$: 6,377.00

COMPLETE VMS PTE LTD

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun