

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SEA 4471Y

DATE 8/12/2017 16:57

MAKE :

CHINA

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover X repair			\$ 562.30
	Front Bumper Bracket Top (RH) ?			\$ 22.40
	Front Bumper Retainer Mounting ?			\$ 9.20
	Front Door Mirror (LH) —			\$ 980.50
	Front Wheel Hub Cap (LH) —			\$ 150.70
	SUB TOTAL			\$ 1,725.10
	LESS 20%			\$ 345.02
	DISCOUNTED TOTAL			\$ 1,380.08
	Front Fender Advertisement Logo (LH) —			\$ 100.00 Nett
	Front Door Comfort Logo (LH) —			\$ 75.00 Nett
	Front Door Advertisement Logo (LH) —			\$ 100.00 Nett
	Rear Door Comfortdelgro & Apps Sticker (LH) —			\$ 80.00 Nett
	Rear Fender Advertisement Logo (LH) —			\$ 100.00 Nett
				\$ 455.00
	Labour Charge			300
	Panel Beating			\$ 350.00
	Spray Painting Charge			\$ 1,000.00 410
	Wiring Charge			\$ 50.00 20
	Tuff Kote			\$ 50.00 X
	FRT Wheel Alignment			\$ 120.00 X
	TOTAL LABOUR			\$ 1,570.00
	ESTIMATE TOTAL			\$ 3,405.08

Kalvin LKK
 11/12/17 1030 hrs.
 3 Days.
 PIP
 Before paint & hub

LKK Auto Consultants will notify
 the Repairer of the following:
 • To repair the damaged part(s) only after spray painting
 • To repair the damaged part(s) only after survey
 • Parts prices are subject to confirmation
 • Third party survey is on a "no win, no fee" basis
 • No illegal modification
 • Supplementary work must be surveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.