

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Winnie Chua Ping Ping

Date: 14 Dec 2017

Preliminary Advice

Vehicle No	: SKX315K	Accident Date	: 10/12/2017
Make	: TOYOTA HARRIER	Policy No.	: MSD/VPCP/17-002384
Assignment Date	: 12/12/2017	Excess	: S\$1,500.00
Date of Inspection	: 13/12/2017	Est. Duration of Repair	: 7.00
Inspection At	: HITACHI CAPITAL ASIA PACIFIC PTE. LTD (HQ) NO 8 FOURTH LOK YANG ROAD SINGAPORE 629705		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and undercarriage and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,368.00
Revised Amount	:S\$	4,740.50
Check Items (Estimated)	:S\$	1,670.00
Total	:S\$	6,410.50

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	112,000.00
COE / PARF Rebate	:S\$	67,403.00
Salvage Value	:S\$	
Margin for Repair	:S\$	44,597.00

Remarks

(X) The vehicle is economical for repair. Kindly let us have your approval please.

() The above survey was conducted on a 'without prejudice' basis.