

INS CASE OWNER:

JOWYN

CC6/CTI17023591 / Aha332

LKK:

IDAC:

ASSIGNMENT

Surveyor:

ADRIAN

DOI:

11/12/17

Date / Time:

11/12/17

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

GBC 8140L

Claim No.:

SNM17007027/CO2/0

Name of Insured:

SICYY (SINGAPORE) DESIGN WORKSHOP

Policy No.:

DMCUSEN 3058691703

Insured Tel No.:

HP:

Make / Model:

MITSUBISHI CANTER FEAO1BR1500B

Excess Sec II :SS

D.O.A.: 09/12/17

Place of Accident:

CCEU
CTE TOWARDS CITY BEFORE PIE

Is driver the owner?

(YES) (NO)

Nature of Accident:

If NO, Driver Name / Age: ZHANG HE

OI GIA REPORT: YES / NO; TP GIA REPORT: YES / NO

Driver Tel No.: 9773 9611

(V/L: YES / NO)

Insured Liability:

%

Final? Yes / No

SKH 9030G



INSRS:

WSP: MG solution

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

SKH 9030G - NA/ATG17023478/h4 DOA: 09/12/17
GBC 8140L - NA/ATG17023478/h4 DOA: 09/12/17

STAGE

DATE / PIC

15/12/17 (V/L)

* NO ESTIMATE & PA.

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

18-12-17

CALLED OIC OFFICE.

@ 3:51

OIC MR. KENNY, IN A MEETING.

18-12-17

OIC KENNY NOT AVAILABLE

@ 4:24

skydwsc@singnet.com.sg

19/12/17 @ 10:30AM

CALL OIC OFFICE, SPOKE TO A STAFF.

INFORMED ABOUT TP CLAIM & LIABILITY.

TO SETtle & NCD ISSUES. HE WILL

INFORM BOSS (MR KENNY). SEND LETTER

IN BUNDL TO OI.

SEND PA TO OI.

16/01/18

TYPE REPORT WHILE PENDING TP LOD.

02/02/18

REPORT DONE

07/02/18

TP LOD IN BY BUNDL. RECOVER MANDATE BY BUNDL

OI APPROVED MANDATE. SEND 1st OFFER.

PRELIMINARY ADVICE

Date/Time: 16/01/18

Sent By: VIC

06/02/18

- ORIGINAL DOCS IN. ALL IN ORDER. TO CLOS

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

HS

SS 9,200.00 (7 days) Reduction: 60 %

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100 (Agreed / Assessed) BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost:

(w/ GST)

SS 9,844.00

COLD REPAIR-ENDED TP

Loss of Rental (LOR):

SS

(days)

Loss of Use (LOU):

SS

80.00 (\$ 90 x 9 days)

Loss of Income (LOI):

SS

(\$ x days)

LOR only ☐ LOU only ☐LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search

SS

5.35

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$400.00

Total:

SS

10,639.35

Global Sum SS:

10,630.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

10,630.00

Name 1:

MG SOLUTION PTE LTD

Payee 2: (Strike if N.A.)

SS

-

Name 2:

Payee 3: (Strike if N.A.)

SS

-

Name 3:

REF:

ASSIGNMENT

22/12/08

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 7 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKIT 90306 Yr Regn: 2008 Dec
 Type: M.Cap / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Lexus GS 300 cc 2995
 Colour: White A/C: Insured / Std / NI / NA
 Sp. Reading: 117036 T/Radio: Insured / Std / NI / NA

Eng/No: _____
 C/No: JTBH96SX05062845

Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/50R17.
 R: 225/50R17.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front		Rear	
R/Bal. <u>06</u> mm		R/Bal. <u>06</u> mm	
L/Bal. <u>06</u> mm		L/Bal. <u>06</u> mm	
D.O.A.		D.O.I. <u>11/12/17.</u>	

Survey held at MG Solution.Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision:

Date / Time	Action / Instruction
	TP Ching.
	LIS @ 9,200.00
	CRAP: @ 13,767.35 (60%)
	MV: 40.5K
	9V: 30.2K
	Nett: 10.3K

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

) \$ - RS \$ _____

) Photos

) Others

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CTI17023591/Aha3

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 12-12-2017



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBC 8140L	Veh. Inspected	SKH 9030G
Policy No.	DMCVSN3058691703	Coverage (\$)	0.00
Claim No.	SNM17D07027/C02/0	Excess (\$)	0.00
Assign From		Assign Date	12/12/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer		Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	09/12/2017	Inspection Date	11/12/2017
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: SNM17D07027/C02/0
Our ref: CC6/CTI17023591/Aha3

Date: 16.01.2018

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SKH 9030G


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 11.12.2017 at the premises of M/s MG SOLUTION PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$	22,967.35
Revised Estimate Amount	: S\$	11,502.75
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 7 days

Yours faithfully,

ADRIAN LING
Licensed Appraiser

18	BOOTLID INNER TRIM <i>new</i>	1	\$ 900.30	\$ 900.30	✓
19	REAR BUMPER <i>Disturbed</i>	1	\$ 1,130.60	\$ 1,130.60	✓
20	REAR BUMPER TOWING COVER <i>old</i>	1	\$ 70.50	\$ 70.50	✓
21	REAR BUMPER SPONGE <i>old</i>	1	\$ 310.90	\$ 310.90	✓
22	REAR BUMPER REINFORCEMENT BAR <i>Best</i>	1	\$ 833.20	\$ 833.20	567.20
23	TAIL LAMP PANEL RH <i>2 Disturbed</i>	1	\$ 493.00	\$ 493.00	243.80
24	TAIL LAMP PANEL LH	1	\$ 493.00	\$ 493.00	243.80
25	TAILLAMP RH <i>3 old</i>	1	\$ 638.50	\$ 638.50	455.50
26	TAILLAMP LH	1	\$ 638.50	\$ 638.50	455.50
27	REAR END PANEL <i>Disturbed</i>	1	\$ 832.50	\$ 832.50	753.60
28	REAR END PANEL TOP GARNISH <i>Disturbed</i>	1	\$ 524.00	\$ 524.00	295
29	REAR FLOOR PANEL <i>2pc</i>	1	\$ 2,200.00	\$ 2,200.00	+
30	REAR FLOOR PANEL TOP BOARD <i>new</i>	1	\$ 752.50	\$ 752.50	+
31	EXHAUST PIPE <i>Best</i>	1	\$ 1,050.20	\$ 1,050.20	✓

8997.50
8097.75

TOTAL PRICE \$ 19,321.50
LESS 10% \$ 1,932.15
SUB TOTAL PRICE \$ 17,389.35

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	BOOTLID INNER TRIM CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00	+
2	REAR BUMPER CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00	✓
3	TAIL LAMP CLIP (SET) <i>new</i>	1	\$ 25.00	\$ 25.00	✓
4	REAR END PANEL TOP GARNISH CLIPS (SET) <i>new</i>	1	\$ 30.00	\$ 30.00	10
5	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 100.00	\$ 100.00	60
6	REAR FLOOR PANEL INSULATION SEAL <i>new</i>	1	\$ 100.00	\$ 100.00	x
7	REVERSE CAMERA <i>2nd</i>	1	\$ 813.00	\$ 813.00	450
8	REVERSE SENSOR <i>2nd</i>	1	\$ 220.00	\$ 220.00	✓

795

TOTAL \$ 1,348.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,800.00	1200	
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,800.00	1200	
3	TUFF COAT	\$ 120.00	60	
4	WIRING CHECK	\$ 150.00	30	
5	TO REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 120.00	60	

6	TRANSFER BOOTLID MECHANISM	\$ 120.00	60	
7	CONDUCT WATER LEAKAGE TEST	\$ 120.00	x	

TOTAL

\$4,230.00

2610

ESTIMATE REPORT

TOTAL PARTS COST : \$ 18,737.35

TOTAL LABOUR COST : \$ 4,230.00

TOTAL REPAIR COST : \$ 22,967.35

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

FAX :

PART BY PART / LUMP SUM :

NO OF DAYS :

Adrian Lij
c/s 12/12/17.

07 days.

total: 11,502.75
c/s: 9.2k.

9.2k

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting.
- To display damaged part(s) during resurvey.
- Parts prices are subject to confirmation.
- Third party survey is on a "Without Prejudice" basis.
- No illegal modification(s) is allowed.
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company.

Acknowledged by Repairer

Signature:

Date:

Vic (LKKAUTO)

From: MG Solution <mg3solution@gmail.com>
Sent: Friday, 2 March, 2018 11:04 AM
To: Vic (LKKAUTO)
Cc: Asher Sng (LKKAUTO); Admin A
Subject: Re: 3rd Party Claim for Accident involving Vehicle SKH 9030G & GBC 8140L on 09/12/2017 LKK REF CC6/CTI17023591/Aha3s2
Attachments: DV for SKH9030G.pdf; TI189058 for SKH9030G (SMG188035).pdf

Your Ref: **CC6/CTI17023591/Aha3s2 (GBC8140L)**

Our Ref: **SKH9030G**

Dear Vic,

Please find attached **TAX INVOICE** and our duty signed **DV** by our client for your kind onward action. Original copy will sent to you by post.

Best Regards,

Su Wong
MG SOLUTION PTE LTD
No 23 Kaki Bukit Avenue 4
AAS Kaki Bukit Centre
#02-03B Singapore 415933
Tel: 6243 1373 | Fax: 6243 1376

On Wed, Feb 7, 2018 at 11:29 AM, Vic (LKKAUTO) <vicalpeh@lkkauto.com> wrote:

Without Prejudice

Dear Su Wong,

We refer further to our below email.

Purely for an amicable settlement on a without prejudice basis and without admission of liability to our Insured's part, we have our principal's mandate and we offer a global sum of **\$10,650.00** (all in) to settle your client's claim.

If agreeable, kindly let the owner sign the enclosed DV then forward to us a the original hard copy together with the LOD, Final Repair Invoice and all supporting documents for payment processing.

The above amount is to be made payable to **MG SOLUTION PTE LTD.**

Thank you.

"Please note that our above offer and any settlement arising from the above offer are made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our Insured Driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From: Vic (LKKAuto)

Sent: Wednesday, 7 February, 2018 10:15 AM

To: MG Solution

Cc: Asher Sng (LKKAuto); Vic (LKKAuto); Admin A

Subject: RE: 3rd Party Claim for Accident involving Vehicle SKH 9030G & GBC 8140L on 09/12/2017 LKK REF CC6/CTI17023591/Aha3s2

Without Prejudice

Dear Su Wong,

We refer to your below email and the contents were noted.

We will get back to you for an update/offer.

Thank you.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From: MG Solution [<mailto:mg3solution@gmail.com>]

Sent: Wednesday, 7 February, 2018 9:44 AM

To: Vic (LKKAuto)

Cc: Asher Sng (LKKAuto)

Subject: 3rd Party Claim for Accident involving Vehicle SKH 9030G & GBC 8140L on 09/12/2017

Your Ref: **GBC 8140L**

Our Ref: **SKH 9030G**

Dear Vic,

Please find attached our LOD for your onward action. Original Copy will send to you by **POST**.
Please feel free to contact the under mentioned should you require any further information.
Your prompt action will be greatly appreciated.

Best Regards,

Su Wong

MG SOLUTION PTE LTD

No 23 Kaki Bukit Avenue 4

AAS Kaki Bukit Centre

#02-03B Singapore 415933

Tel: 6243 1373 | Fax: 6243 1376




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref : CC6/CTI17023591/Aha3s2	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Date : 07-03-2018	
			Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBC 8140L	Veh. Inspected	SKH 9030G	
Policy No.	DMCVSN3058691703	Coverage (\$)	0.00	
Claim No.	SNM17D07027/C02/0	Excess (\$)	0.00	
Assign From		Assign Date	11/12/2017	
2. Vehicle Particulars & Condition				
Make & Model	LEXUS GS300	c.c	2995	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	JTHBH96SX05062845	Colour	WHITE	
Odometer	117036	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/50R17	YOKOHAMA	6 mm	
L/H Front Tyre	225/50R17	YOKOHAMA	6 mm	
R/H Rear Tyre	225/50R17	YOKOHAMA	6 mm	
L/H Rear Tyre	225/50R17	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	09/12/2017	Inspection Date	11/12/2017	
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKH 9030G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	SIDE FENDER RH	TO REPAIR SEE LABOUR	1,602.30	-
1	SIDE FENDER LH	TO REPAIR SEE LABOUR	1,602.30	-
1	BOOTLID	DISTORTED	1,150.20	1,150.20
1	BOOTLID MOULDING	CRACKED	765.20	765.20
1	BOOTLID LOGO	NECESSARY	70.80	70.80
1	BOOTLID EMBLEM "LEXUS"	NECESSARY	70.80	70.80
1	BOOTLID EMBLEM "GS300"	NECESSARY	70.80	70.80
1	BOOTLID NUMBER PLATE LIGHT	CRACKED	109.30	109.30
1	BOOTLID TOP LOCK	DAMAGED	730.30	458.00
1	BOOTLID LOWER CATCH	NOT NECESSARY	82.40	-
1	BOOT LID LAMP RH	CRACKED	612.50	235.90
1	BOOT LID LAMP LH	CRACKED	612.50	235.90
1	BOOTLID WEATHERSTRIP	CUT	253.20	253.20
2	BOOTLID DAMPER @ \$30.00	NOT NECESSARY	60.00	-
2	BOOTLID SHOCK ABSORBER @ \$250.60	NOT NECESSARY	501.20	-
1	BOOTLID HINGE COVER RH	NOT NECESSARY	80.00	-
1	BOOTLID HINGE COVER LH	NOT NECESSARY	80.00	-
1	BOOTLID INNER TRIM	NOT NECESSARY	900.30	-
1	REAR BUMPER	DISTORTED	1,130.60	1,130.60
1	REAR BUMPER TOWING COVER	DEFORMED	70.50	70.50
1	REAR BUMPER SPONGE	CRACKED	310.90	310.90
1	REAR BUMPER REINFORCEMENT BAR	BENT	833.20	567.20
1	TAIL LAMP PANEL RH	DENTED	493.00	243.80
1	TAIL LAMP PANEL LH	DENTED	493.00	243.80
1	TAILLAMP RH	CRACKED	638.50	455.90
1	TAILLAMP LH	CRACKED	638.50	455.90
1	REAR END PANEL	DISTORTED	832.50	753.60
1	REAR END PANEL TOP GARNISH	DEFORMED	524.00	295.00
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	2,200.00	-

Report Ref No. CC6/CT117023591/Aha3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR FLOOR PANEL TOP BOARD	NOT NECESSARY	752.50	-
1	EXHAUST PIPE	BENT	1,050.20	1,050.20
	LESS 10% DISCOUNT		-1,932.15	-899.75
			17,389.35	8,097.75
	SPECIAL NETT ITEMS			
1	SET BOOTLID INNER TRIM CLIP (SN)	NOT NECESSARY	30.00	-
1	SET REAR BUMPER CLIP (SN)	NECESSARY	30.00	30.00
1	SET TAIL LAMP CLIP (SN)	NECESSARY	25.00	25.00
1	SET REAR END PANEL TOP GARNISH CLIPS (SN)	NECESSARY	30.00	10.00
1	REAR END PANEL INSULATION SEAL (SN)	NECESSARY	100.00	60.00
1	REAR FLOOR PANEL INSULATION SEAL (SN)	NOT NECESSARY	100.00	-
1	REVERSE CAMERA (SN)	DAMAGED	813.00	450.00
1	REVERSE SENSOR (SN)	DAMAGED	220.00	220.00
			1,348.00	795.00
	LABOUR			
	PANEL BEATING, REMOVAL AND REPLACING PARTS. INCLUSIVE OF THE REPAIR OF SIDE FENDER RH, SIDE FENDER LH AND REAR FLOOR PANEL.		1,800.00	1,200.00
	TO SPRAY PAINT AFFECTED AREA.		1,800.00	1,200.00
	TUFF COAT.		120.00	60.00
	WIRING CHECK.		150.00	30.00
	TO REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING.		120.00	60.00
	TRANSFER BOOTLID MECHANISM.		120.00	60.00
	CONDUCT WATER LEAKAGE TEST.	NOT NECESSARY	120.00	-
			4,230.00	2,610.00
	GRAND TOTAL		22,967.35	11,502.75
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			9,200.00

Report Ref No. CC6/CTI17023591/Aha3s2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.