
Vah No: SKV 8048 / Yr Regn: 01 OCT 2015

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make Honda vezei cc 1496

Colour Red A/C Insured / Std / NI / NA

Sp. Reading 27528 T.Radio: Insured / Std / NI / NA

Eng/No:

C/No RU1102746

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: Inoperable / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Type Size: F: 25/60 R46

2. 0. 1.

BS / DUB / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Sal 716 1000

L/Bal. 46 mm

D.O.A.

Survey held at W/S 4pm

Des. of Damages: Frt / Rear / (O/S) N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

The U/C / Chassis frame / Body Structure affected due to collision

"NO PHOTO FILMS"

☐: Prel. Report

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

Transportation

Add Fee: Site Insp (\$

1. *Journal of the American Medical Association*, 1997; 277: 1033-1037.

□ interview (S

	Tech. Invs.	\$
--	-------------	----

☐ Weekend \$

— 22 —

Lump Sum / I.B.I.: (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC4/AIG17023594/Ghb3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 12-12-2017



Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGR 2959T	Veh. Inspected	SKV 8048P
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	12/12/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer		Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	06/12/2017	Inspection Date	11/12/2017
Survey held at	ETHICARZ PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Singapore NRIC
Owner ID	6912H
Vehicle Details	
Vehicle No.	SKV8048P
Vehicle to be Exported	No
Intended De-registration Date	13 Dec 2017
Vehicle Make	HONDA
Vehicle Model	VEZEL 1.5X CVT
Primary Colour	Red
Manufacturing Year	2015
Engine No.	L15B4022755
Chassis No.	RU11102746
Maximum Power Output	96.0 kW (128 bhp)
Open Market Value	\$19,709.00
Original Registration Date	01 Oct 2015
First Registration Date	01 Oct 2015
Transfer Count	0
Actual ARF Paid	\$9,709.00
Intended PARF Rebate Details	
PARF Eligibility	Yes
PARF Eligibility Expiry Date	30 Sep 2025
PARF Rebate Amount	\$7,281.00
Intended COE Rebate Details	
COE Expiry Date	30 Sep 2025
COE Category	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years)	10
QP Paid	\$56,209.00
COE Rebate Amount	\$43,827.00
Total Rebate Amount	\$51,108.00

The information contained herein is correct as at 13 Dec 2017

OK



Ethicarz Pte. Ltd. 56 Loyang Way, Singapore (508775) #04-04
Loyang Enterprise Building, Email: johnong@ethicarz.sg
Tel: 63844404, FAX: 63840444

VEHICLE NUM:	SV 804BP
MAKE & MODEL:	HONDA VEZEL
MILEAGE:	37520
TYRE:	CHASPGC EL 500 215/60 R16 95H
CHASSIS NUM:	RUI - 1102746

ATTN:		
QTY	DESCRIPTION - PARTS	PRICE
1.	front head lamp (R) R / CEA	
1	front head lamp clip (R) X	
1.	front bumper X	NN
1.	front bumper clip X	
2	front bumper bracket (L+R) X	
2	front bumper retainer (L+R) RH - MEC	
1.	Front Bumper X NN	repair
1.	Front fender (R) - MEC	
1.	Front fender cowling clip (R) - MEC	
1.	Front fender cowling clip garnish (R) - RE	
1.	Front fender cowling garnish clip (R) - MEC.	
1.	Front door (R) - MEC.	
1.	Front door power motor (R) X NN	
1.	Front door regulator (R) R / BT	
1.	Front door window sticker (R) - MEC.	
1.	Front door lock (R) X	NN
1.	Front door handle (R) X	
1.	Front door outer mould (R) X	
1.	Front door • board (R) X	
1.	Front door weather strip (R) R / MEC	
1.	Front door pillar (R) X Repair.	
1.	Front door hinge up / down (R) - BT	
1.	Front door checker (R) R / BT	
1.	Front door inner weather strip (R) X NN	
1.	Front door lower rubber (R) R / MEC	
1.	Front fender inner panel (R) X repair.	
1.	Front Rocker Panel R / (R) MEC	
1.	Front Rocker Panel Garnish (R) - RE.	
1.	Front Rocker Panel Garnish Clip (R) - MEC.	
1.	Front door step garnish (R) X	NN
1.	Front door step garnish clip (R) X	
1.	Front window glass mould. X	
1.	Front tyre absorber (R) X	
1.	Front tyre knuckle (R) X	
1.	Front tyre knuckle bearing (R) - MEC	
1.	Front tyre lower arm X NN	

	Special Nett				
	Front Rim	X	(R)	NN	500
	Front tyre	-	(K)	SCR	100 200
	Front door pillar sealant	(R)	X		100
	Rockers panel sealant	(R)	X	NN	100
	Front windscreen glass sealant (R)	X			80
QTY	DESCRIPTION - PARTS LABOUR				PRICE

1.	To R/R Accident affected (Front)	600 800	1800
1.	To R/R ad respray accident affected (Front)	800	1600
1.	To Rust proof accident affected area (Front)	60	90
1.	To reassemble door mechanism	60	120
1.	To check wiring light and headlamp focus	30	120
1.	To R/R front windscreen glass	X	180
1.	To R/R front dashboard mechanism	200 X	400
1.	To R/R upholstery & attach part	60	300
1.	To R/R front undercarriage system	40	280
1.	To check wheel alignment	60	150
1.	To check chassis alignment	NN / X	400
1.	To check water seepage	X	80

7 Days.

Guo Qiang - 85880282

Guo Qiang @ lkk auto . com

Lumpsum repair.

After repair photos.

11/12/17.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company


Acknowledged by Repairer

Signature:

Date:

- Pre repair inspection request - SKV8048P VS SGR2959T (OI) DOA: 06/12/2017

- Pre repair inspection request - SKV8048P VS SGR2959T (OI) DOA: 06/12/2017

From: Chan, Yoke Shi
To: assignments, Admin A
Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim; Noor Mariesa; Md Ishak; Mohd Imran; Lim, Sheng Yang
Sent: Monday, 11 December 2017 11:42:59 AM
Attachments:  SGR2959T - PRI.TIF

Hi,

Please refer to the enclosed request from **Ethicarz Pte Ltd**.

Kindly carry out Policy coverage verification first before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.

** Please assist to have survey by today if possible. **

Thank you.

Regards,

Yoke Shi @ Ashley

AIG

Claim Adjuster II, Singapore FNOI, Claims Operations - Auto
Shared Services - Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)
Menara Worldwide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia
Tel +6 03 2719 6000 | Ext 1012102

yokeshi.chan@aig.com | www.aig.com

From: John Ong [mailto:claims@ethicarz.sg]
Sent: Monday, December 11, 2017 10:46 AM
To: Chan, Yoke Shi
Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim; Noor Mariesa; Md Ishak; Mohd Imran; Lim, Sheng Yang
Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLES GR2959T AND SKV8048P ON 06/12/2017

Dear Ashley,

Please have anyone in LKK survey the vehicle, by today if possible.

Best Regards,
John Ong

Sent from Mail for Windows 10

From: Chan, Yoke Shi
Sent: Monday, 11 December 2017 9:07 AM
To: claims@ethicarz.sg
Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim; Noor Mariesa; Md Ishak; Mohd Imran; Lim, Sheng Yang
Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLES GR2959T AND SKV8048P ON 06/12/2017

Dear Sir/Madam,

Reminder for pre-repair survey.

11/12/2017 @ 1:18pm
John veh in
60

Vic (LKKAUTO)

From: Shu Pei (LKKAUTO)
Sent: Thursday, 14 December, 2017 11:43 AM
To: Loh, Chee-Heng
Cc: Chan, Yoke Shi; Abu Kassim, Noor Mariesa; Lim, Sheng Yang; Admin A; Vic (LKKAUTO); Asher Sng (LKKAUTO)
Subject: RE: 8475827674SG-007, accident involving SGR2959T and SKV8048P on 6 Dec 2017
****LKK REF:CC4/AIG17023594/GHB3

Dear Chee Heng,

Thank you for your email.

Our respective case handler will look into the matter and revert to you in due course.

Dear Vic,

For your information and necessary action please.

To check availability of the case handler, you may contact the undersigned.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Loh, Chee-Heng [mailto:Chee-Heng.Loh@aig.com]
Sent: Thursday, 14 December, 2017 8:42 AM
To: Admin A <admin-a@lkkauto.com>
Cc: Chan, Yoke Shi <yokeshi.chan@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>; Lim, Sheng Yang <ShengYang.Lim@aig.com>
Subject: 8475827674SG-007, accident involving SGR2959T and SKV8048P on 6 Dec 2017

Dear Sir,

Noted that SHD9684B hit onto 3 parked vehicles, SLD5333T -> OIV -> TPV.

Thus, BOLA 28 does not apply for this accident. Kindly assist to redirect PD claim from SKV8048P to the insurer of SHD9684B.

Thank you.

Best regards,
Loh Chee Heng
AIG

Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore(079120)

Tel +(65) 6419 1881 | Fax +(65) 6835 7416

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: Chan, Yoke Shi
Sent: Monday, December 11, 2017 11:43 AM
To: assignments; Admin A
Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang
Subject: aigencrypt - Pre repair inspection request - SKV8048P VS SGR2959T (OI) DOA: 06/12/2017

Hi,

Please refer to the enclosed request from **Ethicarz Pte Ltd**.

Kindly carry out Policy coverage verification **first** before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.

**** Please assist to have survey by today if possible. ****

Thank you.

Regards,

Yoke Shi @ Ashley
AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto
Shared Services – Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)
Menara Worldwide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia
Tel +6 03 2719 6000 | Ext 1012102

yokeshi.chan@aig.com | www.aig.com

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Vic (LKKAuto)

From: Vic (LKKAuto)
Sent: Thursday, 14 December, 2017 1:53 PM
To: claims@ethicarz.sg; johnong@ethicarz.sg
Cc: Admin A; Vic (LKKAuto); Asher Sng (LKKAuto)
Subject: Your Ref: SKV 8048P_ACCIDENT INVOLVING VEHICLES SGR 2959T AND SKV 8048P ON 06/12/2017
Attachments: SGR 2959T STATEMENT.pdf

Your Ref: SKV 8048P
Our Ref: CC4/AIG17023594/Ghb3

Without Prejudice

Dear Sir/Madam,

ACCIDENT INVOLVING VEHICLES SGR 2959T AND SKV 8048P ON 06/12/2017

We refer to the above matter.

Our principal had further reviewed the matter and based on the scenario, BOLA 28 (chain collision) is not applicable for this matter. Please refer to our Insured's statement (enclosed).

As such, you may redirect the claim to the insurer of the taxi SHD 9684B instead.

We will now close the matter.

Thank you.


Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contains confidential and privileged material, and is for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

Vic (LKKAUTO)

From: Vic (LKKAUTO)
Sent: Thursday, 14 December, 2017 1:55 PM
To: Shu Pei (LKKAUTO); Loh, Chee-Heng
Cc: Chan, Yoke Shi; Abu Kassim, Noor Mariesa; Lim, Sheng Yang; Admin A; Asher Sng (LKKAUTO); Vic (LKKAUTO)
Subject: RE: 8475827674SG-007, accident involving SGR2959T and SKV8048P on 6 Dec 2017 *****LKK REF:CC4/AIG17023594/GHB3

Dear Chee Heng,

We refer to your below email and the contents were noted.

We will inform TP to redirect claim and submit WP report.

Thank you.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From: Shu Pei (LKKAUTO)
Sent: Thursday, 14 December, 2017 11:43 AM
To: Loh, Chee-Heng
Cc: Chan, Yoke Shi; Abu Kassim, Noor Mariesa; Lim, Sheng Yang; Admin A; Vic (LKKAUTO); Asher Sng (LKKAUTO)
Subject: RE: 8475827674SG-007, accident involving SGR2959T and SKV8048P on 6 Dec 2017 *****LKK REF:CC4/AIG17023594/GHB3

Dear Chee Heng,

Thank you for your email.

Our respective case handler will look into the matter and revert to you in due course.

Dear Vic,

For your information and necessary action please.

To check availability of the case handler, you may contact the undersigned.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupe@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Loh, Chee-Heng [<mailto:Chee-Heng.Loh@aig.com>]

Sent: Thursday, 14 December, 2017 8:42 AM

To: Admin A <admin-a@lkkauto.com>

Cc: Chan, Yoke Shi <yokeshi.chan@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>; Lim, Sheng Yang <ShengYang.Lim@aig.com>

Subject: 84758276745G-007, accident involving SGR2959T and SKV8048P on 6 Dec 2017

Dear Sir,

Noted that SHD9684B hit onto 3 parked vehicles, SLD5333T -> OIV -> TPV.

Thus, BOLA 28 does not apply for this accident. Kindly assist to redirect PD claim from SKV8048P to the insurer of SHD9684B.

Thank you.

Best regards,

Loh Chee Heng

AIG

Complex Claims Examiner

Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore(079120)

Tel +(65) 6419 1881 | Fax +(65) 6835 7416

Chee-Heng.Loh@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: Chan, Yoke Shi

Sent: Monday, December 11, 2017 11:43 AM

To: assignments; Admin A

Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang

Subject: algencrypt - Pre repair inspection request - SKV8048P VS SGR2959T (OI) DOA: 06/12/2017

Hi,

Please refer to the enclosed request from **Ethicarz Pte Ltd**.

Kindly carry out Policy coverage verification **first** before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.

**** Please assist to have survey by today if possible. ****

Thank you.

Regards,

Yoke Shi @ Ashley

AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto
Shared Services – Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)

Menara Worldwide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia

Tel +6 03 2719 6000 | Ext 1012102

yokeshi.chan@aig.com | www.aig.com

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Revoked / No settlement




































CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Dec 2017 Edit Reg		11 Dec 2017 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:		CHIA SEOW POH KAREN, ID: -							
Main Claimant:		LIM MENG CHEE							
Vehicle Reg. No.:		SKV8048P	Date of Loss:	06/12/2017 00:00 - :59					
Claim Type:		TP / 8475827674SG	Policy/Cover Note No.:	(Comprehensive)					
Vehicle Reg. No. (Insured):		SGR2959T	Policy No. (Claimant):						
		Excess:							
Repairer:		Ethicarz Pte Ltd (HQ) 56 LOYANG WAY #04-04 LOYANG ENTERPRISE BUILDING, 508775 Loyang - Tel: 63844404							
Handling Insurer:		AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 21/12/2017]							
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKV8048P (8475827674SG)
[SGR2959T]
TP
LIM MENG CHEE
Dec 6 2017 12:00AM
[CHIA SEOW POH KAREN]
Ethicarz Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View <div>View in Browser</div>	
Photos/Images										3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	14/12/17 14:12	Odometer Reading							 Load JPG	<input checked="" type="checkbox"/>	
2	14/12/17 14:12	Chassis Number							 Load JPG	<input checked="" type="checkbox"/>	
3	14/12/17 14:12	General View							 Load JPG	<input checked="" type="checkbox"/>	
4	14/12/17 14:12	General View							 Load JPG	<input checked="" type="checkbox"/>	
5	14/12/17 14:12	General View							 Load JPG	<input checked="" type="checkbox"/>	
6	14/12/17 14:12	General View							 Load JPG	<input checked="" type="checkbox"/>	
7	14/12/17 14:12	General View							 Load JPG	<input checked="" type="checkbox"/>	
8	14/12/17 14:12	General View							 Load JPG	<input checked="" type="checkbox"/>	
9	14/12/17 14:12	General View							 Load JPG	<input checked="" type="checkbox"/>	
10	14/12/17 14:12	General View							 Load JPG	<input checked="" type="checkbox"/>	
11	14/12/17 14:12	General View							 Load JPG	<input checked="" type="checkbox"/>	
12	14/12/17 14:12	General View							 Load JPG	<input checked="" type="checkbox"/>	
13	14/12/17 14:12	General View							 Load JPG	<input checked="" type="checkbox"/>	
14	14/12/17 14:12	General View							 Load JPG	<input checked="" type="checkbox"/>	
15	14/12/17 14:12	General View							 Load JPG	<input checked="" type="checkbox"/>	
16	14/12/17 14:12	General View							 Load JPG	<input checked="" type="checkbox"/>	
17	14/12/17 14:12	General View							 Load JPG	<input checked="" type="checkbox"/>	
18	14/12/17 14:12	General View							 Load JPG	<input checked="" type="checkbox"/>	
19	14/12/17 14:12	General View							 Load JPG	<input checked="" type="checkbox"/>	
20	14/12/17 14:12	General View							 Load JPG	<input checked="" type="checkbox"/>	
21	14/12/17 14:12	General View							 Load JPG	<input checked="" type="checkbox"/>	
22	14/12/17 14:12	General View							 Load JPG	<input checked="" type="checkbox"/>	
23	14/12/17 14:12	General View							 Load JPG	<input checked="" type="checkbox"/>	
24	14/12/17 14:12	General View							 Load JPG	<input checked="" type="checkbox"/>	
25	14/12/17 14:12	General View							 Load JPG	<input checked="" type="checkbox"/>	
26	14/12/17 14:12	General View							 Load JPG	<input checked="" type="checkbox"/>	
27	14/12/17 14:12	General View							 Load JPG	<input checked="" type="checkbox"/>	
28	14/12/17 14:12	General View							 Load JPG	<input checked="" type="checkbox"/>	
29	14/12/17 14:12	General View							 Load JPG	<input checked="" type="checkbox"/>	
30	14/12/17 14:12	General View							 Load JPG	<input checked="" type="checkbox"/>	
31	14/12/17 14:12	General View							 Load JPG	<input checked="" type="checkbox"/>	
32	14/12/17 14:12	General View							 Load JPG	<input checked="" type="checkbox"/>	
33	14/12/17 14:12	General View							 Load JPG	<input checked="" type="checkbox"/>	
34	14/12/17 14:12	General View							 Load JPG	<input checked="" type="checkbox"/>	
35	14/12/17 14:12	General View							 Load JPG	<input checked="" type="checkbox"/>	

36	14/12/17 14:12	General View	1	Load JPG	<input checked="" type="checkbox"/>
37	14/12/17 14:12	General View	1	Load JPG	<input checked="" type="checkbox"/>
38	14/12/17 14:12	General View	1	Load JPG	<input checked="" type="checkbox"/>
39	14/12/17 14:12	General View	1	Load JPG	<input checked="" type="checkbox"/>
40	14/12/17 14:12	General View	1	Load JPG	<input checked="" type="checkbox"/>
41	14/12/17 14:12	General View	1	Load JPG	<input checked="" type="checkbox"/>
42	14/12/17 14:12	General View	1	Load JPG	<input checked="" type="checkbox"/>
43	14/12/17 14:12	General View	1	Load JPG	<input checked="" type="checkbox"/>
44	14/12/17 14:12	General View	1	Load JPG	<input checked="" type="checkbox"/>
45	14/12/17 14:12	General View	1	Load JPG	<input checked="" type="checkbox"/>
46	14/12/17 14:12	General View	1	Load JPG	<input checked="" type="checkbox"/>
47	14/12/17 14:16	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
48	14/12/17 14:16	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
49	14/12/17 14:16	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
50	14/12/17 14:16	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
51	14/12/17 14:16	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
52	14/12/17 14:16	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
53	14/12/17 14:16	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
54	14/12/17 14:16	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
55	14/12/17 14:16	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
56	14/12/17 14:16	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
57	14/12/17 14:16	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
58	14/12/17 14:16	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
59	14/12/17 14:16	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
60	14/12/17 14:16	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
61	14/12/17 14:16	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
62	14/12/17 14:16	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
63	14/12/17 14:16	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
64	14/12/17 14:16	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
65	14/12/17 14:16	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
66	14/12/17 14:16	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
67	14/12/17 14:16	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
68	14/12/17 14:16	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
69	14/12/17 14:16	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
70	14/12/17 14:16	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
71	14/12/17 14:16	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
72	14/12/17 14:16	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
73	14/12/17 14:16	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
74	14/12/17 14:16	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
75	14/12/17 14:16	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
76	14/12/17 14:16	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
77	14/12/17 14:16	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
78	14/12/17 14:16	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
79	14/12/17 14:16	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
80	14/12/17 14:16	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
81	14/12/17 14:16	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
82	14/12/17 14:16	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
83	14/12/17 14:16	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
84	14/12/17 14:16	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
85	14/12/17 14:16	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>

86	14/12/17 14:16	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
87	14/12/17 14:16	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
88	14/12/17 14:16	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
89	14/12/17 14:16	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
90	14/12/17 14:16	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
91	14/12/17 14:16	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
92	14/12/17 14:16	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
93	14/12/17 14:16	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
94	14/12/17 14:16	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
95	14/12/17 14:16	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
96	14/12/17 14:16	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
97	14/12/17 14:16	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
98	14/12/17 14:16	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
99	14/12/17 14:16	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
100	14/12/17 14:16	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
101	14/12/17 14:16	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
102	14/12/17 14:16	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
103	14/12/17 14:16	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
104	14/12/17 14:16	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
105	14/12/17 14:16	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
106	14/12/17 14:16	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
107	14/12/17 14:16	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
108	14/12/17 14:16	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
109	14/12/17 14:16	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
110	14/12/17 14:16	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
111	14/12/17 14:16	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
Documentation					
				1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	12/12/17 17:08	EMAIL FROM AIG DD 11122017	1	Load PDF	
2	12/12/17 17:08	WKSP NOTICE	1	Load PDF	
3	14/12/17 09:12	TP ESTIMATE- MARKED	1	Load PDF	
4	14/12/17 09:12	TP GIA REPORT	1	Load PDF	
5	14/12/17 12:54	EMAIL FROM AIG	1	Load PDF	
6	14/12/17 14:03	EMAIL TO AIG	1	Load PDF	
7	14/12/17 14:03	EMAIL TO TP	1	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	13/12/17 10:59	OI GIA REPORT	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG17023594/GHB3Q2

Date: 26/01/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SKV8048P

Insured Vehicle No : SGR2959T

Date of Loss: 06/12/2017

Nature of Claim: TP

Claim No: 8475827674SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKV8048P

Make & Model: ADIVA AD200A, 200cc (M)

Engine No: L15B4022755

Reg. Date: 01/10/2015 (Man. Year: 2015)

Chassis No: RU11102746

Colour: Red

Odometer: 37528 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size:

215/60 R16

Front Left Side: Dunlop 6 mm

Rear Left Side:

Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side:

Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 11/12/2017

Date Inspected: 11/12/2017 Inspected At:

Ethicarz Pte Ltd (HQ)
56 LOYANG WAY #04-04 LOYANG
ENTERPRISE BUILDING
Singapore 508775

Estimated Period of Repair: 7.0 days

Adjuster: XING GUO QIANG

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT HEAD LAMP (R)	Cracked	0.00 F	*-F
2	1		*FRONT HEAD LAMP CLIP (R)	Not Necessary	0.00 F	*-F
3	1		*FRONT BUMPER	Not Necessary	0.00 F	*-F
4	1		*FRONT BUMPER CLIP	Not Necessary	0.00 F	*-F
5	2		*FRONT BUMPER BRACKET (L&R)	Not Necessary	0.00 F	*-F
6	1		*FRONT BUMPER RETAINER (L&R)	O/S Necessary	0.00 F	*-F
7	1		*FRONT BONNET	Not Necessary	0.00 F	*-F
8	1		*FRONT FENDER (R)	Buckled	0.00 F	*-F
9	1		*FRONT FENDER COWLING CLIP (R)	Necessary	0.00 F	*-F
10	1		*FRONT FENDER COWLING GARNISH (R)	Deformed	0.00 F	*-F
11	1		*FRONT FENDER COWLING GARNISH CLIP (R)	Necessary	0.00 F	*-F
12	1		*FRONT DOOR (R)	Buckled	0.00 F	*-F
13	1		*FRONT DOOR POWER MOTOR (R)	Not Necessary	0.00 F	*-F
14	1		*FRONT DOOR REGULATOR (R)	Bent	0.00 F	*-F
15	1		*FRONT DOOR WINDOW STICKER (R)	Necessary	0.00 F	*-F
16	1		*FRONT DOOR LOCK (R)	Not Necessary	0.00 F	*-F
17	1		*FRONT DOOR HANDLE (R)	Not Necessary	0.00 F	*-F
18	1		*FRONT DOOR OUTER MOULD (R)	Not Necessary	0.00 F	*-F
19	1		*FRONT DOOR BOARD (R)	Not Necessary	0.00 F	*-F
20	1		*FRONT DOOR WEATHER STRIP (R)	Necessary	0.00 F	*-F
21	1		*FRONT DOOR PILLAR (R)	Repair	0.00 F	*-F
22	1		*FRONT DOOR HINGE UP /DOWN (R)	Bent	0.00 F	*-F
23	1		*FRONT DOOR CHECKER (R)	Bent	0.00 F	*-F
24	1		*FRONT DOOR INNER WEATHER STRIP (R)	Not Necessary	0.00 F	*-F
25	1		*FRONT DOOR LOWER RUBBER (R)	Necessary	0.00 F	*-F
26	1		*FRONT FENDER INNER PANEL (R)	Repair	0.00 F	*-F
27	1		*FRONT ROCKER PANEL (R)	Buckled	0.00 F	*-F
28	1		*FRONT ROCKER PANEL GARNISH (R)	Deformed	0.00 F	*-F
29	1		*FRONT ROCKER PANEL GARNISH CLIP (R)	Necessary	0.00 F	*-F
30	1		*FRONT DOOR STEP GARNISH (R)	Not Necessary	0.00 F	*-F
31	1		*FRONT DOOR STEP GARNISH CLIP (R)	Not Necessary	0.00 F	*-F
32	1		*FRONT WINDSCREEN GLASS MOULD	Not Necessary	0.00 F	*-F
33	1		*FRONT TYRE ABSORBER (R)	Not Necessary	0.00 F	*-F
34	1		*FRONT TYRE KNUCKLE (R)	Not Necessary	0.00 F	*-F
35	1		*FRONT TYRE KNUCKLE BEARING (R)	Necessary	0.00 F	*-F
36	1		*FRONT TYRE LOWER ARM	Not Necessary	0.00 F	*-F
37	1		*FRONT RIM (R)	Not Necessary	0.00 F	*-F
38	1		*FRONT TYRE (R)	Scratched	0.00 F	*-F
39	1		*FRONT DOOR PILLAR SEALANT (R)	Not Necessary	0.00 F	*-F
40	1		*ROCKER PANEL SEALANT (R)	Not Necessary	0.00 F	*-F
41	1		*FRONT WINDSCREEN GLASS SEALANT (R)	Not Necessary	0.00 F	*-F
Total Parts (\$\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >