



Ethicarz Pte. Ltd. 56 Loyang Way, Singapore (508775) #04-04
Loyang Enterprise Building, Email: johnong@ethicarz.sg
Tel: 63844404, FAX: 63840444

VEHICLE NUM:
MAKE & MODEL:
MILEAGE:
TYRE:
CHASSIS NUM:

SKH 8958L
RENAULT SCENIC
100402
DIREZZA DZ102 215/55 R17
YFJ209 B34 8401407

ATTN:		CHASSIS NUM:	7HJ204 B34 840140+
QTY	DESCRIPTION - PARTS	PRICE	
1.	TAILGATE X		
1.	TAILGATE LOCK X		
1.	Tailgate weather strip ?		
1.	Tailgate logo (RENAULT) X		
1.	Tailgate emblem (SCENIC) X		
1.	Tailgate emblem (dci) X		
1.	Tailgate opener X		
1.	Tailgate camera X		
2.	Tailgate Carport lamp		
1.	REAR BUMPER. / RL		
1.	REAR BUMPER Reinforcement Bar. ?		
1.	REAR BUMPER SPACER ?		
1.	REAR BUMPER INNER GASKET. ?		
2.	REAR BUMPER CLIP. (LTR) / RL		
2.	REAR BUMPER BRACKET (LTR) ?		
2.	Rear Bump retainer (LTR) / RL		
1.	Rear towing cap. / Cut		
4.	REVERSE SENSOR. ?		
4.	Reverse sensor wiring X NN		
1.	Rear Bumper reflector (LH) / RL		
1.	Rear Bumper Cover. / Cut		
1.	Rear end panel. ?		
1.	Rear end panel top gasket. ?		
1.	Rear floor panel. ?		
1.	Rear floor panel top gasket. X		
1.	Rear exhaust pipe. X Repair		
1.	Rear underbody glass mould. X		
1.	Rear Exhaust Pipe		
1.	Rear exhaust pipe mount X		
1.	Rear Exhaust pipe heat seal. /		
1.	Rear exhaust pipe gasket. X		
	SPECIAL NOTE		
1.	Rear Bumper Sticker /	20	
1.	Rear Windscreen Glass Sealant X	\$ 40-	
1.	Rear end Panel Sealant ?	\$ 80	
1.	Rear floor panel Sealant X	\$ 80	
		\$ 80	

LABOUR.		
1.	To Rep accident affected Back	400-600 \$1500.
1.	To putty and respray accident affected Back	400 \$1200
1.	To refit front accident affected area	? \$ 60
1.	To Rep tailgate windscreen glass	X \$ 120.
1.	To Rep tailgate mechanism	X \$ 80.
QTY	DESCRIPTION - PARTS	PRICE
1.	To check wing and layout and rear reverse sensor function	40 \$ 80
1.	To check wing and layout and rear bumper lower lamp function	30 \$ 80.
1.	To check water seepage	X \$ 80
1.	To Rep exhaust pipe.	80 \$180
1.	To move luggage compartments	

4 Days.

Lump Sum Repair.

After repair photos.

Gmo & op - 8288 0282

13/12/17

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: