

Kalvin

REF: CC3/TMU7023617/Kalvin

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To inspect Vehicle No: \_\_\_\_\_  
 at Workshop No: \_\_\_\_\_  
 of: \_\_\_\_\_  
 Insured: SLE 5839X  
 Policy No: M4007738  
 Claims No: M1706260  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.  
 Bel. or Market Value: \_\_\_\_\_  
 IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR. Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
 Vehicle: IN / OUT



Veh No: SHP4375B Reg: 12 JLY 212  
 Type: M/Car / M/Cycle / Bus / Van / Lorry / T/Tr / Prime Mover /  
 Truck / Trailer or  
 Make: Hyundai Sonata cc: 1894  
 Colour: Blue A/C: In / Std / Nil / NA  
 Sp. Reading: 743459 T. Radio: In / Std / Nil / NA  
 Eng No: \_\_\_\_\_  
 O No: KMHE T41VMCA 827014  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In / Jammed / Leaked / Burnt or  
 Brake: In / Jammed / Leaked / Burnt or  
 Mod: Nil / S/Rim / STD / A/Rim or  
 Tyre Size: F: 215/60R16  
 R: \_\_\_\_\_  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or hankook  
 Front: \_\_\_\_\_ Rear: \_\_\_\_\_  
 R.Bal. 2 mm R.Bal. 2 mm  
 L.Bal. 7 mm L.Bal. 7 mm  
 D.O.A. 12/12/17 D.O.I. 12/12/17  
 Survey held at: COKE (Goyang)  
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or  
o/s front / MS front / Rear  
 The UIC / Chassis frame / Body Structure affected due to collision

Date	Time	Action / Instruction
		SHP 1375 B - NS/INC 16/12/17/973 / High3rd
		SLE 5839X - NA/ATG 17/03/495 / 13

13/12/17 Email GIA to Shirley  
 18/12/17 Cont. of 4s & 6350/4 Py. (Real 9298.68, 5990)

RECEIVED 26 DEC 2017

Date/Time: File Pass to?  : Prel. Report  
 : Final Report  
 Date/Time: File Return to? \_\_\_\_\_  
 : 26/12 - typist  
 Report Format: \_\_\_\_\_, merimen  
 Lump Sum / I.Bil: \$ 6350/2  
 Days Of Repair: 4  
 Resurvey No. of Trip: 1  
 Survey Fee: \_\_\_\_\_  
 Transceptor: \_\_\_\_\_  
 Add Fee:  Site Insp \$ \_\_\_\_\_  
 Interview \$ \_\_\_\_\_  
 Testimony \$ \_\_\_\_\_  
 Weekend \$ \_\_\_\_\_  
 \$-FE \$: \_\_\_\_\_  
 Shop: \_\_\_\_\_  
 Date: \_\_\_\_\_  
 TOTAL: 300  
10

## Survey Department Check List (Case Handler)

Reference No.: CC3/TMI/17023617/Klvb  
 Policy Type: OD/TP/TP RES/TL/EVA

Case Handler

Typist

Admin ( ): Case handler to make sure all Information created by the assignment team are ACCURATE.

		Case Handler		Typist	
		Y-Date	N-Date	Y-Date	N-Date
<b>(1) Office Assign Form</b>					
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA/REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor ( ): Case handler to make sure the surveyor completed all required information.

		Case Handler		Typist	
		Y-Date	N-Date	Y-Date	N-Date
<b>(1) Assignment Form</b>					
C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

<b>(2) System - (Views/Merimen)</b>					
C	Damaged Vehicle Photographs Uploaded	✓			

<b>(3) Workshop Estimate/Assignment Form</b>					
N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

<b>(4) System - (Views/Merimen)</b>					
C	Resurvey photo Uploaded	✓			

Check By: VERON 20/12/17  
 Case Handler Date

\*C: Critical \*N: Non-Critical



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

TOKIO MARINE INSURANCE SINGAPORE LTD Ref : CC3/TMI17023617/K1vb

20 MCCALLUM STREET #09-01  
TOKIO MARINE CENTRESINGAPORE 069046

Date : 12-12-2017



Code : TMI

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLE 5839X	Veh. Inspected	SHD 4375B
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	12/12/2017

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--	--

## 5. General Information

Accident Date	10/12/2017	Inspection Date	12/12/2017
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

**...CLAIM SUBFOLDER...(Pending for Survey Report)**

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Dec 2017 17:52 Sendback Est	12 Dec 2017 18:09 S\$14,700.76	13 Dec 2017 09:08 Edit Adj Rpt				<b>Pending for Survey Report</b> Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS			
<b>Insured:</b>	CTPL, Co. Reg. No.: 199303821R		
<b>Main Claimant:</b>	CTPL		
<b>Vehicle Reg. No.:</b>	<b>SHD4375B</b>	<b>Date of Loss:</b>	10/12/2017 19:00 - :59
<b>Claim Type:</b>	<b>TP / M1706260</b>	<b>Policy/Cover Note No.:</b>	MU007738 (Comprehensive) Coverage: 27/07/2017 - 26/07/2018
<b>Vehicle Reg. No. (Insured):</b>	<b>SLE5839X</b>	<b>Policy No. (Claimant):</b>	
		<b>Excess:</b>	S\$600.00
<b>Repairer:</b>	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300		
<b>Handling Insurer:</b>	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Zheng Hanyang - 65926416]		
<b>Adjuster:</b>	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KALVIN ANG WEI KUN ] ... [Final Rpt due 22/12/2017]		
<b>ASSOCIATED MAIL RECEIVED</b>		<a href="#">View All</a>	<a href="#">Compose Case Mail</a>
There are no mail for this case.			
<input type="checkbox"/> <b>ALL ASSOCIATED TASKS</b> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>			
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b>
<b>Subject</b>	<b>Handler</b>	<b>Assigned By</b>	<b>Completed On</b>
<b>Created On</b>	<b>Done?</b>		
No results.			

Veron Chen (LKKAuto)

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Wednesday, 13 December, 2017 8:53 AM  
**To:** 'Too Joon Hwa'  
**Cc:** SUR; priscilla@tokiomarine.com.sg  
**Subject:** DIRECT SURVEY INSPECTION ON WORKSHOP - COMFORTDELGRO ENGINEERING PTE LTD, DOA: 10/12/2017, SHD 4375B (TP VEHICLE), SLE 5839X (OI VEHICLE)  
**Attachments:** EST.pdf, GIA.pdf

Dear Shirley,

Please be informed that we had inspected the vehicle SHD 4375B M/s: COMFORTDELGRO ENGINEERING PTE LTD, 59 LOYANG DRIVE SINGAPORE 508969

Enclosed herewith a copy of TP's GIA report and estimated cost of repair.

Meanwhile, kindly create claim in merimen for our necessary action.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

SHD 4375B

$$\textcircled{1} \text{ Cost of taxi} = 77367.98$$

$$\text{ARF GST} = 9688.25$$

$$\begin{aligned} \text{Depreciation} &= (77367.98 - 9688.25) \div 96 \\ &= 708.00 \end{aligned}$$

$$\begin{aligned} \textcircled{2} \text{ Book value} &= (708 \times 31) + 9688.25 \\ &= 31543.25 \end{aligned}$$

$$\begin{aligned} \textcircled{3} \text{ Net value} &= 31543.25 - 22528 \\ &= \underline{\underline{\$ 9015.25}} \end{aligned}$$

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	11/12/2017 16:06
Date Of Accident	10/12/2017 19:30
Exact Location Of Accident	MSCP OF BLK 611A CHOA CHU KANG ST
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD4375B
<b>Insured/Policyholder</b>	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGCOM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

### Vehicle Particulars

Manufacturer	HYUNDAI
Model	SONATA-2.0 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0016
Cover Note Number	

### Driver

Name of Driver	KANG FOOK SEN
NRIC No	S1635366C
Date Of Birth	27/11/1964
Occupation	OUTDOOR
Date Of Driving Pass	14/12/1984
Driving Experience	32 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address 611 CHOA CHU KANG STREET 62 #09-171  
 Postcode S680611  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General Information of the Accident**

Type Of Accident HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Was any body injured in the Accident? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 0

**Details of Police Action**

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

PLS SEE ATTACHED

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SLE5839X  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Name of Driver  
 NRIC/Passport Number  
 Contact Number  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage OVERBODY  
 No. Of Passenger (Including Driver)

**Details of Witness**

Name  
 Phone Number  
 Email Address

**DETAILS OF OTHER VEHICLE PROPERTY 2**

Vehicle Registration Number UNKNOWN  
 Vehicle Make/Model/Colour



Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage NOT SURE

No. Of Passenger (Including Driver)

**Details of Witness**

Name

Phone Number

Email Address

**DETAILS OF OTHER VEHICLE PROPERTY 3**

Vehicle Registration Number UNKNOWN

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage NOT SURE

No. Of Passenger (Including Driver)

**Details of Witness**

Name

Phone Number

Email Address

**DETAILS OF OTHER VEHICLE PROPERTY 4**

Vehicle Registration Number UNKNOWN

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage NOT SURE

No. Of Passenger (Including Driver)

**Details of Witness**

Name

Phone Number

Email Address



## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type	Company
Owner ID	3821R

### Vehicle Details

Vehicle No.	SHD4375B
Vehicle to be Exported	Yes
Intended De-registration Date	12 Dec 2017
Vehicle Make	HYUNDAI
Vehicle Model	SONATA NF 2.0 CRDI AT ABS 2WD 4DR TURBO
Primary Colour	Blue
Manufacturing Year	2012
Engine No.	D4EAC120846
Chassis No.	KMHET41VMCA827014
Maximum Power Output	110.0 kW (147 bhp)
Open Market Value	\$14,905.00
Original Registration Date	12 Jul 2012
First Registration Date	12 Jul 2012
Transfer Count	0
Actual ARF Paid	\$14,905.00

### Intended PARF Rebate Details

PARF Eligibility	Yes
PARF Eligibility Expiry Date	11 Jul 2020
PARF Rebate Amount	\$10,433.00

### Intended COE Rebate Details

COE Expiry Date	11 Jul 2020
COE Category	A - Car (1600cc & below)
COE Period(Years)	8
QP Paid	\$37,512.00
COE Rebate Amount	\$12,095.00
Total Rebate Amount	\$22,528.00

### Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 12 Dec 2017

Co. Code : CTFPL  
 Licence Pl. No : SHD4375B  
 Old Asset No :  
 Vch. Model : Hyundai Sonata  
 Reg. Date : 12.07.2012  
 Cap. Date : 12.07.2012  
 Accident. Date : 10.12.2017  
 Vch. Age : 065

Asset No	SA No	Bal. Dep. Mths	Per. Mth. Dep	Bal. Dep. Value	Asset Description 1	Cost	Op. Acc. Dep	Cur. Year Dep	Accum. Dep	Net Book Value	Scrap value/Estimated PP&P Refund
			\$	\$		\$	\$	\$	\$	\$	\$
10029274	0	025	242.54	6,063.50	SHD4375B HSN 12.07.2012 BASIC COST \$21830 W AIRCON	21,830.00	13,097.40	2,667.99	15,765.39	6,064.61	1.00
10029274	1	025	33.12	828.00	SHD4375B HSN 12.07.2012 IMPORT DUTY	2,980.98	1,788.59	364.34	2,152.93	828.05	0.00
10029274	2	025	66.24	1,656.00	SHD4375B HSN 12.07.2012 ASF 10090W914905	14,995.00	3,577.20	728.69	4,305.89	10,599.11	8,943.00
10029274	3	025	416.80	10,420.00	SHD4375B HSN 12.07.2012 COE 80%	37,512.00	22,507.20	4,584.80	27,092.00	10,420.00	0.00
10029274	4	000	0.00	0.00	SHD4375B HSN 12.07.2012 COE TOP UP	0.00	0.00	0.00	0.00	0.00	0.00
10029274	5	025	0.00	0.00	SHD4375B HSN 12.07.2012 AIR CONDITIONER	0.00	0.00	0.00	0.00	0.00	0.00
10029274	6	025	0.00	0.00	SHD4375B HSN 12.07.2012 PRINTER DIGITAL THERMAL	0.00	0.00	0.00	0.00	0.00	0.00
10029274	7	025	0.00	0.00	SHD4375B HSN 12.07.2012 TAXIMETER DIGITAX FI	0.00	0.00	0.00	0.00	0.00	0.00
10029274	8	025	1.56	39.00	SHD4375B HSN 12.07.2012 VEH REG FEE	140.00	84.01	17.11	101.12	38.88	0.00
			760.26	19,006.50		77,367.98	41,054.40	8,362.93	49,417.33	27,950.65	

Vehicle : Without T/M & COE  
 Vehicle : Without T/M, With COE  
 Taximeter

COE	416.80	10,420.00
Vehicle	343.46	6,586.50
	760.26	19,006.50

## JOB REQUISITION FOR BREAKDOWN / TOWING SERVICE

Job Requisition		
1. Date: <u>11/12/2012</u> Time Received: <u>12:52am</u> 2. <input type="checkbox"/> New <input type="checkbox"/> SPARK Kakis Name of Customer : _____ Contact No. : <u>91463193</u> Vehicle No. : <u>S4D4375B</u> Make / Model / Colour : <u>Savitar Blue</u> Email : _____	3. Vehicle Type: <input type="checkbox"/> Private <input checked="" type="checkbox"/> Taxi (CTPL/CCPL) <input type="checkbox"/> Fleet <input type="checkbox"/> STK (Boon Lay) 4. Type of Towing: <input type="checkbox"/> Normal Tow <input type="checkbox"/> King Dolly <input type="checkbox"/> Flat Bed <input type="checkbox"/> Crane-up 5. Nature of Service: <input type="checkbox"/> Jumpstart <input checked="" type="checkbox"/> Recovery <input type="checkbox"/> Change Tyre / Battery 6. Parts Replaced/Remarks: <u>(MSCP)</u>	
Location: <u>611A CCK S1 62 MSCP 101</u> Workshop: <input type="checkbox"/> Braddell <input checked="" type="checkbox"/> Loyang <input type="checkbox"/> Sin Ming <input type="checkbox"/> Sungei Kadut <input type="checkbox"/> Senoko <input type="checkbox"/> Komoco (UBI / Leng Kee) <input type="checkbox"/> Others: _____ <input type="checkbox"/> Pandan <input type="checkbox"/> Ubi <input type="checkbox"/> Cycle & Carriage (PD)	8. Vehicle Tow - In Workshop: <input type="checkbox"/> Smoky Exhaust <input type="checkbox"/> Wheel Jammed <input type="checkbox"/> Overheating <input type="checkbox"/> Steering Faulty <input type="checkbox"/> Brake Faulty <input type="checkbox"/> Alternator Faulty <input type="checkbox"/> Starting Problem <input type="checkbox"/> Loss Power <input checked="" type="checkbox"/> Accident <input type="checkbox"/> Engine Stalled <input type="checkbox"/> Return Taxi	
10. Odometer Reading : _____ Fuel Level : <input type="checkbox"/> F <input type="checkbox"/> 1/4 <input type="checkbox"/> 1/2 <input type="checkbox"/> 3/4 <input type="checkbox"/> E	11. Radio / CD Player <input checked="" type="checkbox"/> OK <input type="checkbox"/> Faulty <input type="checkbox"/> Not tested	
<b>Job Attended</b> 12. Tow Truck / Recovery Van : <input type="checkbox"/> VRS <input type="checkbox"/> QA <input checked="" type="checkbox"/> GAO <input type="checkbox"/> TZ <input type="checkbox"/> YISHUN <input type="checkbox"/> OTHERS TOWING Name of Driver : <u>Moh's</u> Vehicle No. : <u>M191487</u> Time Dispatch : <u>12:52am</u> Time of Arrival : <u>01:25am</u> Time Completed : <u>01:55am</u>		
 #: Cracked X Dented /: Scatched O: Missing Signature of Customer: _____		
<b>Cash Invoice Details (if applicable)</b> 13. Cash Invoice No. : _____		
<b>Customer Acknowledgement</b> a. I have been advised to remove all valuable items in my vehicle, including Global Positioning System (GPS), audio compact disk, thumbdrive, carpark coupons, cash cards, spectacles, pen, etc. b. I understand that any items left behind are at my own risk and SPARK Car Care™ will not be held liable for such losses. c. Surcharge: Towing fee will be levied if the customer decides neither to tow nor proceed with the repairs in SPARK Car Care™.		
<u>11/12/2012</u> Date	<u>12:52am</u> Time	Signature of Customer
14. WORKSHOP Name of Attending Staff/Guard : _____ Date & Time of Arrival : _____ Signature of Attending Staff/Guard : _____		

Date/Time: 11.12.2017 17:21 Page : 1

Job: ARC Repair TP(CLSO)1

**JOB CARD** Sales Order:

JC NO 305096865

OMER IS COMFORT TRANSPORTATION PTE LTD OMER NO 7010045 ADDRESS 383 SIN MING DRIVE Singapore SINGAPORE 575717 (R) 65508755 (O) (P) IDENTIFICATION CARD NO.	REGN NO: SHD4375B	MILEAGE
	MAKE: HYUNDAI	FUEL E.....1/2.....F
	MODEL SONATA	DATE/TIME IN 10.12.2017 19:30
	YR OF MANU 12.07.2012	TARGET DATE
	CHASSIS CODE RMHET41VMCA827014	COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 10.12.2017  
 NATURE: 3P 10.12.17

/NO	LABOR CODE	DESCRIPTION
-----	------------	-------------

PREPARED & PASSED OUT BY: \_\_\_\_\_

\_\_\_\_\_  
 SERVICE ADVISOR

\_\_\_\_\_  
 CUSTOMER'S SIGNATURE

Check-out Slip

Exit Pass

No.: SHD4375B LIMITS

Vehicle No.: SHD4375B

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard



**COMFORTDELGRO ENGINEERING PTE LTD**

**REPAIR ESTIMATE\***

VEHICLE NO : SHD 4375B

MODEL : HYUNDAI SONATA

Tyre: Westlake

TOKIO Marine L/S

TS

DATE 12/12/2017 11:13

LKE - Calvin P1/2

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Front Bumper Cover			\$ 538.80	
	Front Bumper Bracket Top (LH/RH) ✓		\$ 22.40	\$ 44.80	
	Front Bumper Protector (LH/RH) ✓		\$ 29.20	\$ 58.40	
	Front Bumper Bracket (LH/RH) ✓		\$ 20.10	\$ 40.20	
	Headlamp Support Panel Assy ?			\$ 1,023.00	
	Headlamp (LH/RH) LH ✓ RH ?		\$ 797.90	\$ 1,595.80	
	Front Fender (LH/RH) ✓		\$ 593.00	\$ 1,186.00	
	Front Fender Shield (LH/RH) ?		\$ 86.00	\$ 172.00	
	Front Fender Retainer ?		\$ 9.20	\$ 18.40	
	Front Wheel Rim (LH) ✓			\$ 284.70	
	Front Wheel Hub Cap (LH) ✓			\$ 145.00	
	Front Wheel Bearing ✓			\$ 258.50	
	Front Shock Absorber (Assy) (LH) ✓			\$ 203.70	
	Front Shock Absorber Mounting (LH) ?			\$ 72.00	
	Front Shock Absorber Fork (LH) ✓			\$ 203.30	
	Front Suspension Upper Arm (LH) ✓			\$ 240.00	
	Front Drive Shaft (LH) ?			\$ 1,025.00	
	Rack & Pinion Assy ?			\$ 2,093.00	
	STG Tie End ✓			\$ 66.50	
	Stabilizer Bar ?			\$ 213.20	
	Stabilizer Bar Bush (LH) ?			\$ 12.80	
	Stabilizer Bar Link ✓			\$ 78.30	
	Stabilizer Bracket ?			\$ 23.00	
	Front Suspension Lower Arm (LH) ✓			\$ 685.20	
	Knuckle Arm (LH) ✓			\$ 558.60	
	Engine Under Cover ?			\$ 328.70	
	Engine Crossmember ?			\$ 2,143.70	
	Ball Joint - 84.00				
	Hub Bearing - 176.60				
	ABS sensor wire - 279.10				
	<b>SUB TOTAL</b>			<b>\$ 13,312.60</b>	
				\$ 2,662.52	
	<b>DISCOUNTED TOTAL</b>			<b>\$ 10,650.08</b>	
	Front Fender Advertisement Logo (LH/RH) ✓		\$ 100.00	\$ 200.00	Nett
	Front Tyre (LH) ✓ 506 103.10			\$ 207.00	Nett
				<b>\$ 407.00</b>	
	<b>Labour Charge</b>				
	Panel Beating			\$ 850.00	600
	Spray Painting Charge			<del>400.00</del>	360
	Wiring Charge			\$ 50.00	20
	Tuff Kote			\$ 50.00	20
	Towing Charge			\$ 50.00	
	Remove/Refix Undercarriage (FRT)			\$ 400.00	150
	FRT Wheel Alignment			\$ 120.00	60
	Remove/Refix Aircon & Refill Gas			\$ 150.00	?
	<b>TOTAL LABOUR</b>			<b>\$ 2,070.00</b>	
	<b>ESTIMATE TOTAL</b>			<b>\$ 13,127.08</b>	

**COMFORTDELGRO ENGINEERING PTE LTD**  
**REPAIR ESTIMATE\***

*Tokio Marine - 4/5* *TS*  
 DATE 12/12/2017 11:10  
*LKK - Calvin P2/2*

VEHICLE NO : SHD 4375B

MAKE :  
 MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid			\$ 1,349.50
	Boot Lid Rubber ✕			\$ 110.90
	Boot Lid Lock Upper ✕			\$ 132.10
	Boot Lid Lock Lower ✕			\$ 30.30
	Boot Lid Sonata Plate			\$ 43.60
	Boot Lid Hyundai Plate			\$ 24.20
	Boot Lid 'H' Emblem			\$ 26.10
	Boot Lid CRDI Plate			\$ 22.70
	Boot Lid Trimboard ✕			\$ 165.40
	Boot Lid Trimboard Clips (10pcs) ✕			\$ 10.00
	<i>Ren RH For Lwr ✕ 1 pc</i>			
	<b>SUB TOTAL</b>			<b>\$ 1,914.80</b>
	<b>LESS 20%</b>			<b>\$ 382.96</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$ 1,531.84</b>
	Boot Lid Comfort Logo & Tel No. Sticker			\$ 30.00
				<b>\$ 30.00</b>
	<b>Labour Charge</b>			
	Panel Beating			\$ <del>350.00</del> <sup>200</sup>
	Spray Painting Charge			\$ <del>200.00</del> <sup>180</sup>
	<b>TOTAL LABOUR</b>			<b>\$ 550.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$ 2,111.84</b>

Nett

*Calvin LKK*  
*12/12/17 1545hrs*  
*4 Days*  
*4/5*  
*After Repair plz*  
*Boo LKK*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental item(s) to be repaired and is subject to final approval from Insurance Company

Acknowledged by Repairer:  
 Signature: \_\_\_\_\_  
 Date: \_\_\_\_\_

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.



**ComfortDelGro Engineering Pte Ltd** (Co.Reg.No:199506048W)

59 Loyang Drive  
Singapore 508969  
Tel: 6214 8300

**TP INSURER:**  
**CTPL**

**Tokio Marine Insurance Singapore Ltd (HQ)**

Singapore

**PARTICULARS OF CLAIM**

Claim Type:	Third Party	Ref. No:	
Policy No:		Date of Loss:	10/12/2017
Vehicle Reg. No.:	<b>SHD4375B</b>	Driveable?	NO
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI SONATA, 2.0 D CRDi Turbo (NF) (A)	Vehicle Reg. Date:	12/07/2012
Vehicle Colour:	Blue	Gen Condition:	Good
Engine No:	D4EAC120846	Chassis No:	KMHET41VMCA827014
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	<b>NO</b>		
Est. Duration of Repair (day)	6		

Present Location: COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)

<b>COST OF CLAIMS</b>	<b>Amount</b>
Parts	12,070.76
Miscellaneous Items	10.00
Labour	2,620.00
Paintwork Labour	0.00
Towing	0.00
	<u>15,648.68</u>
<b>Gross Total (S\$)</b>	<b>14,700.76</b>
<b>+ GST 7.00% (S\$)</b>	<b>1,029.05</b>
<b>Nett Amount (S\$)</b>	<b>15,729.81</b>

**This claim is handled by: LIM TIEN SIONG**

*Generated using Merimen e-Claims Internet Estimation & Adjusting System*

# REPAIR DETAILS

## Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 12 Dec 2017)  
 Parts: 143 HYUNDAI SONATA 2.0 D CRDi Turbo (NF) (A) (Catalogue:Merimen Singapore 1.0)  
 Labour: Repairer's (Price-denominated Standard List)  
 Print Code: ComfortDelGro Engineering Pte Ltd/SHD4375B/12/12/2017 18:09  
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

## Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT BUMPER De	20.00	0.00	*538.80 FL
2	2		*FRT BUMPER TOP BRACKET RH/LH crq	20.00	0.00	*44.80 FL
3	2		*FRT BUMPER BRACKET RH/LH nec	20.00	0.00	*40.20 FL
4	2		*FRT BUMPER PROTECTOR RH/LH crq	20.00	0.00	*58.40 FL
5	1		*HEADLAMP SUPPORT PANEL svc	20.00	0.00	*1,023.00 FL X
6	2		*HEADLAMP RH/LH n/s grazed o/s svc	20.00	0.00	*1,595.80 FL 797.90
7	2		*FRT FENDER RH/LH dd	20.00	0.00	*1,186.00 FL
8	2		*FRT FENDER SHIELD RH/LH n/s Torn o/s svc	20.00	0.00	*172.00 FL 86
9	2		*FRT FENDER RETAINER RH/LH svc	20.00	0.00	*18.40 FL X
10	1		*FRT WHEEL RIM LH bt	20.00	0.00	*284.70 FL
11	1		*FRT WHEEL CAP LH crq	20.00	0.00	*145.00 FL
12	1		*FRT WHEEL BEARING LH bt	20.00	0.00	*258.50 FL
13	1		*FRT SHOCK ABSORBER LH bt	20.00	0.00	*203.70 FL
14	1		*FRT SHOCK ABSORBER MTG LH svc	20.00	0.00	*72.00 FL X
15	1		*FRT SHOCK ABSORBER FORK LH bt	20.00	0.00	*203.30 FL
16	1		*FRT SUSPENSION LOWER ARM LH bt	20.00	0.00	*240.00 FL
17	1		*DRIVESHAFT LH svc	20.00	0.00	*1,025.00 FL X
18	1		*RACK AND PINION ASSY svc	20.00	0.00	*2,093.00 FL X
19	1		*STEERING TIE-ROD LH bt	20.00	0.00	*66.50 FL
20	1		*STABILIZER BAR svc	20.00	0.00	*213.20 FL X
21	1		*STABILIZER BAR BUSH LH svc	20.00	0.00	*12.80 FL X
22	1		*STABILIZER BAR LINK LH bt	20.00	0.00	*78.30 FL
23	1		*STABILIZER BAR BRACKET LH svc	20.00	0.00	*23.00 FL X
24	1		*FRT KUNCKLE ARM LH bt	20.00	0.00	*558.60 FL
25	1		*ENGINE UNDER COVER svc	20.00	0.00	*328.70 FL X
26	1		*ENGINE CROSSMEMBER svc	20.00	0.00	*2,143.70 FL X
27	2		*FRT FENDER ADVERTISEMENT RH/LH nec	0.00	0.00	*200.00 F
28	1		*FRT TYRE LH 50% cut	0.00	0.00	*207.00 F 103.50
29	1		*BOOTLID dd	20.00	0.00	*1,349.50 FL
30	1		*BOOTLID RUBBER svc	20.00	0.00	*110.90 FL X
31	1		*BOOTLID UPR LOCK svc	20.00	0.00	*132.10 FL X
32	1		*BOOTLID LWR LOCK svc	20.00	0.00	*30.30 FL X
33	1		*BOOTLID SONATA EMBLEM nec	20.00	0.00	*43.60 FL
34	1		*BOOTLID HYUNDAI EMBLEM nec	20.00	0.00	*24.20 FL
35	1		*BOOTLID H EMBLEM nec	20.00	0.00	*26.10 FL
36	1		*BOOTLID CRDI EMBLEM nec	20.00	0.00	*22.70 FL
37	1		*BOOTLID TRIMBOARD svc	20.00	0.00	*165.40 FL X
38	10		*BOOTLID TRIMBOARD CLIPS nn	20.00	0.00	*10.00 FL X
39	1		*BOOTLID COMFORT STICKER nec	0.00	0.00	*20.00 F
40	1		*BOOTLID 65521111 STICKER nec	0.00	0.00	*10.00 F

F=Franchise part. L=ListitemDisc.

Sub Total (\$\$)	14,979.20
- List Item Discount on L Items (\$\$)	2,908.44
<b>Total Parts (\$\$)</b>	<b>12,070.76</b>

ComfortDelGro Engineering Pte Ltd/SHD4375B/12/12/2017 18:09. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

## Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			10.00
1	1	OD/TP Case (Insurer)	
<b>Sub Total (\$\$)</b>			<b>10.00</b>

## Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	PANEL BEATING - FRT AND REAR	New	1,200.00
2	SPRAY PAINTING - FRT AND REAR	New	600.00
3	WIRING CHECK	New	50.00
4	TUFF KOTE	New	50.00
5	TOWING CHARGE	New	400.00
6	R/I FRT UNDERCARRIAGE ETC	New	120.00
7	WHEEL ALIGNMENT	New	150.00
8	R/I AIR CON CONDENSER ETC		
<b>Gross Labour Cost (\$\$)</b>			<b>2,620.00</b>

800  
540  
20  
20  
✓  
150  
60  
X

ComfortDelGro Engineering Pte Ltd/SHD4375B/12/12/2017 18:09. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive  
Singapore 508969  
Tel: 6214 8300

**(SUPPLEMENTARY)**

TP INSURER: **Tokio Marine Insurance Singapore Ltd (HQ)**  
CTPL

Singapore

**PARTICULARS OF CLAIM**

Claim Type:	Third Party	Ref. No:	
Policy No:	MU007738	Date of Loss:	10/12/2017
Vehicle Reg. No.:	<b>SHD4375B</b>	Driveable?	NO
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI SONATA, 2.0 D CRDi Turbo (NF) (A)	Vehicle Reg. Date:	12/07/2012
Vehicle Colour:	Blue	Gen Condition:	Good
Engine No:	D4EAC120846	Chassis No:	KMHET41VMCA827014
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	<b>NO</b>		
Est. Duration of Repair (day)	6		

Present Location: COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)

<b>COST OF CLAIMS</b>	<b>Amount</b>
Parts	947.92
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
	<b>Gross Total (S\$) 947.92</b>
	<b>+ GST 7.00% (S\$) 66.35</b>
	<b>Nett Amount (S\$) 1,014.27</b>
	<b>+ Previous Estimates (S\$) 15,729.81</b>
	<b>Claim Total (S\$) 16,744.08</b>

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 24 Dec 2017)  
**Parts:** 143      HYUNDAI SONATA 2.0 D CRDi Turbo (NF) (A) (Catalogue:Merimen Singapore 1.0)  
**Labour:** Repairer's      (Price-denominated Standard List)  
**Print Code:** ComfortDelGro Engineering Pte Ltd/SHD4375B/24/12/2017 08:57  
**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT LOWER ARM LH <i>Broken</i>	20.00	0.00	*685.20 FL
2	1		*FRT BALL JOINT LH <i>Bt</i>	20.00	0.00	*84.00 FL
3	1		*FRT WHEEL HUB LH <i>Bt</i>	20.00	0.00	*176.60 FL
4	1		*FRT WHEEL ABS SENSOR LH <i>Short</i>	20.00	0.00	*239.10 FL
<b>Sub Total (S\$)</b>						<b>1,184.90</b>
- List Item Discount on L Items (S\$)						236.98
<b>Total Parts (S\$)</b>						<b>947.92</b>

F=Franchise part. L=ListItemDisc.

ComfortDelGro Engineering Pte Ltd/SHD4375B/24/12/2017 08:57. Not valid without Reference section.  
 Generated using Merimen e-Claims IEAS

## Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

## Estimates on Labour

There are no labour items selected.

ComfortDelGro Engineering Pte Ltd/SHD4375B/24/12/2017 08:57. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

# COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

Our Job Ref No : 305096865  
Date : 18/12/17

## FINALIZATION FORM

To : LKK Fax : \_\_\_\_\_  
Attn : KALVIN ANG  
Vehicle Reg No. : SHD4375B Date of Accident : 10-Dec-17


The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: TOKIO MARINE --- SLE5839X
2. The finalized amount shall be:
 

(a)	Spare Parts after List discount	_____
(b)	Labour Charges	_____
<b>Total for Part-By-Part Repair Cost</b>		_____
(c)	Lumpsum Repair (if applicable)	
	Total for Lumpsum repair cost after Less: <u>20%</u>	<u>\$6,350.00</u>
	<b>Final Lumpsum Repair cost</b>	<b><u>\$6,350.00</u></b>

3. Estimated normal period for repairs: 4 working days.
4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature :   
Name : LIM T S  
Tel : 62148398  
Fax : 65468156

Signature :   
Name : KALVIN  
Date : 18/12/17

### For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid				
3. Survey Fees	-----			
4. LTA Search Fee				
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks: \_\_\_\_\_  
\_\_\_\_\_



COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE\*

VEHICLE NO : SHD 4375B

MODEL : HYUNDAI SONATA

Tyre: Westlake

TOKIO Marine LK

TS

DATE 12/12/2017 11:13

LKK - Kalvin P1/2

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover <i>Pat</i>			\$ 538.80
	Front Bumper Bracket Top (LH/RH) <i>Pat</i>	S	22.40	\$ 44.80
	Front Bumper Protector (LH/RH) <i>Pat</i>	S	29.20	\$ 58.40
	Front Bumper Bracket (LH/RH) <i>Pat</i>	S	20.10	\$ 40.20
	Headlamp Support Panel Assy <i>X sm</i>			\$ 1,023.00
	Headlamp (LH/RH) <i>LH &amp; RH X sm</i>	S	797.90	\$ 1,595.80
	Front Fender (LH/RH) <i>Pat</i>	S	593.00	\$ 1,186.00
	Front Fender Shield (LH/RH) <i>LH &amp; RH X sm</i>	S	86.00	\$ 172.00
	Front Fender Retainer <i>X sm</i>	S	9.20	\$ 18.40
	Front Wheel Rim (LH) <i>Pat</i>			\$ 284.70
	Front Wheel Hub Cap (LH) <i>Pat</i>			\$ 145.00
	Front Wheel Bearing <i>Pat</i>			\$ 258.50
	Front Shock Absorber (Assy) (LH) <i>Pat</i>			\$ 203.70
	Front Shock Absorber Mounting (LH) <i>X sm</i>			\$ 72.00
	Front Shock Absorber Fork (LH) <i>Pat</i>			\$ 203.30
	Front Suspension Upper Arm (LH) <i>Pat</i>			\$ 240.00
	Front Drive Shaft (LH) <i>X sm</i>			\$ 1,025.00
	Rack & Pinion Assy <i>X sm</i>			\$ 2,093.00
	STG Tie End <i>Pat</i>			\$ 66.50
	Stabilizer Bar <i>X sm</i>			\$ 213.20
	Stabilizer Bar Bush (LH) <i>X sm</i>			\$ 12.80
	Stabilizer Bar Link <i>Pat</i>			\$ 78.30
	Stabilizer Bracket <i>X sm</i>			\$ 23.00
	Front Suspension Lower Arm (LH) <i>Pat</i>			\$ 685.20
	Knuckle Arm (LH) <i>Pat</i>			\$ 558.60
	Engine Under Cover <i>X sm</i>			\$ 328.70
	Engine Crossmember <i>X sm</i>			\$ 2,143.70
	<i>Pat / Int - 84.00 Pat</i>			
	<i>Hub Bearings - 176.60 Pat</i>			
	<i>ABS Sensor wire - 239.10 Pat</i>			
	<b>SUB TOTAL</b>			\$ 13,312.60
	<b>LESS 20%</b>			\$ 2,662.52
	<b>DISCOUNTED TOTAL</b>			\$ 10,650.08
	Front Fender Advertisement Logo (LH/RH) <i>nlc</i>	S	100.00	\$ 200.00 <b>Nett</b>
	Front Tyre (LH) <i>50% of</i>		<del>103.50</del>	\$ 207.00 <b>Nett</b>
				\$ 407.00
	<b>Labour Charge</b>			
	Panel Beating			\$ 850.00 <i>600</i>
	Spray Painting Charge			\$ <del>400.00</del> <i>360</i>
	Wiring Charge			\$ 50.00 <i>20</i>
	Tuff Kote			\$ 50.00 <i>20</i>
	Towing Charge			\$ 50.00 <i>—</i>
	Remove/Refix Undercarriage (FRT)			\$ 400.00 <i>150</i>
	FRT Wheel Alignment			\$ 120.00 <i>60</i>
	Remove/Refix Aircon & Refill Gas			\$ 150.00 <i>Xn</i>
	<b>TOTAL LABOUR</b>			\$ 2,070.00
	<b>ESTIMATE TOTAL</b>			\$ 13,127.08

6250  
LK

Pat / Int - 84.00 Pat  
Hub Bearings - 176.60 Pat  
ABS Sensor wire - 239.10 Pat

600  
360  
20  
20  
—  
150  
60  
Xn

**COMFORTDELGRO ENGINEERING PTE LTD**  
**REPAIR ESTIMATE\***

Tokio Marine - 45 TS

VEHICLE NO : SHD 4375B

DATE 12/12/2017 11:10

MAKE :

LKK - Calvin P2/2

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid			\$ 1,349.50
	Boot Lid Rubber			\$ 110.90
	Boot Lid Lock Upper			\$ 132.10
	Boot Lid Lock Lower			\$ 30.30
	Boot Lid Sonata Plate			\$ 43.60
	Boot Lid Hyundai Plate			\$ 24.20
	Boot Lid 'H' Emblem			\$ 26.10
	Boot Lid CRDI Plate			\$ 22.70
	Boot Lid Trimboard			\$ 165.40
	Boot Lid Trimboard Clips (10pcs)			\$ 10.00
	Rem RH Front Door			\$ 1,914.80
	<b>SUB TOTAL</b>			\$ 1,914.80
	<b>LESS 20%</b>			\$ 382.96
	<b>DISCOUNTED TOTAL</b>			\$ 1,531.84
	Boot Lid Comfort Logo & Tel No. Sticker			\$ 30.00
				\$ 30.00
	<b>Labour Charge</b>			
	Panel Beating			\$ <del>350.00</del>
	Spray Painting Charge			\$ <del>200.00</del>
				180
	<b>TOTAL LABOUR</b>			\$ 550.00
	<b>ESTIMATE TOTAL</b>			\$ 2,111.84

Calvin LKK  
 12/12/17 1545hrs  
 4 Days  
 45  
 After Repair plz  
 Book Calvin

LKK Auto Consultants hence notify the Repairer of the following:

- To survey before/after spray painting
- To replace damaged part(s) during resurvey
- Part prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No legal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.



**...CLAIM SUBFOLDER...(Pending for Survey Report)**

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Dec 2017 17:52 <a href="#">Sendback Est</a>	12 Dec 2017 18:09 <b>S\$14,700.76</b>	13 Dec 2017 09:08 <a href="#">Edit Adj Rpt</a>	<b>S\$6,350.00</b> <a href="#">Edit Estimates</a>	<b>S\$6,350.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>
Supp #1	24 Dec 2017 08:56	24 Dec 2017 08:57 <b>S\$947.92</b>	24 Dec 2017 08:57			(Combined)	<b>Combined with Main</b> <a href="#">Uncombine Suppl.</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS			
Insured:	YAP LAI SAN, Co. Reg. No.: YAP LAI SAN		
Main Claimant:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R		
Vehicle Reg. No.:	SHD4375B	Date of Loss:	10/12/2017 19:00 - :59
Claim Type:	TP / M1706260	Policy/Cover Note No.:	MU007738 (Comprehensive) Coverage: 27/07/2017 - 26/07/2018
Vehicle Reg. No. (Insured):	SLE5839X	Policy No. (Claimant):	
		Excess:	S\$600.00
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300		
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Zheng Hanyang - 65926416]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KALVIN ANG WEI KUN ] ... [Final Rpt due 22/12/2017]		
			<a href="#">View All</a> <a href="#">Compose Case Mail</a>
ASSOCIATED MAIL RECEIVED			
There are no mail for this case.			
ALL ASSOCIATED TASKS <input type="checkbox"/>			
		<a href="#">View All</a>	<a href="#">Search Tasks</a>
		<a href="#">Create New Task</a>	<a href="#">Complete</a>
Due Date	Priority	Type	Task Group
Subject	Handler	Assigned By	Completed On
Created On	Done?		
No results.			

## Claim Documents

SHD4375B (M1706260)  
[SLE5839X]  
TP  
COMFORT TRANSPORTATION PTE LTD  
Dec 10 2017 7:00PM  
[YAP LAI SAN]  
ComfortDelGro Engineering Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View <input type="button" value="View in Browser"/>		
<b>Assessment Reports</b>									1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)						Thumbnail	Print		
1	12/12/17 18:10	<b>Repairer Estimates</b>							Load HTM	<input type="checkbox"/>	
2	24/12/17 08:57	<b>Repairer Estimates Suppl. #1</b>							Load HTM	<input type="checkbox"/>	
<b>Photos/Images</b>									3 per page	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	13/12/17 17:28	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
2	13/12/17 17:28	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
3	13/12/17 17:28	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
4	13/12/17 17:28	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
5	13/12/17 17:28	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
6	13/12/17 17:28	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
7	13/12/17 17:28	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
8	13/12/17 17:28	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
9	13/12/17 17:28	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
10	13/12/17 17:28	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
11	13/12/17 17:28	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
12	13/12/17 17:28	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
13	13/12/17 17:28	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
14	13/12/17 17:28	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
15	13/12/17 17:28	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
16	13/12/17 17:28	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
17	13/12/17 17:28	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
18	13/12/17 17:28	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
19	13/12/17 17:28	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
20	13/12/17 17:28	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
21	13/12/17 17:28	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
22	13/12/17 17:28	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
23	13/12/17 17:28	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
24	13/12/17 17:28	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
25	13/12/17 17:28	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
26	13/12/17 17:28	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
27	13/12/17 17:28	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
28	13/12/17 17:28	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
29	13/12/17 17:28	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
30	13/12/17 17:28	<b>General View</b>							Load JPG	<input checked="" type="checkbox"/>	
31	15/12/17 08:12	<b>Reinspection Photo</b>							Load JPG	<input checked="" type="checkbox"/>	

32	15/12/17 08:12	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
33	15/12/17 08:12	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
34	15/12/17 08:12	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
35	15/12/17 08:12	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
36	15/12/17 08:12	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
37	15/12/17 08:12	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
38	15/12/17 08:12	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
39	15/12/17 08:12	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
40	15/12/17 08:12	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
41	15/12/17 08:12	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
42	15/12/17 08:12	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
43	15/12/17 08:12	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
44	15/12/17 08:12	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
45	15/12/17 08:12	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
46	15/12/17 08:12	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
47	15/12/17 08:12	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
48	15/12/17 08:12	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
49	15/12/17 08:12	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
50	15/12/17 08:12	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
51	15/12/17 08:12	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
52	15/12/17 08:12	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
53	15/12/17 08:12	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
54	15/12/17 08:12	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
55	15/12/17 08:12	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
56	15/12/17 08:12	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
57	15/12/17 08:12	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
58	15/12/17 08:12	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
59	15/12/17 08:12	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
60	19/12/17 07:42	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
61	19/12/17 07:42	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
62	19/12/17 07:42	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
63	19/12/17 07:42	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
64	19/12/17 07:42	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
65	19/12/17 07:42	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
66	19/12/17 07:42	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
67	19/12/17 07:42	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
				1 per page	<input checked="" type="checkbox"/>
<b>Documentation</b>					
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)		<b>Thumbnail</b>	<b>Print</b>
1	28/12/17 10:55	LOD, Invoice, LOR, Mileage Record, LA, LTA Search Fee	1	Load PDF	
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		<b>Thumbnail</b>	<b>Print</b>
1	12/12/17 18:10	E-filed GIA report	1	Load PDF	
No	Finalized On	Tokio Marine Insurance Singapore Ltd (HQ)		<b>Thumbnail</b>	<b>Print</b>
1	29/12/17 15:36	TP - SKG3747S (1/5) - Singapore Accident Statement	1	Load PDF	
2	29/12/17 15:36	TP - SKX5699U (3/5) - Singapore Accident Statement	1	Load PDF	
3	29/12/17 15:36	TP - SHD2148D (4/5) - Singapore Accident Statement	1	Load PDF	
4	29/12/17 15:36	OI - SLE5839X (5/5) - Singapore Accident Statement	1	Load PDF	
5	29/12/17 13:01	TP - SHD4375B - Letter of Demand from Third Party (8 PAGES) LOD - COMFORTDELGRO ENGINEERING PTE LTD DATED 27.12.2017	1	Load TIF	
6	29/12/17 13:01	TP - SHD4375B - E-filed GIA report	1	Load TIF	

## Documents Checklist

<a href="#">Reset</a> <a href="#">Save</a> <a href="#">Print</a>
<b>DOCUMENTS CHECKLIST</b>
There are no document checklists configured.

<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>
<div style="border: 1px solid black; height: 40px; width: 100%;"></div>
<b>Show Remarks To:</b> <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer
<small>Note: Remarks are private unless you show it to other parties.</small>

## LKK Auto Consultants Pte Ltd (Co.Reg.No.199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/TMI17023617/K1VBS2  
**Date:** 02/01/2018

#### REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd	Policy No: MU007738	
Claimant Vehicle No: SHD4375B	Insured Vehicle No: SLE5839X	
Date of Loss: 10/12/2017	Nature of Claim: TP	Claim No: M1706260

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD4375B	Engine No:	D4EAC120846
Make & Model:	HYUNDAI SONATA, 2.0 D CRDi Turbo (NF) (A)	Chassis No:	KMHET41VMCA827014
Reg. Date:	12/07/2012 (Man. Year: 2012)	Odometer:	743459 km
Colour:	Blue		
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

#### CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	West Lake 7 mm	Rear Left Side:	West Lake 7 mm
Front Right Side:	West Lake 7 mm	Rear Right Side:	West Lake 7 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,018.68	6,286.86	6,731.82	51.71
Miscellaneous Items	10.00	10.00	0.00	0.00
Labour	2,620.00	1,640.00	980.00	37.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>15,648.68</b>	<b>7,936.86</b>	<b>7,711.82</b>	<b>49.28</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>6,350.00</b>		
	(S\$)	15,648.68	6,350.00	9,298.68
	+ GST 7.00/7.00% (S\$)	1,095.40	444.50	650.90
	<b>Nett Amount (S\$)</b>	<b>16,744.08</b>	<b>6,794.50</b>	<b>9,949.58</b>

#### INSPECTION

Date of Assignment:	13/12/2017 Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	12/12/2017 Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	4.0 days	



---

**Adjuster:** KALVIN ANG WEI KUN

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 02 Jan 2018)
<b>Parts:</b> 143	HYUNDAI SONATA 2.0 D CRDi Turbo (NF) (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SHD4375B)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Deformed	538.80 FL	*538.80 FL
2	2		*FRT BUMPER TOP BRACKET RH/LH	Cracked	44.80 FL	*44.80 FL
3	2		*FRT BUMPER BRACKET RH/LH	Necessary	40.20 FL	*40.20 FL
4	2		*FRT BUMPER PROTECTOR RH/LH	Cracked	58.40 FL	*58.40 FL
5	1		*HEADLAMP SUPPORT PANEL	Serviceable	1,023.00 FL	*- FL
6	1		*HEADLAMP RH/LH	N/s Grazed/O/s Serviceable	1,595.80 FL	*797.90 FL
7	2		*FRT FENDER RH/LH	Dented	1,186.00 FL	*1,186.00 FL
8	1		*FRT FENDER SHIELD RH/LH	N/s Torn/O/s Serviceable	172.00 FL	*86.00 FL
9	2		*FRT FENDER RETAINER RH/LH	Serviceable	18.40 FL	*- FL
10	1		*FRT WHEEL RIM LH	Bent	284.70 FL	*284.70 FL
11	1		*FRT WHEEL CAP LH	Cracked	145.00 FL	*145.00 FL
12	1		*FRT WHEEL WHEEL BEARING LH	Bent	258.50 FL	*258.50 FL
13	1		*FRT SHOCK ABSORBER LH	Bent	203.70 FL	*203.70 FL
14	1		*FRT SHOCK ABSORBER MTG LH	Serviceable	72.00 FL	*- FL
15	1		*FRT SHOCK ABSORBER FORK LH	Bent	203.30 FL	*203.30 FL
16	1		*FRT SUSPENSION LOWER ARM LH	Bent	240.00 FL	*240.00 FL
17	1		*DRIVESHAFT LH	Serviceable	1,025.00 FL	*- FL
18	1		*RACK AND PINION ASSY	Serviceable	2,093.00 FL	*- FL
19	1		*STEERING TIE-ROD LH	Bent	66.50 FL	*66.50 FL
20	1		*STABILIZER BAR	Serviceable	213.20 FL	*- FL
21	1		*STABILIZER BAR BUSH LH	Serviceable	12.80 FL	*- FL
22	1		*STABILIZER BAR LINK LH	Bent	78.30 FL	*78.30 FL
23	1		*STABILIZER BAR BRACKET LH	Serviceable	23.00 FL	*- FL
24	1		*FRT KUNCKLE ARM LH	Bent	558.60 FL	*558.60 FL
25	1		*ENGINE UNDER COVER	Serviceable	328.70 FL	*- FL
26	1		*ENGINE CROSSMEMBER	Serviceable	2,143.70 FL	*- FL
27	2		*FRT FENDER ADVERTISEMENT RH/LH	Necessary	200.00 F	*200.00 FS
28	1		*FRT TYRE LH (50%)	Cut	207.00 F	*103.50 FS
29	1		*BOOTLID	Dented	1,349.50 FL	*1,349.50 FL
30	1		*BOOTLID RUBBER	Serviceable	110.90 FL	*- FL
31	1		*BOOTLID UPR LOCK	Serviceable	132.10 FL	*- FL
32	1		*BOOTLID LWR LOCK	Serviceable	30.30 FL	*- FL
33	1		*BOOTLID SONATA EMBLEM	Necessary	43.60 FL	*43.60 FL
34	1		*BOOTLID HYUNDAI EMBLEM	Necessary	24.20 FL	*24.20 FL
35	1		*BOOTLID H EMBLEM	Necessary	26.10 FL	*26.10 FL
36	1		*BOOTLID CRDI EMBLEM	Necessary	22.70 FL	*22.70 FL
37	1		*BOOTLID TRIMBOARD	Serviceable	165.40 FL	*- FL
38	10		*BOOTLID TRIMBOARD CLIPS	Not Necessary	10.00 FL	*- FL
39	1		*BOOTLID COMFORT STICKER	Necessary	20.00 F	*20.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
40	1		*BOOTLID 65521111 STICKER	Necessary	10.00 F	*10.00 F	
<b>Supplementary #1</b>							
41	1		*FRT LOWER ARM LH	Broken	685.20 FL	*685.20 FL	
42	1		*FRT BALL JOINT LH	Bent	84.00 FL	*84.00 FL	
43	1		*FRT WHEEL HUB LH	Bent	176.60 FL	*176.60 FL	
44	1		*FRT WHEEL ABS SENSOR LH	Shorted	239.10 FL	*239.10 FL	
					<b>Sub Total (S\$)</b>	<b>16,164.10</b>	<b>7,775.20</b>
					<b>- List Item Discount on L Items 20.00/20.00% (S\$)</b>	<b>3,145.42</b>	<b>1,488.34</b>
					<b>Total Parts (S\$)</b>	<b>13,018.68</b>	<b>6,286.86</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

### Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	OD/TP Case (Insurer)	10.00	10.00
<b>Sub Total (S\$)</b>			<b>10.00</b>	<b>10.00</b>

### Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING - FRT AND REAR	New	1,200.00	800.00
2	SPRAY PAINTING - FRT AND REAR	New	600.00	540.00
3	WIRING CHECK	New	50.00	20.00
4	TUFF KOTE	New	50.00	20.00
5	TOWING CHARGE	New	50.00	50.00
6	R/I FRT UNDERCARRIAGE ETC	New	400.00	150.00
7	WHEEL ALIGNMENT	New	120.00	60.00
8	R/I AIR CON CONDENSER ETC	New	150.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>2,620.00</b>	<b>1,640.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >