

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 4375B

MODEL : HYUNDAI SONATA

DATE 12/12/2017 11:13

Tokio Marine 4/5

TS

Tyre: Westlake

LKK-Kalvin P1/2

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover			\$ 538.80
	Front Bumper Bracket Top (LH/RH) ?		\$ 22.40	\$ 44.80
	Front Bumper Protector (LH/RH) ?		\$ 29.20	\$ 58.40
	Front Bumper Bracket (LH/RH) ?		\$ 20.10	\$ 40.20
	Headlamp Support Panel Assy ?			\$ 1,023.00
	Headlamp (LH/RH) LH ✓ RH ?		\$ 797.90	\$ 1,595.80
	Front Fender (LH/RH) ✓		\$ 593.00	\$ 1,186.00
	Front Fender Shield (LH/RH) ?		\$ 86.00	\$ 172.00
	Front Fender Retainer ?		\$ 9.20	\$ 18.40
	Front Wheel Rim (LH) ✓			\$ 284.70
	Front Wheel Hub Cap (LH) ✓			\$ 145.00
	Front Wheel Bearing ✓			\$ 258.50
	Front Shock Absorber (Assy) (LH) ?			\$ 203.70
	Front Shock Absorber Mounting (LH) ?			\$ 72.00
	Front Shock Absorber Fork (LH) ?			\$ 203.30
	Front Suspension Upper Arm (LH) ?			\$ 240.00
	Front Drive Shaft (LH) ?			\$ 1,025.00
	Rack & Pinion Assy ?			\$ 2,093.00
	STG Tie End ?			\$ 66.50
	Stabilizer Bar ?			\$ 213.20
	Stabilizer Bar Bush (LH) ?			\$ 12.80
	Stabilizer Bar Link ?			\$ 78.30
	Stabilizer Bracket ?			\$ 23.00
	Front Suspension Lower Arm (LH) ✓			\$ 685.20
	Knuckle Arm (LH) ?			\$ 558.60
	Engine Under Cover ?			\$ 328.70
	Engine Crossmember ?			\$ 2,143.70
	SUB TOTAL			\$ 13,312.60
	LESS 20%			\$ 2,662.52
	DISCOUNTED TOTAL			\$ 10,650.08
	Front Fender Advertisement Logo (LH/RH) ✓		\$ 100.00	\$ 200.00
	Front Tyre (LH) ?			\$ 207.00
				\$ 407.00
	Labour Charge			
	Panel Beating			\$ 850.00
	Spray Painting Charge			\$ 400.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	Towing Charge			\$ 50.00
	Remove/Refix Undercarriage (FRT)			\$ 400.00
	FRT Wheel Alignment			\$ 120.00
	Remove/Refix Aircon & Refill Gas			\$ 150.00
	TOTAL LABOUR			\$ 2,070.00
	ESTIMATE TOTAL			\$ 13,127.08

Nett

Nett

600

360

20

20

150

60

?

TOKIO Marine - 4/5

TS

DATE 12/12/2017 11:10

Lef-Kalvin P2/2

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid ✓			\$ 1,349.50
	Boot Lid Rubber ✕			\$ 110.90
	Boot Lid Lock Upper ✕			\$ 132.10
	Boot Lid Lock Lower ✕			\$ 30.30
	Boot Lid Sonata Plate ✓			\$ 43.60
	Boot Lid Hyundai Plate ✓			\$ 24.20
	Boot Lid 'H' Emblem ✓			\$ 26.10
	Boot Lid CRDI Plate ✓			\$ 22.70
	Boot Lid Trimboard ✕			\$ 165.40
	Boot Lid Trimboard Clips (10pcs) ✕			\$ 10.00
	Rear RH Frn Lwr ✕ Repair			
	SUB TOTAL			\$ 1,914.80
	LESS 20%			\$ 382.96
	DISCOUNTED TOTAL			\$ 1,531.84
	Boot Lid Comfort Logo & Tel No. Sticker ✓			\$ 30.00
				\$ 30.00
	Labour Charge			200
	Panel Beating			\$ 350.00
	Spray Painting Charge			\$ 200.00 180
	TOTAL LABOUR			\$ 550.00
	ESTIMATE TOTAL			\$ 2,111.84
	Kahe 16KRY			
	12/12/17 1545hrs			
	4 Days			
	4/5			
	After Repair pld			
	Boo ka he			
	LKK Auto Consultants hence notify the Repairer of the following:			
	• To resurvey before/after spray painting			
	• To display damaged part(s) during resurvey			
	• Parts prices are subject to confirmation			
	• Third party survey is on a "Without Prejudice" basis			
	• No illegal modification(s) is allowed			
	• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company			
	Acknowledged by Repairer			
	Signature:			
	Date:			
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			