

Surveyor:

ywk

DOI:

ASSIGNMENT

11-12-17

Date / Time

11-12-17

(Registered in Merimen):

Pre-assign / CCU / FTE



Insured Vehicle No.:

SFN 3339J

Name of Insured:

BARWATI SUPAR

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

09-12-17

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Yam KAH YUE

Driver Tel No.:

90622162

(V/L: YES / NO)

Claim No.:

SNM170070950219

Policy No.:

DMPCSN 3083931701

Make / Model:

7. Camry 2.4 (A)

Place of Accident:

Tesensola Road

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SHB 1783L



INSRS:

WSP:

Tel:

Liability:

RMKS:

SMRT, WL



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

DATE / PIC

18/12
MMA

SHB 1783L - X; SFN 3339J - X

STAGE

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

27/12/17

confirm accident details. inform TP claim.
agree to settle and away xcd will
be affected. water and out

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

Confirm by:

FINALIZATION

Date/Time:

Confirm with:

Repair Cost:

SS

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

%

100 (Agreed / Assessed) BOLA S/N No.:

N/A

If NO or B 28, Ass. Lia:

Repair Cost:

SS 1286.13

Loss of Rental (LOR):

SS 449.40 (4 days) x 112.35

Loss of Use (LOU):

SS 200.00 (\$50 x 4 days)

Loss of Income (LOI):

SS - (\$ x days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

SS 5.00

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/ Independent)

Legal Cost

SS -

Total:

SS 1940.53

Global Sum SS:

1900.00

Email

Call

FINAL PAYMENT

Date/Time:

Confirm with:

Payee 1:

SS 1900.00

Name 1:

SMRT Taxis Pte Ltd.

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

RECEIVED 19 JAN 2018

19/1/18

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

REF:

Structure

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 2 days Res.: Yes or NoLum Sum: 2-B-2 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHB 1783L Yr Regn: 5/2/2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Prins. c.c. 1798Colour: Maroon A/C: Insured / Std / NI / NASp. Reading: 321892 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDKN364 105767364

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15R: 1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Fallun

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 5 mmD.O.A. 9/12/2017 D.O.I. 11/12/2017Survey held at SMARTDes. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop orN/S front

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time | Action / Instruction

11/1/18 Confirm 2-B-2 \$1286.13 with 2 working days

TAX 12/17/2050

Ukr.

China Taping

(Red. \$3534.94
73%)

Date/Time, File Pass to?

☐

Preli. Report

1) Date/Time, File Return to?

☐

Final Report

2) _____

Report Format :

Lump Sum / I.B.I: (\$ _____)

Days Of Repair:

Resurvey No. of Trip: _____

Add Fee:

☐

Site Insp (\$ _____)

☐

Interview (\$ _____)

☐

Tech. Invs (\$ _____)

☐

Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS. \$ _____

Photos

Others

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC3/CTI17023620/Swa3		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 12-12-2017		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SFN 3339J	Veh. Inspected	SHB 1783L	
Policy No.	DMPCSN3083931701	Coverage (\$)	0.00	
Claim No.	SNM17D07095C02/9	Excess (\$)	0.00	
Assign From		Assign Date	12/12/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	09/12/2017	Inspection Date	11/12/2017	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA
Our ref: CC3/CTI17023620/Swa3

Date: 13.12.2017

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHB 1783L


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 11/12/2017 at the premises of M/s SMRT Automotive Services Pte Ltd (Woodlands) and have the following to report:-

Workshop Estimate Amount	: S\$	4,821.07
Revised Estimate Amount	: S\$	1,137.69
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
N/S Front Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 2.0 days

Yours faithfully,

SEBASTIAN YEANG
Licensed Appraiser

Mei Kwan (LKKAUTO)

From: Joel Goh <joel.goh@sg.cntaiping.com>
Sent: Thursday, 14 December, 2017 1:18 PM
To: Mei Kwan (LKKAUTO)
Cc: Jas Khine (LKKAUTO); Vivian Lau (LKKAUTO); Admin A
Subject: RE: Direct Settlement - Accident Involving SFN3339J (OI : CAI - SNM17D07095C02/9) and SHB1783L (TP : LKK REF - CC3/CTI17023620/Swa3) on 09/12/2017
Attachments: MCHM17163875-SFN3339J.pdf
Follow Up Flag: Follow up
Flag Status: Completed
Categories: HMK

Dear Mei Kwan

Attached our insured accident report for your attention.

Best Regards

Joel Goh
Claims Executive (Motor Division)
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-02
Springleaf Tower Singapore 079909
Co. Reg. No. 200208384E
DID: 6389 6184
Fax: 6224 7175 / 6224 7478
Email: claimsdept@sg.cntaiping.com
joel.goh@sg.cntaiping.com
Website: www.sg.cntaiping.com

Disclaimer : This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Mei Kwan (LKKAUTO) [mailto:Meikwan@lkkauto.com]
Sent: Wednesday, 13 December, 2017 9:27 AM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Cc: Joel Goh <joel.goh@sg.cntaiping.com>; Jas Khine (LKKAUTO) <jaskhine@lkkauto.com>; Vivian Lau (LKKAUTO) <vivianlau@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: Direct Settlement - Accident Involving SFN3339J (OI : CAI - TBA) and SHB1783L (TP : LKK REF - CC3/CTI17023620/Swa3) on 09/12/2017

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

This is a TP direct settlement case.

We had inspected TP vehicle SHB 1783L at M/s SMRT Automotive Services Pte Ltd (Woodlands).

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Company
Owner ID	5369K
Vehicle Details	
Vehicle No.	SHB1783L
Vehicle to be Exported	No
Intended De-registration Date	12 Dec 2017
Vehicle Make	TOYOTA
Vehicle Model	PRIUS TAXI (SMRT)
Primary Colour	Maroon
Manufacturing Year	2015
Engine No.	2ZR1666444
Chassis No.	JTDKN36U105767364
Maximum Power Output	100.0 kW (134 bhp)
Open Market Value	\$29,508.00
Original Registration Date	05 Feb 2016
First Registration Date	05 Feb 2016
Transfer Count	0
Actual ARF Paid	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility	Yes
PARF Eligibility Expiry Date	04 Feb 2024
PARF Rebate Amount	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date	04 Feb 2024
COE Category	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years)	8
PQP Paid	\$43,040.00
COE Rebate Amount	\$33,064.00
Total Rebate Amount	\$36,814.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 12 Dec 2017



Please read through the [Privacy Statement](#), [Terms of Use](#), and [Disclaimer](#).

Please do not use the Back or Forward buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 10 and above, Chrome, Firefox, and Safari.

Copyright 2017 LTA [Privacy Statement](#) [Terms of Use](#) [Disclaimer](#) [Rate the Website](#) [Rate this e-Service](#)

Last updated on 19 Nov 2017 at 12:12 AM

12-12-17 / 16:00

13-12-17 / 11:00 (ADV)


13-12-17 / 15:00

11-12-17 / 15:00

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB1783L
 Ref. No : TAX/12/17/2050
 Reg. Date : 05/02/2016
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : FOO YONG LIANG EUGENE
 Type of Accident : HEAD TO SIDE
 Date / Time of Accident : 09/12/2017 12:50:00 AM
 Accident Reported Date / Time : 09/12/2017 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by : Sebastian
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024093528
 Special Instruction to ARC, if any :



SFN3339J - CHINA TAIPING - LKK
 BEFORE PAINT PHOTO, FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL SURVEYOR SEBASTIAN
 (LKK) & Email : sebastianyeang @lkkauto.com HP: 90036121
 Prepared Date : 09/12/2017 10:23:40 AM

Recording Camera

☒ ☐

Radio Antenna

☒ ☐

1st witness

Date 11.12.17

2nd witness

Date 12/12/17

16-00 12/12/17 Pass 321891km

1 — 1/4 1/2 3/4 — 6格油

321955km

1 — 1/4 1/2 3/4 — 7格油

LEE SHENG AUTO PTE LTD

Vehicle Return Date: 12/12/2017

Vehicle Return Time: 14:55

SMRT staff sign:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U105767364

Mileage

: 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 845.00	400.00
Total Spray Painting Charges	: 936.00	450.00
Total Material Charges	: 167.69	167.69
Other Charges	: 728.44	268.44
TOTAL	: 2,677.13	1,286.13
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 5.00	2.00 /
Prepared / Adjusted By	:	SEBASTIAN (LKK)
Arc / Surveyor Sign Off Date	: 09/12/2017 11:21:50 AM	11/12/2017 03:00:16 PM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 09/12/2017 11:21:01 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : QN-1712-0378

Invoice No :

Quotation Date : 14/12

Invoice Date :

Invoice Amount : 0.00

Prepared Date : 12/11/2017 3:18:57 PM

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH PORTION	845.00	400.00 /
Total Labour	845.00	400.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	200.00 /
TO RESPRAY FRONT FENDER LH	378.00	200.00 /
TO RESPRAY RIM	180.00	50.00 /
Total Spray Painting & Panel Beating	936.00	450.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	30.00 /
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	60.00 /
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	148.44	148.44 / net
TO REPLACE SUNDRY PARTS	100.00	0.00
TO WASH AND VACUUM	60.00	0.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	30.00 /
Total Other Costs	728.44	268.44

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52119-47930		6505517	BUMPER FRT	R 1	482.00	100.00	0.00	Replace	Repair	No R
53802-47050		6505558	FENDER FRT/LH	R 1	723.40	100.00	0.00	Replace	Repair	No R
75374-47051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace	No ✓ NEC
53876-47030		6505554	FENDER LINER FRT/LH	1	171.70	25.00	128.77	Replace	Replace	No ✓ TW
		6503707	TYRE	X 0	126.74	0.00	0.00	Replace	Not given	No X NN
42611-47140 (Frt)		6505658	WHEEL DISC. FRONT	R 1	1,484.20	100.00	0.00	Replace	Repair	No R
TOTAL MATERIALS								167.70	167.69	
TOTAL MATERIALS(Discounted)								167.69	167.69	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

167.69 /
+ 400.00 /
+ 718.44 /

1286.13 /

Sebastian
20/12/2017

5349.38

SMRT Accident Vehicle Repair Estimates

Ching
6/11/17

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB1783L
 Ref. No : TAX/12/17/2050
 Reg. Date : 05/02/2016
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : FOO YONG LIANG EUGENE
 Type of Accident : HEAD TO SIDE
 Date / Time of Accident : 09/12/2017 12:50:00 AM
 Accident Reported Date / Time : 09/12/2017 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024093528
 Special Instruction to ARC, if any :
 SFN3339J
 Prepared Date : 09/12/2017 10:23:40 AM


Sebastian.
11/12/2017.
- Part by part repair.
- Question Mark Item Photo
- Photo Before Paint.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U105767364

Mileage

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 845.00	0.00
Total Spray Painting Charges	: 936.00	0.00
Total Material Charges	: 2,311.63	2,311.63
Other Charges	: 728.44	0.00
TOTAL	: 4,821.07	0.00
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 5.00	0.00
Prepared / Adjusted By	:	2 days
Arc / Surveyor Sign Off Date	: 09/12/2017 11:21:50 AM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 09/12/2017 11:21:01 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH PORTION	845.00	0.00 400
Total Labour	845.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	0.00 200
TO RESPRAY FRONT FENDER LH	378.00	0.00 200
TO RESPRAY RIM	180.00	0.00 50
Total Spray Painting & Panel Beating	936.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 X
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 30
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0.00 60
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	148.44	0.00 ✓
TO REPLACE SUNDRY PARTS	100.00	0.00 X
TO WASH AND VACUUM	60.00	0.00 X
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0.00 30
Total Other Costs	728.44	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52119-47930		6505517	BUMPER FRT	1	482.00	25.00	361.50	Replace	Replace <i>R</i>	No
53802-47050		6505558	FENDER FRT/LH	1	723.40	25.00	542.55	Replace	Replace <i>R</i>	No
75374-47051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace <i>J nec</i>	No
53876-47030		6505554	FENDER LINER FRT/LH	1	171.70	25.00	128.77	Replace	Replace <i>J TN</i>	No
		6503707	TYRE	1	126.74	0.00	126.74	Replace	Replace <i>X</i>	No
42611--47140 (Frt)		6505658	WHEEL DISC. FRONT	1	1,484.20	25.00	1,113.15	Replace	Replace <i>R</i>	No
TOTAL MATERIALS								2,311.64	2,311.63	
TOTAL MATERIALS(Discounted)							2,311.63	2,311.63		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref : CC3/CTI17023620/Swa3n2	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Date : 22-01-2018	
			Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SFN 3339J	Veh. Inspected	SHB 1783L	
Policy No.	DMPCSN3083931701	Coverage (\$)	0.00	
Claim No.	SNM17D07095C02/9	Excess (\$)	0.00	
Assign From		Assign Date	11/12/2017	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JTDKN36U105767364	Colour	MAROON	
Odometer	321892	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	FALKEN	6 mm	
L/H Front Tyre	195/65 R15	FALKEN	6 mm	
R/H Rear Tyre	195/65 R15	FALKEN	6 mm	
L/H Rear Tyre	195/65 R15	FALKEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	09/12/2017	Inspection Date	11/12/2017	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 1783L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	NAME PLATE (HYBRID)(DISC 25%)	NECESSARY	51.90	38.92
1	FENDER LINER FRT/LH (DISC 25%)	TORN	171.70	128.77
1	ADVERTISEMENT STICKER (SN)	NECESSARY	148.44	148.44
1	TYRE	NOT NECESSARY	126.74	-
1	BUMPER FRT	TO REPAIR SEE LABOUR	482.00	-
1	FENDER FRT/LH	TO REPAIR SEE LABOUR	723.40	-
1	WHEEL DISC,FRONT	TO REPAIR SEE LABOUR	1,484.20	-
			3,188.38	316.13
LABOUR				
	PANEL BEATING & BODY WORK.INCLUSIVE OF THE REPAIR OF BUMPER FRT,FENDER FRT/LH AND WHEEL DISC,FRONT.		845.00	400.00
	SPRAY PAINT.		936.00	450.00
	TO CHECK WIRING AND SYSTEM FUNCTION.	NOT NECESSARY	80.00	-
	TO APPLY RUST-PROOFING ON AFFECTED AREA.		100.00	30.00
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE).		120.00	30.00
	TO DO WHEEL ALIGNMENT/TYRE BALANCING.		120.00	60.00
			2,361.00	970.00
GRAND TOTAL			5,549.38	1,286.13
RECOMMENDED COST OF REPAIRS				1,286.13

Report Ref No. CC3/CTI17023620/Swa3n2

YEANG WAI KEEN
Automotive Assessor

HO LEONG CHUAN
Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.