

ASS. REC. BY:

REF:

TP/

CS/TP17023625/Krbnz

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 16 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

STD 91344

Yr Regn:

09.11

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Chevrolet Epica

c.c

1991

Colour:

White 1Rw

A/C:

Insured / Std / NI / NA

Sp. Reading

359246

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KULIA68RTBB 055347

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

westlake

Front

Rear

R/Bal.

7

mm

R/Bal.

3

mm

L/Bal.

7

mm

L/Bal.

3

mm

D.O.A.

11/8/15

D.O.I.

4/8/15

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

STD 91344 - NA / DAL15013050/d2

DCA: 010815

Call wai Yin to explain we will to Trans-Cab. she ask to sent invoice
for her to take approval.

Submit LIS \$13K, 16 days
Red: \$22,941.92, 64%.

RECEIVED 13 DEC 2017

Date/Time: File Pass to?

1) typst

Date/Time: File Return to?

2)



: Preli. Report

: Final Report

Days Of Repair: 16

Resurvey No. of Trip: -

Add Fee:



: Site Insp

: Interview

: Tech. Insp

: Weekend

Survey Fee:

Transportation:

S + RS

Photo

City

TOTAL

25x15: 375

170+375

50

44

80

719

Report Format:

TP - Independent

Lump Sum / 1-10

13K




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
TRANS-CAB AUTO SERVICES PTE LTD		Ref : CS/TP17023625/Krb		
NO.2 ANG MO KIO STREET 63 SINGAPORE 569111		Date : 13-12-2017		
		Code : TP378		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	Veh. Inspected		SHD 9134Y	
Policy No.	Coverage (\$)		0.00	
Claim No.	Excess (\$)		0.00	
Assign From	Assign Date		04/08/2015	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No. HIDDEN	Year of Reg.			
Chassis No.	Colour			
Odometer -	Steering			
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	01/08/2015	Inspection Date	04/08/2015	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Veron Chen (LKKAUTO)

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Sent: Tuesday, 12 December, 2017 2:06 PM
To: Veron Chen (LKKAUTO)
Cc: 'Jasmine Tan'; SUR; claims@transcab.com.sg
Subject: RE: AW REF: NSV1501810 _ Your Ref: SHD 9134Y (AAD1508-002) _ DOA: 1 August 2015
Attachments: AAD1508-002 - ESTIMATE MARKING.pdf

Dear Veron

Kenneth survey vehicle on 04.08.2015.

Can you help me to check with Kenneth, attached the estimate marking for your easy reference.

Thank You
Best Regards,
Ng Wai Yin
Finance Department
TEL: 6603 1265 Ext.308

***** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg**



TRANS-CAB SERVICES PTE LTD
No. 2 Ang Mo Kio Street 63, Singapore 569111
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764
Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]
Sent: Thursday, December 07, 2017 12:22 PM
To: Ng Wai Yin <waiyin.ng@transcab.com.sg>; SUR <sur@lkkauto.com>
Cc: 'Jasmine Tan' <jasminetan@transcab.com.sg>; claims@transcab.com.sg
Subject: RE: AW REF: NSV1501810 _ Your Ref: SHD 9134Y (AAD1508-002) _ DOA: 1 August 2015

Dear Wai Yin,

We have no record for SHB 9608H in our system.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ng Wai Yin [<mailto:waiyin.ng@transcab.com.sg>]
Sent: Thursday, 7 December, 2017 12:00 PM
To: SUR <sur@lkkauto.com>
Cc: 'Jasmine Tan' <jasminetan@transcab.com.sg>; claims@transcab.com.sg
Subject: FW: AW REF: NSV1501810 _ Your Ref: SHD 9134Y (AAD1508-002) _ DOA: 1 August 2015

Dear Sirs

Kindly forward us a copy of survey report done by your surveyor for the above vehicle No. SHB9608H.

Additional details information:-

Our TCS Ref: AAD1508-002
Our TCS vehicle No: SHD9134Y
Vehicle Make: CHEVROLET
Vehicle Model: EPICA-2.0 (A)
Date of Accident: 01-08-15 11:40 AM
Place of Accident: CTE (City) before AMK Ave 1 exit
Third Party Insurer: ALLIED WORLD ASSURANCE COMPANY

Thank You
Best Regards,
Ng Wai Yin
Finance Department
TEL: 6603 1265 Ext.308

***** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg**



TRANS-CAB SERVICES PTE LTD
No. 2 Ang Mo Kio Street 63, Singapore 569111
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764
Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Wong, Kin [<mailto:Kin.Wong@awac.com>]
Sent: Thursday, December 07, 2017 8:54 AM
To: 'Jasmine Tan' <jasminetan@transcab.com.sg>; 'Ng Wai Yin' <waiyin.ng@transcab.com.sg>
Subject: AW REF: NSV1501810 _ Your Ref: SHD 9134Y _ DOA: 1 August 2015

WITHOUT PREJUDICE

Dear Wai Yin

We refer to your claim and note that no PRI was conducted.

Can we have your survey report on how cost of repair was arrived?

Thank you.

Regards,

Kin Wong

Allied World Assurance Company, Ltd.

60 Anson Road #08-01

Singapore 079914

T: +65 6423 0894

F: +65 6423 0864

E: kin.wong@awac.com

W: www.awac.com

The information contained in this e-mail and any attachments hereto is confidential. If you are not the intended recipient, you must not use or disseminate any of this information. If you have received this e-mail in error, please immediately notify the sender by reply e-mail and permanently delete the original e-mail (and any attachments hereto) and any copies or printouts thereof. Although this e-mail and any attachments hereto are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by Allied World Assurance Company Holdings, GmbH or its subsidiaries or affiliates, either jointly or severally, for any loss or damage arising in any way from its use.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/08/2015 09:00
Date Of Accident	01/08/2015 11:40
Exact Location Of Accident	CTE (City) before AMK Ave 1 exit
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD9134Y
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	claims@transcabservices.com.sg
Mobile Phone No	
Alternative Phone No	Office-62876666

Vehicle Particulars

Manufacturer	CHEVROLET
Model	EPICA-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	Hire and Reward
Are you claiming under your own insurance policy for repair to your vehicle?	No
If No, Please state action to be taken	Third Party
Vehicle Category	Taxi

Insurance Company

Name of Insurance Company	First Capital Insurance Ltd
Type Of Coverage	Third Party
Fleet Policy	Yes
Policy Number	D-12047359MFSH/3587
Cover Note Number	

Driver

Name of Driver	TAN AH CHOON
NRIC No	S1335799D
Date Of Birth	05/02/1958
Occupation	Outdoor
Date Of Driving Pass	02/06/1977
Driving Experience	38 Years And 1 Month
Gender	Male
Mobile Number	(Local) +65-94335977
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 8 LORONG LEW LIAN #05-176
Postcode	531008
Was driver an employee of the Insured's Company	No
If No, Relationship of the Driver with the Insured	Other - Hirer
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	Collision- Chain Collision
Weather Conditions	Clear
Road Surface	Dry

Other Information

Was any foreign vehicle involved in this accident?	No
Was any body injured in the Accident?	Yes
Was any other material or property damaged?	Yes
Was there any video captured by Car Camera?	No
Number of Passengers (Including Driver)	2

Details of Police Action

Was the accident reported to the police?	Yes
If Yes, Please state which Police Station	
Police Station Name	Serangoon Neighbourhood Police Centre
Police Station Address	ROAD: 50 Serangoon Ave 2 #01-02 , POSTCODE: 556129 , COUNTRY: Singapore
Police Station Contact	TEL NO: 1800-4880999 - FAX NO: 64883561
Was notice of intended Prosecution given?	No
If Yes, against whom?	

Circumstances of Accident

Please refer to Police Report - T/20150802/2023

Are accident photos available for attachment?	Yes
---	-----

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJU5204U
Vehicle Make/Model/Colour	UNKNOWN
Details Of Properties	
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SJH4918R
Vehicle Make/Model/Colour	PROTON GEN21.6ATHLE

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

DETAILS OF INJURED PERSON 1

Name

TAN AH CHOON

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SHD9134Y

Were seat belts worn?

Yes

Was injured conveyed to hospital by ambulance?

No

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that :
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

→ CTE (CITY) BEFORE AMK AVE 1 EXIT A: SHD 9134Y

→ B: SDU 5204J

→ C: SJH 9918R

→

B	A	C
---	---	---

Describe Circumstances of the Accident

Describe Circumstances of the Accident

PLS REFER TO POLICE REPORT

Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date &
Time

Driver's Signature (If driver is not the policyholder) / Date & Time.

Witnessed by Reporting Centre
Personnel

Police Report Pg.1

Police Station Of Origin:
Serangoon N.P.C
50 Serangoon Avenue 2 #01-02 SINGAPORE
556129
Tel No: 1800-4880999



T/20150802/2023

1 of 3

Report No. T/20150802/2023

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 02/08/2015 10:25		Vide Report No.:		Station Diary No.: 22	
Informant's Particulars					
Name of Informant: TAN AH CHOON			Address: APT BLK 8 LORONG LEW LIAN #05-176 SINGAPORE 531008		
ID Type / ID No.: NRIC NO / S1335799D			Contact No.: Home/Office:		Mobile: 94335977
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 57	Date of Birth: 05/02/1958	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Taxi driver			Driving Licence Information: Class:		Date of Expiry:

General Information of the Accident				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 01/08/2015 11:40	Type of Location: Straight Road
Location: Along Road 1 CENTRAL EXPRESSWAY after Ang Mo Kio Ave 5 exit and before Ang Mo Kio Ave 1 exit				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control:		Traffic Volume:
Type of Collision: Between Moving Vehicles - Chain Collision				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHD9134Y	Car	CHEVROLET			Seriously Damaged	0
SJH4918R	Car					0
SJU5204U	Car					0

Police Station Of Origin:
Serangoon N.P.C
50 Serangoon Avenue 2 #01-02 SINGAPORE
556129
Tel No: 1800-4880999



T/20150802/2023

2 of 3

Report No. T/20150802/2023

CONTINUATION OF REPORT

Brief Details.

On 01/08/2015 at about 1140hrs at CTE just after Ang Mo Kio Ave 5 exit before Ang Mo Kio Ave 1 exit, I was driving my taxi (SHD9134Y) at the most right lane. The vehicle (SJH4918R) in front of me slow down and I follow along and control my brake. However, a vehicle (SJU5204U) suddenly hit onto my rear. It caused my vehicle to hit the vehicle in front of me. We stopped at the right lane and check whether anyone was injured. I noticed that the vehicle that hit me from the rear, its air bag was activated. I have a passenger in my taxi and he gave me his contact number (97620769) to stand as a witness.

When I reached home, I felt pain at my neck and lower back. I also have difficulty in turning my head. I went to a family clinic where I was certified with a 5 days MC.

Police Station Of Origin:
Serangoon N.P.C
50 Serangoon Avenue 2 #01-02 SINGAPORE
556129
Tel No: 1800-4880999



T/20150802/2023

3 of 3

Report No. T/20150802/2023

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

F /

Muhammad Syahiran Bin Badarrudin

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / AEIT /

Wong Sieu Lui

Contact No.: 65476423

Authentication Stamp

NP168

Signature Of Informant:

Date/Time:

02/08/2015 10:25

Classification Of Case:

Text size + -

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Company
Owner ID: 200303878K

Vehicle Details

Vehicle No.: SHD9134Y
Vehicle to be Exported: Yes
Intended De-registration Date: 03 Aug 2015
Vehicle Make: CHEVROLET
Vehicle Model: EPICA 2.0DSL AT ABS D/AB 2WD 4DR TURBO
Primary Colour: Red
Manufacturing Year: 2011
Engine No.: Z20S1443297K
Chassis No.: KL1LA69RJBB055347
Maximum Power Output: 110.0 kW (147 bhp)
Open Market Value: \$14,178.00
Original Registration Date: 09 Sep 2011
First Registration Date: 09 Sep 2011
Transfer Count: 0
Actual ARF Paid: \$14,178.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 08 Sep 2019
PARF Rebate Amount: \$10,633.00

Intended COE Rebate Details

COE Expiry Date: 08 Sep 2019
COE Category: A - Car (1600cc & below)
COE Period (Years): 8
QP Paid: \$34,570.00
COE Rebate Amount: \$17,705.00
Total Rebate Amount: \$28,338.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 03 Aug 2015

OK



Please read through the Privacy Statement, Terms of Use and Disclaimer.
Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.
Best viewed with IE 6.0 SP3 and above, 1024 X 768 resolution
Copyright © 2015 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)

✓ **Trans-Cab Auto Services Pte Ltd**
No. 42 Sungei Kadut Street 1
Singapore 729346
Co./ GST Reg. No.: 201019626G

Case Handle by: R62
A&D No.: 1508-002
1508-602
1'-003

Notification of Accident

☐ Toyota Wish 1.8 ☐ Toyota Wish 2.0 ☐ Mercedes Benz ☒ Chevrolet Epica ☐ Renault Latitude

Taxi Registration Number : SHD9134Y Claim Against: _____

Third Party Vehicle Number : SJU5204U SJH4918R

Date and Time of Accident : 01/08/2015 @ 11:40 Hrs Surveyor: (11608902002) KURNIA - 04 AUG 2015

Location : CTE (City) before AMK Ave 1 exit

Accident by Hirer / Relief : TAN AH CHOON

NRIC No. : S1335799D Reported on: 03/08/2015

Estimated no. of repair days : 4 days AL Doc. No. _____ Check By _____

In: 01.08.15 @ 1140hrs Tow: Y NAV updated Yes / No _____

Out: 18 AUG 2015 @ 1504hrs NAV updated Yes / No _____

Any outstanding Rental Yes / No _____ S\$ _____

Any outstanding Accident Liabilities Yes / No _____ S\$ _____

Any outstanding Deposit Yes / No _____ S\$ _____

Release Vehicle Yes / No _____

If your answer is **YES** for Outstanding and release vehicle, please provide your remark:

Please put a tick [✓] for the item which is applicable:

[✓] 100% against third party. **KIV loss of earnings for 6 months.** - Carroll Collision Yes / No

[] 50% / 50% against third party. **Excess is applicable.**

[✓] At fault. **Excess is applicable.** - Try to claim

[] Late Report. **Excess is applicable.**

[] Mutual Settlement. Remark _____

[] No repair / self repaired. Driver claimed no involvement / not at fault.

[] Windscreen damaged.

[] Excess is applicable due to resigned.

ACE	
ACE	
ACE	

ACE	
-----	--

Declaration

I, TAN AH CHOON bearing NRIC no. S1335799D (Hirer / Relief) confirmed no injury sustained pertaining to the above accident.

The above was clearly explained and accepted by me.

Hirer/Relief : _____
(Signature and Date)

No. 42 Sungei Kadut Street 1 Singapore 729346
Tel: 6287 6666 Fax: 6366 8862

LOD Submission Date: _____
DV Received Date: _____
Invoice No.: _____
Cheque Received Date: _____
Completion Date: _____

TRANS-CAB AUTO SERVICES PTE LTD

NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHD 9134Y -**ROEL**

Not Authorized
1/1/15 @ 11,800.00

INV1509 - 382

79, 912,626.00

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHD 9134Y - ROEL
KL1LA69RJBB055347
CHEVROLET
EPICA 2.0
01.08.2015

PART**LIST**

1	1	Front Bumper	\$	1,202.00	✓
2	1	Front Bumper Lower Absorber	\$	180.00	X
3	1	Front Bumper Reinforcement	\$	356.00	✓
4	1	Front Bumper Retainer RH	\$	102.00	X
5	1	Front Bumper Retainer LH	\$	102.00	X
6	1	Front Bumper Lower Grille	\$	78.00	X
7	1	Front Bumper Lower Stiffener	\$	134.37	✓
8	1	Front Bumper Fog Lamp Outer Cover RH	\$	32.40	X
9	1	Front Bumper Fog Lamp Outer Cover LH	\$	32.40	X
10	1	Front Support Panel Assy	\$	1,222.32	✓
11	1	Headlamp RH (Lamp A-Head RH)	\$	816.00	X
12	1	Headlamp LH (Lamp A-Head LH)	\$	816.00	✓
13	1	Bonnet (Panel A-Hood)	\$	1,250.00	✓
14	1	Bonnet Moulding	\$	257.00	✓
15	1	Centre 'CHEVROLET' Logo Badge	\$	144.30	✓
16	1	Radiator Assembly	\$	618.00	✓
17	1	Radiator Grille	\$	367.00	✓
18	1	Radiator Grille Top Cover	\$	45.02	✓
19	1	Fan Blade (Small)	\$	536.00	✓
20	1	Fan Blade (Big)	\$	634.00	X
21	1	Aircon Condenser	\$	600.00	✓
22	1	Air Intercooler	\$	652.00	✓
23	1	Front Fender RH	\$	837.60	X
24	1	Front Fender LH	\$	837.60	✓
25	1	Rear Bumper	\$	1,202.00	✓
26	1	Rear Bumper Beam	\$	239.94	✓
27	1	Rear Bumper Centre Absorber	\$	260.00	✓
28	1	Rear Bumper Side Retainer RH	\$	68.76	✓
29	1	Rear Bumper Side Retainer LH	\$	68.76	✓
30	1	Rear Bumper Reflectors RH	\$	119.74	✓
31	1	Rear Bumper Reflectors LH	\$	119.74	✓
32	1	Rear Bumper Tow Hook Cover	\$	93.00	✓
33	1	Rear Luggage Floor Panel	\$	973.00	✓
34	1	Rear Luggage Floor Panel Insulator	\$	63.50	✓
35	1	Rear Luggage Floor Panel Trim Board	\$	378.00	X
36	1	Rear End Panel Outer	\$	623.76	✓

TRANS-CAB AUTO SERVICES PTE LTD

NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHD 9134Y -

ROEL

37	1	Rear End Panel Inner Trim	\$
38	1	Bootlid	\$
39	1	Bootlid inner trim board	\$
40	1	Bootlid Weatherstrip	\$
41	1	Bootlid Lock - Top	\$
42	1	Bootlid 'CHEVROLET' Badge	\$
43	1	Bootlid Logo	\$
44	1	Bootlid 'EPICA LT' Badge	\$
45	1	Bootlid Reflector Centre	\$
46	1	Bootlid Reflector RH	\$
47	1	Bootlid Reflector LH	\$
48	1	Rear Gas T/Gate Spring RH	\$
49	1	Rear Gas T/Gate Spring LH	\$
50	1	Bootlid Hinge RH	\$
51	1	Bootlid Hinge LH	\$
52	1	Rear Tail Lamp RH	\$
53	1	Rear Tail Lamp Panel RH	\$
54	1	Rear Tail Lamp LH	\$
55	1	Rear Tail Lamp Panel LH	\$
56	1	Rear Exhaust Box (Muffler A-EXH,RR)	\$

263.84	✓
973.00	✓
400.00	X
344.28	✓
466.56	X
120.62	✓
138.84	✓
119.84	✓
217.97	X
128.40	X
128.40	✓
286.90	X
286.90	✓
120.00	X
120.00	X
479.30	✓
359.00	X
479.30	✓
359.00	X
1,110.00	X

TOTAL	\$	22,964.36
10%	\$	2,296.44
	\$	20,667.92

Special Net

1	1 Set	Front Bumper Fastener Clip	\$
2	1 Set	Radiator Grille Top Cover Clip	\$
3	1 Cans	Radiator Coolant	\$
4	1 Set	Radiator Grille clip	\$
5	1 Set	Bonnet under weatherstrip seal clips	\$
6	1 Set	Bonnet insulator clip	\$
7	2	Bonnet stopper	\$
8	2Set	Front Fender Liner Clip	\$
9	1 Set	Front Licence Plate With Holder	\$
10	1 Set	Rear Bumper Parking Sensor	\$
11	1 Set	Rear Bumper Fastener Clip	\$
12	1	Rear Boot Sticker 'Trans-cab'	\$
13	1	Rear Boot Sticker '6555-3333'	\$
14	1Set	Bootlid inner trim board Clip	\$
15	1	Rear Exhaust Mounting	\$
16	1 Set	Rear Bumper End Dust Cover Clip	\$
17	1 Set	Rear Fender Inner Trim Clip RH	\$
18	1 Set	Rear Fender Inner Trim Clip LH	\$
19	1 Set	Rear Fender Inner Cowling LH Clip	\$

24.00	✓
10.00	X
60.00	201X
35.00	✓
30.00	X
30.00	X
15.00	X
60.00	X
80.00	655X
300.00	✓
30.00	✓
30.00	✓
30.00	✓
40.00	X
10.00	X
30.00	X
30.00	X
30.00	X
30.00	X

TRANS-CAB AUTO SERVICES PTE LTD

NO.42 SUNGEI KADUT ST 1 SINGAPORE 729348

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHD 9134Y -**ROEL**

20	1 Set	Rear Fender Inner Cowling RH Clip	\$
21	2	Rear Windscreen Sealant	\$
22	1	Rear Windscreen Inner Sponge Seal	\$

nn 30.00 ✓
nn 100.00 X
nn 100.00 λ

TOTAL	\$	1,134.00
TOTAL PARTS	\$	21,801.92

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of Parts,
Adjust And Realign The Same

\$

5,400.00 *2200*

To Check Electrical Lighting Concerned.

\$

170.00 *400*

To Rust-Proofing Of The Affected Areas.

\$

170.00 *1500*

Putty And Spray Painting Of The Affected Portion.

\$

5,350.00 *1800*

To reinstall rear bumper parking sensor.

\$

170.00 *600*

To transfer of bootlid fittings, attachments and
perform water seepage test.

\$

170.00 *600*

To repair and realign rear exhaust pipe.

\$

170.00 *600*

To supply and re-do rear luggage floor panel
insulation padding.

\$

380.00 *800*

To transfer of end panel fittings and conduct
water seepage test.

\$

170.00 *800*

To drop rear exhaust box, renew the same, to repair
and realign centre exhaust pipe.

\$

Repair 170.00 X

Towing Fees

\$

120.00 *500*

To dismantle and refit aircon assy and attachment,
vacuum and charge-in-gas.

\$

380.00 *700*

To vacuum, replace, refix and recharge air condenser

\$

380.00 }

To replace, refix and top up coolant for radiator

\$

380.00 *500*

To vacuum, replace, refix and recharge Air
Intercooler

\$

170.00 *500*

TRANS-CAB AUTO SERVICES PTE LTD

NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHD 9134Y -**ROEL**

To Remove And Refit Rear W/Screen Glass To
Facilitate Bodywork Repair.

\$

~~ 170.00 X

To check steering geometry and computer wheel
alignment

\$

220.00 *800*

TOTAL	\$	14,140.00
--------------	-----------	------------------

Over All Total	\$	35,941.92
-----------------------	-----------	------------------

Repair Days~~20 Days~~*16 days*

TRANS-CAB AUTO SERVICES PTE LTD

NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHD 9134Y -*Not Authorized
1/1/2015***ROEL**

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 9134Y - ROEL

KL1LA69RJB055347

CHEVROLET

EPICA 2.0

01.08.2015

PART**LIST**

1	1	Front Bumper	\$	<i>Br</i> 1,202.00 ✓
2	1	Front Bumper Lower Absorber	\$	<i>Sm</i> 180.00 X
3	1	Front Bumper Reinforcement	\$	<i>Br</i> 356.00 ✓
4	1	Front Bumper Retainer RH	\$	<i>Sm</i> 102.00 X
5	1	Front Bumper Retainer LH	\$	<i>Sm</i> 102.00 X
6	1	Front Bumper Lower Grille	\$	<i>Sm</i> 78.00 X
7	1	Front Bumper Lower Stiffener	\$	<i>R</i> 134.37 X
8	1	Front Bumper Fog Lamp Outer Cover RH	\$	<i>Sm</i> 32.40 X
9	1	Front Bumper Fog Lamp Outer Cover LH	\$	<i>Sm</i> 32.40 X
10	1	Front Support Panel AssY	\$	<i>Br</i> 1,222.32 ✓
11	1	Headlamp RH (Lamp A-Head RH)	\$	<i>Br</i> 816.00 X
12	1	Headlamp LH (Lamp A-Head LH)	\$	<i>Sm</i> 816.00 X
13	1	Bonnet (Panel A-Hood)	\$	<i>Br</i> 1,250.00 ✓
14	1	Bonnet Moulding	\$	<i>Br</i> 257.00 ✓
15	1	Centre 'CHEVROLET' Logo Badge	\$	<i>Br</i> 144.30 ✓
16	1	Radiator Assembly	\$	<i>Br</i> 618.00 X
17	1	Radiator Grille	\$	<i>CR</i> 367.00 ✓
18	1	Radiator Grille Top Cover	\$	<i>Sm</i> 45.02 X
19	1	Fan Blade (Small)	\$	<i>CR</i> 536.00 ✓
20	1	Fan Blade (Big)	\$	<i>Sm</i> 634.00 X
21	1	Aircon Condenser	\$	<i>Sm</i> 600.00 X
22	1	Air Intercooler	\$	<i>Sm</i> 652.00 X
23	1	Front Fender RH	\$	<i>R</i> 837.60 X
24	1	Front Fender LH	\$	<i>R</i> 837.60 X
25	1	Rear Bumper	\$	<i>Br</i> 1,202.00 ✓
26	1	Rear Bumper Beam	\$	<i>Br</i> 239.94 ✓
27	1	Rear Bumper Centre Absorber	\$	<i>CR</i> 260.00 ✓
28	1	Rear Bumper Side Retainer RH	\$	<i>CR</i> 68.76 ✓
29	1	Rear Bumper Side Retainer LH	\$	<i>CR</i> 68.76 ✓
30	1	Rear Bumper Reflectors RH	\$	<i>Br</i> 119.74 ✓
31	1	Rear Bumper Reflectors LH	\$	<i>CR</i> 119.74 ✓
32	1	Rear Bumper Tow Hook Cover	\$	<i>Sm</i> 93.00 X
33	1	Rear Luggage Floor Panel	\$	<i>Br</i> 973.00 ✓
34	1	Rear Luggage Floor Panel Insulator	\$	<i>Br</i> 63.50 ✓
35	1	Rear Luggage Floor Panel Trim Board	\$	<i>Sm</i> 378.00 X
36	1	Rear End Panel Outer	\$	<i>Br</i> 623.76 ✓

TRANS-CAB AUTO SERVICES PTE LTD**ROEL**

NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHD 9134Y -

37	1	Rear End Panel Inner Trim	\$	263.84	✓
38	1	Bootlid	\$	973.00	✓
39	1	Bootlid inner trim board	\$	400.00	X
40	1	Bootlid Weatherstrip	\$	344.28	✓
41	1	Bootlid Lock - Top	\$	466.56	✓
42	1	Bootlid 'CHEVROLET' Badge	\$	120.62	✓
43	1	Bootlid Logo	\$	138.84	✓
44	1	Bootlid 'EPICA LT' Badge	\$	119.84	✓
45	1	Bootlid Reflector Centre	\$	217.97	X
46	1	Bootlid Reflector RH	\$	128.40	X
47	1	Bootlid Reflector LH	\$	128.40	X
48	1	Rear Gas T/Gate Spring RH	\$	286.90	X
49	1	Rear Gas T/Gate Spring LH	\$	286.90	X
50	1	Bootlid Hinge RH	\$	120.00	X
51	1	Bootlid Hinge LH	\$	120.00	X
52	1	Rear Tail Lamp RH	\$	479.30	✓
53	1	Rear Tail Lamp Panel RH	\$	359.00	X
54	1	Rear Tail Lamp LH	\$	479.30	✓
55	1	Rear Tail Lamp Panel LH	\$	359.00	X
56	1	Rear Exhaust Box (Muffler A-EXH,RR)	\$	1,110.00	X

TOTAL	\$	22,964.36
10%	\$	2,296.44
	\$	20,667.92

Special Nett

1	1 Set	Front Bumper Fastener Clip	\$	24.00	✓
2	1 Set	Radiator Grille Top Cover Clip	\$	10.00	X
3	1 Cans	Radiator Coolant	\$	60.00	2 cans
4	1 Set	Radiator Grille clip	\$	35.00	✓
5	1 Set	Bonnet under weatherstrip seal clips	\$	30.00	X
6	1 Set	Bonnet insulator clip	\$	30.00	X
7	2	Bonnet stopper	\$	15.00	X
8	2Set	Front Fender Liner Clip	\$	60.00	X
9	1 Set	Front Licence Plate With Holder	\$	80.00	4552
10	1 Set	Rear Bumper Parking Sensor	\$	300.00	✓
11	1 Set	Rear Bumper Fastener Clip	\$	30.00	✓
12	1	Rear Boot Sticker 'Trans-cab'	\$	30.00	✓
13	1	Rear Boot Sticker '6555-3333'	\$	30.00	✓
14	1Set	Bootlid inner trim board Clip	\$	40.00	X
15	1	Rear Exhaust Mounting	\$	10.00	X
16	1 Set	Rear Bumper End Dust Cover Clip	\$	30.00	X
17	1 Set	Rear Fender Inner Trim Clip RH	\$	30.00	X
18	1 Set	Rear Fender Inner Trim Clip LH	\$	30.00	X
19	1 Set	Rear Fender Inner Cowling LH Clip	\$	30.00	X

TRANS-CAB AUTO SERVICES PTE LTD**ROEL**

NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHD 9134Y -

20	1 Set	Rear Fender Inner Cowling RH Clip	\$	<i>nn</i> 30.00 ✓
21	2	Rear Windscreen Sealant	\$	<i>nn</i> 100.00 X
22	1	Rear Windscreen Inner Sponge Seal	\$	<i>nn</i> 100.00 λ

TOTAL	\$	1,134.00
TOTAL PARTS	\$	21,801.92

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	5,400.00	<i>2200</i>
To Check Electrical Lighting Concerned.	\$	170.00	<i>400</i>
To Rust-Proofing Of The Affected Areas.	\$	170.00	<i>1500</i>
Putty And Spray Painting Of The Affected Portion.	\$	5,350.00	<i>1800</i>
To reinstall rear bumper parking sensor.	\$	170.00	<i>600</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	<i>600</i>
To repair and realign rear exhaust pipe.	\$	170.00	<i>600</i>
To supply and re-do rear luggage floor panel insulation padding.	\$	380.00	<i>800</i>
To transfer of end panel fittings and conduct water seepage test.	\$	170.00	<i>800</i>
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	<i>Repair</i> X
Towing Fees	\$	120.00	<i>500</i>
To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	380.00	<i>7000</i>
To vacuum, replace, refix and recharge air condenser	\$	380.00	
To replace, refix and top up coolant for radiator	\$	380.00	<i>500</i>
To vacuum, replace, refix and recharge Air Intercooler	\$	170.00	<i>500</i>

TRANS-CAB AUTO SERVICES PTE LTD**ROEL**

NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHD 9134Y -To Remove And Refit Rear W/Screen Glass To
Facilitate Bodywork Repair.

\$

~~ 170.00 X

To check steering geometry and computer wheel
alignment

\$

220.00 600

TOTAL	\$	14,140.00
Over All Total	\$	35,941.92

Repair Days

20 Days

16 days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

TRANS-CAB AUTO SERVICES PTE LTD

Ref : CS/TP17023625/Krbn2

NO.2 ANG MO KIO STREET 63 SINGAPORE 569111

Date : 14-12-2017



Code : TP378

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	Veh. Inspected	SHD 9134Y
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	04/08/2015

2. Vehicle Particulars & Condition

Make & Model	CHEVROLET EPICA (A)	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	KL1LA69RJBB055347	Colour	WHITE / RED
Odometer	359246	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	WEST LAKE	7 mm
L/H Front Tyre	195/65 R15	WEST LAKE	7 mm
R/H Rear Tyre	195/65 R15	WEST LAKE	3 mm
L/H Rear Tyre	195/65 R15	WEST LAKE	3 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	01/08/2015	Inspection Date	04/08/2015
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	16 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 9134Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	BUCKLED	1,202.00	1,202.00
1	FRONT BUMPER LOWER ABSORBER	SERVICEABLE	180.00	-
1	FRONT BUMPER REINFORCEMENT	BENT	356.00	356.00
1	FRONT BUMPER RETAINER RH	SERVICEABLE	102.00	-
1	FRONT BUMPER RETAINER LH	SERVICEABLE	102.00	-
1	FRONT BUMPER LOWER GRILLE	SERVICEABLE	78.00	-
1	FRONT BUMPER LOWER STIFFENER	TO REPAIR SEE LABOUR	134.37	-
1	FRONT BUMPER FOG LAMP OUTER COVER RH	SERVICEABLE	32.40	-
1	FRONT BUMPER FOG LAMP OUTER COVER LH	SERVICEABLE	32.40	-
1	FRONT SUPPORT PANEL ASSY	BUCKLED	1,222.32	1,222.32
1	HEADLAMP RH (LAMP A-HEAD RH)	SERVICEABLE	816.00	-
1	HEADLAMP LH (LAMP A-HEAD LH)	SERVICEABLE	816.00	-
1	BONNET (PANEL A-HOOD)	BUCKLED	1,250.00	1,250.00
1	BONNET MOULDING	DENTED	257.00	257.00
1	CENTRE "CHEVROLET" LOGO BADGE	NECESSARY	144.30	144.30
1	RADIATOR ASSEMBLY	SERVICEABLE	618.00	-
1	RADIATOR GRILLE	CRACKED	367.00	367.00
1	RADIATOR GRILLE TOP COVER	SERVICEABLE	45.02	-
1	FAN BLADE (SMALL)	CRACKED	536.00	536.00
1	FAN BLADE (BIG)	SERVICEABLE	634.00	-
1	AIRCON CONDENSER	SERVICEABLE	600.00	-
1	AIR INTERCOOLER	SERVICEABLE	652.00	-
1	FRONT FENDER RH	TO REPAIR SEE LABOUR	837.60	-
1	FRONT FENDER LH	TO REPAIR SEE LABOUR	837.60	-
1	REAR BUMPER	BENT	1,202.00	1,202.00
1	REAR BUMPER BEAM	BENT	239.94	239.94
1	REAR BUMPER CENTRE ABSORBER	CRACKED	260.00	260.00
1	REAR BUMPER SIDE RETAINER RH	CRACKED	68.76	68.76
1	REAR BUMPER SIDE RETAINER LH	CRACKED	68.76	68.76
1	REAR BUMPER REFLECTORS RH	BROKEN	119.74	119.74
1	REAR BUMPER REFLECTORS LH	CRACKED	119.74	119.74
1	REAR BUMPER TOW HOOK COVER	SERVICEABLE	93.00	-

Report Ref No. CS/TP17023625/Krnb2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR LUGGAGE FLOOR PANEL	BENT / BUCKLED	973.00	973.00
1	REAR LUGGAGE FLOOR PANEL INSULATOR	NECESSARY	63.50	63.50
1	REAR LUGGAGE FLOOR PANEL TRIM BOARD	SERVICEABLE	378.00	-
1	REAR END PANEL OUTER	BENT	623.76	623.76
1	REAR END PANEL INNER TRIM	BUCKLED	263.84	263.84
1	BOOTLID	BUCKLED	973.00	973.00
1	BOOTLID INNER TRIM BOARD	SERVICEABLE	400.00	-
1	BOOTLID WEATHERSTRIP	CUT	344.28	344.28
1	BOOTLID LOCK-TOP	DENTED	466.56	466.56
1	BOOTLID "CHEVROLET" BADGE	NECESSARY	120.62	120.62
1	BOOTLID LOGO	NECESSARY	138.84	138.84
1	BOOTLID "EPICA LT" BADGE	NECESSARY	119.84	119.84
1	BOOTLID REFLECTOR CENTRE	SERVICEABLE	217.97	-
1	BOOTLID REFLECTOR RH	SERVICEABLE	128.40	-
1	BOOTLID REFLECTOR LH	SERVICEABLE	128.40	-
1	REAR GAS T/GATE SPRING RH	SERVICEABLE	286.90	-
1	REAR GAS T/GATE SPRING LH	SERVICEABLE	286.90	-
1	BOOTLID HINGE RH	TO REPAIR SEE LABOUR	120.00	-
1	BOOTLID HINGE LH	TO REPAIR SEE LABOUR	120.00	-
1	REAR TAIL LAMP RH	MTG CRACKED	479.30	479.30
1	REAR TAIL LAMP PANEL RH	TO REPAIR SEE LABOUR	359.00	-
1	REAR TAIL LAMP LH	MTG CRACKED	479.30	479.30
1	REAR TAIL LAMP PANEL LH	TO REPAIR SEE LABOUR	359.00	-
1	REAR EXHAUST BOX (MUFFLER A-EXH,RR)	TO REPAIR SEE LABOUR	1,110.00	-
	LESS 10% DISCOUNT		-2,296.44	-1,245.94
			20,667.92	11,213.46
	SPECIAL NETT ITEMS			
1	SET FRONT BUMPER FASTENER CLIP (SN)	NECESSARY	24.00	24.00
1	SET RADIATOR GRILLE TOP COVER CLIP (SN)	NOT NECESSARY	10.00	-
1	CANS RADIATOR COOLANT (SN)	NECESSARY	60.00	20.00
1	SET RADIATOR GRILLE CLIP (SN)	NECESSARY	35.00	35.00
1	SET BONNET UNDER WEATHERSTRIP SEAL CLIPS (SN)	NOT NECESSARY	30.00	-

Report Ref No. CS/TP17023625/Krbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET BONNET INSULATOR CLIP (SN)	NOT NECESSARY	30.00	-
2	BONNET STOPPER (SN)	SERVICEABLE	15.00	-
2	SET FRONT FENDER LINER CLIP (SN)	NOT NECESSARY	60.00	-
1	SET FRONT LICENCE PLATE WITH HOLDER (SN)	CRACKED	80.00	45.00
1	SET REAR BUMPER PARKING SENSOR (SN)	DENTED / SHORTED	300.00	300.00
1	SET REAR BUMPER FASTENER CLIP (SN)	NECESSARY	30.00	30.00
1	REAR BOOT STICKER "TRANS-CAB" (SN)	NECESSARY	30.00	30.00
1	REAR BOOT STICKER "6555-3333" (SN)	NECESSARY	30.00	30.00
1	SET BOOTLID INNER TRIM BOARD CLIP (SN)	NOT NECESSARY	40.00	-
1	REAR EXHAUST MOUNTING (SN)	SERVICEABLE	10.00	-
1	SET REAR BUMPER END DUST COVER CLIP (SN)	NOT NECESSARY	30.00	-
1	SET REAR FENDER INNER TRIM CLIP RH (SN)	NOT NECESSARY	30.00	-
1	SET REAR FENDER INNER TRIM CLIP LH (SN)	NOT NECESSARY	30.00	-
1	SET REAR FENDER INNER COWLING LH CLIP (SN)	NOT NECESSARY	30.00	-
1	SET REAR FENDER INNER COWLING RH CLIP (SN)	NECESSARY	30.00	30.00
2	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	100.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
			1,134.00	544.00
	LABOUR			
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF FRONT BUMPER LOWER STIFFENER,FRONT FENDER RH,FRONT FENDER LH,BOOTLID HINGE RH,BOOTLID HINGE LH,REAR TAIL LAMP PANEL RH,REAR TAIL LAMP PANEL LH AND REAR EXHAUST BOX (MUFFLER A-EXH,RR).		5,400.00	2,200.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	40.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	150.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		5,350.00	1,800.00
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00
	TO TRANSFER OF BOOTLID FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		170.00	60.00
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.		170.00	60.00
	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING.		380.00	80.00
	TO TRANSFER OF END PANEL FITTINGS AND CONDUCT WATER SEEPAGE TEST.		170.00	80.00

Report Ref No. CS/TP17023625/Krnb2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DROP REAR EXHAUST BOX,RENEW THE SAME,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE. TOWING FEES.	REPEATED	170.00	-
			120.00	50.00
	TO DISMANTLE AND REFIT AIRCON ASSY AND ATTACHMENT,VACUUM AND CHARGE-IN-GAS. }		380.00	100.00
	TO VACUUM,REPLACE,REFIX AND RECHARGE AIR CONDENSER. }		380.00	-
	TO REPLAVE,REFIX AND TOP UP COOLANT FOR RADIATOR.		380.00	50.00
	TO VACUUM,REPLACE,REFIX AND RECHARGE AIR INTERCOOLER.		170.00	50.00
	TO REMOVE AND REFIT REAR W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR.	NOT NECESSARY	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.		220.00	60.00
			14,140.00	4,840.00
GRAND TOTAL			35,941.92	16,597.46
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				13,000.00

Report Ref No. CS/TP17023625/Krbn2

KSC
KONG SENG CHEONG
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.