

22/03/2002

ASS. REC. BY:

REF: CS/MSG17023629/ Utbnz Special Instruction:

SUPERVISOR:

MARCUS

ASSIGNMENT (Office)

From (Person):

Irene Tan

of

MSIG

Date/Time: 13/12/17 @ 9.40am

Estimated Cost:

Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLR83004

Insured:

YN9532C

at Workshop m/s

Pegasus Engineering

Tel:

68581846

of

51 Defu Lane 10, 539216

Policy No:

29032674MKG

Claim No:

538428

Sum Insured:

Excess:

Make of Veh:

D.O.A.

23/11/2017

(Client's Record)

CA / REV / REP. / REV 24 HRS

up

08012018 @ after 100m

H.O.D. Endorsement:

Date/Time:

9.45am @ 13/12/17

Person Contacted:

Alvin

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLR83004 - X

YN9532C - X

Mar 05

MSIG

Form Date 08/01/2018

Estimated Cost

OD TP VS TP RES CO RES EVA INV MV

To inspect Vehicle No SLR83004

at Work/home Pagasus

51 Dofu Lane 10

Insured

Policy No

Claims No

Sum Insured

Excess

Client's Record

After 10 am

Make of Vehicle

Policy Condition

Remark: The veh had commenced its repair at the time of inspection.



Est. of Market Value

CA Accident Report

Consistent? Yes or No

CA PR Seen

Consistent? Yes or No

Est. Repair

4

days

Res:

Yes or No

Sum Surp

20

%

3 Val:

Yes or No

CA / REV

REP. / 24 HRS

up

Vehicle IN / OUT

Date

Person Contacted

SLR83004

P 17

Truck Trans CA /

Honda Civic Hybrid 1496

3 owner

36057

Eng No

CND

Ru31228689

Gen Cond Good / Fair / Poor / Burnt

Steering In order / Jammed / Leaked / Burnt

Brake In order / Jammed / Leaked / Burnt

Mod Nil / STD A / Rim of

Tyre Size

R

2.5 / 60 R16

BS / ZON / EXNOVA / GY / FS / LIZA / MIC / CHTSU / PIR / SUMI

TOYO / YOKO or

Front

R Bat

8

mm

Rear

R Bat

8

mm

LBat

8

mm

LBat

8

mm

DCA

23/1/17

DCA

8/1/18

Surveyed at

Des of Damages: Frt / Rear / OS / NS / U/C / Roof top of

Rear

The U/C / Chassis frame / Body Structure affected due to collision

8/1/18 confirmed L/S @ 2900 with willian. (Red: 6006.32.1678)

RECEIVED 15 JAN 2010

Use The File Photo?



Prell. Report

1511 Typist



Final Report

Use The File Photo?

Days Of Repair

4

Resurvey No. of Trip

Add Fee



Stained



High



Deep



As is

Survey Fee

Transport

Labour

Other

Total

200

10

210

Report Format

0

TP.

2900



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG17023629/Ut6

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 13-12-2017



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YN 9532C	Veh. Inspected	SLR 8300U
Policy No.	29032674MKC	Coverage (\$)	0.00
Claim No.	538428	Excess (\$)	0.00
Assign From	MERIMEN (IRENE TAN)	Assign Date	13/12/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	23/11/2017	Inspection Date
Survey held at	51 DEFU LANE 10	
Repairer	PEGASUS ENGINEERING & TRADING PTE LTD	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Nov 2017		13 Dec 2017 09:40 Assign				New Assignment Cancel Case

[Main](#)[Reference](#)[Claim Details](#)[Documents](#)[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	AUTOWAY LOGISTIC PTE LTD, Co. Reg. No.: 200614599H		
Main Claimant:	GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G		
Vehicle Reg. No.:	SLR8300U	Date of Loss:	23/11/2017 15:00 - :59
Claim Type:	TP / 538428	Policy/Cover Note No.:	29032674MKC (Comprehensive) Coverage: 14/10/2017 - 13/10/2018
Vehicle Reg. No. (Insured):	YN9532C	Policy No. (Claimant):	
		Excess:	S\$800.00
Repairer:	Pegasus Engineering & Trading Pte Ltd (HQ) 51 DEFU LANE 10, 539216 Defu Lane - Tel: 68581846		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 14/12/2017]		
Driver/Custodian (Insured):	MUHAMMAD SOFWAT BIN MOHD SHAHIR (/ Male), NRIC: S8603529D		
Adj Asg. Remarks:	Please assign to Surveyor Marcus		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/11/2017 19:19
Date Of Accident	23/11/2017 16:00
Exact Location Of Accident	JUNCT OF CHANGI SOUTH AVE 2 AND CHANGI SOUTH AVE 3
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLR8300U
Insured/Policyholder	
Name Of Registered Owner	GRAB RENTALS PTE LTD
Co Reg No	201617200G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-98235008

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL-1.5 HYBRID X (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	GREAT AMERICAN INSURANCE COMPANY
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	
Cover Note Number	MTGRAB20172192

Driver

Name of Driver	NG AIK KOON
NRIC No	S1241774H
Date Of Birth	03/05/1957
Occupation	OUTDOOR
Date Of Driving Pass	29/07/1977
Driving Experience	40 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-88136722
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLOCK 707 YISHUN AVENUE 5 #12-36
Postcode	760707
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

On 23.11.2017 at about 1600 hours, I was driving my vehicle (A: SLR8300U) and I was travelling at the right lane along Changi South Avenue 2 towards the traffic junction of Changi South Avenue 3. When the vehicle in front came to a halt due to "red" light, I followed suit. While stationary, out of sudden I felt an impact from the rear of my vehicle and realized that a Lorry (B: YN9532C) had hit onto the rear portion of my vehicle. Vehicle A: No passenger onboard Lorry B: No passenger onboard.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YN9532C
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	MUHAMMAD SOFWAT BIN MOHAMAD SHAHIR
NRIC/Passport Number	
Contact Number	94601706
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 24.11.2017 @ 1055 hrs

Reporting Centre Personnel's Signature
Name: *aymen*
NRIC/FIN No.: *G2869646X*

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to GIA Report

DECLARATION

DECLARATION
I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)

Date & Time: 24-11-2017 @ 10:55 hrs

Reporting Centre Personnel's Signature
Name: caumen

NRIC/FIN No.:

G28596X6X

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Company
Owner ID	7200G

Vehicle Details

Vehicle No.	SLR8300U
Vehicle to be Exported	Yes
Intended De-registration Date	24 Nov 2017
Vehicle Make	HONDA
Vehicle Model	VEZEL HYBRID 1.5X AUTO
Primary Colour	Brown
Manufacturing Year	2016
Engine No.	LEB5928702
Chassis No.	RU31228689
Maximum Power Output	112.0 kW (150 bhp)
Open Market Value	\$27,019.00
Original Registration Date	29 Aug 2017
First Registration Date	29 Aug 2017
Transfer Count	0
Actual ARF Paid	\$5,000.00

Intended PARF Rebate Details

PARF Eligibility	Yes
PARF Eligibility Expiry Date	28 Aug 2027
PARF Rebate Amount	\$3,750.00

Intended COE Rebate Details

COE Expiry Date	28 Aug 2027
COE Category	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years)	10
QP Paid	\$50,001.00
COE Rebate Amount	\$40,000.00
Total Rebate Amount	\$43,750.00

The information contained herein is correct as at 24 Nov 2017

OK

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :
PEGASUS ENGINEERING & TRADING PTE LTD
C/O 51 DEFU LANE 10
SINGAPORE 539216
Officer in Charge : ALVIN LOW WAI LUN
Tel :
Email :

Customer :
GRAB RENTALS PTE LTD
18 SIN MING LANE
#01-08 MIDVIEW CITY
SINGAPORE 573960
Attn :
Tel :
Fax :
Not Admit
2/5 \$29.00
42
the 2nd Attorney
LKH
maras
1100
8/1/18
conforms on 8/1/18

Quotation No : QO17/11-1142	Quotation Date : 24/11/2017	Terms : 30 DAYS
Vehicle No : SLR8300U	Chassis No : RU31228689	Third Party Insurer :
Model : VEZEL		Date of Accident :
marks : TP INSURER: MSIG, INSURED'S VEHICLE NO: YN9532C, DATE OF ACCIDENT: 23.11.2017		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
1	TAILGATE LID <i>body</i>	1	953.3000	953.30
2	TAILGATE LID VEZEL BADGE <i>rec</i>	1	56.3000	56.30
3	TAILGATE LID HYBRID BADGE <i>rec</i>	1	66.2000	66.20
4	TAILGATE LID REFLECTOR LIGHT <i>11</i>	2	239.6000	479.20
5	TAILGATE LID INNER TRIMBOARD <i>11</i>	1	185.0000	185.00
6	TAILGATE LID INNER TRIMBOARD CLIPS <i>11</i>	6	3.9000	23.40
7	TAILGATE LID RUBBER STOPPER <i>11</i>	2	12.0000	24.00
8	TAILGATE LID LOCK TOP <i>7m</i>	1	180.0000	180.00
9	TAILGATE LID LOCK STRIKER BOTTOM <i>11</i>	1	27.5000	27.50
10	TAILGATE LID WEATHERSTRIP <i>7m</i>	1	135.0000	135.00
11	REAR LICENCE PLATE LAMP <i>11</i>	2	38.5000	77.00
12	REAR WINDSHIELD GLASS SIDE WEATHERSTRIP SEAL <i>rec</i>	2	68.0000	136.00
13	REAR BUMPER CENTER <i>10/20</i>	1	767.7000	767.70
14	REAR BUMPER SIDE <i>11</i>	2	95.0000	190.00
15	REAR BUMPER SIDE RETAINER <i>11</i>	2	22.0000	44.00
16	REAR BUMPER CLIPS <i>rec</i>	10	3.9000	39.00
17	REAR BUMPER REFLECTOR <i>11</i>	2	141.0000	282.00
18	REAR BUMPER SCREW SPACER <i>11</i>	2	12.0000	24.00
19	REAR END PANEL <i>11</i>	1	514.0000	514.00
20	REAR END PANEL INNER TRIM <i>11</i>	1	92.3000	92.30
21	REAR LUGGAGE FLOOR PANEL COMPARTMENT TOOL BOX <i>11</i>	1	130.0000	130.00
22	REAR FENDER WHEEL ARC GARNISH <i>11</i>	2	95.0000	190.00
23	REAR FENDER INNER LINER/COWLING <i>11</i>	2	90.4000	180.80

C/F 0.00

2333.5
1866.80

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD C/O 51 DEFU LANE 10 SINGAPORE 539216 Officer in Charge : ALVIN LOW WAI LUN Tel : Email :

Customer : GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax :

Quotation No : QO17/11-1142	Quotation Date : 24/11/2017	Terms : 30 DAYS
Vehicle No : SLR8300U	Chassis No : RU31228689	Third Party Insurer :
Model : VEZEL	Date of Accident :	
marks : TP INSURER: MSIG, INSURED'S VEHICLE NO: YN9532C, DATE OF ACCIDENT: 23.11.2017		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)	
					B/F 0.00
24	REAR LAMP 11	2	542.0000	1,084.00	X
25	REAR LAMP CLIP HOLDER 11	4	4.5000	18.00	q
26	REAR BUMPER LOWER COVER/DIFFUSER 11	1	180.0000	180.00	q
27	REAR EXHAUST BOX 11	1	517.7000	517.70	q
28	REAR EXHAUST BOX CHROME CUTTER 11	1	136.0000	136.00	q
29	REAR EXHAUST MOUNT 11	2	16.5000	33.00	X
30	REAR EXHAUST HEAT SHEILD 11	1	55.0000	55.00	X
31	LESS 20% ITEM (1-30)	1	-1,364.0800	-1,364.08	
32	REAR WINDSHEILD GLASS SEALANT nu	1	180.0000	180.00	40
33	REAR WINDSHEILD GLASS SPONGE SEAL nu	1	100.0000	100.00	30
34	REAR BUMPER PARKING SENSOR sw/rd	1 set	450.0000	450.00	200
35	SUNDRIES AND CLIPS 11	1	150.0000	150.00	X
36	TO REINSTALL OF REAR BUMPER PARKING SENSOR.	1	150.0000	150.00	50
37	TO CHECK ELECTRICAL LIGHTING CONCERNED.	1	60.0000	60.00	30
38	TO TRANSFER OF TAILGATE FITTINGS, FIXTURE AND PERFORM WATERSEEPAGE TEST.	1	150.0000	150.00	60
39	TO REMOVE AND REFIT REAR WINDSCREEN GLASS.	1	180.0000	180.00	120
40	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR.	1	160.0000	160.00	80
41	TO RUST-PROOFING OF THE AFFECTED AREAS.	1	120.0000	120.00	30
42	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	1	900.0000	900.00	520

C/F 0.00

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :

PEGASUS ENGINEERING & TRADING PTE LTD
C/O 51 DEFU LANE 10
SINGAPORE 539216

Officer in Charge : ALVIN LOW WAI LUN
Tel :
Email :

Customer :

GRAB RENTALS PTE LTD
18 SIN MING LANE
#01-08 MIDVIEW CITY
SINGAPORE 573960

Attn :
Tel :
Fax :

Quotation No : QO17/11-1142	Quotation Date : 24/11/2017	Terms : 30 DAYS
Vehicle No : SLR8300U	Chassis No : RU31228689	Third Party Insurer :
Model : VEZEL		Date of Accident :
Remarks : TP INSURER: MSIG, INSURED'S VEHICLE NO: YN9532C, DATE OF ACCIDENT: 23.11.2017		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
				B/F 0.00
43	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	1	850.0000	600 850.00

3626-8

- KKK Auto Consultants hence notify the Repairer of the following:
- Resurvey before/after spray painting
 - To spray damaged part(s) during resurvey
 - Price is subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal application(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sub Total	8,906.32
GST(7.00%)	623.44
Total (SGD)	9,529.76

Please conduct the survey at
Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17023629/UTBN2

Date: 16/01/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 29032674MKC
 Claimant Vehicle No: SLR8300U Insured Vehicle No: YN9532C
 Date of Loss: 23/11/2017 Nature of Claim: TP Claim No: 538428

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLR8300U Engine No: LEB5928702
 Make & Model: HONDA VEZEL, 1.5 HYBRID X (A) Chassis No: RU31228689
 Reg. Date: 29/08/2017 (Man. Year: 2016) Odometer: 36051 km
 Colour: Brown
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/60R16 Rear Tyre Size: 215/60R16
 Front Left Side: Dunlop 8 mm Rear Left Side: Dunlop 8 mm
 Front Right Side: Dunlop 8 mm Rear Right Side: Dunlop 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	6,336.32	2,136.80	4,199.52	66.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,570.00	1,490.00	1,080.00	42.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,906.32	3,626.80	5,279.52	59.28
Approved Total (Overridden) (S\$)		2,900.00		
(S\$)	8,906.32	2,900.00	6,006.32	67.44
+ GST 7.00/7.00% (S\$)	623.44	203.00	420.44	67.44
Nett Amount (S\$)	9,529.76	3,103.00	6,426.76	67.44

INSPECTION

Date of Assignment: 13/12/2017

Date Inspected: 08/01/2018 Inspected At:

Pegasus Engineering & Trading Pte Ltd
 (HQ)
 51 DEFU LANE 10
 Singapore 539216

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Jan 2018)
Parts:	M1-SUV	HONDA VEZEL 1.5 HYBRID X (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLR8300U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE LID	Badly Dented	953.30 FL	*953.30 FL
2	1		*TAILGATE LID VEZEL BADGE	Necessary	56.30 FL	*56.30 FL
3	1		*TAILGATE LID HYBRID BADGE	Necessary	66.20 FL	*66.20 FL
4	2		*TAILGATE LID REFLECTOR LIGHT	Not Necessary	479.20 FL	*- FL
5	1		*TAILGATE LID INNER TRIMBOARD	Not Necessary	185.00 FL	*- FL
6	6		*TAILGATE LID INNER TRIMBOARD CLIPS	Not Necessary	23.40 FL	*- FL
7	2		*TAILGATE LID RUBBER STOPPER	Not Necessary	24.00 FL	*- FL
8	1		*TAILGATE LID LOCK TOP	Twisted	180.00 FL	*180.00 FL
9	1		*TAILGATE LID LOCK STRIKER BOTTOM	Not Necessary	27.50 FL	*- FL
10	1		*TAILGATE LID WEATHERSTRIP	Twisted	135.00 FL	*135.00 FL
11	2		*REAR LICENCE PLATE LAMP	Not Necessary	77.00 FL	*- FL
12	2		*REAR WINDSHIELD GLASS SIDE WEATHERSTRIP SEAL	Necessary	136.00 FL	*136.00 FL
13	1		*REAR BUMPER CENTER	Dented/Deformed	767.70 FL	*767.70 FL
14	2		*REAR BUMPER SIDE	Not Necessary	190.00 FL	*- FL
15	2		*REAR BUMPER SIDE RETAINER	Not Necessary	44.00 FL	*- FL
16	10		*REAR BUMPER CLIPS	Necessary	39.00 FL	*39.00 FL
17	2		*REAR BUMPER REFLECTOR	Not Necessary	282.00 FL	*- FL
18	2		*REAR BUMPER SCREW SPACER	Not Necessary	24.00 FL	*- FL
19	1		*REAR END PANEL	Repair	514.00 FL	*- FL
20	1		*REAR END PANEL INNER TRIM	Not Necessary	92.30 FL	*- FL
21	1		*REAR LUGGAGE FLOOR PANEL COMPARTMENT TOOL BOX	Not Necessary	130.00 FL	*- FL
22	2		*REAR FENDER WHEEL ARC GARNISH	Not Necessary	190.00 FL	*- FL
23	2		*REAR FENDER INNER LINER/COWLING	Not Necessary	180.80 FL	*- FL
24	2		*REAR LAMP	Not Necessary	1,084.00 FL	*- FL
25	4		*REAR LAMP CLIP HOLDER	Not Necessary	18.00 FL	*- FL
26	1		*REAR BUMPER LOWER COVER/DIFFUSER	Not Necessary	180.00 FL	*- FL
27	1		*REAR EXHAUST BOX	Not Necessary	517.70 FL	*- FL
28	1		*REAR EXHAUST BOX CHROME CUTTER	Not Necessary	136.00 FL	*- FL
29	2		*REAR EXHAUST MOUNT	Not Necessary	33.00 FL	*- FL
30	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	55.00 FL	*- FL
31	1		*REAR WINDSHIELD GLASS SEALANT	Necessary	180.00 FS	*40.00 FS
32	1		*REAR WINDSHIELD GLASS SPONGE SEAL	Necessary	100.00 FS	*30.00 FS
33	1		*SET REAR BUMPER PARKING SENSOR	Shorted	450.00 FS	*200.00 FS
34	1		*SUNDRIES AND CLIPS	Not Necessary	150.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc

Sub Total (S\$) **7,700.40** **2,603.50**
 - List Item Discount on L Items 20.00/20.00% (S\$) **1,364.08** **466.70**

Total Parts (S\$) **6,336.32** **2,136.80**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REINSTALL OF REAR BUMPER PARKING SENSOR	New	150.00	50.00
2	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	60.00	30.00
3	TO TRANSFER OF TAILGATE FITTINGS, FIXTURE AND PERFORM WATERSEEPAGE TEST	New	150.00	60.00
4	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	180.00	120.00
5	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR	New	160.00	80.00
6	TO RUST-PROOFING OF THE AFFECTED AREAS	New	120.00	30.00
7	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	New	900.00	520.00
8	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	850.00	600.00
Gross Labour Cost (S\$)			2,570.00	1,490.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >