

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AXA Insurance Pte Ltd  
8 Shenton Way #24-01  
AXA Tower  
Singapore 068811

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Jas Tan

Date: 15 Dec 2017

## **Preliminary Advice**

Vehicle No	: SCN898S	Accident Date	: 08/12/2017
Make	: PORSCHE BOXSTER	Policy No.	: P1482100
Assignment Date	: 13/12/2017	Excess	: S\$7,500.00
Date of Inspection	: 13/12/2017	Est. Duration of Repair	: 6.00
Inspection At	: STUTTGART AUTO PTE LTD (HQ) 12 SUNGEI KADUT AVE SINGAPORE 729648		

### **Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear o/s portion and o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,812.48
Revised Amount	:S\$	8,676.24
Check Items (Estimated)	:S\$	1,606.24
Total	:S\$	10,282.48

Lump Sum Repair :S\$

### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	213,000.00
COE / PARF Rebate	:S\$	123,837.00
Salvage Value	:S\$	
Margin for Repair	:S\$	89,163.00

### **Remarks**

( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.

( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

( X ) Other comments : SURVEY DATE AND TIME: 13/12/2017 AT 2PM

WE HAVE AUTHORISE REPAIR.