



Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

General Details

Involving
1 2008 HONDA STREAM 1.8 (SFH5100Z)

Date of Loss
December 10, 2017

Time of Loss
11.00

Loss Description
INSD (SFH5100Z) REVERSED AND HIT ON TO THE PILLAR

Comment

Workshop Details

Total Rebate Amount

12680

Nett Loss Amount

\$9,320.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (OD)

Target Date of Completion *

02/19/2018

Days of work completion *

53

⏪

Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Vehicle & Driver Details

Vehicle Registration#

SFH5100Z

Registration State

SINGAPORE

Mileage

157813

Purchase Date

mm/dd/yyyy

📅

Registration Date *

04/09/2009

📅

Age of Vehicle

8

CATEGORY	Manufacturing Year
POLICY INFORMATION	2008
ASSESSMENT INFORMATION	2008
CATEGORY	Make
POLICY INFORMATION	HONDA

CATEGORY	Model
POLICY INFORMATION	STREAM 1.8
ASSESSMENT INFORMATION	STREAM 1.8X A
CATEGORY	Type
POLICY INFORMATION	
ASSESSMENT INFORMATION	
CATEGORY	Type of Paint
POLICY INFORMATION	
ASSESSMENT INFORMATION	
CATEGORY	Chassis No
POLICY INFORMATION	RN61093610
ASSESSMENT INFORMATION	RN61093610
CATEGORY	Engine No
POLICY INFORMATION	R18A1803772
ASSESSMENT INFORMATION	R18A1803772
CATEGORY	Engine Capacity
POLICY INFORMATION	
ASSESSMENT INFORMATION	1799



Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Detailed Assessment

Inspection Date *

12/13/2017

Total Loss

Yes No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

500

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Condition of Vehicle at time of survey

General condition

Good ▾

Footbrake (Serviceable)

Yes No

Handbrake (Serviceable)

Yes No

Engine Modification

Yes No

Pre-accident condition

Good ▼

Tyre Condition

Age of Tyres

Front Tyre Size

205/55R16

Front left side

YOKOHAMA5mm

Front right side

YOKOHAMA5mm

Spare wheel

Rear Tyre Size

205/55R16

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny



1

1

REAR WINDSCREEN

Damaged

0

0

Reviewing



[]



2

1

REAR WINDSCREEN MOULDING

Necessary

0

0

Reviewing



3

1

REAR GATE

Damaged

0

0

Reviewing



4

1

REAR GATE LOGO

Serviceable

0

0

0

0

0

Deny





5

1

REAR GATE EMBLEM 'STREAM'

Necessary

0

0

Reviewing



6

1

REAR GATE THIRD BRAKE LIGHT

Damaged

0

0

Reviewing



7

1

REAR GATE INNER TRIM BOARD

Serviceable

0

0

0

0

0

Deny



8

1

FRT BUMPER

Repair

0

0

0

0

0

Deny



9

1

FRT BUMPER SIDE RETAINER LH

Bent

0

0

Reviewing



10

10

FRT BUMPER CLIP

Necessary

0

0

Reviewing



Labour

Add	Approve	Deny
-----	---------	------



1

WIRE CHECKING

20

0

0

Reviewing



2

REMOVE & REFIX REAR WINDSCREEN

120

0

0

Reviewing



3

TRANSFER REAR GATE COMPONENT FROM OLD TO NEW

50

0

0

Reviewing



4

LABOUR CHARGE

300

0

0

Reviewing



5

SPRAY PAINTING

350

0

0

Reviewing



Assessment Details

General & Workshop Details		Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio
Parts & Labour	Miscellaneous	Summary	Add	Approve Deny
		1		
		REAR WINDSCREEN GUM		
		Reviewing		
		40		
		NECESSARY		
		2		
		REAR THIRD BRAKE LIGHT COVER RH		
		Reviewing		
		0		
		(BROKEN) SUPPLEMENTARY ADDED 28/12/2017		

3

PARTS SUPPLIED BY AXAS
SUPPLIER \$1377.00

Reviewing



4

DAYS OF REPAIR : 3 DAYS

Approve





Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Claim Amount	
\$380.00	
CATEGORY	Labour
ESTIMATE	\$840.00
REVISED AMOUNT	\$840.00
CATEGORY	Miscellaneous
ESTIMATE	\$40.00
REVISED AMOUNT	\$40.00
CATEGORY	Excess
ESTIMATE	-\$500.00
REVISED AMOUNT	-\$500.00
Submit for Review	

