

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHF515E -**AAD1712-096***Not Noted*
11 Sep 8 2600h

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHF515E - JHOW

VF1ABL15AUC278253

RENAULT

LATITUDE

11.12.2017

AIG

PART			LIST	
1	1	BUMPER COVER FRT	\$	<i>Bu Inc</i> 1,259.42 ✓
2	1	BUMPER ABSORBER FRT	\$	<i>Sn</i> 394.68
3	1	BUMPER BEAM FRT	\$	<i>R</i> 914.08
4	1	BUMPER SPOILER FRT	\$	<i>Sn</i> 181.75
5	1	BUMPER GRILLE LOWER FRT	\$	<i>Sn</i> 266.80
6	1	BUMPER FOG LAMP GRILLE LH	\$	<i>Sn</i> 207.22
7	1	BUMPER RETAINER FRT LH	\$	<i>Sn</i> 151.41
8	1	BUMPER BRACKET FRT LH	\$	<i>R</i> 181.75
9	1	HEADLAMP LH	\$	<i>Sn</i> 1,184.43
10	1	HEADLAMP PANEL FRT LH	\$	<i>R</i> 152.15
11	1	FENDER PANEL FRT LH	\$	<i>R</i> 783.83 ✓
12	1	FENDER INSULATOR LH	\$	<i>Sn</i> 130.84
13	1	FENDER BRACKET FRT LH	\$	<i>Sn</i> 34.14
14	1	WHEELARCH FRT LH	\$	<i>Sn</i> 278.84
15	1	WIPER RESERVOIR	\$	<i>Sn</i> 348.25
16	1	WIPER RESERVOIR NECK	\$	<i>Sn</i> 136.11
17	1	WIPER RESERVOIR MOTOR	\$	<i>Sn</i> 270.06
18	1	RADAITOR GRILLE	\$	<i>Sn</i> 1,707.78
19	1	RADAITOR GRILLE BADGE 'RENAULT'	\$	<i>Sn</i> 173.36
20	1	RADAITOR GRILLE FRAME	\$	<i>Sn</i> 1,353.75
21	1	FRAME FULL SUPPORT PANEL	\$	<i>R</i> 615.90
22	1	FRAME FULL SUPPORT BRACKET	\$	<i>R</i> 89.79
23	1	BONNET	\$	<i>R</i> 1,941.63
24	1	BONNET HINGE LH	\$	<i>R</i> 348.31
25	1	BONNET STRUT LH	\$	<i>Sn</i> 88.61
26	1	DOOR PANEL FRT LH	\$	<i>R</i> 2,844.66
27	1	DOOR HINGE UPPER LH	\$	<i>R</i> 274.50
28	1	DOOR HINGE LOWER LH	\$	<i>R</i> 300.55
29	1	DOOR CHECK FRT LH	\$	<i>Sn</i> 194.77
30	1	DOOR MOULDING FRT LH	\$	<i>Sn</i> 176.82
31	1	DOOR MIRROR LH	\$	<i>Sn</i> 1,483.40
32	1	DOOR MIRROR GLASS LH	\$	<i>Sn</i> 148.20
33	1	DOOR MIRROR BACK COVER LH	\$	<i>Sn</i> 218.46
34	1	DOOR WHETHERSTRIP FRT LH	\$	<i>Sn</i> 474.21

TRANS-CAB AUTO SERVICES PTE LTD**AAD1712-096**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHF515E -

35	1	DOOR SEAL FRT LH	\$	<i>SH</i> 68.67 <i>X</i>
36	1	ROCKER PANEL OUTER LH	\$	<i>SH</i> 987.49 <i>X</i>
37	1	DOOR PANEL REAR LH	\$	<i>SH</i> 2,844.66 <i>X</i>

TOTAL	\$	23,211.28
10%	\$	2,321.13
	\$	20,890.15

Specical Nett

1	1SET	WHEELARCH CLIP FRT LH	\$	<i>SH</i> 66.00 <i>X</i>
2	1SET	FRONT BUMPER CLIP	\$	<i>SH</i> 66.00 <i>—</i>
3	1	RIM LH FRT	\$	<i>SH</i> 385.00 <i>X</i>
4	1	TYRE LH FRT	\$	<i>SH</i> 330.00 <i>X</i>
5	1	DOOR STICKER "Trans-cab"	\$	<i>SH</i> 80.00 <i>60SH</i>
6	1	DOOR STICKER "Classic"	\$	<i>SH</i> 30.00 <i>15SH</i>
7	1	DOOR STICKER "6555-3333"	\$	<i>SH</i> 80.00 <i>X</i>

TOTAL	\$	1,037.00
TOTAL PARTS	\$	21,927.15

To Check Electrical Lighting Concerned.	\$	170.00 <i>15/</i>
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,200.00 <i>500/</i>
Towing fees	\$	<i>SH</i> 120.00 <i>X</i>
Putty and spray painting of the affected portion.	\$	4,500.00 <i>660/</i>
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	<i>SH</i> 170.00 <i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>SH</i> 170.00 <i>X</i>
To check steering geometry and computer wheel alignment	\$	220.00 <i>60/</i>
To Remove And Refit Front W/Screen Glass To Facilitate Bodywork Repair.	\$	<i>SH</i> 170.00 <i>X</i>
To rust-proofing of the affected areas.	\$	170.00 <i>30/</i>

TRANS-CAB AUTO SERVICES PTE LTD

AAD1712-096

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHF515E -

To transfer of door fittings, attachment and
perform water seepage test.

\$

170.00 X

TOTAL	\$	10,060.00
Over All Total	\$	31,987.15

(PARTS BY PARTS) Repair Days~~15 Days~~*3 days*