## COMFORTDELGRO ENGINEERING PTE LTD **REPAIR ESTIMATE\***

ALG

VEHICLE NO: SHD 7076U

DATE 11/12/2017 12:56

MAKE :

MODEL : HYUNDAI i40

DOA: 10.12.17

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper			\$ 603.60
	Rear Bumper Reinforcement ?			\$ 504.35
	Rear Bumper Reinforcement Bracket (LH/RH) <sup>2</sup>		\$ 180.00	\$ 360.00
	Rear Bumper Side Bracket ?			\$ 49.00
	Rear Bumper Clips /			\$ 22.00
	Rear Bumper Sponge 2			\$ 143.40
	Rear Bumper Under Cover 🗶			\$ 225.00
	SUB TOTAL			\$ 1,907.35
	LESS 20%			\$ 381.47
	DISCOUNTED TOTAL			\$ 1,525.88
	Labour Charge			200
	Panel Beating			\$ 380.00
	Spray Painting Charge			\$ 200.00
	Spray Fainting Charge			180
	TOTAL LABOUR			\$ 580.00
	TOTAL LABOUR			\$ 560.00
	ESTIMATE TOTAL			\$ 2,105.88
	Kalur (Clay			
	12/12/07 1000h. 2 Py, PIP Before Paid pht			
	2 // 41			
	910			
	al Post of	LKK Aut	Communication of the Communica	ify
	Before rain fr	the Rep	are ii	1 1
		• To resur	ing .	
			ay tambo ing 10 galan ay desigas lieling ta	Ney
Larry N9			rivisurana sich af William	eig
Ferry		* Sec. 20.	1 m. 2 m. 10 m	
		• Laptie estable	refers the semillar control final accretional from unart	eyertan Negarinaan
			H by Repairer	
			т ру глерапет	
	This is an initial estimate based on a visual inspection of the	ne above v	ehicle. The final repair	quantum will