

REPAIR ESTIMATE*

VEHICLE NO : SH 6354Y

DATE 12/12/2017 10:27

MAKE :

DVA: 09.12.17

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Radiator Grille ✓			\$ 1,480.00
	Front Bumper Cover X repair			\$ 1,052.20
	Front Bumper Bracket (LH) X			\$ 24.60
	SUB TOTAL			\$ 2,556.80
	LESS 20%			\$ 511.36
	DISCOUNTED TOTAL			\$ 2,045.44
	Labour Charge			200
	Panel Beating			\$ 380.00
	Spray Painting Charge			\$ 200.00 180
	TOTAL LABOUR			\$ 580.00
	ESTIMATE TOTAL			\$ 2,625.44
<p>Kalme (OK)</p> <p>12/12/17 1120 hrs</p> <p>2 Pys</p> <p>P/P</p> <p>After Repair pls</p>				
<p>Larry Ng</p>				
<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before spray painting • To display damage to artist during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Surplus (warranty item(s)) must be resurveyed and is subject to final approval from Insurance company <p>Acknowledged by Repairer</p> <p>Signature</p> <p>Date</p>				
<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>				