

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

11-Dec-17

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6089 U

1 pc	Front bumper emblem	\$	44.00
1 pc	Bonnet grille	\$	386.00
2 pcs	n/s & o/s head lamp @\$1028.00	\$	2,056.00
		\$	2,486.00
	Less 10%	\$	248.60
		\$	1,243.00

S/NETT

1 set	Front bumper clips	\$	48.00
1 pc	Front no. plate	\$	50.00 35
	Sundry	\$	50.00 20
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the bonnet	\$	650.00 200
	To putty and spray painting on front bumper, bonnet, bonnet grille	\$	600.00 360
	To apply rustproofing on the repaired and replaced panels.	\$	120.00 X
		\$	2,761.00

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

K. L. (K. L.)

12/12/17 1320hrs

2 Pys

4s

After Repair photo