

CITY CAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 7154H

MAKE :

MODEL : HYUNDAI i40

DATE 9/12/2017 11:34

POA: 08.12.17

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Headlamp (RH) ✓			\$ 1,388.00
	Front Bumper x repair			\$ 1,388.00
	Front fender (RH) x repair			\$ 277.60
	SUB TOTAL			\$ 1,110.40
	LESS 20%			
	DISCOUNTED TOTAL			
	Labour Charge			200
	Panel Beating			\$ 300.00
	Spray Painting Charge			\$ 400.00
	Wiring Charge			\$ 50.00
	TOTAL LABOUR			\$ 750.00
	ESTIMATE TOTAL			\$ 1,860.40
	Kavin LKK 12/12/17 1430hrs 2 Days P/P After Repair photo.			
	LKK Auto Consultants hence notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature:			
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

Larry Ng