

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

12-Dec-17

## ESTIMATE RPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6637 M

		\$	
1 pc	Bootlid emblem — <i>ne</i>	\$	27.00 —
1 pc	Bootlid CRDi — <i>ne</i>	\$	29.00 —
1 pc	Boot lid lower garnish — <i>ne</i>	\$	290.00 —
1 pc	o/s taillamp panel @ \$218.00 — <i>Ref</i>	\$	218.00 —
1 pc	Rear o/s tail lamp @ \$421.00 — <i>ne</i>	\$	421.00 —
1 pc	Bootlid o/s reflector @ \$350.00 — <i>ne</i>	\$	350.00 —
1 pc	Rear bumper — <i>Ref</i>	\$	696.00 —
1 pc	Rear bumper lower cover — <i>ne</i>	\$	206.00 —
1 pc	Rear bumper o/s side bracket @ \$29.00 <i>X</i> <i>su</i>	\$	29.00 —
1 pc	Rear bumper inner sponge <i>X</i> <i>su</i>	\$	114.00 —
1 pc	Rear bumper reinforcement <i>X</i> <i>su</i>	\$	607.00 —
1 pc	Rear bumper stay o/s & n/s @ \$53.00 <i>n/s x su o/s X su</i>	\$	108.00 —
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00 <i>n/s x su o/s X su</i>	\$	36.00 —
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00 <i>n/s x su o/s X su</i>	\$	36.00 —
1 pc	Rear bumper o/s reflector @ \$46.00 — <i>ne</i>	\$	46.00 —
1 pc	Rear muffler assy — <i>Ref</i>	\$	1,009.00 —
1 pc	Rear exhaust pipe hanger <i>X</i> <i>su</i>	\$	49.00 —
<i>+ GUPP</i>		\$	4,271.00
Less 10%		\$	427.10
		\$	3,843.90

### S/NETT

1 set	Rear bumper clips — <i>ne</i>	\$	48.00 —
1 set	Bootlid lower garnish clips — <i>ne</i>	\$	60.00 —
1 set	Bootlid stickers — <i>ne</i>	\$	100.00 —
1 set	Reverse sensor — <i>should</i>	\$	280.00 — <i>200</i>
1 pc	Rear o/s fender sticker — <i>ne</i>	\$	60.00 —
<i>Bumper top protection mat — ne</i>		\$	50.00 —

*+ GUPP*

Towing Fee	\$ 50.00 /
Sundry	\$ <del>50.00</del> 20
To dismantle / replace exhaust pipe	\$ <del>120.00</del> 50
To dismantle / replace / test reverse sensor to new bumper and reset to the same	\$ <del>120.00</del> 20
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$ <del>180.00</del> 50
To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the rear o/s tail lamp panel. Including knock-out, straighten, repair, reshape and adjust of the end panel	\$ <del>1,400.00</del> 800
To putty and spray painting on bootlid, bootlid lower garnish, rear o/s fender, rear bumper, end panel, rear o/s taillamp panel,	\$ <del>1,200.00</del> 900
To apply rustproofing on the repaired and replaced panels.	\$ <del>250.00</del> 100
	<u>\$ 7,861.90</u>

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

**THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.**

Kahr 16164

12/12/17 162L

5 Days

P/P

Before Part photo.

12/1/18  
continued up \$ 6200 / 5 M.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey and repair the damaged parts
- To display damaged parts in a conspicuous place
- Parts prices on a "best price" basis
- Third party claims on a "best price" basis
- No repair cost unless approved by LKK Auto Consultants
- Supplier's terms and conditions are subject to LKK Auto Consultants approval

Acknowledged by Repairer  
Signature \_\_\_\_\_

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG:200707743D GST REG:200707743D

13-Dec-17

## SUPPLEMENTARY ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6337 M

1 pc	Bootlid		\$	1,119.00	
1 pc	Rear o/s fender		\$	1,205.00	
1 pc	Rear windscreen moulding		\$	87.00	
1pc	End panel		\$	250.00	
				\$	2,661.00
					\$2661.00
				Less 10%	\$
					266.10
				\$	2,394.90
					\$2394.90
<u>S/NETT</u>					
1 pc	sealant				
				S/NETT = \$50/-	\$
					50.00

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE  
ANY UNFORESEEN DAMAGES.





**Victory Recovery** (Business Reg No.: 53096358B)

65 Teban Gardens Rd #23-617, Singapore 600065.

Mobile: 9618 0311 Fax: 6267 8996

CASH /  
W.O. No. 90013

**TOW JOB WORKS ORDER**

M Primer Taxi Svc Date 12.12.17  
Car Make/Model Kia Vehicle No. SHC 6637  
M'ship/NRIC No./Card No. \_\_\_\_\_ Contact No. \_\_\_\_\_  
Time - Rec'd \_\_\_\_\_ Arrived 0023 Completed 0118  
Amount Charge S\$ \_\_\_\_\_ Tow Truck No. CR 97340  
Destination (from) Woodlands Dr 16 (to) Changi South 23  
Remark (if any) mat's C/PK  
Tow Driver's Signature \_\_\_\_\_ Member's Signature \_\_\_\_\_

- ☐ Change Tyres & Towing
- ☐ Basement / Multi Carpark
- ☐ Causeway / 2nd Link

- ☐ Using King Dolley
- ☐ Low Spoiler / Low Oil Sump
- ☐ Accident / Over-turn

- ☐ Use Car Carrier
- ☐ Release Brake / Shaft
- ☐ Loaded

**Note :** The owner or his representative is required to follow along to the towing destination, failing which the tow operator shall not be liable for any alleged damages to the car nor missing items from the same. Vehicle is towed at owner's risk. The tow operator accepts no responsibility for any damages to the owner's vehicle whilst being towed.