

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG:200707743D GST REG:200707743D

12-Dec-17

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6637 M

		\$
1 pc	<i>Boot lid</i> Bootlid emblem	\$ 27.00
1 pc	Bootlid CRDi	\$ 29.00
1 pc	Boot lid lower garnish	\$ 290.00
1 pc	o/s taillamp panel @ \$218.00	\$ 218.00
1 pc	Rear o/s tail lamp @ \$421.00	\$ 421.00
1 pc	Bootlid o/s reflector @ \$350.00	\$ 350.00
1 pc	Rear bumper	\$ 696.00
1 pc	Rear bumper lower cover	\$ 206.00
1 pc	Rear bumper o/s side bracket @ \$29.00	\$ 29.00
1 pc	Rear bumper inner sponge	\$ 114.00
1 pc	Rear bumper reinforcement	\$ 607.00
1 pc	Rear bumper stay o/s & n/s @ \$53.00 <i>n/s x o/s?</i>	\$ 108.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00 <i>n/s x o/s?</i>	\$ 36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00 <i>n/s x o/s?</i>	\$ 36.00
1 pc	Rear bumper o/s reflector @ \$46.00	\$ 46.00
1 pc	Rear muffler assy	\$ 1,009.00
1 pc	Rear exhaust pipe hanger <i>X</i>	\$ 49.00
		\$ 4,271.00
	Less 10%	\$ 427.10
		\$ 3,843.90

### S/NETT

1 set	Rear bumper clips	\$ 48.00
1 set	Bootlid lower garnish clips	\$ 60.00
1 set	Bootlid stickers	\$ 100.00
1 set	Reverse sensor	\$ 280.00 <i>200</i>
1 pc	Rear o/s fender sticker	\$ 60.00
	<i>Bumper top protective mat</i>	\$ 50

Towing Fee	\$ 50.00 /
Sundry	\$ <del>50.00</del> 20
To dismantle / replace exhaust pipe	\$ <del>120.00</del> 50
To dismantle / replace / test reverse sensor to new bumper and reset to the same	\$ <del>120.00</del> 20
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$ <del>180.00</del> 50
To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the rear o/s tail lamp panel. Including knock-out, straighten, repair, reshape and adjust of the end panel	\$ <del>1,400.00</del> 800
To putty and spray painting on bootlid, bootlid lower garnish, rear o/s fender, rear bumper, end panel, rear o/s taillamp panel,	\$ <del>1,200.00</del> 900
To apply rustproofing on the repaired and replaced panels.	\$ <del>250.00</del> 100
	<u>\$ 7,841.90</u>

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

**THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.**

Kaluz 16/12/14

12/12/17 163L

5 Days

P/P

Before Paint photo.

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey bid and after repair painting
- To display car body parts during survey
- Parts prices are subject to confirmation
- Third party claims on a "no-fault" basis
- No illegal modifications to be made
- Supplementary claims must be surveyed and approved by the insurance Company
- is subject to final approval

Acknowledged by Repairer

Signature: \_\_\_\_\_