

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 2134Z

DATE 12/12/2017 14:15

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid ✓			\$ 1,349.50
	Boot Lid Rubber ✕			\$ 110.90
	Boot Lid Lock Upper ✕			\$ 132.10
	Boot Lid Lock Lower ✕			\$ 30.30
	Boot Lid Sonata Plate ✓			\$ 43.60
	Boot Lid Hyundai Plate ✓			\$ 24.20
	Boot Lid 'H' Emblem ✓			\$ 26.10
	Boot Lid CRDI Plate ✓			\$ 22.70
	Boot Lid Lamp (LH/RH) LH✓ RH✕		\$ 230.20	\$ 460.40
	Boot Lid Trimboard ✕			\$ 165.40
	Boot Lid Trimboard Clips (10pcs) ✕			\$ 10.00
	Rear Bumper ✓			\$ 578.40
	Rear Bumper Reinforcement ?			\$ 483.30
	Rear Bumper Clip ✓			\$ 22.00
	Rear Bumper Sponge ?			\$ 137.40
	Rear Bumper Under Cover ?			\$ 185.80
	Rear Bumper Protector (LH/RH) ✕ Repair		\$ 38.00	\$ 76.00
	Tail Lamp (LH/RH) ✓		\$ 344.00	\$ 688.00
	Rear Panel ✕ Repair			\$ 391.80
	Rear Panel Garnish ?			\$ 95.80
	SUB TOTAL			\$ 5,033.70
	LESS 20%			\$ 1,006.74
	DISCOUNTED TOTAL			\$ 4,026.96
	Boot Lid Comfort Logo & Tel No. Sticker ✓			\$ 30.00 Nett
	Rear No. Plate ✕			\$ 25.00 Nett
	Rear Bumper Reverse Sensor ✓			\$ 135.70 Nett
	Rear Bumper Advertisement Logo ✓			\$ 50.00 Nett
	Labour Charge			
	Panel Beating			\$ 850.00
	Spray Painting Charge			\$ 600.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	Towing Fees (Not for from accident case)			\$ 50.00
	Remove/Refix Reverse Sensor			\$ 120.00
	TOTAL LABOUR			\$ 1,720.00
	ESTIMATE TOTAL			\$ 5,987.66
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Acknowledged by Reparer
Signature:



JOB REQUISITION FOR BREAKDOWN / TOWING SERVICE

Job Requisition

1. Date: <u>11/12/17</u> Time Received: <u>2210</u>		3. Vehicle Type: ☐ Private ☒ Taxi (CTPL/CCPL) ☐ Fleet ☐ STK (Boon Lay)	4. Type of Towing: ☒ Normal Tow ☐ King Dolly ☐ Flat Bed ☐ Crane-up
2. ☐ New ☐ SPARK Kakis Name of Customer : <u>Mr Wong</u> Contact No. : <u>91098387</u> Vehicle No. : <u>SHE 21342</u> Make / Model / Colour : <u>Saatchi / Yellow</u> Email :		5. Nature of Service: ☐ Jumpstart ☒ Recovery ☐ Change Tyre / Battery	6. Parts Replaced/Remarks:

7. Location: <u>Blk 662 Honggang Ave 4</u>	8. Vehicle Tow - In Workshop: ☐ Smoky Exhaust ☐ Wheel Jammed ☐ Overheating ☐ Steering Faulty ☐ Brake Faulty ☐ Alternator Faulty ☐ Starting Problem ☐ Loss Power ☒ Accident ☐ Engine Stalled ☐ Return Taxi
9. Preferred Workshop: ☐ Braddell ☒ Loyang ☐ Pandan ☐ Sin Ming ☐ Sungei Kadut ☐ Ubi ☐ Senoko ☐ Komoco (UBI / Leng Kee) ☐ Cycle & Carriage (PD) ☐ Others: _____	

10. Odometer Reading : _____ Fuel Level : ☐ F ☐ 1/4 ☐ 1/2 ☐ 3/4 ☐ E	11. Radio / CD Player ☐ OK ☐ Faulty ☐ Not tested	 #: Cracked X: Dented /: Scratched O: Missing <u>Aut</u> Signature of Customer
---	--	--

Job Attended

12. Tow Truck / Recovery Van : ☐ VRS ☒ QA ☐ STD ☒ TZ ☐ IRS ☐ OTHERS
Name of Driver : <u>Sore</u>
Vehicle No. : <u>YH2914</u>
Time Dispatch : <u>2215</u>
Time of Arrival : <u>2240</u>
Time Completed : _____

Cash Invoice Details (if applicable)

13. Cash Invoice No. : _____

Customer Acknowledgement

- a. I have been advised to remove all valuable items in my vehicle, including Global Positioning System (GPS), audio compact disk, thumbdrive, carpark coupons, cash cards, spectacles, pen, etc.
- b. I understand that any items left behind are at my own risk and SPARK Car Care™ will not be held liable for such losses.
- c. Surcharge: Towing fee will be levied if the customer decides neither to tow nor proceed with the repairs in SPARK Car Care™.

_____	_____	<u>Aut</u>
Date	Time	Signature of Customer

14. WORKSHOP

_____	_____	_____
Name of Attending Staff/Guard	Date & Time of Arrival	Signature of Attending Staff/Guard