

REPAIR ESTIMATE*

VEHICLE NO : SH 7126H

DATE 12/12/2017

MAKE :

MODEL : HYUNDAI IONIQ

EQ Ins-CP/P) TS
LKK Kalvin

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Radiator Grille — <i>con</i>			1227.50	
	Radiator Grille U Moulding <i>X con</i>			108.50	
	Front Bumper Cover — <i>Reh</i>			490.50	
	Front Bumper Sponge <i>X su</i>				
	Front Bumper Reinforcement <i>X su</i>				
	Front Bumper Centre Grille <i>X su</i>				
	Front Bumper Bracket Top (LH/RH) <i>X su</i>				
	Front Bumper Retainer Mounting <i>X su</i>				
	Headlamp (RH) — <i>hnd</i>			1198.80	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party's survey is on "Without prejudice" basis
- No repair or replacement is allowed
- Surveys must be supervised and is subject to approval from insurance Company