Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AXA17023674/UPA3Q2

Date: 17/09/2020

REFERENCE

Handling Insurer: AXA Insurance Pte Ltd Policy No: P1680520

Claimant Plant Property Property No. P1680520

Vehicle No: SKM588Y Insured Vehicle No: SHB7998U

Date of Loss: 08/12/2017 Nature of Claim: TP Claim No: C0464499

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKM588Y

Make & Model: VOLKSWAGEN JETTA, 1.4 (A) Engine No: CAV299348

Reg. Date: 09/09/2011 (Man. Year: 2011) Chassis No: WVWZZZ16ZBM106996

Colour: Brown Odometer: 159765 km

Engine Capacity: 1390 cc
Market Value/New Car

Price: N/A

Price.

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/35R19 Rear Tyre Size: 235/35R19
Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm
Front Right Side: Goodyear 6 mm
Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-----------------------------------|----------------------|------------|------------|--------|
| Parts | 2,731.00 | 1,364.35 | 1,366.65 | 50.04 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 1,350.00 | 920.00 | 430.00 | 31.85 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$ | 4,081.00 | 2,284.35 | 1,796.65 | 44.02 |
| Approved Total (Overridden) (S | 5) | 1,800.00 | | |
| (53 | 4,081.00 | 1,800.00 | 2,281.00 | 55.89 |
| + GST 7.00/7.00% (S\$ | 285.67 | 126.00 | 159.67 | 55.89 |
| Nett Amount (S\$ | 4,366.67 | 1,926.00 | 2,440.67 | 55.89 |
| + Car Rental (3.5 x S\$100.00/day | + 7.00% GST) (S\$) | 374.50 | | |
| | Nett Liability (S\$) | 2,300.50 | | |
| Global Sum Settlement (S\$) | | 2,250.00 | | |

INSPECTION

Date of Assignment: 12/12/2017

Date Inspected: 13/12/2017 Inspected At: Stytech Auto Pte Ltd (HQ)

2 Kaki Bukit Ave 2 #02-30, Kaki Bukit

Autohub

Singapore 417921

Estimated Period of Repair: 3.0 days

Adjuster Report Page 2 of 4

Adjuster: MARCUS CHUA Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

| Reference | | | | |
|--|--|--|--|--|
| Part Source | : MRM-SG | Version: 1.0 (Last Synchronised: 17 Sep 2020) | | |
| Parts: | 143 | VOLKSWAGEN JETTA 1.4 (A) (Catalogue:Merimen Singapore 1.0) | | |
| Labour: | Repairer's | (Price-denominated Standard List) | | |
| Print Code: | (Unsubmitted, no print-code for SKM588Y) | | | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | | | |
| Further Info: Items/values not in reference catalogue are prefixed with an asterisk *. | | | | |

Recommended Parts

| No. | Qty | Part No | . Particulars | Condition | Repairer's | Amount |
|---|---------|------------|--|---------------------------------------|------------|-----------------------|
| 1 | 1 | | *REAR BUMPER (CONSISTENT) | Deformed / Torn | 1,180.00 F | *1,180.00 FL |
| 2 | 1 | | *REAR BUMPER RETAINERS (CONSISTENT) | O/S Necessary | 196.00 F | *98.00 FL |
| 3 | 1 | | *SET REAR BUMPER CLIPS (CONSISTENT) | Necessary | 30.00 FS | *30.00 FS |
| 4 | 1 | | *REAR BUMPER REFLECTOR O/S (CONSISTENT) | Cracked | 95.00 F | *95.00 FL |
| 5 | 1 | | *REAR TYRE RIM O/S (CONSISTENT) | Repair | 1,200.00 F | *-FL |
| 6 | 1 | | *SET REAR FENDER INNER SHIELD CLIPS O/S (CONSISTENT) | Necessary | 30.00 FS | *30.00 FS |
| F=Fra | anchise | part. S=Sp | cNett. L=ListItemDisc List Item Discount on L Item | Sub Total (S\$) s 0.00/5.00% (S\$) | • | 1,433.00 68.65 |
| | | | | Total Parts (S\$) | 2,731.00 | 1,364.35 |
| Report was unsubmitted during this print-out. | | | | | | |

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount | | | | |
|-----|--|---------------------|------------|--------|--|--|--|--|
| Lab | Labour Items | | | | | | | |
| 1 | TO DISMANTLE & REFIX UPHOLSTERY | New | 100.00 | 60.00 | | | | |
| 2 | TO CHECK WIRING | New | 50.00 | 20.00 | | | | |
| 3 | TO SPRAY ANTI RUST PROOFING | New | 80.00 | 0.00 | | | | |
| 4 | TO CONDUCT WHEEL ALIGNMENT | New | 120.00 | 60.00 | | | | |
| 5 | LABOUR FOR PANEL BEATING & REPLACING PARTS | New | 400.00 | 300.00 | | | | |
| 6 | TO PUTTY & SPRAY PAINTING | New | 600.00 | 480.00 | | | | |
| | Gross Labo | 1,350.00 | 920.00 | | | | | |
| | Report was unsubmitted duri | ing this print-out. | | | | | | |

< END OF ESTIMATES >