

SKM 5884 ✓

- 1) Rear Bumper — 2e/70. ✓
- 2) Rear Bumper Retainer (2k) — 2/5 rec 12 ✓
- 3) Rear Bumper clips — rec —
- 4) Rear Bumper Reflector (Rec) — crx —
- 5) Rear Tyre Rim (Rm) — n x
- 6) Rear Fender Filler Shield clip (Rm) — rec ✓

Labour! -

- 1) Interior Upholstery — 100V — 60
- 2) Check Wiring — 50V — 20
- 3) Anti Rust Proofing — 80V — n x
- 4) Balance Tyre Rim x / fix up with Alignment — 120V — 60
- 5) Panel Beating — 400V — 300
- 6) Paintwork — 600V — 480

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature: _____
Date: _____

Not done

RM

4/53

32

13/12/17

to be kept in the shop