

Estimate

Vehicle: SKM588U

Make & Model: Volkswagen Jetta

Year: _____

Chassis No: WUV2221623M106986

	Parts / Labour	Condition	Price	recommend
	Rear bumper	del/ torn	1180.00	✓
2pcs	Rear bumper retainers @ 98.00	o/s nec	196.00	1pc
1set	Rear bumper clips	nec	30.00 S. Nett	✓
	Rear bumper reflector o/s	one	95.00	✓
	Rear tyre rim o/s	n	1200.00	X
1set	Rear fender inner shield clips o/s	nec	30.00 S. Nett	✓
		5% 27594.45		
	To dismantle & refix upholstery		100.00	60
	To check wiring		50.00	20
	To spray antirust proofing	n	80.00	X
	To correct wheel alignment		120.00	60
	labour for panel beating & replacing parts		400.00	300
	To putty & spray painting		600.00	480
			1,470.00	
		TA	21,944.45	
			P-1373	
			5%	
			1304.35	
			60.00 S. W	
		labr - 920		
			2284.35	
			1827.48	

Not Authorized
LKK

2/5 @ 1800/3

3 day.

To be phd. After repair

13-12-17

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: