

12/03/2017

ASS: REC BY:

REF: CS/PCI17023677 / Uvd3n7

Special Instructions:

Surveyor:

Marcus

ASSIGNMENT (Office)

aws

From (Person): Lurene jaw

of PCI

Date/Time: 11:10am @ 13/12/17

Estimated Cost:

Bill to:

OD (IP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLP 42685

Insured:

SHC7116T

at Workshop m/s

Pegasus Engineering

Tel:

68581846

of

51 Deft Leake 10

Policy No:

Claim No:

D17011423MFSH

Sum Insured:

Excess:

D.O.A 10/12/2017

Make of Veh:

(Client's Record)

CA / REV / REP. / REV 24 HRS

(wp)

R.O.D. Endorsement:

Date/Time:

11:22am @ 13/12/17

Person Contacted:

Alvin Law

Vehicle IN

OUT

Date/Time

Action/Instruction () Estimate

Pending ID's VF to Determine Liability

SLP42685 - X

SHC7116T - X

28/12/17

Email preli revised to FCI

ASSIGNMENT

From: _____ Date: 27/12/17

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLP 4268S

at Workshop m/s pegasus

of 51 Defu Lane 10

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

after 9am

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

G/A / PR Seen: 2 Consistent?: Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lump Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLP 4268S Yr Regn: 6 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /

Make: made 3 C.C. 1496

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 32168 T/Radio: Insured / Std / NI / NA

Eng/No: JM6BN22A8H0154136

C/No: _____

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 7 mm

L/Bal. 7 mm

D.O.A. 10/12/17

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Body.

The U/C / Chassis frame / Body Structure affected due to collision.

Rear

R/Bal. 7 mm

L/Bal. 7 mm

D.O.I. 27/12/17

27/12/17 confirmed L/S @ 2300 with William. (Red 2522-40, 5290)

RECEIVED 2-9 DEC 2017

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1)

Date/Time, File Return to?

2) 28/12 - typist

Report Format: CWS

Lump Sum / I.B.I.: (\$ 2300/2)

Days Of Repair: 3

Resurvey No. of Trip: -

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Insp (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + R + S (\$)

Photos:

Others:

TOTAL

135

50

27

212

Survey Department Check List (Case Handler)

Reference No.: CS/FCI 17023677/ Uvd3

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

		Y-Date	N-Date	Y-Date	N-Date
(1) Office Assign Form					
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No				
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

		Y-Date	N-Date	Y-Date	N-Date
(1) Assignment Form					
C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)		✓			
C	Damaged Vehicle Photographs Uploaded				

(3) Workshop Estimate/Assignment Form		✓			
N	ALL Parts condition				
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)					
C	Resurvey photo Uploaded				

Check By: VERON 28/12/17
Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17023677/Uvd3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 13-12-2017



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 7116T	Veh. Inspected	SLP 4268S
Policy No.		Coverage (\$)	0.00
Claim No.	D17011423MFSH	Excess (\$)	0.00
Assign From	CWS (LURENE JAW)	Assign Date	13/12/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	10/12/2017	Inspection Date
Survey held at	51 DEFU LANE 10	
Repairer	PEGASUS ENGINEERING & TRADING PTE LTD	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D17011423MFSH
Our ref: CS/FCI17023677/Uvd3

DATE: 28/12/2017

The Motor Claims Department
M/s First Capital Insurance Limited

WITHOUT PREJUDICE

Dear Sir/Madam


INITIAL INSPECTION REPORT OF VEHICLE NO. SLP 4268S

We thank for your instruction on 13/12/2017

Please be informed that we had conducted the inspection of the above mentioned vehicle on vehicle on 27/12/2017 at the premises of M/s PEGASUS ENGINEERING & TRADING PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$4,822.40
Revised Estimate Amount	: S\$2,300.00 (Lump sum)
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:
The vehicle sustained damages at the
o/s body



Comments/Present Status:
Damages Consistent

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C

GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	12-12-2017	Our Ref No. D17011423MFSH
Accident Date	10-12-2017	Claim Type. Third Party
Insured Vehicle	SHC7116T	Third Party Vehicle. SLP4268S
Survey Location	51 DEFU LANE 10	
Contact Person.	ALVIN LOW	
Contact No.	68581846/ 0	Fax No. 64876070
Survey Type	WITHOUT PREJUDICE: PENDING ID'S VF TO DETERMINE LIABILITY	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PEGASUS ENGINEERING & TRADING PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/231761)



PRI Documents



Close



PRI Header Details

Claim No	D17011423MFSH	Policy No	D-15072702MFSH	Claimant S.No & Name	1 & PEGASUS PTE LTD
Workshop Name	PEGASUS ENGINEERING & TRADING PTE LTD (Contact Person : ALVIN LOW)	Survey Location & Contact Details	51 DEFU LANE 10 Mobile: 0 , Phone: 68581846 , Fax: 64876070 EmailId: CLAIMS@PEGASUSENGR.G.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: PENDING ID'S VF TO DETERMINE		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHC7116T	TP Vehicle No	SLP4268S
PRI Recieved Date	12-12-2017 05:05:25 PM	Surveyor Appointed Date	13-12-2017 11:09:10 AM	Surveyor Accept Date	13-12-2017 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	13-12-2017	Upload Survey Report *:	Choose File
------------------------------------	--	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 28 December, 2017 12:22 PM
To: 'Claim Workflow System'
Cc: LURENEJAW@FIRST-INSURANCE.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D17011423MFSH/1, SLP 4268S
Attachments: SLP 4268S PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SLP 4268S
Date of survey: 27/12/2017
Number of days:3 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, 13 December, 2017 2:40 PM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: LURENEJAW@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D17011423MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]
Sent: Wednesday, 13 December, 2017 11:09 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; LURENEJAW@FIRST-INSURANCE.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D17011423MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Company
Owner ID	7200G

Vehicle Details

Vehicle No.	SLP4268S
Vehicle to be Exported	Yes
Intended De-registration Date	11 Dec 2017
Vehicle Make	MAZDA
Vehicle Model	MAZDA3 SEDAN 1.5 AT EU6
Primary Colour	Grey
Manufacturing Year	2017
Engine No.	P520446059
Chassis No.	JM6BN22A8H0154136
Maximum Power Output	88.0 kW (118 bhp)
Open Market Value	\$14,761.00
Original Registration Date	05 Jun 2017
First Registration Date	05 Jun 2017
Transfer Count	0
Actual ARF Paid	\$9,761.00

Intended PARF Rebate Details

PARF Eligibility	Yes
PARF Eligibility Expiry Date	04 Jun 2027
PARF Rebate Amount	\$7,320.00

Intended COE Rebate Details

COE Expiry Date	04 Jun 2027
COE Category	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years)	10
QP Paid	\$52,000.00
COE Rebate Amount	\$41,600.00
Total Rebate Amount	\$48,920.00

The information contained herein is correct as at 11 Dec 2017

OK

Messrs Grab Rentals Pte Ltd

Estimate To Repair

Vehicle No :

Chassis No :

Mazda 3-1.5 4 Door Sedan

SLP4268S

JM6BN22A8H0154136

Third Party Insurer : First Capital
Insured's Veh No : SHC7116T
Date of accident : 10.12.2017

Date : 11.12.2017

LKK 1015

Pages : 1 of 1

S/No	Quantity	Description	Unit price	Amount
LIST ITEMS				
1	1 pc	front door o/s	\$ 1,062.00	\$ 1,062.00
2	1 pc	front door window glass channel weatherstrip	\$ 165.00	\$ 165.00
3	1 pc	front door outer weatherstrip	\$ 77.00	\$ 77.00
4	1 pc	front door weatherstrip	\$ 107.00	\$ 107.00
5	1 pc	rear door o/s	\$ 1,006.00	\$ 1,006.00
6	1 pc	rear door hinge bottom	\$ 58.00	\$ 58.00
7	1 pc	rear door window glass channel weatherstrip	\$ 117.00	\$ 117.00
8	1 pc	rear door outer weatherstrip moulding	\$ 140.00	\$ 140.00
9	1 pc	rear door weatherstrip	\$ 121.00	\$ 121.00
				\$ 2,853.00
Less 20%				\$ 570.60
				\$ 2,282.40
LABOUR & MISC. CHARGES				
1		To transfer of door fittings and perform water seepage test.		\$ 120.00
2		To rust-proofing of the affected areas.		\$ 120.00
3		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.		\$ 500.00
4		Putty and spray painting of the affected portion.		\$ 1,800.00
				\$ 2,540.00
Grand Total				\$ 4,822.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please conduct the survey at

Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17023677/Uvd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 03-01-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7116T	Veh. Inspected	SLP 4268S	
Policy No.	D-15072702MFSH	Coverage (\$)	0.00	
Claim No.	D17011423MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	13/12/2017	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA 3 (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JM6BN22A8H0154136	Colour	GREY	
Odometer	32168	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	BRIDGESTONE	7 mm	
L/H Front Tyre	205/60 R16	BRIDGESTONE	7 mm	
R/H Rear Tyre	205/60 R16	BRIDGESTONE	7 mm	
L/H Rear Tyre	205/60 R16	BRIDGESTONE	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	10/12/2017	Inspection Date	27/12/2017	
Survey held at	51 DEFU LANE 10			
Repairer	PEGASUS ENGINEERING & TRADING PTE LTD			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT.				
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.				
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLP 4268S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT DOOR O/S	DENTED / BENT	1,062.00	1,062.00
1	FRONT DOOR WINDOW GLASS CHANNEL WEATHERSTRIP	NOT NECESSARY	165.00	-
1	FRONT DOOR OUTER WEATHERSTRIP	NOT NECESSARY	77.00	-
1	FRONT DOOR WEATHERSTRIP	NECESSARY	107.00	107.00
1	REAR DOOR O/S	DENTED / BENT	1,006.00	1,006.00
1	REAR DOOR HINGE BOTTOM	NOT NECESSARY	58.00	-
1	REAR DOOR WINDOW GLASS CHANNEL WEATHERSTRIP	NOT NECESSARY	117.00	-
1	REAR DOOR OUTER WEATHERSTRIP MOULDING	NOT NECESSARY	140.00	-
1	REAR DOOR WEATHERSTRIP	NECESSARY	121.00	121.00
	LESS 20% DISCOUNT		-570.60	-459.20
			2,282.40	1,836.80
LABOUR				
	TO TRANSFER OF DOOR FITTINGS AND PERFORM WATER SEEPAGE TEST.		120.00	120.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		120.00	60.00
	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.		500.00	300.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		1,800.00	600.00
			2,540.00	1,080.00
GRAND TOTAL			4,822.40	2,916.80
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,300.00

Report Ref No. CS/FCI17023677/Uvd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.