

22/03/2002

ASS. REC. BY:

REF: CS/CT117023682/Kw322

Special Instruction:

Surveyor:

Munimen

ASSIGNMENT (Office)

From (Person):

Joel Goh

of

CT1

Date/Time:

13/12/17 @ 2:26pm

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLU 1599E

Insured:

XD 4518S

at Workshop m/s

MBM Wheelpower

Tel:

6262 8888

of

160 Hin Ming Drive # 06-02, 575722

Policy No:

DMCVSN1762791700

Claim No:

SNM17D07059C02/8

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

09/12/2017

CA / REV / REP. / REV 24 HRS

'wup'

15/12/17 @ 2:30pm owner waiting

H.O.D. Endorsement:

Date/Time:

2:50pm @ 13/12/17

Person Contacted:

Danny

Vehicle IN / ☒ OUT

Date/Time	Action/Instruction (✓) Estimate
	SLU 1599E - X
	XD 4518S - X
12/13	\$ 4435.00 Confirmed by email
13/18	Final fig \$ 4360 confirmed by email (Ref 4580, 517)

REF: C71

ASSIGNMENT

From: Date 15/12/17

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLU1599E
at Workshop no: MBM Wheelpower
of 160 Sin Ming Drive #06-02

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4-6 days Res.: Yes or No

Lump Sum: 1-131 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'wpr

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: 2U1599E Page 11 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy

Colour: M. Maroon

Sp Reading: 4687

Eng No:

C/No: 27X10 206288

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/50R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 9 mm

R/Bal: 9 mm

L/Bal: 9 mm

L/Bal: 9 mm

D.O.A: 9/12/17

D.O.A: 15/12/17

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

18/12 File pass to Catherine

RECEIVED 17 Dec 2018

Date/Time File Pass to:

☐

: Preli. Report

☐

: Final Report

Days Of Repair: 6

Resurvey No. of Trip: 1

Survey Fee

Transportation

Lump Sum / B.B. / B.B.

Photos

Other

TOTAL

Date/Time File Return to:

13/3-typist

Report Format:

Lump Sum / B.B. / B.B.

merimen

4360/2

Add Fee:

☐

Site Insp. \$

☐

Interview \$

☐

Test drive \$

☐

Nearend \$

220

220

Survey Department Check List (Case Handler)

Reference No.: CS/CTI 17023682/Kvd3
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA/REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 13/3/18
Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI17023682/Kvd3		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 13-12-2017		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XD 4518S	Veh. Inspected	SLU 1599E	
Policy No.	DMCVSN1762791700	Coverage (\$)	0.00	
Claim No.	SNM17D07059C02/8	Excess (\$)	0.00	
Assign From	MERIMEN (JOEL GOH)	Assign Date	13/12/2017	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	09/12/2017	Inspection Date		
Survey held at	MBM WHEELPOWER PTE LTD 176 SIN MING DRIVE #01-15 SIN MING AUTOCARE SINGAPORE 575721			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Dec 2017		13 Dec 2017 14:26 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:	KOK TONG TRANSPORT & ENGINEERING WORKS PTE LTD, Co. Reg. No.: 199904117E		
Main Claimant:	ISAFE AGENCY, Co. Reg. No.: 53289574J		
Vehicle Reg. No.:	SLU1599E	Date of Loss:	09/12/2017 07:00 - :59
Claim Type:	TP / SNM17D07059C02/8	Policy/Cover Note No.:	DMCVSN1762791700 (Comprehensive)
Vehicle Reg. No. (Insured):	XD4518S	Policy No. (Claimant):	5096204737
		Excess:	S\$0.00
Repairer:	MBM Wheelpower Pte Ltd (HQ) 160 SIN MING DRIVE #06-02, SIN MING AUTOCITY, 575722 Sin Ming - Tel: 6262 8888		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Joel Goh]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 22/12/2017]		
Driver/Custodian (Insured):	PONNALAGU ALAGAPPAN (45 / Male), NRIC: S7268539C, Tel: +6590250587		
Adj Asg. Remarks:	ESTIMATES AS ATTACHED SELECTED AS SJE FOR WP PRS		

ASSOCIATED MAIL RECEIVED	View All Compose Case Mail
There are no mail for this case.	

ALL ASSOCIATED TASKS <input type="checkbox"/>	View All Search Tasks Create New Task Complete
<div style="display: flex; justify-content: space-between;"> <div>Due Date</div> <div>Priority</div> <div>Type</div> <div>Task Group</div> <div>Subject</div> <div>Handler</div> <div>Assigned By</div> <div>Completed On</div> <div>Created On</div> <div>Done?</div> </div>	
No results.	

Enquire Transfer Fee

Vehicle Details

Vehicle No.	SLU1599E
Vehicle Type	Z11 - Private Hire (Chauffeur) Station Wagon/Jeep/Land Rover
Vehicle Attachment 1	No Attachment
Vehicle Scheme	Normal
Vehicle Make	TOYOTA
Vehicle Model	C-HR HYBRID 1.8G CVT
Chassis No.	ZYX102062988
Propellant	Petrol-Electric
Engine No.	2ZR8164701
Motor No.	20A317605145
Engine Capacity	1797 cc
Power Rating	53.0 kW
Maximum Power Output	90.0 kW (120 bhp)
Maximum Laden Weight	1715 kg
Unladen Weight	1440 kg
Year Of Manufacture	2017
Original Registration Date	23 Nov 2017
Lifespan Expiry Date	-
COE Category	E - Open - all except motorcycle
Quota Premium	\$57,501.00
COE Expiry Date	22 Nov 2027
Road Tax Expiry Date	22 May 2018
PARF Eligibility Expiry Date	22 Nov 2027
Inspection Due Date	22 Nov 2020
Intended Transfer Date	26 Dec 2017
CO2 Emission	88.00 (g/km)
CEVS Rebate Utilised Amount	\$30,000.00

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use [Enquire Road Tax Payable](#) for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/12/2017 09:39
Date Of Accident	09/12/2017 07:50
Exact Location Of Accident	ALONG WOODLANDS AVE 5
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLU1599E
Insured/Policyholder	
Name Of Registered Owner	ISAFE AGENCY
Co Reg No	53289574J
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-93809444
Vehicle Particulars	
Manufacturer	TOYOTA
Model	C-HR HYBRID-1.8 S CVT (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE HIRE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5096204737
Cover Note Number	

Driver

Name of Driver	JURAIMI BIN RAHMAT
NRIC No	S1693847E
Date Of Birth	01/09/1968
Occupation	OUTDOOR
Date Of Driving Pass	06/09/2000
Driving Experience	17 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93809444
Fax Number	
Contact Number	
Email Address	JURAIMI.DRLED@GMAIL.COM

Address	BLK 176C EDGEFIELD PLANS #13-184
Postcode	823176
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	AFTER RAIN
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE SIZE TOO BIG
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XD4518S
Vehicle Make/Model/Colour	ISUZU
Details Of Properties	
Name of Driver	PONNALAGU ALAGADDAN
NRIC/Passport Number	S7268539C
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

SKETCH PLAN


IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver.**
3. Information provided must be as **truthful and accurate as possible.** Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability.**
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

ISAFE AGENCY
181 Kitchener Road #01-29
New Park Hotel Shopping Arcade
Singapore 208533
Tel: 62922002 Fax: 62515003




Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

It happened on the 9th of December 2017 at around 7.50am at Woodlands Ave 5 traffic light junction. I had just drop off a passenger at Singapore American School and was on the way to pick up another passenger while doing Uber. At the junction I was on the 2nd lane and had signalled right for the turn. The traffic light was red, so my car was stationary. Suddenly there was an impact hitting the behind of my car. I got out and saw a lorry behind me. I took pictures and videos and exchanged particulars with the other driver.

↓ VIDEO FOOTAGE CAPTURED
 ↓ NO INJURIES

DECLARATION


I/We declare the foregoing particulars are true in every respect.

SAFE AGENCY
 181 Kitchener Road #01-29
 New Park Hotel Shopping Arcade
 Singapore 208533
 Tel: 62922002 Fax: 62922003

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

MBM WHEELPOWER PTE LTD



Your Ref: XD4518S
Our Ref: SLU1599E

To: CHINA TAIPING INSURANCE (SINGAPORE)

Date: 10/12/2017

CC

From: Danny

Fax: 62509015

Email

Contact: 93288668

Make / Model: TOYOTA C-HR HYBRID 1.8G

Chassis No.: ZYX102062988

Fax

Engine No.: 2ZR8164701

Year of Make: 2017

Accident Date: 9 December 2017

*Not at hand
1-B1
Resurvey B4 party
-6 days
@ 4435.00*

ESTIMATE FOR VEHICLE NO. : SLU1599E

DESCRIPTION

REAR BUMPER

890.00

REAR BUMPER LOWER COVER

320.

REAR BUMPER CLIPS

REAR LOWER COVER TOWING HOOK COVER

REAR INFORCEMENT

310.00

REAR BUMPER RH PLATE

TAILGATE

1200.00

TAILGATE LOCK

TAILGATE TOP & LOWER GARNISH

END PANEL

640.00

QTY

1

1

10

1

1

1

1

1

1

1

List Price

Pr 1,650.00

Pr 420.00

Pr 65.00

Pr 35.00

Pr 400.00

Pr 120.00

Pr 1,500.00

Pr 480.00

Pr 1,350.00

Pr 800.00

Total: \$ 6,820.00

LESS 25% \$ (1,705.00)

Parts Total: \$ 5,115.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) in the resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "No Prejudice" basis
- No illegal modification is allowed
- Supplementary survey is subject to final approval by the Insurance Company

Acknowledged by Repairer

Signature:

Mbm wheelpower pte ltd

160 SIN MING DRIVE

#06-02

SIN MING AUTOCITY

t 62828888 f 64529823

Company Registration Number : 200204110W

SPECIAL NETT

NUMBER PLATE & HOLDER	1	\$	80.00
REAR BUMPER SENSORS	2	\$	300.00 X
WINDSCREEN SEALANT	1	\$	200.00

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS. INCLUDING TO KNCOK-OUT, STRAIGHTEN, ON THE AFFECTED PARTS	\$	1,000.00
TO REMOVE & REFIT TAILGATE WINDSCREEN TO FACILIATE REPAIR	\$	200.00
TO REMOVE, REFIT & UPHOLSTERY TO FACILITATE REPAIRS	\$	100.00
TO REMOVE & REPLACE BUMPER SENSORS	\$	40.00
TO CHECK & RECONNECT ALL NECESSARY WIRING	\$	80.00
TO SPRAY PAINTING ON THE REAR BUMPER, TAILGATE, END PANEL, TAILGATE TOP & LOWER GARNISH	\$	1,600.00

Total:	\$	8,715.00
7% GST:	\$	610.05
Grand Total:	\$	9,325.05

8940


Please survey the vehicle at :-
160 SIN MING DRIVE,
#06-09 SIN MING AUTOCITY,
SINGAPORE 575722

(Kindly contact Danny @ 93288668)

Mbm wheelpower pte ltd
160 SIN MING DRIVE
#06-02
SIN MING AUTOCITY
t 62828888 f 64529823

Company Registration Number : 200204110W

MBM WHEELPOWER PTE LTD



Your Ref: XD4518S

Our Ref: SLU1599E

To: CHINA TAIPING INSURANCE (SINGAPORE)

CC

Email

Fax

Date: 8/1/2018
From: Danny
Fax: 62509015
Contact: 93288668
Make / Model: TOYOTA C-HR HYBRID 1.8G
Chassis No.: ZYX102062988
Engine No.: 2ZR8164701
Year of Make: 2017
Accident Date: 9 December 2017

SUPPLEMENTARY ITEMS FOR VEHICLE NO : SLU1599E

DESCRIPTION

END PANEL TOP GARNISH

QTY		LIST PRICE	
1	\$	<i>ny 1m</i>	300.00 ✓
Less 25%	\$		75.00
Parts Total:	\$		225.00

Mbm wheelpower pte ltd

160 SIN MING DRIVE

#06-02

SIN MING AUTOCITY

t 62828888 f 64528823

Company Registration Number : 200204110W

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 13 March 2018 3:53 PM
To: yinsiew.kon@mbmwheelpower.com.sg; SUR
Cc: kenneth@mbmwheelpower.com.sg; 'danny.ong'; Kenneth Kong (LKKAUTO)
Subject: RE: SLU1599E - DOA 09/12/2017 - FINALISE

Dear Yin Siew,

Confirmed finalise amount at \$4,360.00/- with 06 days repair.

Final invoice and all supporting documents sent to China TaiPing

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: yinsiew.kon@mbmwheelpower.com.sg [mailto:yinsiew.kon@mbmwheelpower.com.sg]
Sent: Tuesday, 13 March 2018 3:37 PM
To: SUR <sur@lkkauto.com>
Cc: kenneth@mbmwheelpower.com.sg; 'danny.ong' <danny.ong@mbmwheelpower.com.sg>; Kenneth Kong (LKKAUTO) <KennethKong@lkkauto.com>
Subject: SLU1599E - DOA 09/12/2017 - FINALISE


Dear All

Revised finalise amount at \$4360.00/- with 06 days repair.

Kindly confirm on your side.

Best regards,

Kon Yin Siew | Claims Officer



T 6262 8888 | F 6250 9015 | M 8588 3198

Email: yinsiew.kon@mbmwheelpower.com.sg

MBM Wheelpower Pte Ltd

160 Sin Ming Drive • #06-02

Sin Ming AutoCity • Singapore 575722

www.mbmwheelpower.com.sg

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Dec 2017		13 Dec 2017 14:26 Edit Adj Rpt	S\$4,360.00 Edit Estimates	S\$4,360.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS				[Created by insurer]		
Insured:	KOK TONG TRANSPORT & ENGINEERING WORKS PTE LTD, Co. Reg. No.: 199904117E					
Main Claimant:	ISAFE AGENCY, Co. Reg. No.: 53289574J					
Vehicle Reg. No.:	SLU1599E	Date of Loss:	09/12/2017 07:00 - :59			
Claim Type:	TP / SNM17D07059C02/8	Policy/Cover Note No.:	DMCVSN1762791700 (Comprehensive)			
Vehicle Reg. No. (Insured):	XD4518S	Policy No. (Claimant):	5096204737			
		Excess:	S\$0.00			
Repairer:	MBM Wheelpower Pte Ltd (HQ) 160 SIN MING DRIVE #06-02, SIN MING AUTOCITY, 575722 Sin Ming - Tel: 6262 8888					
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Joel Goh]					
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:					
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 22/12/2017]					
Driver/Custodian (Insured):	PONNALAGU ALAGAPPAN (45 / Male), NRIC: S7268539C, Tel: +6590250587					
Adj Asg. Remarks:	ESTIMATES AS ATTACHED SELECTED AS SJE FOR WP PRS					

ASSOCIATED MAIL RECEIVED		View All Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS				View All Search Tasks Create New Task Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLU1599E (SNM17D07059C02/8)
[XD4518S]**

TP

ISAFE AGENCY




























Dec 9 2017 7:00AM

[KOK TONG TRANSPORT & ENGINEERING WORKS PTE LTD]

MBM Wheelpower Pte Ltd

[Upload Documents](#) | [Upload Photos](#) | [Compose New Letter](#)

View [View in Browser](#) ▼

Assessment Reports			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	MBM Wheelpower Pte Ltd (HQ)	Thumbnail	Print
1	11/12/17 10:03	Accident Statement	 Load HTM	
Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	MBM Wheelpower Pte Ltd (HQ)	Thumbnail	Print
1	11/12/17 10:03	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	11/12/17 10:03	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
3	11/12/17 10:03	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
4	11/12/17 10:03	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
5	11/12/17 10:03	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
6	11/12/17 10:03	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
7	11/12/17 10:03	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
8	11/12/17 10:03	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
9	11/12/17 10:03	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
10	11/12/17 10:03	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
11	11/12/17 10:03	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/12/17 13:41	General View	 Load JPG	<input checked="" type="checkbox"/>
2	18/12/17 13:41	General View	 Load JPG	<input checked="" type="checkbox"/>
3	18/12/17 13:41	General View	 Load JPG	<input checked="" type="checkbox"/>
4	18/12/17 13:41	General View	 Load JPG	<input checked="" type="checkbox"/>
5	18/12/17 13:41	General View	 Load JPG	<input checked="" type="checkbox"/>
6	18/12/17 13:41	General View	 Load JPG	<input checked="" type="checkbox"/>
7	18/12/17 13:41	General View	 Load JPG	<input checked="" type="checkbox"/>
8	18/12/17 13:41	General View	 Load JPG	<input checked="" type="checkbox"/>
9	18/12/17 13:41	General View	 Load JPG	<input checked="" type="checkbox"/>
10	18/12/17 13:41	General View	 Load JPG	<input checked="" type="checkbox"/>
11	18/12/17 13:41	General View	 Load JPG	<input checked="" type="checkbox"/>
12	18/12/17 13:41	General View	 Load JPG	<input checked="" type="checkbox"/>
13	18/12/17 13:41	General View	 Load JPG	<input checked="" type="checkbox"/>
14	13/03/18 13:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
15	13/03/18 13:34	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

16	13/03/18 13:34	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
17	13/03/18 13:34	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
18	13/03/18 13:34	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
19	13/03/18 13:34	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
20	13/03/18 13:34	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
21	13/03/18 13:34	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
22	13/03/18 13:34	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	13/12/17 14:29	ESTIMATES	1 Load PDF	
2	13/12/17 14:29	OI GIA REPORT	1 Load PDF	
No	Finalized On	MBM Wheelpower Pte Ltd (HQ)	Thumbnail	Print
1	11/12/17 09:59	Sketch Plan [Linked Accident Report Documents]	1 Load TIF	
2	11/12/17 09:59	Sketch Plan #2 [Linked Accident Report Documents]	1 Load TIF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/03/18 08:58	Supplementary	1 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	MBM Wheelpower Pte Ltd (HQ)	Thumbnail	Print
1	11/12/17 10:03	Accident Statement	1 Load HTM	
Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	MBM Wheelpower Pte Ltd (HQ)	Thumbnail	Print
1	11/12/17 10:03	Accident Photo	1 Load JPG	<input checked="" type="checkbox"/>
2	11/12/17 10:03	Accident Photo	1 Load JPG	<input checked="" type="checkbox"/>
3	11/12/17 10:03	Accident Photo	1 Load JPG	<input checked="" type="checkbox"/>
4	11/12/17 10:03	Accident Photo	1 Load JPG	<input checked="" type="checkbox"/>
5	11/12/17 10:03	Accident Photo	1 Load JPG	<input checked="" type="checkbox"/>
6	11/12/17 10:03	Accident Photo	1 Load JPG	<input checked="" type="checkbox"/>
7	11/12/17 10:03	Accident Photo	1 Load JPG	<input checked="" type="checkbox"/>
8	11/12/17 10:03	Accident Photo	1 Load JPG	<input checked="" type="checkbox"/>
9	11/12/17 10:03	Accident Photo	1 Load JPG	<input checked="" type="checkbox"/>
10	11/12/17 10:03	Accident Photo	1 Load JPG	<input checked="" type="checkbox"/>
11	11/12/17 10:03	Accident Photo	1 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	MBM Wheelpower Pte Ltd (HQ)	Thumbnail	Print
1	11/12/17 09:59	Sketch Plan	1 Load TIF	
2	11/12/17 09:59	Sketch Plan #2	1 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT117023682/KVD3E2

Date: 14/03/2018

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN1762791700

Claimant Vehicle No: SLU1599E Insured Vehicle No: XD4518S

Date of Loss: 09/12/2017 Nature of Claim: TP Claim No: SNM17D07059C02/8

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLU1599E**

Make & Model: TOYOTA C-HR HYBRID, 1.8 S CVT (A) Engine No: 2ZR8164701

Reg. Date: 23/11/2017 (Man. Year: 2017) Chassis No: ZYX102062988

Colour: Metallic Maroon Odometer: 4687 km

Engine Capacity: 1797 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50 R18 Rear Tyre Size: 225/50 R18

Front Left Side: Michelin 9 mm Rear Left Side: Michelin 9 mm

Front Right Side: Michelin 9 mm Rear Right Side: Michelin 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,920.00	2,860.00	3,060.00	51.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,020.00	1,500.00	1,520.00	50.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,940.00	4,360.00	4,580.00	51.23
+ GST 7.00/7.00% (S\$)	625.80	305.20	320.60	51.23
Nett Amount (S\$)	9,565.80	4,665.20	4,900.60	51.23

INSPECTION

Date of Assignment: 13/12/2017

Date Inspected: 15/12/2017 Inspected At: MBM Wheelpower Pte Ltd (HQ)
160 SIN MING DRIVE #06-02, SIN MING AUTOCITY
Singapore 575722

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference**

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Mar 2018)
Parts:	M1-SUV	TOYOTA C-HR HYBRID 1.8 S CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLU1599E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	1,650.00 FL	*890.00 FL
2	1		*REAR BUMPER LOWER COVER	Dented / Cut	420.00 FL	*320.00 FL
3	10		*REAR BUMPER CLIPS	Necessary	65.00 FL	*65.00 FL
4	1		*REAR LOWER COVER TOWING HOOK COVER	Scratched	35.00 FL	*35.00 FL
5	1		*REAR INFORCEMENT	Buckled	400.00 FL	*310.00 FL
6	1		*REAR BUMPER RH PLATE	Serviceable	120.00 FL	*- FL
7	1		*TAILGATE	Bent	1,500.00 FL	*1,200.00 FL
8	1		*TAILGATE LOCK	Repair	480.00 FL	*- FL
9	1		*TAILGATE TOP & LOWER GARNISH	Serviceable	1,350.00 FL	*- FL
10	1		*END PANEL	Bent	800.00 FL	*640.00 FL
11	1		*NUMBER PLATE & HOLDER	Serviceable	80.00 FS	*- FS
12	2		*REAR BUMPER SENSORS	Serviceable	300.00 FS	*- FS
13	1		*WINDSCREEN SEALANT	Necessary	200.00 FS	*40.00 FS
14	1		*END PANEL TOP GARNISH	MTG Cracked	300.00 FL	*300.00 FL

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (S\$)	7,700.00	3,800.00
- List Item Discount on L Items 25.00/25.00% (S\$)	1,780.00	940.00
Total Parts (S\$)	5,920.00	2,860.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS. INCLUDING TO KNOCK-OUT, STRAIGHTEN, ON THE AFFECTED PARTS	New	1,000.00	600.00
2	TO REMOVE & REFIT TAILGATE WINDSCREEN TO FACILITATE REPAIR	New	200.00	120.00
3	TO REMOVE, REFIT & UPHOLSTERY TO FACILITATE REPAIRS	New	100.00	60.00
4	TO REMOVE & REPLACE BUMPER SENSORS	New	40.00	40.00
5	TO CHECK & RECONNECT ALL NECESSARY WIRING	New	80.00	20.00
6	TO SPRAY PAINTING ON THE REAR BUMPER, TAILGATE, END PANEL, TAILGATE TOP & LOWER GARNISH	New	1,600.00	660.00
Gross Labour Cost (S\$)			3,020.00	1,500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >