

QUOTATION FOR VEHICLE RD 6146 P

PARTS				
1	1	FRONT BUMPER	<i>Butler</i> \$	1,262.64 ✓
2	1	FRONT BUMPER SIDE BRACKET (RH)	\$	<i>Di</i> 28.56 ✓
3	1	FRONT HEADLAMP (RH)	\$	<i>Di</i> 1,388.40 ✓
4	1	FRONT FENDER (RH) <i>(Fabric)</i>	<i>CMA</i> \$	742.80 ✓
		SUB TOTAL	\$	3,422.40
		LESS 10%	\$	342.24
		DISCOUNTED SUB TOTAL	\$	3,080.16
S/NETT				
1	1	FRONT BUMPER SENSOR (1 SET of 4)	\$	<i>Di</i> 337.00 X
2	1	FRONT NUMBER PLATE	\$	<i>Di</i> 40.00 ✓
3	1	FRONT NUMBER PLATE SCREW	\$	<i>Di</i> 25.00 ✓
		SUB TOTAL	\$	402.00
LABOUR				
1		PANEL BEATING	\$	480.00 <i>360</i>
2		SPRAYPAINTING CHARGES	\$	480.00 <i>400</i>
3		WIRING CHARGES	\$	30.00 <i>20</i>
4		REMOVE/REFIX FRONT BUMPER SENSOR	\$	100.00 <i>80</i>
		SUB TOTAL	\$	1,090.00
		GRAND TOTAL	\$	<u>4,572.16</u>

PLEASE NOTE THAT THE ABOVE IS ONLY AN ESTIMATE.
THEREFORE SHOULD THERE BE ANY ADDITIONAL PARTS
REQUIRE OR DISCOVER DAMAGE DURING OUR COURSE OF
REPAIRS. WE WOULD INFORM YOU ACCORDINGLY FOR THE
NECESSARY ACTIONS. PRICES OF PARTS QUOTED ARE
SUBJECT TO CHANGE WITHOUT NOTICE.

SOON HOCK MOTOR PTE LTD
Blk 10 Ang Mo Kio Industrial Park 2A
#01-05/06 AMK Autopoint
Singapore 568047
Tel: 6483 6016 (3 Lines) Fax: 6483 6016
(Co. Reg. No. 199804869H)

Not Notified
U/Sy &?
Return After Repair
2 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: