| 15/5/2010 INS. CASE OWNER: | Cynthia | CC 3 ASTA | 7684,6 | - \$65 SZ ILKK: IDAC: | |
|------------------------------------------|--------------------|------------------------------------------------------|------------------------------|---------------------------------------------------------|-----------------------|
| 10. CASE OFFICIAL | Esc | ASSIGNM DOI: | 12/1/2 | Date / Time : (\(\sum_{\ell}\)) | 19 |
| Surveyor: | (30 | DOI. | 1 | Registered in Merimen: | |
| Pre-assign/CCU/ | | vuutaa ara-aattu v | | . STWOUTES | 1 22028 |
| Insured Vehicle No. | | 75224 | Claim No. | 1 HALL8 | |
| Name of Insured | TAN SWEE | 2 | Policy No. | : NISSAM | Alott . |
| Insured Tel No. | * | HP: 97609477 D.O.A: 00 17 19 15 | Make / Model Place of Accide | aver at 1 | ANTONMENT RO |
| Excess Sec II :S\$ Is driver the owner? | (YES)/NO) | Nature of Accident : | Place of Accide | tep | |
| If NO, Driver Name | _ | | | TYES / NO ; TP GIA R | EPORT: YES / NO |
| Driver Tel N | | (V/L:YES/NO) | Insured Liability | y: % Final | ? Yes/No |
| SHC 4629 | <u>T</u> — — | | | | |
| INSRS: THA | NSRS: | | INSRS: WSP: | 6 4 | INSRS: WSP: |
| Tel: | Nh Tel: | B-A | Tel: Liability: | n n | Tel : Liability : |
| Liability: | RMKS | 1/6 - 1/1 | RMKS: | | RMKS: |
| Date/Time | | | | | DATE / PIC |
| 15/11/17 | SPIC IS BOURT - NO | 1 1 | 11. | STAGE Non-Reporting ltr (1st): | DATE/FIC |
| 11.7 | suffame ma | MILL CHIMOGRAMANA | 2 MENTING | Non-Reporting ltr (2nd): Non-Reporting ltr (Final): | |
| un (| t gmart daim | | | Notification ltr (if non-picku Call OI: | p): |
| * | | | | After call ltr to OI: | 61.01/10 |
| 171 | it his obtain ev | idenu." | | Documentation Check List | |
| 23/1/18@3.5al | wa Couland OI I | Mr Tan. Confirm a | crident. | Notification ltr (if non-picku After call ltr to OI: | |
| 15 1100 3.34 | Both morres | urning Novideul | erdenu. | Authorisation To Act: | |
| | Adused him'r | the 17150 race H | He agreed | Release Voucher: | |
| ¥. | to let inche | nie oette x au | re MCD | Final Repair Bill: Car Rental Invoice: | |
| T | . 92221 | | | Towing Invoice | |
| 13/14/8 - | DV SOAT DECE | IVED 2 8 NOV 201 | 9 | LTA / GIA : | |
| 161.11 | Classic de | shu kei tu clar. | 0 | Medical Bill: PIR: | |
| 18/11/10 - | HO parson | AND GE ISH YOUR | | Mulate/Reject Instruction | on: |
| | | | | LOD | |
| C | Date/Time: \VIII | VY Sent By: | | Payment Breakdown For Post-Repair Photos: | m: |
| PRELIMINARY ADVICE | Date/Time: cq[t/t | Ty Selli Dy. Wy | | Others: | |
| FINALIZATION | Date Time: | Confirm with: | | Confirm by: | |
| Repair Cost: | SS SOLIDITO | days) Reduction: | % | Email Call | Call |
| First Liability: | Date/Time: (A) | Confirm with / Assessed) BOLA S/N No. : | 11 | If NO or B 28, Ass. Lia: | |
| Remair Cost: 3312.W | ss 65850 | | | | |
| Loss of Rental (LOR)300. 2 | 8ss 152.19 (3 | 4 days) × \$ 101.46 | | COMPY 9 | SWA |
| Loss of Use (LOU): | SS 75.W (SSU x | days) | | Lo MIW | |
| DOR only LOU only | LOR + LOU L | OR + LOI [Tick only one |] | | |
| GIA/LTA Search | ss 2-32 | | | 1) Claim status: Normal/ | Reject/Private Settle |
| Medical: Disbursement: | ss – | (e.g. Tow/ Independer | nt) | 2) Report Format: | |
| Leggi Cost | ss - | 10 | | 3) Survey fee: | |
| Total: | SS\S'9\.07 | Global Sum S\$: \\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ | 7 | Email Call | |
| Fi AL PAYMENT Payee 1: | SS (8W-U0 | Name 1: Trans- cob & | Be Auth San | | |
| Payee 1: Payee 2: (Strike if N.A.) | SS | Name 2: | | 100.00 | |
| Payee 3: (Strike if N.A.) | SS | Name 3: | | | |
| 14 F | | | | | |
| 1- | | | | | |
| Witten Unite | | | | | |
| 100 | | | | | |



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| | | Affiliated to Federation In | ternationale Des Experts En Autom | obile |
|-----|---------------------------------|------------------------------------------|--------------------------------------------------------|----------------------|
| AXA | INSURANCE PTE | LTD | Ref : CC3/AXA17023 | 684/Kpb3 |
| | HENTON WAY #24- TOWERSINGAPO | | Date: 13-12-2017 Code: AXA2 | |
| 1. | | Policy Partic | ulars :- THIRD PARTY CLAI | M |
| | Insured Veh. | SLJ 7522U | Veh. Inspected | SHC 5629T |
| | Policy No. | | Coverage (\$) | 0.00 |
| | Claim No. | | Excess (\$) | 0.00 |
| | Assign From | | Assign Date | 13/12/2017 |
| 2. | | Vehicle | Particulars & Condition | |
| | Make & Model | | c.c | 0 |
| | Engine No. | HIDDEN | Year of Reg. | |
| | Chassis No. | | Colour | |
| | Odometer - Steering | | | |
| | Brakes Modification | | | |
| | General | | | |
| 3. | | | Conditions of Tyres | |
| | | Size | Make | Balance |
| | R/H Front Tyre | | | mm |
| | L/H Front Tyre | | 1 | mm |
| | R/H Rear Tyre | | | mm |
| | L/H Rear Tyre | 4. 1 | 9 | mm |
| 4. | | De | scription of Damages | MANAGEMENT OF |
| 5. | | | General Information | |
| J. | Accident Date | 09/12/2017 | Inspection Date | 12/12/2017 |
| | Survey held at | TRANS-CAB AUTO SER | | 2012 2137 (00/00/20 |
| | Survey field at | NO.2 ANG MO KIO ST 6 SINGAPORE 569111 | | |
| 5a. | | | Remarks | |
| | A)THE INSPECTION | ON WAS CONDUCTED O | N A"WITHOUT PREJUDICE" BAS ONS, WE HAVE NOT AUTHORI | SIS. SED REPAIRS. |

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111 TEL NO. 6287 6666 FAX NO. 6257 1330 CO/GST REG NO. 201019626G

SHC5629T - AXA

Vehicle No.: Chassis No.: Vehicle Make: Vehicle Model: Date of Accident: Third Party Insurer: Not Northerns 218m & 310cl

SHC5629T - CANDY

VF1ABL15AUC279628 RENAULT LATITUDE

09.12.2017

AXA

| | | PART | | LIST |
|----|---|---------------------------------|----|-------------------------|
| 1 | 1 | BUMPER COVER FRT | \$ | Bu 1,259.42 — |
| 2 | 1 | BUMPER ABSORBER FRT | 5 | Jh 394.68 X |
| 3 | 1 | BUMPER BEAM FRT | S | 77 914.08 X |
| 4 | 1 | BUMPER SPOILER FRT | S | J _⊆ 181.75 × |
| 5 | 1 | BUMPER GRILLE LOWER FRT | S | Ju 266.80 X |
| 6 | 1 | BUMPER FOG LAMP GRILLE RH | S | ∫ 207.22 ✓ |
| 7 | 1 | BUMPER RETAINER FRT RH | \$ | suc 12-y 151.41 X |
| 8 | 1 | BUMPER BRACKET FRT RH | S | /7 181 75 Å |
| 9 | 1 | HEADLAMP RH | s | M31 Pt 1,184.43 |
| 10 | 1 | HEADLAMP PANEL FRT RH | s | R 152.15 X |
| 11 | 1 | FENDER PANEL FRT RH | S | By 783.83 |
| 12 | 1 | FENDER INSULATOR RH | \$ | SL 130.84) |
| 13 | 1 | FENDER BRACKET FRT RH | s | n 34.14 |
| 14 | 1 | WHEELARCH FRT RH | s | 5 278.84 |
| 15 | 1 | WIPER RESERVOIR | S | Ju 348.25 |
| 16 | 1 | WIPER RESERVOIR NECK | s | 136.11 |
| 17 | 1 | WIPER RESERVOIR MOTOR | s | July 270.06 |
| 18 | 1 | RADAITOR GRILLE | 5 | ∫ ₄ 1,707.78 |
| 19 | 1 | RADAITOR GRILLE BADGE 'RENAULT' | 5 | الم 173.36 \ |
| 20 | 1 | RADAITOR GRILLE FRAME | s | JL 1,353.75 X |
| 21 | 1 | FRAME FULL SUPPORT PANEL | s | Sec 615.90 |
| 22 | 1 | FRAME FULL SUPPORT BRACKET | S | 77 89.79 |
| 23 | 1 | BONNET | s | 7 1,941.63 |
| 24 | 1 | BONNET HINGE RH | S | 7 348.31 |
| 25 | 1 | BONNET STRUT RH | s | N 88.61 |
| 26 | 1 | LOWER ARM RH | s | Su 685.76 |
| 27 | 1 | KUNCKLE ARM RH | s | Fin 846.98 |
| 28 | 1 | ABSORBER FRT RH | S | JL 360.54 |
| 29 | 1 | WHEEL HOUSING PANEL FRT RH | s | 7 4,682.09 |
| 30 | 1 | DOOR PANEL FRT RH | s | /7 2,844.66 |
| 31 | 1 | DOOR HINGE UPPER RH | s | 77 274.50 |
| 32 | 1 | DOOR HINGE LOWER RH | s | N 300.55 |
| 33 | 1 | DOOR CHECK FRT RH | \$ | 194.77 |
| 34 | 1 | DOOR MOULDING FRT RH | \$ | 7 176.82 |

| | | AB AUTO SERVICES PTE LTD | | AAD1712-087 |
|----|-------|---------------------------------------------------|----|---------------|
| | | MO KIO ST63 SINGAPORE 569111 | | |
| | | 87 6666 FAX NO. 6257 1330 EG NO. 201019626G | | |
| | | - AXA | | |
| | 00020 | | | |
| 35 | 1 | DOOR MIRROR RH | \$ | Ju 1,483.40 |
| 36 | | DOOR MIRROR GLASS RH | S | Ju 148.20 |
| 37 | | DOOR MIRROR BACK COVER RH | \$ | 5 218.46 |
| 38 | | DOOR WHETHERSTRIP FRT RH | S | Sm 474.21 () |
| 39 | 1 | DOOR SEAL FRT RH | \$ | Jh 68.67 |
| 40 | | ROCKER PANEL OUTER RH | S | R 987.49 |
| 41 | | DOOR PANEL REAR RH | \$ | A 2,844.66 |
| | | TOTAL | \$ | 29,786.65 |
| | | 10% | \$ | 2,978.66 |
| | | | \$ | 26,807.98 |
| | | Specical Nett | | |
| 1 | 1SET | WHEELARCH CLIP FRT RH | \$ | nn 66.00 X |
| 2 | 1SET | FRONT BUMPER CLIP | S | NE 66.00 _ |
| 3 | 1 | RIM RH FRT | \$ | 5 385.00 ✓ |
| 4 | 1 | TYRE RH FRT | \$ | Sm 330.00 ⊀ |
| 5 | 1 | DOOR STICKER "Trans-cab" | \$ | 1 € 80.00 × |
| 6 | 1 | DOOR STICKER "Classic" | \$ | 22 30.00 X |
| 7 | 1 | DOOR STICKER "6555-3333" | \$ | 22 80.00 X |
| | | TOTAL | \$ | 1,037.00 |
| | | TOTAL PARTS | \$ | 27,844.98 |
| | | | \$ | 170.00 2 2/ |
| | | To Check Electrical Lighting Concerned. | J. | 170.00 20/ |
| | | Panel beating, knocking and straightening the | | 9 |
| | | necessary portion, remove and renewal of parts, | 22 | 4001 |
| | | adjust and realign the same | \$ | 4,200.00 |
| | | Towing fees | \$ | NO 120.00 X |
| | | Putty and spray painting of the affected portion. | \$ | 4,500.00 4401 |
| | | To Transfer Of Fender Fittings, Attachments And | | 4 45000 Y |
| | | Perform Water Seepage Test. | \$ | 1 170.00 X |
| | | To transfer of tire, rim and on wheel balancing. | S | 170.00 X |
| | | To check steering geometry and computer wheel | 2 | |
| | | alignment | S | Na 220.00 X |

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111 TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5629T - AXA

| Over All Total | \$ | 38,284.98 |
|-----------------------------------------------------------------------------------------------|----|-------------|
| TOTAL | \$ | 10,440.00 |
| To dismantle and refit front end suspension, undercarriage parts, final checking and testing. | S | れん 380.00 X |
| To rust-proofing of the affected areas. | \$ | 170.00 30 |
| To transfer of door fittings, attachment and perform water seepage test. | S | 22 170.00 X |
| To Remove And Refit Front W/Screen Glass To Facilitate Bodywork Repair. | \$ | NN 170.00 X |

(PARTS BY PARTS) Repair Days

AAD1712-087

15 Days

Hsiao Tong (LKKAuto)

From:

Hsiao Tong (LKKAuto)

Sent:

Tuesday, 23 January 2018 3:58 PM

To:

'jasminetan@transcab.com.sg'; 'Zhe Wei' (zhewei.kek@transcab.com.sg); 'Ng Wai

Yin'; claims@transcab.com.sg

Subject:

<Request for Evidence> Your ref: SHC 5629T *Our Ref: CC3/ASM17023684/Kpb3

[ACCIDENT INVOLVING SLJ 7522U(AXA) & SHC 5629T ON 09/12/2017]

Attachments:

STATEMENT OF SLJ 7522U.pdf

Your ref: SHC 5629T

WITHOUT PREJUDICE

Our Ref: CC3/ASM17023684/Kpb3

Dear Sir/Madam,

ACCIDENT INVOLVING SLJ 7522U(AXA) & SHC 5629T ON 09/12/2017

We refer to the above matter.

Please be informed that liability is unclear. Our insured driver reported that he was turning right at the junction of Cantonment Road and Keppel Viaduct, suddenly he felt an impact on his left side of his car. Attached here with a copy of our insured driver accident report for your easy reference.

Kindly let us have evidences (ie: video footage/ scene photos / PIR) in order for us to look into the matter.

Appreciate an early reply.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Hsiao Tong (LKKAuto)

From:

Ng Wai Yin <waiyin.ng@transcab.com.sg>

Sent:

Tuesday, 23 January 2018 5:26 PM

To:

Hsiao Tong (LKKAuto)

Cc:

'Jasmine Tan'; 'Zhe Wei'; claims@transcab.com.sg

Subject:

RE: <Request for Evidence> Your ref: SHC 5629T (AAD1712-087) *Our Ref:

CC3/ASM17023684/Kpb3 [ACCIDENT INVOLVING SLJ 7522U(AXA) & SHC 5629T

ON 09/12/2017]

Attachments:

SHC5629T 11.12.2017 - Witness Statement.pdf

WITHOUT PREJUDICE


Dear Hsiao Tong

Sorry we do not have video footage for this captioned accident.

However we attach the witness statement for your investigation.

Brief Details.

On 9/12/2017 at 1645hrs, I was stationary on the 2nd lane of a 3 lane road along Cantonment road due to red traffic. I was at the X junction of Cantonment Road and I intend to turn right onto Keppel Road. When the traffic turned green, I proceeded and made the right turn. Suddenly, I felt an impact from the back. Vehicle SLJ7522U which travelling on the 1st lane collided onto the right rear all the way to the front of myvehicle. I suspect that the driver wanted to proceed straight into PSA Gantry and collided onto my vehicle however the driver deny that he wanted to turn right into Keppel Road. One of the passenger in my vehicle complained of giddiness and shoulder pain.



Thank You Best Regards, Ng Wai Yin Finance Department TEL: 6603 1265 Ext.308

*** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg



TRANS-CAB SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63, Singapore 569111 Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764

Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Hsiao Tong (LKKAuto) [mailto:chewht@lkkauto.com]

Sent: Tuesday, 23 January, 2018 3:58 PM

To: 'jasminetan@transcab.com.sg' <jasminetan@transcab.com.sg>; 'Zhe Wei' (zhewei.kek@transcab.com.sg)

<zhewei.kek@transcab.com.sg>; 'Ng Wai Yin' <waiyin.ng@transcab.com.sg>; claims@transcab.com.sg

Subject: <Request for Evidence> Your ref: SHC 5629T *Our Ref: CC3/ASM17023684/Kpb3 [ACCIDENT INVOLVING SLI

7522U(AXA) & SHC 5629T ON 09/12/2017]

Your ref: SHC 5629T

WITHOUT PREJUDICE

Our Ref: CC3/ASM17023684/Kpb3

Dear Sir/Madam,

ACCIDENT INVOLVING SLJ 7522U(AXA) & SHC 5629T ON 09/12/2017

We refer to the above matter.

Please be informed that liability is unclear. Our insured driver reported that he was turning right at the junction of Cantonment Road and Keppel Viaduct, suddenly he felt an impact on his left side of his car. Attached here with a copy of our insured driver accident report for your easy reference.

Kindly let us have evidences (ie: video footage/ scene photos / PIR) in order for us to look into the matter.

Appreciate an early reply.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: <u>chewht@lkkauto.com</u> | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933) Reporting about accident at Keppel Road: We were travelling in Taxi (Just Grab) SHC 5629 Twe were in the second lane and turning to Keppel Road. The driver in the first lave (5LJ 75224) cut across and come into our lane banging the right side of the Just Grab Time this bappened was 4-45 pm I was travelling with my wife and daughter who were seated in the back. My daughter who was seated on the back right had a jerk - neck area and right hand side. acceded Mender Mohamed Hurrain Abdul Khader S 2186174Z



<SEEK MANDATE> - S7M005ES [ACCIDENT INVOLVING SLJ 7522U(OI) & SHC 5629T(TP) ON 09/12/2017]

Type

Q Question

Message

Liability: 50%. Both parties had given a conflict of verison. No video/ concrete evidence from both parties. Inform OI about third party claim. Agreed to settle and aware NCD issue. We seek your mandate up to 50% - \$1,891.04(all-in), IA with mandate had been uploaded in Smartclaims. Kindly let us have your approval/instruction. Hsiao Tong - 18 Aug 2018



51 UBLAVE 1, 802-25 PAVA UBUINDUSTRIAL PARK, SINGAPORE 408933 TEL; (065) 62563561 FAX: (065) 62564315

Immediate Advice

To: AXA Insurance Pte Ltd Date: 18.08.2018

Survey Details:

| Date of loss | 09.12.2017 |
|---------------------|---------------------------------|
| Date of appointment | 12.12.2017 |
| Date of survey | 12.12.2017 |
| Location of survey | TRANS-CAB AUTO SERVICES PTE LTE |

Vehicle Details:

| Claim Type: | Third party |
|----------------------|---------------------------|
| Vehicle number | SHC 5629T |
| Make and Model | Renault Latitude (1995cc) |
| Date of registration | 04.11.2014 |
| Excess | NIL |
| Market Value | |
| Parf/COE Rebate | |
| Nett Loss | |

Repair details:

| Initial Estimate | \$ 38,284.98 |
|------------------|-----------------|

Proposed/Revised repair cost:

| Parts | \$ | 2,970.91 |
|-------------------------|-----|----------|
| Check items (estimate) | NIL | |
| Labour | \$ | 890.00 |
| Supplementary | NIL | |
| Total | \$ | 3,860.91 |
| Lump Sum(if applicable) | \$ | 3,100.00 |

| Number of days for repair | <u>2</u> |
|---------------------------|----------|



51 UBI AVE 1, #02-25 PAVA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL; (065) 62563561 FAX; (065) 62564315

Date: 18.08.2018

Remarks:

| Both parties had given a conflict of verison. No video/ concrete evidence from both parties. | |
|----------------------------------------------------------------------------------------------|--|
| | |
| | |
| | |

Mandate:

| Liability(TP) | 50% | |
|------------------------------|----------------|--------------------|
| Proposed repair cost (w/GST) | \$ 3,317.00 | |
| Loss of use | NIL | |
| Loss of rental | \$ 304.38 | (3days x \$101.46) |
| Loss of income | \$ 150.00 | (3days x \$50.00) |
| | \$ 3,771.38 | |
| @ 50% | \$ 1,885.69 | |
| LTA/GIA search fees | \$ 5.35 | |
| Others | NIL | |
| Proposed Total | \$ 1,891.04 | |



Re:RE: <SEEK MANDATE> - S7M005ES [ACCIDENT INVOLVING SLJ 7522U(OI) & SHC 5629T(TP) ON 09/12/2017]

Type

Q Question

Message

MANDATE APPROVED

Reply

Hsiao Tong (LKKAuto)

From: Jasmine Tan <jasminetan@transcab.com.sg>

Sent: Monday, 8 October 2018 11:02 AM
To: Hsiao Tong (LKKAuto); 'Ng Wai Yin'

Cc: 'Zhe Wei'; claims@transcab.com.sg

Subject: RE: <Request for Evidence> Your ref: SHC 5629T (AAD1712-087) *Our Ref:

CC3/ASM17023684/Kpb3 [ACCIDENT INVOLVING SLJ 7522U(AXA) & SHC 5629T

ON 09/12/2017]

Without Prejudice

Dear Hsiao Tong

Please proceed to send us the DV.

Thank you Best Regards Jasmine Tan



TRANS-CAB SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63, Singapore 569111 Main Line :(65) 6287 6666 Fax Line: (65) 6257 1330

Direct Line :(65) 6603 1250 Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet

From: Hsiao Tong (LKKAuto) [mailto:chewht@lkkauto.com]

Sent: Thursday, 4 October 2018 11:55 AM

To: Ng Wai Yin <waiyin.ng@transcab.com.sg>

Cc: 'Jasmine Tan' <jasminetan@transcab.com.sg>; 'Zhe Wei' <zhewei.kek@transcab.com.sg>;

claims@transcab.com.sg

Subject: RE: <Request for Evidence> Your ref: SHC 5629T (AAD1712-087) *Our Ref: CC3/ASM17023684/Kpb3

[ACCIDENT INVOLVING SLJ 7522U(AXA) & SHC 5629T ON 09/12/2017]

Without Prejudice

Hi Wai Yin,

We refer to the above matter.

We are of the opinion that this is a case of conflicting versions. There is no concrete evidence (ie: Video footage) yet to support either party's version. Enclosed herewith in this email is a copy of our insured's accident report for your perusal.

Strictly without admission of liability whatever, but with a view towards a resolutions of your client's claim in the above matter without resort to litigation, we propose settlement at a global sum of \$1,800.00(all-in).

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>

Sent: Tuesday, 23 January 2018 5:26 PM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Cc: 'Jasmine Tan' < jasminetan@transcab.com.sg >; 'Zhe Wei' < zhewei.kek@transcab.com.sg >;

claims@transcab.com.sg

Subject: RE: <Request for Evidence> Your ref: SHC 5629T (AAD1712-087) *Our Ref: CC3/ASM17023684/Kpb3

[ACCIDENT INVOLVING SLI 7522U(AXA) & SHC 5629T ON 09/12/2017]

WITHOUT PREJUDICE


Dear Hsiao Tong

Sorry we do not have video footage for this captioned accident.

However we attach the witness statement for your investigation.

Brief Details.

On 9/12/2017 at 1645hrs, I was stationary on the 2nd lane of a 3 lane road along Cantonment road due to red traffic. I was at the X junction of Cantonment Road and I intend to turn right onto Keppel Road. When the traffic turned green, I proceeded and made the right turn. Suddenly, I felt an impact from the back. Vehicle SLJ7522U which travelling on the 1st lane collided onto the right rear all the way to the front of my vehicle. I suspect that the driver wanted to proceed straight into PSA Gantry and collided onto my vehicle however the driver deny that he wanted to turn right into Keppel Road. One of the passenger in my vehicle complained of giddiness and shoulder pain.



Thank You Best Regards, *** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg



TRANS-CAB SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63, Singapore 569111 Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764

Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Hsiao Tong (LKKAuto) [mailto:chewht@lkkauto.com]

Sent: Tuesday, 23 January, 2018 3:58 PM

To: 'jasminetan@transcab.com.sg' <<u>jasminetan@transcab.com.sg</u>>; 'Zhe Wei' (<u>zhewei.kek@transcab.com.sg</u>) <zhewei.kek@transcab.com.sg>; 'Ng Wai Yin' <waiyin.ng@transcab.com.sg>; claims@transcab.com.sg

Subject: <Request for Evidence> Your ref: SHC 5629T *Our Ref: CC3/ASM17023684/Kpb3 [ACCIDENT INVOLVING SLJ

7522U(AXA) & SHC 5629T ON 09/12/2017]

Your ref: SHC 5629T

WITHOUT PREJUDICE

Our Ref: CC3/ASM17023684/Kpb3

Dear Sir/Madam,

ACCIDENT INVOLVING SLJ 7522U(AXA) & SHC 5629T ON 09/12/2017

We refer to the above matter.

Please be informed that liability is unclear. Our insured driver reported that he was turning right at the junction of Cantonment Road and Keppel Viaduct, suddenly he felt an impact on his left side of his car. Attached here with a copy of our insured driver accident report for your easy reference.

Kindly let us have evidences (ie: video footage/scene photos / PIR) in order for us to look into the matter.

Appreciate an early reply.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

| Vehicle No: | SLJ 7522U (Insd veh) | | Model: | RENAULT LATITUDE (A) | |
|-------------------------|------------------------------|----------|-----------------------|--------------------------------|--|
| | SHC 5629T (TP veh) | | | | |
| Date of Accident: | 09/12/2017 | | | | |
| | | | | - | |
| Global Sum Settlem | ent : [X] Yes | T | [] No | | |
| Repair Estimate | | : \$ | 40,964.93 | | |
| Final Repair Cost | | : \$ | 3,317.00 | | |
| Loss of Token Sum | | : \$ | 150.00 | 3 days at \$50.00 per day | |
| Rental (if any) | | :\$ | 304.38 | 3 days | |
| @50% | | :\$ | 1,885.69 | | |
| LTA / GIA Search F | ee | : \$ | 5.35 | | |
| Others: | | : \$ | | | |
| | | : \$ | | | |
| Final Settlement Su | m (GLOBAL SUM) | : \$ | 1,800.00 | | |
| Is Third Party Wor | kshop GIA Registered | ? | [] YES [) | X] NO (Kindly indicate | |
| A) For Non GIA R | egistered Workshop: | | Agreed Liability _ | 50(%) | |
| B) For GIA Regist | tered Workshop: | | BOLA Applicable: | Yes/ No BOLA Scenario No: | |
| BOLA Liability : | (%) | | Assessed Liability | y (*):(%) | |
| * Assessed Lia | bility to be filled only for | chair | collisions and for ca | ses where BOLA does not apply. | |
| Remarks PLEASE SE | ND THE CHEQUE PAYM | IENT | TO TRANS-CAB AUTO | SERVICES PTE LTD | |
| | NO.2 ANG MC | KIO | ST 63 SINGAPORE 56 | 9111 | |
| | | | | | |
| Payment Instruction | on: Payee's Breakdowi | n | | | |
| 1) TRANS-CAB | AUTO SERVICES PTE I | LTD | : \$ | 1,800.00 | |
| | | - D 1/2/ | | | |
| | ILAH BTE ABDOL VAHAB | | 23/11/2018 | | |
| | 77 10 // 1900 | | Date | | |

Please attach all the supporting documents to the form. (Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any)



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| | | Affiliated to Federation Interna | tionale Des Experts En Autom | nobile | |
|-----|---------------------------------------------------------|-----------------------------------------------------|------------------------------|-----------------------------------------|--|
| AXA | XA INSURANCE PTE LTD | | Ref : CC3/ASM17023684/Kpb3s2 | | |
| | | | | | |
| | ENTON WAY #24- | | Date: 23-11-2018 | | |
| | TOWERSINGAPO | DRE 068811 | Code: ASM | | |
| | N: CYNTHIA LOH | Policy Portions | | W | |
| | Insured Veh. | SLJ 7522U | rs :- THIRD PARTY CLAI | SHC 5629T | |
| | Policy No. | GA148919/1 | Coverage (\$) | 0.00 | |
| | P. (5-7. N. V.) . (1. (1. (1. (1. (1. (1. (1. (1. (1. (| S7M005ES | | 0.00 | |
| | Claim No. | 37MI003E3 | Excess (\$) | 12/12/2017 | |
| | Assign From | | Assign Date | 12/12/2017 | |
| 2. | | | rticulars & Condition | | |
| | Make & Model | RENAULT LATITUDE (A) | c.c | 1995 | |
| | Engine No. | HIDDEN | Year of Reg. | 2014 | |
| | Chassis No. | VF1ABL15AUC279628 | Colour | METALLIC WHITE / RED | |
| | Odometer | 499663 | Steering | IN ORDER | |
| | Brakes | IN ORDER | Modification | NIL | |
| | General | GOOD | | | |
| 3. | | Cond | ditions of Tyres | | |
| | | Size | Make | Balance | |
| | R/H Front Tyre | 215/60R16 | LING LONG | 5 mm | |
| | L/H Front Tyre | 215/60R16 | LING LONG | 5 mm | |
| | R/H Rear Tyre | 215/60R16 | LING LONG | 6 mm | |
| | L/H Rear Tyre | 215/60R16 | LING LONG | 6 mm | |
| ١. | | Descrip | otion of Damages | | |
| | THE VEHICLE SU | STAINED DAMAGES AT THE C | O/S FRONT PORTION. | | |
| | DAMAGES SEE D | FTAII S | | | |
| 5. | D7.1111 (020 022 0 | | eral Information | | |
| | Accident Date | 09/12/2017 | Inspection Date | 12/12/2017 | |
| | Survey held at | TRANS-CAB AUTO SERVICE | ES PTE LTD | 20 000 00 000 000 000 00 000 00 000 000 | |
| | | NO.2 ANG MO KIO ST 63 SINGAPORE 569111 | | | |
| 5a. | | | Remarks | | |
| | | ON WAS CONDUCTED ON A"V CE TO YOUR INSTRUCTIONS, | | | |
| 5b. | | Estima | te Days of Repair | | |
| | ESTIMATED NOR | MAL PERIOD FOR REPAIR: | 2 Working Day | ys | |



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5629T

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|----------------------------------------------|-------------------------|-------------------------------|-------------------|
| | REPLACEMENT OF PARTS | 0: | | |
| 1 | BUMPER COVER FRT (CONSISTENT) | BUCKLED | 1,259.42 | 1,259.42 |
| 1 | BUMPER ABSORBER FRT (CONSISTENT) | SERVICEABLE | 394.68 | 7 |
| 1 | BUMPER BEAM FRT (CONSISTENT) | TO REPAIR SEE LABOUR | 914.08 | 5 |
| 1 | BUMPER SPOILER FRT (CONSISTENT) | SERVICEABLE | 181.75 | 8 |
| 1 | BUMPER GRILLE LOWER FRT (CONSISTENT) | SERVICEABLE | 266.80 | 8 |
| 1 | BUMPER FOG LAMP GRILLE RH (CONSISTENT) | SERVICEABLE | 207.22 | 3 |
| 1 | BUMPER RETAINER FRT RH (CONSISTENT) | SERVICEABLE | 151.41 | |
| 1 | BUMPER BRACKET FRT RH (CONSISTENT) | TO REPAIR SEE LABOUR | 181.75 | ä |
| 1 | HEADLAMP RH (CONSISTENT) | MTG CRACKED | 1,184.43 | 1,184.43 |
| 1 | HEADLAMP PANEL FRT RH (CONSISTENT) | TO REPAIR SEE LABOUR | 152.15 | 6 |
| 1 | FENDER PANEL FRT RH (CONSISTENT) | BENT | 783.83 | 783.83 |
| 1 | FENDER INSULATOR RH (CONSISTENT) | SERVICEABLE | 130.84 | 3 |
| 1 | FENDER BRACKET FRT RH (CONSISTENT) | TO REPAIR SEE LABOUR | 34.14 | 8 |
| 1 | WHEELARCH FRT RH (CONSISTENT) | SERVICEABLE | 278.84 | |
| 1 | WIPER RESERVOIR (CONSISTENT) | SERVICEABLE | 348.25 | |
| 1 | WIPRE RESERVOIR NECK (CONSISTENT) | SERVICEABLE | 136.11 | 5 |
| 1 | WIPER RESERVOIR MOTOR (CONSISTENT) | SERVICEABLE | 270.06 | |
| 1 | RADIATOR GRILLE (CONSISTENT) | SERVICEABLE | 1,707.78 | |
| 1 | RADIATOR GRILLE BADGE 'RENAULT' (CONSISTENT) | SERVICEABLE | 173.36 | 8 |
| 1 | RADIATOR GRILLE FRAME (CONSISTENT) | SERVICEABLE | 1,353.75 | * |
| 1 | FRAME FULL SUPPORT PANEL (CONSISTENT) | SERVICEABLE | 615.90 | |
| 1 | FRAME FULL SUPPORT BRACKET (CONSISTENT) | TO REPAIR SEE LABOUR | 89.79 | 9 |
| 1 | BONNET (CONSISTENT) | TO REPAIR SEE LABOUR | 1,941.63 | 5 |
| 1 | BONNET HINGE RH (CONSISTENT) | TO REPAIR SEE LABOUR | 348.31 | ê |
| 1 | BONNET STRUT RH (CONSISTENT) | TO REPAIR SEE LABOUR | 88.61 | 8 |

Report Ref No. CC3/ASM17023684/Kpb3s2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|---------------------------------------------|-------------------------|-------------------------------|-------------------|
| 1 | LOWER ARM RH (CONSISTENT) | SERVICEABLE | 685.76 | |
| 1 | KNUCKLE ARM RH (CONSISTENT) | SERVICEABLE | 846.98 | |
| 1 | ABSORBER FRT RH (CONSISTENT) | SERVICEABLE | 360.54 | |
| 1 | WHEEL HOUSING PANEL FRT RH (CONSISTENT) | TO REPAIR SEE LABOUR | 4,682.09 | , |
| 1 | DOOR PANEL FRT RH (CONSISTENT) | TO REPAIR SEE LABOUR | 2,844.66 | |
| 1 | DOOR HINGE UPPER RH (CONSISTENT) | TO REPAIR SEE LABOUR | 274.50 | 3 |
| 1 | DOOR HINGE LOWER RH (CONSISTENT) | TO REPAIR SEE LABOUR | 300.55 | |
| 1 | DOOR CHECK FRT RH (CONSISTENT) | SERVICEABLE | 194.77 | 5 |
| 1 | DOOR MOULDING FRT RH (CONSISTENT) | TO REPAIR SEE LABOUR | 176.82 | |
| 1 | DOOR MIRROR RH (CONSISTENT) | SERVICEABLE | 1,483.40 | |
| 1 | DOOR MIRROR GLASS RH (CONSISTENT) | SERVICEABLE | 148.20 | |
| 1 | DOOR MIRROR BACK COVER RH (CONSISTENT) | SERVICEABLE | 218.46 | |
| 1 | DOOR WEATHERSTRIP FRT RH (CONSISTENT) | SERVICEABLE | 474.21 | |
| 1 | DOOR SEAL FRT RH (CONSISTENT) | SERVICEABLE | 68.67 | |
| 1 | ROCKER PANEL OUTER RH (CONSISTENT) | TO REPAIR SEE LABOUR | 987.49 | |
| 1 | DOOR PANEL REAR RH (CONSISTENT) | TO REPAIR SEE LABOUR | 2,844.66 | |
| | LESS 10% DISCOUNT | CALLANA AND A CALLA | -2,978.67 | -322.77 |
| | | | 26,807.98 | 2,904.91 |
| | SPECIAL NETT ITEMS | | | |
| 1 | SET WHEELARCH CLIP FRT RH (SN) (CONSISTENT) | NOT NECESSARY | 66.00 | |
| 1 | SET FRONT BUMPER CLIP (SN) (CONSISTENT) | NECESSARY | 66.00 | 66.00 |
| 1 | RIM RH FRT (SN) (CONSISTENT) | SERVICEABLE | 385.00 | a |
| 1 | TYRE RH FRT (SN) (CONSISTENT) | SERVICEABLE | 330.00 | |
| 1 | DOOR STICKER "TRANS-CAB" (SN) (CONSISTENT) | NOT NECESSARY | 80.00 | |
| 1 | DOOR STICKER "CLASSIC" (SN) (CONSISTENT) | NOT NECESSARY | 30.00 | |
| 1 | DOOR STICKER "6555-3333" (SN) (CONSISTENT) | NOT NECESSARY | 80.00 | |
| | | | 1,037.00 | 66.00 |

Report Ref No. CC3/ASM17023684/Kpb3s2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|-------------------------------|-------------------|
| | LABOUR | | | |
| | TO CHECK ELECTRICAL LIGHTING CONCERNED. | | 170.00 | 20.00 |
| | PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF BUMPER BEAM FRT, BUMPER BRACKET FRT RH, HEADLAMP PANEL FRT RH, FENDER BRACKET FRT RH, FRAME FULL SUPPORT BRACKET, | | 4,200.00 | 400.00 |
| | BONNET, BONNET STRUT RH, BONNET STRUT RH, WHEEL HOUSING PANEL FRT RH, DOOR PANEL FRT RH, DOOR HINGE UPPER RH, DOOR HINGE LOWER RH, DOOR MOULDING FRT RH, ROCKER PANEL OUTER RH AND DOOR PANEL REAR RH. | | | |
| | TOWING FEES. | NOT NECESSARY | 120.00 | |
| | PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION. | | 4,500.00 | 440.00 |
| | TO TRANSFER OF FENDER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST. | NOT NECESSARY | 170.00 | |
| | TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING. | NOT NECESSARY | 170.00 | |
| | TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT. | NOT NECESSARY | 220.00 | 3 |
| | TO REMOVE AND REFIT FRONT W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR. | NOT NECESSARY | 170.00 | |
| | TO TRANSFER OF DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST. | NOT NECESSARY | 170.00 | |
| | TO RUST-PROOFING OF THE AFFECTED AREAS. | | 170.00 | 30.00 |
| | TO DISMANTLE AND REFIT FRONT END SUSPENSION , UNDERCARRIAGE PARTS, FINAL CHECKING AND TESTING. | NOT NECESSARY | 380.00 | 2 |
| | | | 10,440.00 | 890.00 |
| | GRAND TOTAL | | 38,284.98 | 3,860.91 |
| 48 | RECOMMENDED COST OF LUMP SUM REPAIRS | la reconstant | | 3,100.00 |

Report Ref No. CC3/ASM17023684/Kpb3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.