

TRANS-CAB AUTO SERVICES PTE LTD
 NO.2 ANG MO KIO ST63 SINGAPORE 569111
 TEL NO. 6287 6666 FAX NO. 6257 1330
 CO/GST REG NO. 201019626G
SHC5629T - AXA

AAD1712-087

Not Authored
21 Pm @ 310cl

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHC5629T - CANDY
 VF1ABL15AUC279628
 RENAULT
 LATITUDE
 09.12.2017
AXA

		PART		LIST
1	1	BUMPER COVER FRT	\$	<i>Bu</i> 1,259.42 ✓
2	1	BUMPER ABSORBER FRT	\$	<i>SL</i> 394.68 X
3	1	BUMPER BEAM FRT	\$	<i>R</i> 914.08 X
4	1	BUMPER SPOILER FRT	\$	<i>SL</i> 181.75 X
5	1	BUMPER GRILLE LOWER FRT	\$	<i>SL</i> 266.80 X
6	1	BUMPER FOG LAMP GRILLE RH	\$	<i>SL</i> 207.22 X
7	1	BUMPER RETAINER FRT RH	\$	<i>Dir</i> 151.41 X
8	1	BUMPER BRACKET FRT RH	\$	<i>R</i> 181.75 X
9	1	HEADLAMP RH	\$	<i>ms, R</i> 1,184.43 ✓
10	1	HEADLAMP PANEL FRT RH	\$	<i>R</i> 152.15 X
11	1	FENDER PANEL FRT RH	\$	<i>B</i> 783.83 ✓
12	1	FENDER INSULATOR RH	\$	<i>SL</i> 130.84
13	1	FENDER BRACKET FRT RH	\$	<i>R</i> 34.14
14	1	WHEELARCH FRT RH	\$	<i>SL</i> 278.84
15	1	WIPER RESERVOIR	\$	<i>SL</i> 348.25
16	1	WIPER RESERVOIR NECK	\$	<i>SL</i> 136.11
17	1	WIPER RESERVOIR MOTOR	\$	<i>SL</i> 270.06
18	1	RADAITOR GRILLE	\$	<i>SL</i> 1,707.78
19	1	RADAITOR GRILLE BADGE 'RENAULT'	\$	<i>SL</i> 173.36
20	1	RADAITOR GRILLE FRAME	\$	<i>SL</i> 1,353.75
21	1	FRAME FULL SUPPORT PANEL	\$	<i>SL</i> 615.90
22	1	FRAME FULL SUPPORT BRACKET	\$	<i>R</i> 89.79
23	1	BONNET	\$	<i>R</i> 1,941.63
24	1	BONNET HINGE RH	\$	<i>R</i> 348.31
25	1	BONNET STRUT RH	\$	<i>R</i> 88.61
26	1	LOWER ARM RH	\$	<i>SL</i> 685.76
27	1	KUNCKLE ARM RH	\$	<i>SL</i> 846.98
28	1	ABSORBER FRT RH	\$	<i>SL</i> 360.54
29	1	WHEEL HOUSING PANEL FRT RH	\$	<i>R</i> 4,682.09
30	1	DOOR PANEL FRT RH	\$	<i>R</i> 2,844.66
31	1	DOOR HINGE UPPER RH	\$	<i>R</i> 274.50
32	1	DOOR HINGE LOWER RH	\$	<i>R</i> 300.55
33	1	DOOR CHECK FRT RH	\$	<i>SL</i> 194.77
34	1	DOOR MOULDING FRT RH	\$	<i>R</i> 176.82

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5629T - AXA**AAD1712-087**

35	1	DOOR MIRROR RH	\$	1,483.40	}
36	1	DOOR MIRROR GLASS RH	\$	148.20	
37	1	DOOR MIRROR BACK COVER RH	\$	218.46	
38	1	DOOR WHETHERSTRIP FRT RH	\$	474.21	
39	1	DOOR SEAL FRT RH	\$	68.67	
40	1	ROCKER PANEL OUTER RH	\$	987.49	
41	1	DOOR PANEL REAR RH	\$	2,844.66	

TOTAL	\$	29,786.65
10%	\$	2,978.66
	\$	26,807.98

Specical Nett

1	1SET	WHEELARCH CLIP FRT RH	\$	66.00	X
2	1SET	FRONT BUMPER CLIP	\$	66.00	✓
3	1	RIM RH FRT	\$	385.00	✓
4	1	TYRE RH FRT	\$	330.00	✓
5	1	DOOR STICKER "Trans-cab"	\$	80.00	X
6	1	DOOR STICKER "Classic"	\$	30.00	✓
7	1	DOOR STICKER "6555-3333"	\$	80.00	X

TOTAL	\$	1,037.00
TOTAL PARTS	\$	27,844.98

To Check Electrical Lighting Concerned. \$ 170.00 201

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same \$ 4,200.00 4001

Towing fees \$ 120.00 X

Putty and spray painting of the affected portion. \$ 4,500.00 4401

To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test. \$ 170.00 X

To transfer of tire, rim and on wheel balancing. \$ 170.00 X

To check steering geometry and computer wheel alignment \$ 220.00 X

TRANS-CAB AUTO SERVICES PTE LTD

AAD1712-087

NO. 2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5629T - AXA

To Remove And Refit Front W/Screen Glass To Facilitate Bodywork Repair.	\$	170.00	X
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00	X
To rust-proofing of the affected areas.	\$	170.00	30/
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	380.00	X

TOTAL	\$	10,440.00
Over All Total	\$	38,284.98

(PARTS BY PARTS) Repair Days**15 Days***2 days*