



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com

Website: www.nhtmotor.com

Tel: 6747 9241

Fax: 6741 7276

UEN: 201718370K

CHEW HOCK SENG CONSTRUCTION PTE LTD

11/12/2017

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TPA x A

Thin Thin

Accident date: 10/12/2017

Estimated repair cost for vehicle no: XD9012B ISUZU FXZ77M 9.8 M '14

S/n	Qty	Items	U/price	Amount
1	1	Front L/H Side Mirror Bracket <i>new</i>		\$189.00 ✓
2	1	Front L/H Side Mirror Cover <i>ut</i>		\$57.00 ✓
3	1	Front R/H Door <i>Repair</i>		\$1,392.00 x
4	1	Front R/H Door Glass <i>ut</i>		\$486.00 ✓
5	1	Front R/H Door Lower Cover <i>Repair</i>		\$187.00 x
6	1	Front R/H Door Signal Lamp <i>new</i>		\$38.00 x
7	1	Front R/H Fender <i>Repair</i>		\$387.00 x
8	1	Body Logo (Special Nett) <i>new</i>		\$350.00 180(SN)
Subtotal :-				\$3,086.00

543

461.55

S.N : 180

Labour charges

To remove & refit R/H door, glass, gear motor & trim board

\$380.00 60

To check wiring

\$60.00 30

Tuff kote

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1090

\$80.00 x

\$850.00 400

\$850.00 600

Supplementary : 153

total : 1884.55

Subtotal :- \$2,220.00

Total:- \$5,306.00

1/51 1.5K

030p

1.5K



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

CHEW HOCK SENG CONSTRUCTION PTE LTD

14/12/2017

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date: 11/12/2017

Supplementary repair cost for vehicle no: XD9012B ISUZU FXZ77M 9.8 M '14

S/n	Qty	Items	U/price	Amount
1	1	Front R/H Glass Outer Moulding <i>ut</i>		\$180.00 ✓
2	1	Front R/H Glass Inner Shield Rubber <i>new</i>		\$480.00 ✓

Subtotal :- \$660.00

180

153