CONNECTS

7 Old Toh Tuck Road Singapore 597648 Tel: (65) 9850-9666 Email: Connect3winnie@gmail.com

Roc: 53360061L

QT17/PA7145E/TPC-108

AXA Insurance Singapore Pte Ltd 8 Shenton Way, #27-01 AXA Tower Singapore 068811

Dear Sir,

Cost of Repair to Vehicle PA7145E

With reference to the above-mentioned, we are pleased to quote as follows:-

QUOTATION

No.	DESCRIPTION	QTY	U/PRICE (S\$)	AMOUNT (S\$)
1.	Front bumper	1	1,850.00	1,850.00
2.	Labour charges	1	600.00	600.00
3.	Spray painting	1	1,000.00	1,000.00
			SUB-TOTAL	S\$3,450.00

Thank you.

Yours faithfully,

Winnie Chai

HP: 9850-9666

Rasul
49 9000068
3 days
14/12/17 P1045
Resy after napar

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after apray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: