

21/03/2002

ASS. REC. BY:

REF: CS/RTI17023704/Uqd312

Special Instruction:

Survivor:
Meimen

Marous.

ASSIGNMENT (Office)

From (Person):

Cheng Bron Sen

of

CTI

Date/Time:

13/12/17 @ 4:12pm

Estimated Cost:

Bill to:

OD/HP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKG 8932R

Insured:

at Workshop m/s

Specialists Motor

Tel:

6747 211

of

Blk 3018 A Ubi Road I, # 01-24/25, 408711

Policy No:

DMPCSN 3100311701

Claim No:

SNM17D07018C01

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

7/12/2007

CA / REV

/ REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

5:24pm @ 13/12/17

Person Contacted:

Hui Lin

Vehicle IN/OUT

Date/Time

Action/Instruction

(✓) Estimate

SKG 8932R - CS/CTI17023519 / Krb

D.O.A: 7/12/17

15/12-

Report via Meimen na

18/12/17 @ 2:05pm Susan Teo informed C/A via Meimen.

18/12/17 @ 2:31pm Informed Hui Lin C/A & Ex: 50% by email.

07/1/18 @

9:31am Confirmed with Hui Lin final fig \$ 1643.98, 3 days.

Cred \$ 693.13, 30%.

no lump sum

SAFARI *marcus*

REF:

411/

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
☒ OD / ☐ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV
 To Inspect Vehicle No: *SK68932R*
 at Workshop m/s: *specul.*
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: *Nil*
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: *53k.*
☒ ADAC Accident Rpt: _____ Consistent? : Yes or No
☒ GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: *3* days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / ☒ (REV) / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: *SK68932R* Yr Regn: *10.12*
 Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /
 Truck / Trailer or *CAI*
 Make: *Toyota corolla AH.s* c.c. *1598*
 Colour: *Black* A/C: ☐ Insured / ☐ Std / ☐ NI / ☐ NA
 Sp. Reading: *88292* T/Radio: ☐ Insured / ☐ Std / ☐ NI / ☐ NA
 Eng/No: _____
 C/No: *MR053REE104148937*
 Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt
 Steering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or
 Brake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or
 Modi: ☐ Nil ☒ S/Rim / ☐ STD A/Rim or
 Tyre Size: F: *195/65R15*
 R: _____
 BS ☒ DUN / ☐ EXNOVA / ☐ GY / ☐ FS / ☐ LIZA / ☐ MIC / ☐ OHTSU / ☐ PIR / ☐ SUMI /
 TOYO / YOKO or _____

Front _____ Rear _____
 R/Bal. *7* mm R/Bal. *7* mm
 L/Bal. *7* mm L/Bal. *7* mm
 D.O.A. *21/1/17* D.O.I. *14/1/17*
 Survey held at _____

Des. of Damages: Frt / Rear / ☒ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or
R-f.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction *47A 43824*

Date/Time. File Pass to? ☐ : Preli. Report

1) 07/2/2018 ☐ : Final Report

Date/Time. File Return to?

2)

Days Of Repair: *3*

Resurvey No. of Trip: *1*

Survey Fee:

Transportation:

☐ S + RS. \$

☐ Photos

☐ Others

TOTAL

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$) *1643.78*

220
220




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CT117023704/Uqd3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 13-12-2017	
		Code : CTI	
1. Policy Particulars :- OWN DAMAGE			
Insured Veh.		Veh. Inspected	SKG 8932R
Policy No.	DMPCSN3100311701	Coverage (\$)	0.00
Claim No.	SNM17D07018C01	Excess (\$)	0.00
Assign From	MERIMEN (CHONG BOON SEN)	Assign Date	13/12/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	07/12/2017	Inspection Date	
Survey held at	SPECIALISTS MOTOR PTE LTD BLK 3018A UBI ROAD 1 #01-24-26 SINGAPORE 408711		
5a. General Remarks			
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			

Survey Department Check List (Case Handler)

Reference No: C3/CT117023704/1493
Policy Type: OD / TP / TP RES / TL / EVA

SLG 893212

Case Handler

Typist

Admin (NVTHa): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

Surveyor (Manu): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

(2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

✓			
---	--	--	--

(3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

✓			
✓			
✓			

(4) System - (Views/Merimen)

- C Resurvey photo Uploaded

✓			
---	--	--	--

Check By: Chr 07/18
Case Handler Date

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Dec 2017 Sendback Est	13 Dec 2017 10:35 \$2,337.11	13 Dec 2017 16:12 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	TAY CHENG HAI, ID: S0159581D, Tel: +6596335160			
Vehicle Reg. No.:	SKG8932R	Date of Loss:	07/12/2017 20:00 - :59	
Claim Type:	OD / SNM17D07018C01	Policy/Cover Note No.:	DMPCSN3100311701 (Comprehensive) Coverage: 18/10/2017 - 17/10/2018	
		Excess:	\$50.00	
Repairer:	Specialists Motor Pte Ltd (HQ) Blk 3018A Ubi Road 1, #01-24/25/26, 408711 Ubi - Tel: 6747 2112			
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 22/12/2017]			
Driver/Custodian:	TAY MEI MEI AMELIA (33 / Female), NRIC: S8431825F, Tel: +6598308899			
Adj Asg. Remarks:	SURVEY REVERT			

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 18 December, 2017 2:31 PM
To: Specialists Motor Pte Ltd
Cc: SUR
Subject: VEHICLE SKG 8932R (DOA: 07/12/2017)

Dear Hui Lin,

As instructed by our client China Taiping Insurance, please proceed to repair the insured vehicle **SKG 8932R (Excess \$0/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Shiau Chan (LKKAUTO)

From: SPECIALISTS MOTOR PTE LTD <cardoc@singnet.com.sg>
Sent: Friday, 2 February 2018 9:31 AM
To: Shiau Chan (LKKAUTO)
Cc: SUR
Subject: RE: FINALISE OF VEHICLE SKG 8932R (DOA: 07/12/2017)

Dear Shiau Chan

Confirm finalize figure \$1,643.98 before GST and 3 repair days.

Thanks & Regards
Hui Lin
Specialists Motor Pte Ltd
6747 2112

From: Shiau Chan (LKKAUTO) [mailto:siewsc@lkkauto.com]
Sent: Wednesday, 31 January, 2018 10:27 AM
To: Specialists Motor Pte Ltd
Cc: SUR
Subject: FINALISE OF VEHICLE SKG 8932R (DOA: 07/12/2017)

Dear Hui Lin,

As spoken with you.

Please find the attached.

Offer final fig \$1,643.98 before GST and 3 repair days.
Kindly confirm.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	13 Dec 2017 10:29	Clm Veh Model Changed	(203311) TOYOTA COROLLA ALTIS 1.6 (A).	[R] Karen Ong
2	13 Dec 2017 10:29	Clm Created	Reg No: SKG8932R. Policy No: DMPCSN3100311701. Acct Date: 2017/12/07. Claim Type: OD. Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ). Workshop: Specialists Motor Pte Ltd (HQ)	[R] Karen Ong
3	13 Dec 2017 10:35	Clm Submitted	2337.11.	[R] Karen Ong
4	13 Dec 2017 16:12	Clm Registration Modified	Excess: -> 0.00.	[I] Chong Boon Sen
5	13 Dec 2017 16:12	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):SURVEY REVERT	[I] Chong Boon Sen
6	13 Dec 2017 16:12	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2017/12/22	[I] Chong Boon Sen
7	13 Dec 2017 16:12	Adj Mandate Set	Approved:0.00.	[I] Chong Boon Sen
8	13 Dec 2017 16:45	Assignment 1st Accessed		[A] Nivitha Govindasamy
9	13 Dec 2017 17:50	Adj Adjuster Assigned	[None] -> MARCUS CHUA	[A] Nivitha Govindasamy
10	15 Dec 2017 15:51	Adj Rpt Initiated		[A] DENISE TAY KWEE CHENG
11	15 Dec 2017 15:53	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2017/12/22	[A] DENISE TAY KWEE CHENG
12	15 Dec 2017 15:54	Adj Mandate Request	Cur Req:1744.42:DAMAGE CONSISTENT REPAIR COST ECONOMICAL	[A] DENISE TAY KWEE CHENG
13	15 Dec 2017 16:16	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2017/12/22. Mandate Remarks: PLA DOESNT TALLY AUDATEX (1744.42 VS 1799.76)	[I] Chong Boon Sen
14	15 Dec 2017 16:16	Adj Mandate Set	Maintained:PLA DOESNT TALLY AUDATEX (1744.42 VS 1799.76)	[I] Chong Boon Sen
15	15 Dec 2017 17:12	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2017/12/22	[A] DENISE TAY KWEE CHENG
16	15 Dec 2017 17:13	Adj Mandate Request	Cur Req:1744.42:DAMAGE CONSISTENT REPAIR COST ECONOMICAL	[A] DENISE TAY KWEE CHENG
17	18 Dec 2017 14:05	Adj Next Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date:2017/12/22. Mandate Remarks: PLA DOESNT TALLY AUDATEX (1744.42 VS 1799.76)	[I] Susan Teo
18	18 Dec 2017 14:05	Adj Mandate Set	Approved:1691.73:PLA DOESNT TALLY AUDATEX (1744.42 VS 1799.76)	[I] Susan Teo

ACTIVITY

[13/12/2017 17:27] Nivitha Govindasamy:
Vehicle not i workshop, repairer will arrange.

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1666378	13/12/2017 10:29	Motor	Specialists Motor Pte Ltd (HQ)	Specialists Motor Pte Ltd (HQ)	SKG8932R		xx.xx
1670080	15/12/2017 15:51	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SKG8932R		10.70

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chong Boon Sen

Date: 15 Dec 2017

Preliminary Advice

Vehicle No	: SKG8932R	Accident Date	: 07/12/2017
Make	: TOYOTA COROLLA ALTIS	Policy No.	: DMPCSN3100311701
Assignment Date	: 13/12/2017	Excess	: S\$0.00
Date of Inspection	: 14/12/2017	Est. Duration of Repair	: 3.00
Inspection At	: SPECIALISTS MOTOR PTE LTD (HQ) BLK 3018A UBI ROAD 1, #01-24/25/26 SINGAPORE 408711		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,337.11
Revised Amount	:S\$	1,799.76
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,799.76

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	53,000.00
COE / PARF Rebate	:S\$	43,824.00
Salvage Value	:S\$	
Margin for Repair	:S\$	9,176.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : Repair on part by part as there is no 2nd hand parts

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Singapore NRIC
Owner ID	9581D

Vehicle Details

Vehicle No.	SKG8932R
Vehicle to be Exported	No
Intended De-registration Date	14 Dec 2017
Vehicle Make	TOYOTA
Vehicle Model	COROLLA ALTIS 1.6 AUTO
Primary Colour	Black
Manufacturing Year	2012
Engine No.	1ZRX229956
Chassis No.	MR053REE104148937
Maximum Power Output	90.0 kW (120 bhp)
Open Market Value	\$14,885.00
Original Registration Date	18 Oct 2012
First Registration Date	18 Oct 2012
Transfer Count	0
Actual ARF Paid	\$14,885.00 7842.

Intended PARF Rebate Details

PARF Eligibility	Yes
PARF Eligibility Expiry Date	17 Oct 2022
PARF Rebate Amount	\$10,419.00

Intended COE Rebate Details

COE Expiry Date	17 Oct 2022
COE Category	A - Car (1600cc & below)
COE Period(Years)	10
QP Paid	\$69,000.00
COE Rebate Amount	\$33,405.00
Total Rebate Amount	\$43,824.00

The information contained herein is correct as at 14 Dec 2017

OK

SGCARMART.COM
 THE ONLY PLACE FOR SMART CAR BUYERS

All Car Make or Model

Search

HOME

NEW CARS

USED CARS

SELL CARS

MOTOR DIRECTORY

PRODUCT GUIDE

ARTICLES

FORUM

TOOLS & TIPS


MYCARFORUM
 MARKETPLACE
 Buy / Sell Parts & Accessories
[click here to visit now!](#)

 Username / Email Add
 password
 Submit Qu
 Connect Sign Up New Account
 Forgot Password

Post an Advertisement
 Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

2009 Bentley Continental Flying Spur, Only \$165.8K.


 Special Bank Interest At 3.18%
 For 7 Years Loan, Offer For
 Limited Period Only, Hi
 Faster Auto Trading StarAd

HIN LUNG AUTO
 Ho Bee Group
One Stop Car Hub
 Finance, Insurance, Workshop
 New and Used Cars
 30 years of car sale

Browse by Category

◀ Back (1 2) Next ▶

Sort by Date Posted

20 results/page

28 vehicles

toyota corolla

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	toyota corolla		Any	Any	2012	Any	Any	Any	Available

**Toyota Corolla Altis 1.6A****\$61,800**

\$10,820 /yr

21-Dec-2012

1,598 cc

49,549 km

Sedan

Available

Graded B by **STA**

Super Low Mileage! The Best Selling Japanese Sedan In Tip Top Condition. Low Fuel Consumption, Low Maintenance Model. Please Call To Arrange An Appointment For Viewing.

Autolink Holdings Pte Ltd

Posted: 14-Dec-2017

Tags: 2012 Toyota Corolla, 2012 Toyota Corolla, Toyota Corolla, Toyota Corolla, Toyota Corolla, Corolla, Corolla, Used Toyota

Details

**Toyota Corolla Altis 1.6A Elegance****\$49,800**

\$9,230 /yr

13-Jul-2012

1,598 cc

Sedan

Available

No Admin Fee Or Hidden Charges. Price Negotiable. Well Maintained. Newly Changed Battery And Tires. All Points Checked By Appointed Workshop. No Need To Spend More Money To Replace Anything. Buy With ...

Posted: 14-Dec-2017

Tags: 2012 Toyota Corolla, 2012 Toyota Corolla, Toyota Corolla, Toyota Corolla, Toyota Corolla, Corolla, Corolla, Used Toyota

Details

**Toyota Corolla Altis 1.6A****\$54,800**

\$10,510 /yr

13-Jun-2012

1,598 cc

Sedan

Available

Just Arrived. 1 Owner Car Well Taken Care By Ex Owner. High Loan With High Trade In. Price Nego. Call Now Or Visit Our Showroom Today!

Posted: 13-Dec-2017

Tags: 2012 Toyota Corolla, 2012 Toyota Corolla, Toyota Corolla, Toyota Corolla, Toyota Corolla, Corolla, Corolla, Used Toyota

Details

**Toyota Corolla Altis 1.6A****\$51,800**

\$10,780 /yr

02-Feb-2012

1,598 cc

100,342 km

Sedan

Available

Accredited Company! As Good As New. Excellent Condition. Buy And Drive With Peace Of Mind. Guarantee Low Price! Low Depreciation! High OMV! Low Maintenance! Low Down Payment! Accept Trade In, All Are ...

Fu Ylap Motor Trading

Posted: 13-Dec-2017

Tags: 2012 Toyota Corolla, 2012 Toyota Corolla, Toyota Corolla, Toyota Corolla, Toyota Corolla, Corolla, Corolla, Used Toyota

Details

Car Buying

Car Selling

Car Aftermarket

Car Ownership

On The Move

Lifestyle

**Toyota Corolla Altis 1.6A Elegance (OPC)****\$57,800**

\$10,870 /yr

02-Aug-2012

1,598 cc

Sedan

Available

Can Be Converted To Normal Plate At \$59800.

Think One Automobile & Trading

Posted: 12-Dec-2017

Tags: 2012 Toyota Corolla, 2012 Toyota Corolla, Toyota Corolla, Toyota Corolla, Toyota Corolla, Corolla, Corolla, Used Toyota

Details

**Toyota Corolla Altis 1.6A****\$49,988**

\$9,740 /yr

24-Apr-2012

1,598 cc

Sedan

Available

Perfect White Colour. Low Mileage! The Best Selling Japanese Sedan In Tip Top Condition. Low Fuel Consumption, Low Maintenance Model. Please Call To Arrange An Appointment For Viewing.

Posted: 12-Dec-2017

Tags: 2012 Toyota Corolla, 2012 Toyota Corolla, Toyota Corolla, Toyota Corolla, Toyota Corolla, Corolla, Corolla, Used Toyota

Details

**Toyota Corolla Altis 1.6A****\$52,800**

\$10,830 /yr

01-Mar-2012

1,598 cc

83,135 km

Sedan

Available

Accredited Company! As Good As New. Excellent Condition. Buy And Drive With Peace Of Mind. Guarantee Low Price! Low Depreciation! High OMV! Low Maintenance! Low Down Payment! Accept Trade In, All Are ...

Fu Ylap Motor Trading

Posted: 11-Dec-2017

Tags: 2012 Toyota Corolla, 2012 Toyota Corolla, Toyota Corolla, Toyota Corolla, Toyota Corolla, Corolla, Corolla, Used Toyota

Details

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/12/2017 16:05
Date Of Accident	07/12/2017 20:00
Exact Location Of Accident	FERNVALE LINK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKG8932R
Insured/Policyholder	
Name Of Registered Owner	TAY CHENG HAI
NRIC No	S0159581D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96335160
Alternative Phone No	OTHERS-96335160

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS-1.6 DUAL VVT-I (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN3100311701
Cover Note Number	

Driver

Name of Driver	TAY MEI MEI AMELIA(ZHENG MEI MEI AMELIA)
NRIC No	S8431825F
Date Of Birth	18/10/1984
Occupation	INDOOR
Date Of Driving Pass	06/08/2003
Driving Experience	14 YEARS AND 4 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-98308899
Fax Number	
Contact Number	
EMail Address	AMELIA.TAY.JF@GMAIL.COM

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Specialists Motor Pte Ltd
Blk 3018A Ubi Road 1
#01-24/26
Singapore 408711

Claim Reference:
Assessment Number: SM100202
Version: SPECIALM/1
Date Calculated: 13/12/2017 02:18

Full Report - V1
Registration: SKG 8932 R
Printed: 13/12/2017 10:20

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	Specialist Motor	Date of Incident:	07/12/2017
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	
Policy Number:	DMPCSN3100311701	Quote Due Date:	
Other Reference:	SM/SKG8932R/1712312	Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

*Not about
 the phb before
 policy.
 2x loss nil
 14/12/17
 628643/5*

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	Corolla Altis
Sub Model:	ALTIS
Model Sheet Number:	YCM 13
Registration:	SKG 8932 R
Registration Month:	
Registration Year:	
VIN Number:	
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%

Model Specs

FROM 09/2012	AIR CONDITIONING
1.6 LTR 91 KW	TWO COAT METALLIC
PREPARE OFF VEHICLE	

Vehicle Condition

Vehicle Status

Pre-Accident Condition:
 Steering:

Brakes Pedal Travel:
 Place of Inspection:
 Pre-Accident Damage:

Tyres Condition:
 Tread Depth LHF:
 Tread Depth LHR:
 Damage Areas:

Severity of Impact:
 Vehicle Status on
 Inspection:

Date of Inspection: 13/12/2017

Tread Depth RHF:
 Tread Depth RHR:
 Direction of Impact:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Specialists Motor Pte Ltd

Claim Reference:

Assessment Number: SM100202



Version: SPECIALM/1

Date Calculated: 13/12/2017 02:18

Full Report - V1

Registration: SKG 8932 R

Printed: 13/12/2017 10:20



Addresses

Cost Summary

Total Labour	\$837.20
Total Paint/Material	\$210.51
Total Parts	\$1,135.30
Total of Additional Costs	\$142.00
Excess:	TBA
Grand Total Exc GST:	\$2,325.01
7 % GST:	\$162.75
Grand Total Inc GST:	\$2,487.76

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$46.00/HR

Price/Dent = \$46.00/HR

Repair /

Guide Number Repair Details

		WU	Cost Price (\$)
NO NUMBER	ADJUST HEADLAMPS ✓	3.0	13.80
B140	RENEW FRONT PANEL CPL ✓	9.0	41.40
NO NUMBER	R + R FRONT BUMPER REINFORCEMENT ✓	2.0	9.20
B010	R + R FRONT BUMPER ✓	5.0	23.00
B020)	RENEW FRONT BUMPER (REMOVED) ✓	9.0	41.40
NO NUMBER	R + R LEFT FRONT OUTER BUMPER BRACKET ✓	1.0	4.60
NO NUMBER	R + R RIGHT FRONT OUTER BUMPER BRACKET ✓	1.0	4.60
B040)	R + R LEFT HEADLAMP ✓	1.0	4.60
B040)	R + R RIGHT HEADLAMP ✓	1.0	4.60
B040)	RENEW HEADLAMP ✓	1.0	4.60
70811	R + R ENGINE COMPARTMENT INSULATION ✓	2.0	9.20
851061 ZAX	R + R WASHER NOZZLES ✓	2.0	9.20
M010)	R + R AIR CONDITIONING CONDENSER ✓	3.0	13.80
002889	DRAIN/REFILL AIR CONDITIONING ✓	7.0	32.20
M020	R + R RADIATOR ✓	6.0	27.60
	INCLUDES: BLEED COOLING SYSTEM ✓		

LABOUR COST

Total Work Units	53.0	
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	5.3HRS	\$243.80
Paint Labour	12.9HRS	\$593.40
Total Labour	18.2HRS	\$837.20

PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$46.00/HR

Guide Number Description

WU Cost Price (\$)

- TWO COAT METALLIC

Specialists Motor Pte Ltd

Claim Reference:

Assessment Number: SM100202

Version: SPECIALM/1

Date Calculated: 13/12/2017 02:18

Full Report - V1

Registration: SKG 8932 R

Printed: 13/12/2017 10:20

	- PREPARE OFF VEHICLE	
988	LOCK CARRIER STRUT SURFACE PAINT	4.0
1009	INNER FRT PANEL CPL SURFACE PAINT	6.0
281	FRONT BUMPER NEW PART PAINT K1R	13.0
410	GRILLE REPAIR PAINT PLASTIC	9.0
471	BONNET REPAIR PAINTING >50%	32.0
741	L/F WING REPAIR PAINTING >50%	16.0
742	R/F WING REPAIR PAINTING >50%	16.0
LABOUR COST - PAINT		
	TIME(PAINT)	96.0
	Preparation Main Work Plastic	8.0
	Preparation Main Work Metal	25.0
	Preparation Work Multi Layer Paint	0.0
	Total Work Units (10WU/HR)	129.0
	Total Paintwork Labour	12.9HRS
MATERIAL COST - PAINT		
	New Part Painting - Plastic K1R	\$593.40
	Material-Constant Main Work Metal	Cost Price
	Surface-/Blend Paint	\$67.40
	Repair Painting	\$28.60
	Repair Painting Plastic	\$15.19
	Material-Const Main Work Plastic	\$82.57
	Total Excluding Pearlescent Uplift	\$4.05
	Pearlescent Uplift @ 0.0%	\$12.70
	Total Paint Material Cost	\$210.51

PARTS

				Price Valid: 01/06/2015	
Guide No.	Qty	Description	Part Number	Supplier	Bet. Price (\$)
281	1	FRONT BUMPER	52119 01915		✓ 0% <i>22/02</i> 220.00*
317	1	L/F BUMPER BRACKET	52116 02160		✓ 0% <i>22</i> 22.00*
340	1	BUMPER SUPPORT	52021 02101		0% <i>n</i> 150.00*
350	1	FRT BUMPER CLAMP KIT	USE SINGLE PARTS		0% <i>17</i> 25.00*
410	1	GRILLE	53100 02907		✓ 0% <i>cm</i> 130.00*
431	1	GRILLE BADGE	75301 02050		✓ 0% <i>cm</i> 25.00*
561	1	LEFT HEADLAMP ASSY	81185 12F60		✓ 0% <i>cm</i> 180.00*
1009	1	INNER FRT PANEL CPL	53201 02270		0% <i>n</i> 190.00*
1000	1	FRT BMPR RETAINER LH	Renew		✓ 0% <i>22</i> 22.00*
1000	1	FRT BMPR RETAINER RH	Renew		✓ 0% <i>22</i> 22.00*
f: OEM Parts			Sub Total		\$986.00
g: Original			Mark Up From Cost	(5 %)	\$49.30
h: Secondhand			Sundry Parts	(Fixed)	\$100.00
p: Parallel			Total Parts		\$1,135.30
x: Exchange					

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
FRT NUMBER PLATE SPECIALIST	0%	<i>24</i> \$50.00 <i>35</i>
AUDATEX FEE SPECIALIST		\$42.00 ✓
WASH CAR&TEST DRIVE SPECIALIST	0%	<i>11</i> \$50.00 <i>X</i>
Total Extras		\$142.00

Final Calculation

Specialists Motor Pte Ltd

Claim Reference:

Assessment Number: SM100202

Version: SPECIALM/1

Date Calculated: 13/12/2017 02:18

Full Report - V1

Registration: SKG 8932 R

Printed: 13/12/2017 10:20

Total Parts		\$1,135.30
Labour		
Total Panel/Mechanical	\$243.80	
Total Paintwork	\$593.40	
Total Labour		\$837.20
Additional Costs		
Corr Prot Materials External	\$0.00	
Corr Prot Materials Internal	\$0.00	
Cost of Specialist	\$142.00	
Total of Additional Costs		\$142.00
Total Paint/Material Costs		\$210.51
Grand Total Excludes GST		\$2,325.01
GST @ 7 %		\$162.75
Grand Total Includes GST		\$2,487.76

Assessment Notes

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Bus. Reg No: 199502604 E GST No: 19-9502604-E

INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	SM/SKG8932R/1712312
Policy No:	DMPCSN3100311701	Date of Loss:	07/12/2017
Vehicle Reg. No.:	SKG8932R	Driveable?	
Driver Age/Info:	33 / FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	TAY CHENG HAI	Contact No:	+6596335160
Driver:	TAY MEI MEI AMELIA		

Make/Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Vehicle Reg. Date:	18/10/2012
Vehicle Colour:	BLACK		
Engine No:	1ZRX229956	Chassis No:	MR053REE104148937
Odometer:	0 KM		

Paint Type:
Total Loss? **NO**
Est. Duration of Repair (day) **7**

Present Location: SPECIALISTS MOTOR PTE LTD (HQ)

COST OF CLAIMS

	Amount
Parts	1,289.40
Miscellaneous Items	0.00
Labour	1,047.71
Paintwork Labour	0.00
Towing	0.00
Calculated Gross Total (S\$)	2,337.11
- Excess (S\$)	500.00
(S\$)	1,837.11
+ GST 7.00% (S\$)	128.60
Nett Amount (S\$)	1,965.71

This claim is handled by: KAREN ONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 13 Dec 2017)**Parts:** 143 TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Specialists Motor Pte Ltd/SKG8932R/13/12/2017 10:35**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	NA	*BUMPER SUPPORT	0.00	0.00	*150.00 F <i>XR</i>
2	1	NA	*FRONT BUMPER	0.00	0.00	<i>DD</i> *220.00 F <i>OR</i> ✓
3	1	NA	*FRT BMPR RETAINER LH	0.00	0.00	<i>BT</i> *22.00 F ✓
4	1	NA	*FRT BMPR RETAINER RH	0.00	0.00	<i>BT</i> *22.00 F ✓
5	1	NA	*FRT BUMPER CLAMP KIT	0.00	0.00	*25.00 F <i>XR</i>
6	1	NA	*GRILLE	0.00	0.00	<i>LRA</i> *130.00 F ✓
7	1	NA	*GRILLE BADGE	0.00	0.00	<i>RL</i> *25.00 F ✓
8	1	NA	*INNER FRT PANEL CPL	0.00	0.00	*190.00 F <i>XR</i>
9	1	NA	*L/F BUMPER BRACKET	0.00	0.00	<i>BT</i> *22.00 F ✓
10	1	NA	*LEFT HEADLAMP ASSY	0.00	0.00	<i>LRA</i> *180.00 F ✓
11	1	NA	*SPECIALIST AUDATEX FEE	0.00	0.00	*42.00 F ✓
12	1	NA	*SPECIALIST FRT NUMBER PLATE	0.00	0.00	<i>35</i> *50.00 F <i>BT</i>
13	1	NA	*SPECIALIST WASH CAR&TEST DRIVE	0.00	0.00	*50.00 F <i>BT</i>
14	1	NA	*SUNDRY PARTS	0.00	0.00	<i>RL</i> *100.00 F ✓

F=Franchise part.

Sub Total (S\$)	1,228.00
+ Margin on L,N Items 5.00% (S\$)	61.40
Total Parts (S\$)	1,289.40

Specialists Motor Pte Ltd/SKG8932R/13/12/2017 10:35. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	Total Paint Labour	New 501.40	593.40
2	Total Paint Materials	New 198.53	210.51
3	Total Panel/Mechanical Labour	New 115	243.80
Gross Labour Cost (\$\$)			1,047.71

Specialists Motor Pte Ltd/SKG8932R/13/12/2017 10:35. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

51 Ubi Avenue 1, #01-25
Paya Ubi Industrial Park
Singapore
408933

Claim Reference: SNM17D07018C01
Assessment Number: SM100202
Version: LKKAUTOC/3
Date Calculated: 31/01/2018 02:23

Full Report - V1
Registration: SKG 8932 R
Printed: 31/01/2018 10:24

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	MR LAU	Date of Incident:	07/12/2017
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:	SNM17D07018C01	Estimated Repair Time:	
Policy Number:	DMPCSN3100311701	Quote Due Date:	
Other Reference:	SM/SKG8932R/1712312	Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	TOYOTA
Model:	Corolla Altis
Sub Model:	ALTIS
Model Sheet Number:	YCM 13
Registration:	SKG 8932 R
Registration Month:	
Registration Year:	
VIN Number:	
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%



Model Specs

FROM 09/2012	AIR CONDITIONING
1.6 LTR 91 KW	TWO COAT METALLIC
PREPARE OFF VEHICLE	

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	13/12/2017
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:	Tread Depth RHF:	
Tread Depth LHF:	Tread Depth RHR:	
Tread Depth LHR:	Direction of Impact:	
Damage Areas:		



Addresses

Cost Summary

Total Labour	\$616.40
Total Paint/Material	\$198.53
Total Parts	\$752.05
Total of Additional Costs	\$77.00
Excess:	- \$0.00
Grand Total Exc GST:	\$1,643.98
7 % GST:	\$115.08
Grand Total Inc GST:	\$1,759.06

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$46.00/HR
Price/Dent = \$46.00/HR

Repair /

Guide Number	Repair Details	WU	Cost Price (\$)
NO NUMBER	ADJUST HEADLAMPS	3.0	13.80
NO NUMBER	R + R FRONT BUMPER REINFORCEMENT	2.0	9.20
B010	R + R FRONT BUMPER	5.0	23.00
B020)	RENEW FRONT BUMPER (REMOVED)	9.0	41.40
NO NUMBER	R + R LEFT FRONT OUTER BUMPER BRACKET	1.0	4.60
NO NUMBER	R + R RIGHT FRONT OUTER BUMPER BRACKET	1.0	4.60
B040)	R + R LEFT HEADLAMP	1.0	4.60
B040)	RENEW HEADLAMP	1.0	4.60
NO NUMBER	R + R FRONT ENGINE PROTECTION	2.0	9.20

LABOUR COST

Total Work Units	25.0	
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	2.5HRS	\$115.00
Paint Labour	10.9HRS	\$501.40
Total Labour	13.4HRS	\$616.40

PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$46.00/HR

Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC		
	- PREPARE OFF VEHICLE		
281	FRONT BUMPER NEW PART PAINT K1R	13.0	
410	GRILLE REPAIR PAINT PLASTIC	9.0	
471	BONNET REPAIR PAINTING >50%	32.0	
741	L/F WING SURFACE PAINT	6.0	
742	R/F WING SURFACE PAINT	6.0	
988	LOCK CARRIER STRUT SURFACE PAINT	4.0	

1009	INNER FRT PANEL CPL SURFACE PAINT	6.0	
	LABOUR COST - PAINT		
	TIME(PAINT)	76.0	
	Preparation Main Work Plastic	8.0	
	Preparation Main Work Metal	25.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	109.0	
	Total Paintwork Labour	10.9HRS	\$501.40
	MATERIAL COST - PAINT		Cost Price
	New Part Painting - Plastic K1R		\$67.40
	Material-Constant Main Work Metal		\$28.60
	Surface-/Blend Paint		\$35.61
	Repair Painting		\$50.17
	Repair Painting Plastic		\$4.05
	Material-Const Main Work Plastic		\$12.70
	Total Excluding Pearlescent Uplift		\$198.53
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$198.53

PARTS					
Price Valid: 01/06/2015					
Guide No.	Qty	Description	Part Number	Supplier	Bet. Price (\$)
281	1	FRONT BUMPER	52119 01915		0% 220.00F
317	1	L/F BUMPER BRACKET	52116 02160		0% 22.00*
410	1	GRILLE	53100 02907		0% 130.00*
431	1	GRILLE BADGE	75301 02050		0% 25.00*
561	1	LEFT HEADLAMP ASSY	81185 12F60		0% 180.00*
1000	1	FRT BMPR RETAINER LH	Renew		0% 22.00*
1000	1	FRT BMPR RETAINER RH	Renew		0% 22.00*
f: OEM Parts		Sub Total			\$621.00
g: Original		Mark Up From Cost		(5 %)	\$31.05
h: Secondhand		Sundry Parts		(Fixed)	\$100.00
p: Parallel		Total Parts			\$752.05
x: Exchange					

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras				
Description		Betterment		Price
FRT NUMBER PLATE	SPECIALIST	0%		\$35.00
AUDATEX FEE	SPECIALIST			\$42.00
Total Extras				\$77.00

Final Calculation			
Total Parts			\$752.05
Labour			
Total Panel/Mechanical		\$115.00	
Total Paintwork		\$501.40	
Total Labour			\$616.40
Additional Costs			
Corr Prot Materials External		\$0.00	
Corr Prot Materials Internal		\$0.00	
Cost of Specialist		\$77.00	
Total of Additional Costs			\$77.00
Total Paint/Material Costs			\$198.53

51 Ubi Avenue 1, #01-25 Paya Ubi Industrial Park Singapore
Claim Reference: SNM17D07018C01
Assessment Number: SM100202
Version: LKKAUTOC/3
Date Calculated: 31/01/2018 02:23

Full Report - V1
Registration: SKG 8932 R
Printed: 31/01/2018 10:24

Grand Total Excludes GST	\$1,643.98
GST @ 7 %	\$115.08
Grand Total Includes GST	\$1,759.06

Assessment Notes





豐達汽車私人有限公司

FONG TAT MOTOR CO. PTE. LTD.

Head Office: No. 3 Kallang Way 2A, FONG TAT Building Singapore 347483
Tel: 67494993, 67478232 Fax: 67430880, 67477481 Website: www.fongtat.com
Main Branch (TOWN): 355-357 Serangoon Road Singapore 218115 Tel: 62985333 62949832
Fax: 62992153, 82342354, 62935021
Email: fongtat@boxd.singnet.com.sg
RCB Reg No.: 198301435R

AUTHORISED STOCKISTS:



NISSAN TOYOTA OPEL GENUINE PARTS
TEL: 67499889 62949832 67479232
67426878 62985333 67455824

MITSUBISHI/PROTON
TEL: 62954551
67496954

SHRIMP/DAI/DAI DIV
TEL: 62970588 64542285
67493588

MAZDA/FORD DIV
TEL: 62935722
67420358

AIRCON/W/S GLASS
TEL: 62952336
67495597

INVOICE TO:

SPECIALISTS MOTOR PTE LTD

BLK 3018A #01-26/24

UBI ROAD 1

SINGAPORE 408711

SKG8932R(MR053REE104148937) T/ALYIS

GST Reg. No.: M2-0059747-8

TAX INVOICE

TAX INVOICE NO.: CL379338


INVOICE DATE : 26/12/2017

CREDIT TERMS : 30 Days

SALES ORDER NO.:

SALESMAN : OSM

PAGE(S) : 1



DESCRIPTION	LOC.	QUANTITY	UNIT PRICE
GRILLE		1 PCS	(SIN)
GRILLE EMBLEM		1 PCS	130.00
FRONT BUMPER		1 PCS	25.00
F/RETAINER		1 PCS	220.00
F/RETAINER		1	22.00
FRONT BUMPER BRACKET LH		1	22.00
HEADLAMP UNIT		1 PCS	22.00
		1	180.00

FONG TAT MOTOR CO. PTE. LTD. GOODS SOLD ARE NOT RETURNABLE FOR CASH

GOODS RECEIVED

TOTAL

AUTHORISED SIGNATURE

(0.5)

SIGNATURE



NISSAN Genuine Parts
TOYOTA GENUINE PARTS
OPEL GENUINE PARTS

NISSAN TOYOTA OPEL OEM PARTS
TEL: 67426889 62949832 67479232
67426878 62985333 67455824

Tel: 67494938, 67479292 Fax: 67490380, 67477431 Website: www.fonglat.com.sg
 Main Branch (Town): 355-357 Serangoon Road Singapore 218115 Tel: 62966333, 62949652
 Fax: 62992158, 62942354, 62935021
 Email: figipnet@imbox3.singnet.com.sg
 RCB Reg No.: 198301435R

MAZDA
Genuine Parts

NOLOHD/SHSIBNSIM
MITSUBISHI PHOTON

TEL: 62954551
67496954

10

INVOICE TO: **SPECIALISTS MOTOR PTE LTD**

BLK 3018A #01-26/24

UBI ROAD 1

SINGAPORE 408711

SKG8932R(MR053REE104148937) T/ALTIS

GST Reg. No.: M2-0059747-8

[illegible]

EL: 62954551
67496954
1 HONDA/HYUNDAI DIV
EL: 62970668 84542288
67493368
MAZDA/FORD DIV
EL: 62935722
67420368
MIRCON/W/S GLASS
EL: 62952336
67498987

DESCRIPTION	LOC.	QUANTITY	UNIT PRICE
SKG8932R TOYOTA ALTIS ZRE141			(SIN)
		GST Excl Amount :	621.00
		Special Discount :	
		GST @ 7 % :	43.47

FONG TAT MOTOR CO. PTE. LTD. **GOODS SOLD ARE NOT RETURNABLE FOR CASH**

GOODS RECEIVED

664.47

TOTAL

PRINT BY :

OSM 26/12/2017 09:36:33

AUTHORISED SIGNATURE

SIGNATURE

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Dec 2017 Sendback Est	13 Dec 2017 10:35 S\$2,337.11	13 Dec 2017 16:12 Edit Adj Rpt	S\$1,643.98 Edit Estimates	S\$1,643.98 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	-----------------

CLAIM SUBFOLDER DETAILS

Insured:	TAY CHENG HAI, ID: S0159581D, Tel: +6596335160		
Vehicle Reg. No.:	SKG8932R	Date of Loss:	07/12/2017 20:00 - :59
Claim Type:	OD / SNM17D07018C01	Policy/Cover Note No.:	DMPCSN3100311701 (Comprehensive) Coverage: 18/10/2017 - 17/10/2018
		Excess:	S\$0.00
Repairer:	Specialists Motor Pte Ltd (HQ) Blk 3018A Ubi Road 1, #01-24/25/26, 408711 Ubi - Tel: 6747 2112		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 22/12/2017]		
Driver/Custodian:	TAY MEI MEI AMELIA (33 / Female), NRIC: S8431825F, Tel: +6598308899		
Adj Asg. Remarks:	SURVEY REVERT		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

- CHINA_TAIPIING (18/12/2017): Alert - Adj Mandate Approved (S\$1691.73) - SKG8932R - Claim Handler: Chong Boon ...
- CHINA_TAIPIING (15/12/2017): Alert - Adj Mandate Maintained - SKG8932R - Claim Handler: Chong Boon Sen

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SKG8932R (SNM17D07018C01)

OD


































Dec 7 2017 8:00PM

[TAY CHENG HAI]

Specialists Motor Pte Ltd

Upload Documents | Upload Photos | Compose New Letter

View View in Browser v

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Specialists Motor Pte Ltd (HQ)	Thumbnail	Print
1	13/12/17 10:35	Repairer Estimates	 Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	15/12/17 15:53	Adjuster Immediate Advice	 Load HTM	
2	15/12/17 17:12	Adjuster Immediate Advice	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Specialists Motor Pte Ltd (HQ)	Thumbnail	Print
1	13/12/17 10:38	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	13/12/17 10:38	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	13/12/17 10:38	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	13/12/17 10:38	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/12/17 16:00	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
2	14/12/17 16:00	General View	 Load JPG	<input checked="" type="checkbox"/>
3	14/12/17 16:00	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
4	14/12/17 16:00	General View	 Load JPG	<input checked="" type="checkbox"/>
5	14/12/17 16:00	General View	 Load JPG	<input checked="" type="checkbox"/>
6	14/12/17 16:00	General View	 Load JPG	<input checked="" type="checkbox"/>
7	14/12/17 16:00	General View	 Load JPG	<input checked="" type="checkbox"/>
8	14/12/17 16:00	General View	 Load JPG	<input checked="" type="checkbox"/>
9	14/12/17 16:00	General View	 Load JPG	<input checked="" type="checkbox"/>
10	14/12/17 16:00	General View	 Load JPG	<input checked="" type="checkbox"/>
11	14/12/17 16:00	General View	 Load JPG	<input checked="" type="checkbox"/>
12	14/12/17 16:00	General View	 Load JPG	<input checked="" type="checkbox"/>
13	14/12/17 16:00	General View	 Load JPG	<input checked="" type="checkbox"/>
14	14/12/17 16:00	General View	 Load JPG	<input checked="" type="checkbox"/>
15	14/12/17 16:00	General View	 Load JPG	<input checked="" type="checkbox"/>
16	14/12/17 16:00	General View	 Load JPG	<input checked="" type="checkbox"/>
17	14/12/17 16:00	General View	 Load JPG	<input checked="" type="checkbox"/>
18	14/12/17 16:00	General View	 Load JPG	<input checked="" type="checkbox"/>
19	14/12/17 16:00	General View	 Load JPG	<input checked="" type="checkbox"/>
20	14/12/17 16:00	General View	 Load JPG	<input checked="" type="checkbox"/>
21	14/12/17 16:00	General View	 Load JPG	<input checked="" type="checkbox"/>
22	14/12/17 16:00	General View	 Load JPG	<input checked="" type="checkbox"/>
23	14/12/17 16:00	General View	 Load JPG	<input checked="" type="checkbox"/>
24	14/12/17 16:00	General View	 Load JPG	<input checked="" type="checkbox"/>
25	14/12/17 16:00	General View	 Load JPG	<input checked="" type="checkbox"/>
26	14/12/17 16:00	General View	 Load JPG	<input checked="" type="checkbox"/>

27	14/12/17 16:00	General View	1	Load JPG	<input checked="" type="checkbox"/>
28	14/12/17 16:00	General View	1	Load JPG	<input checked="" type="checkbox"/>
29	14/12/17 16:00	General View	1	Load JPG	<input checked="" type="checkbox"/>
30	14/12/17 16:00	General View	1	Load JPG	<input checked="" type="checkbox"/>
31	14/12/17 16:00	General View	1	Load JPG	<input checked="" type="checkbox"/>
32	14/12/17 16:00	General View	1	Load JPG	<input checked="" type="checkbox"/>
33	14/12/17 16:00	General View	1	Load JPG	<input checked="" type="checkbox"/>
34	14/12/17 16:00	General View	1	Load JPG	<input checked="" type="checkbox"/>
35	14/12/17 16:00	General View	1	Load JPG	<input checked="" type="checkbox"/>
36	14/12/17 16:00	General View	1	Load JPG	<input checked="" type="checkbox"/>
37	14/12/17 16:00	General View	1	Load JPG	<input checked="" type="checkbox"/>
38	14/12/17 16:00	General View	1	Load JPG	<input checked="" type="checkbox"/>
39	14/12/17 16:00	General View	1	Load JPG	<input checked="" type="checkbox"/>
40	15/12/17 15:48	General View pdf	1	Load PDF	
41	26/12/17 18:59	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
42	26/12/17 18:59	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
43	26/12/17 18:59	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
44	26/12/17 18:59	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
45	26/12/17 18:59	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
46	26/12/17 18:59	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
47	26/12/17 18:59	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
Documentation					
			1 per page		<input checked="" type="checkbox"/>
No	Finalized On	Specialists Motor Pte Ltd (HQ)		Thumbnail	Print
1	13/12/17 10:36	E-filed GIA report	1	Load TIF	
2	13/12/17 10:36	E-filed GIA report	1	Load TIF	
3	13/12/17 10:36	E-filed GIA report	1	Load TIF	
4	13/12/17 10:36	E-filed GIA report	1	Load TIF	
5	13/12/17 10:36	Certificate of Insurance	1	Load TIF	
6	13/12/17 10:36	Drivers Driving License	1	Load TIF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	15/12/17 15:46	estimate	1	Load PDF	
2	09/02/18 09:45	Parts Invoice	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>
Show Remarks To: <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CT117023704/UQD3E2

Date: 09/02/2018

REFERENCE

Insured/Claimant: TAY CHENG HAI Policy No: DMPCSN3100311701
Date of Loss: 07/12/2017 Nature of Claim: OD Claim No: SNM17D07018C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKG8932R**
Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A) Engine No: 1ZR229956
Reg. Date: 18/10/2012 (Man. Year: 2012) Chassis No: MR053REE104148937
Colour: Black Odometer: 88292 km
Engine Capacity: 1598 cc
Market Value/New Car Price: S\$53,000.00
Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: Dunlop 7 mm Rear Left Side: Dunlop 7 mm
Front Right Side: Dunlop 7 mm Rear Right Side: Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,289.40	829.05	460.35	35.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,047.71	814.93	232.78	22.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	2,337.11	1,643.98	693.13	29.66
- Excess (\$\$)	500.00	0.00	500.00	100.00
(\$\$)	1,837.11	1,643.98	193.13	10.51
+ GST 7.00/7.00% (\$\$)	128.60	115.08	13.52	10.51
Nett Amount (\$\$)	1,965.71	1,759.06	206.65	10.51

INSPECTION

Date of Assignment: 13/12/2017 Present Location: Specialists Motor Pte Ltd (HQ)
Date Inspected: 14/12/2017 Inspected At: Blk 3018A Ubi Road 1, #01-24/25/26
Singapore 408711
Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 09 Feb 2018)
Parts: 143 TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKG8932R)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*BUMPER SUPPORT	Repair	150.00 F	*- F
2	1	NA	*FRONT BUMPER	Dented/Deformed	220.00 F	*220.00 F
3	1	NA	*FRT BMPR RETAINER LH	Bent	22.00 F	*22.00 F
4	1	NA	*FRT BMPR RETAINER RH	Bent	22.00 F	*22.00 F
5	1	NA	*FRT BUMPER CLAMP KIT	Not Necessary	25.00 F	*- F
6	1	NA	*GRILLE	Cracked	130.00 F	*130.00 F
7	1	NA	*GRILLE BADGE	Necessary	25.00 F	*25.00 F
8	1	NA	*INNER FRT PANEL CPL	Repair	190.00 F	*- F
9	1	NA	*L/F BUMPER BRACKET	Bent	22.00 F	*22.00 F
10	1	NA	*LEFT HEADLAMP ASSY	Cracked	180.00 F	*180.00 F
11	1	NA	*SPECIALIST AUDATEX FEE		42.00 F	*42.00 FS
12	1	NA	*SPECIALIST FRT NUMBER PLATE	Bent	50.00 F	*35.00 FS
13	1	NA	*SPECIALIST WASH CAR&TEST DRIVE	Not Necessary	50.00 F	*- F
14	1	NA	*SUNDRY PARTS	Necessary	100.00 F	*100.00 FS

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	1,228.00	798.00
+ Margin on L,N Items 5.00/5.00% (\$\$)	61.40	31.05
Total Parts (\$\$)	1,289.40	829.05

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	Total Paint Labour	New	593.40	501.40
2	Total Paint Materials	New	210.51	198.53
3	Total Panel/Mechanical Labour	New	243.80	115.00
Gross Labour Cost (S\$)			1,047.71	814.93

Report was unsubmitted during this print-out.

< END OF ESTIMATES >