

HITACHI
 Inspire the Next

TP INSURER: AXA Insurance Pte Ltd (HQ)
TRANS-CAB SERVICES PTE LTD
 UNKNOWN
 Singapore UNKNOWN

Claimant Insurer: MSIG Insurance (Singapore) Pte. Ltd.

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	SKW6474A
Policy No:	VPX/P1680520	Date of Loss:	10/11/2017
Vehicle Reg. No.:	SKW6474A	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	CHOW KERR CHUEN (ZHOU KE QUAN)	Driver (Insured):	NEO HOCK BENG
Make/Model:	TOYOTA VELLFIRE, 2.5 CVT (A)	Vehicle Reg. Date:	09/11/2015
Vehicle Colour:	BLACK		
Engine No:	2ARH640669	Chassis No:	JTNGF3DH208002862
Odometer:	150265 KM		
Paint Type:			
List Item Discount:	25.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	7		
Description of Accident/Loss	PLEASE REFER TO THE ATTACHED.		
Present Location:	HITACHI CAPITAL ASIA PACIFIC PTE. LTD (HQ)		

COST OF CLAIMS

	Amount
Parts	553.50
Miscellaneous Items	0.00
Labour	2,700.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	3,253.50
+ GST 7.00% (S\$)	227.75
Nett Amount (S\$)	3,481.25

This claim is handled by: SUN ZHU MEI

Generated using Merimen e-Claims Internet Estimation & Adjusting System

HITACHI
Inspire the Next**(SUPPLEMENTARY)**

TP INSURER: AXA Insurance Pte Ltd (HQ)
TRANS-CAB SERVICES PTE LTD
UNKNOWN
Singapore **UNKNOWN**

Claimant Insurer: MSIG Insurance (Singapore) Pte. Ltd.

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	SKW6474A
Policy No:	VPX/P1680520	Date of Loss:	10/11/2017
Vehicle Reg. No.:	SKW6474A	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	CHOW KERR CHUEN (ZHOU KE QUAN)	Driver (Insured):	NEO HOCK BENG
Make/Model:	TOYOTA VELLFIRE, 2.5 CVT (A)	Vehicle Reg. Date:	09/11/2015
Vehicle Colour:	BLACK		
Engine No:	2ARH640669	Chassis No:	JTNGF3DH208002862
Odometer:	150265 KM		

Paint Type:

List Item 25.00 %

Discount:

Total Loss? **NO**

Est. Duration of Repair (day) 7

Description of Accident/Loss: PLEASE REFER TO THE ATTACHED.

Present Location:

HITACHI CAPITAL ASIA PACIFIC PTE. LTD (HQ)

COST OF CLAIMS**Amount**

Parts	0.00
Miscellaneous Items	0.00
Labour	1,000.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	1,000.00
+ GST 7.00% (\$\$)	70.00

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 12 Dec 2017)**Parts:** M1-MPV TOYOTA VELLFIRE 2.5 CVT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Hitachi Capital Asia Pacific Pte. Ltd/SKW6474A/12/12/2017 14:22**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Front Bumper	25.00	0.00	615.20 *615.20 FL
2	10		*Front Bumper Clips	25.00	0.00	550.00 *55.00 FL
3	1		*Front Bumper Retainer RH	25.00	0.00	X *67.80 FL
4	1	REPAIR	*Front RH Fender	25.00	0.00	R -
5	1	REPAIR	*Driver Door	25.00	0.00	X -
6	1	REPAIR	*Rear RH Door	25.00	0.00	X -

F=Franchise part. L=ListItemDisc.

Sub Total (S\$) 738.00

- List Item Discount on L Items (S\$) 184.50

Total Parts (S\$) 553.50

Hitachi Capital Asia Pacific Pte. Ltd/SKW6474A/12/12/2017 14:22. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	To putty, respray on damaged front portion	New	<u>500</u> 1,000.00
Gross Labour Cost (\$\$)			<u>1,000.00</u>

Hitachi Capital Asia Pacific Pte. Ltd./SKW6474A/18/01/2018 11:50. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

© **Hitachi Capital Asia Pacific Pte. Ltd. (Main Office)** Co. Reg. No. 199400399N

111 Somerset Road #11-05 Singapore 238164 Tel: (65) 6734 1222 Fax : 6734 8835
www.hitachi-capital.com.sg

Jun Taiyo Service Centre (Automobile Leasing & Workshop)

8 Fourth Lok Yang Road Singapore 629705 Tel: (65) 6466 3022 Fax: (65) 6896 6591

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	Panel beat, cut, weld, re-align and replace damaged parts of FRONT portion	New	350 1000.00
2	Panel beat, cut, weld, re-align and replace damaged parts of REAR portion X	New	500 X 1500.00
3	Check Wiring, re-align headlamps and ensure proper function	New	20 X 80.00
4	Remove & reinstall 2 pieces bumper sensors	New	80 120.00
Gross Labour Cost (\$\$)			2,700.00

Hitachi Capital Asia Pacific Pte. Ltd./SKW6474A/12/12/2017 14:22. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

© Hitachi Capital Asia Pacific Pte. Ltd. (Main Office) Co. Reg. No. 199400399N

111 Somerset Road #11-05 Singapore 238164 Tel: (65) 6734 1222 Fax : 6734 8835
www.hitachi-capital.com.sg

Jun Taiyo Service Centre (Automobile Leasing & Workshop)

8 Fourth Lok Yang Road Singapore 629705 Tel: (65) 6466 3022 Fax: (65) 6896 6591

LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation. • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:

Rasul
4p 90010068

3 days

P/P

18/01/18 @ 1140

Resurvey before paint