

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SJQ 7484H
Accident Date : 06-Dec-2017

Our Ref : 217190 (LONPAC) / CHAN

MADAM SIOW LEE MEN
7 DAIRY FARM ROAD
#07-01
Singapore 679038

No. : 05688

Date : 12-Dec-2017

PAGE : 1

Not Authorized
1/12/17
Penny Ate Peim

ESTIMATED COST OF REPAIR FOR LEXUS IS250 SJV8370U

- =====
- | | |
|------|-------------------------------|
| 1 pc | Rear bumper fascia |
| 1 pc | Rear bumper reinforcement |
| 1 pc | Rear bumper sponge |
| 1 pc | Rear o/s bumper side retainer |
| 1 pc | Rear o/s bumper reflector |

Beats

841.90	✓
431.60	7
115.50	7
66.90	X
99.80	X

Less 10% : 1,555.70
155.57

- 1 pc Rear bumper lower spoiler
1 pc Rear bumper reverse sensor(set

n 1,400.13
350.00 sn X
300.00 sn 7
500.00 429

To putty and spray replaced parts

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

350.00 259

Total : S\$ 2,900.13

Singapore Dollars Two Thousand Nine Hundred and
Cents Thirteen Only

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: