From.	Date: 13.12,2017	Van No. SKB 4327R	Yr Baco: Dor	Sur
Estimated Cost:	Ds.cs	Type: A Car / M. Cycle / Bus / Van / Lorry	•	
OD TP WS / TP RES /		Truck / Trailer or		
To inspect Vehicle No:	SKB 4327R	Make: Volksmaren Passa	71.87 as	1798
at Workshop m/s	Nyfemadau			Std / NI / NA
of	247 Alexandra Rd	Sp. Reading 162118	T-Radic: Insured /	Std / NI / NA
Inquired:		Eng/No:		
Boliov No.		C/No: WV W 222 3C	29656107	9
Claims No.		Gen. Cond: Good Parl Poor / Burnt		
Sum Insured:	Excess:	Steering: Inouder / Jammed / Leaked / B	urnt or	
(Client's Record)		Brake: Knorder / Jammed / Leaked / B	urnt or	
Make of Veh:		Modi: Nil / 8/Rim / STD A/Rim or		
•	9.30cm	Tyre Size: F: 235	421-17	
(Policy Condition)	owner waiting	R:		
Remark: The veh had co		BS / DUN / EXNOVA / GY / FS / LIZA / N	IIC / OHTSU/PIP/	SUMI/
repair at the tin	ne of inspection.	TOYO / YOKO or		
Bal. or Market Value:	34K	Front	Rear /	
IDAC Accident Rport:	Consistent? : Yes or No	R/Bal. mm	R/Bal.	mm
GIA / PR Seen:	Consistent? : Yes or No	L/Bal mm	L'Bal. 6	1 .2
Est. Repairs:	days Res.: Yes or No % 3 Val.: Yes or No	D.O.A. 16 12 17	D.O.1. 14/12 En Mexamak	
Lum Sum:	% 3 Val.: Yes or No	1		• •
CA / REV / REP. /	/ 24 HRS Vehicle: IN / OUT	Des. of Damages From Rear / O/S / !	N/S / U/C / ROOM	ob et
Date: Pe	erson Contacted:	The U/C / Chassis frame / Body S	Structure affected of	iue to collision.
Date / Time Action	/ Instruction			
ul I z. ·	1 1 11 1100			
1415/11 Cur	l to volks when			
		······································		
	NE SEE			
			 ——	
Date/Time: File Pass to?	: Preli. Report	Days Of Repair: 15		
1) typist	: Final Report	Resurvey No. of Trip:	Survey Fee.	220
Cate/Time, File Return to?			Tiensportation.	
3	Add Fee		<u>\$</u> = \$5 <u>\$</u> ;	
	70	: Interview \$	Proces	
Report Format :	[[]	Tech. In As IS	(merc	
Lump Sum-/ I.B.I: (\$	15,175.33	Neekend S		^
			-1-i	סבכ [

...CLAIM SUBFOLDER...(New Assignment)

LAIM SUBFOLDER TRACKING								
Case	Notified	Est Submitted	Adj Assigned	Adj Rot	Adj Submitted	Ins Authled	Status	
Main	13 Dec 2017		13 Dec 2017 17:08 Assign				New Assignment Cancel Case	

Main	Reference	Claim Details	Documents	Show All
CLAIM SUBFOLDER DET	AILS		[Created by insurer]	
Insured:	SEE CHEE MUN(SHI ZHIWEN),	ID: S8636402F		
Main Claimant:	GOH TONG MENG TONY, ID: S	0194631E		
Vehicle Reg. No.:	SKB4327R	Date of Loss:	10/12/2017 16:00 - :59	
Claim Type:	TP / SNM17D07046C02/2S	Policy/Cover Note No.:	DMPCSN3075731600 (Comprehensive)	
Vehicle Reg. No. (Insured):	SLD6682D	Policy No. (Claimant):	A 27905086 QMX	
		Excess:	S\$0.00	
Repairer:	Volkswagen Centre Singapore (Alexandra) 247 Alexandra	Road, 159934 Alexandra - Tel: 64	748288
Handling Insurer:	China Taiping Insurance (Singa	pore) Pte. Ltd. (HQ) - Tel	: 6389 6111 [Handled by Joel (Goh]
Claimant's Insurer:	MSIG Insurance (Singapore) Pt	e. Ltd. (HQ) - Tel: +65 68	27 7888	
Adjuster:	LKK Auto Consultants Pte Ltd (I	HQ) - Tel: 6256-3561 [F	inal Rpt due 22/12/2017]	
Driver/Custodian (Insured)	: SEE CHEE MUN(SHI ZHIWEN) (31 /	/ Male), NRIC: S8636402F	=	
Adj Asg. Remarks:	ESTIMATES AS ATTACHED SELECT	ED AS SJE		
ASSOCIATED MAIL REC	EIVED		View All Compo	se Case Mail
There are no mail for this c	ase.			
ALL ASSOCIATED TASK	(SE)	View All	Search Tasks Create New Task	Complete
Due Date Priority	Type Task Group Subject Ha	indler Assigned By	Completed On Created C	n Done
No results.				



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation Internati	onale Des Experts En Auton	iobile:					
CHINA TAIPING INSU	URANCE (S) PTE LTD	Ref : CS/CTI170237	26/R1rd3					
3 ANSON ROAD #16 SPRINGLEAF TOWE	-00 RSINGAPORE 079909	Date: 14-12-2017 Code: CTI	Archanged a control of the control o					
1	Policy Particulars	:- THIRD PARTY CLAI	M					
Insured Veh.	SLD 6682D	Veh. Inspected	SKB 4327R					
Policy No.	DMPCSN3075731600	Coverage (\$)	0.00					
Claim No.	\$NM17D07046C02/2\$	Excess (\$)	0.00					
Assign From	MERIMEN (JOEL GOH)	Assign Date	14/12/2017					
2.	Vehicle Part	iculars & Condition	The control of the second					
Make & Model	,	c.c	0					
Engine No.	HIDDEN	Year of Reg.						
Chassis No.		Colour						
Odometer -		Steering						
Brakes		Modification						
General		, , ,						
3.0	Condit	ions of Tyres						
	Size	Make	Balance					
R/H Front Tyre			mm					
L/H Front Tyre			mm					
R/H Rear Tyre			mm					
L/H Rear Tyre			mm					
4.4	Val Descripti	on of Damages						
5. 	- I&MeNa. Genera	al Information						
Accident Date	10/12/2017	Inspection Date	14/12/2017					
Survey held at	VOLKSWAGEN GROUP SING	APORE PTE LTD						
	247 ALEXANDRA ROAD SINGAPORE 159934							
5a. 3	R	emarks						
A)THE INSPECTI	ON WAS CONDUCTED ON A"WI	THOUT PREJUDICE" BAS	IS.					
B)IN ACCORDAN	ICE TO YOUR INSTRUCTIONS, V	VE HAVE NOT AUTHORIS	ED REPAIRS.					

MVA (17162350 - VAC - Bukit Batok ENTRY DATE & TIME: 11/12/2017 10:13

MS16 (Not winner) VS wine Taiping out

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process
- 2 This Form must be completed by the Policyholder and/or the Authorised Driver.
 - 3 Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to
 - 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies

 - 6 This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General insurance Association of Singapore(GiA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
 - / By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

gio: czald	year hereby consent to the archiving of this report at the centre and to copies of the report being made available				
Date Of Report	ACCIDENT STATEMENT				
Date Of Accident	11/12/2017 10:13				
Exact Location Of Accident	10/12/2017 16:20				
Country/State of Loss	AYE TOWARDS TUAS				
oddini yi State Of Loss	SINGAPORE				
Vahida Davista V	DETAILS OF OWN VEHICLE				
Vehicle Registration Number	SKB4327R				

Vehicle Registration Number	DETAILS OF OWN VEHICLE
Insured/Policyholder	SKB4327R
Name Of Registered Owner	CONTRACT
NRIC No	GOH TONG MENG TONY
Email Address	S0194631E
Mobile Phone No	NOEMAIL
wone - Hotte Mo	(LOCAL) +65-96333221

(LOCAL) +65-96333221 Alternative Phone No OFFICE-96333221

Vehicle Particulars

Manufacturer VOLKSWAGEN Model PASSAT TSI-1.8 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy

for repair to your vehicle? NO

If No. Please state action to be taken THIRD PARTY Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company MSIG INSURANCE (SINGAPORE) PTE. LTD. Type Of Coverage

COMPREHENSIVE Fleet Policy

NO

Policy Number A 27905086 QMX Cover Note Number

Driver

Name of Driver GOH TONG MENG TONY NRIC No

S0194631E Date Of Birth 22/08/1951 Occupation OUTDOOR Date Of Driving Pass 14/03/1969

Driving Experience 48 YEARS AND 8 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-96333221

Fax Number

Contact Number OFFICE-96333221

EMail Address NOEMAIL Address

2C JALAN MAS KUNING

Postcode

S128691

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident CHAIN COLLISION Weather Conditions

GOING TO RAIN Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident? Was any body injured in the Accident?

NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police?

NO

NO

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

If Yes, against whom?

Circumstances of Accident

ON SUNDAY 10TH DEC 2017 AROND 1620HRS, MET WITH A CHAIN OF VEHICLE COLLISION ALONG AYE, NEAR UNIVERSITY BRIDGE TOWARDS TUAS ROAD. MY VEHICLE (SKB4327R) WAS BEING HIT BY VEHICLE (SLD6682D) AND MY VEHICLE WAS BEING PUSHED FORWARD THEN COLLIDED WITH THE VEHICLE (SJP5756S), VEHICLE 3 THEN COLLIDED INTO NO 4(SHC5274H). MY VEHICLE SUSTAINED DAMAGES ON THE FRONT AND REAR PORTION. Attachment(s)

Are accident photos available for attachment? YES Was there any video captured by Car Camera?

Remarks/ Reasons: FRONT CAMERA

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLD6682D

Vehicle Make/Model/Colour MERCEDES BENZ

Details Of Properties

Name of Driver SEE CHEE MUN

NRIC/Passport Number

Contact Number 81282383

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SJP5756S

· Vehicle Make/Model/Colour

HONDA JAZZ

Details Of Properties

Name of Driver NRIC/Passport Number

GOH CHECK HUANG

Contact Number

96927872

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

SHC5274H

Vehicle Make/Model/Colour

TRANSCAB

Details Of Properties

SENG YEW CHOR

NRIC/Passport Number

91007650

Contact Number

Name of Driver

Address Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance
- Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of
- 8 Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that.

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of ·
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary
 - (ii) investigating the accident and/or my claims;
 - [iii] carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and (c)
- my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud. regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 10/12/17

Dr.ver's Signature

10-25 Am (If driver is not the policyholder)
Date & Time: 10/12/17 10-25 Am

IDAC BURIT BATOK (VAC) 511 Borett Barks St 23

Reporting Centre Personnel's Signature 2 Name: Fax: 3368 0722

NRIC(FINAR: vacbb@singnet.com.sq

Sketch Plan #2 Pg. 1

SKETCH PLAN

-			
March Co.	Agree.		
n — — — — — — — — — — — — — — — — — — —		CKBIBAR SIPERUS. VSI	H <u>C</u> x,
DESCRIBE CIRCUMSTANCES C	OF THE ACCIDENT		
		- C. 200	
		<u></u>	
			
LARATION son the the foregoing participles.	H. The Harriston pro-		
1 1 DEC 2017	- Ton full	And the second	U /
yn Tall garthros Nife o	Construction of the particle of the construction of the particle of the partic	Reporting that repersonnel's Signature of	



MSIG Insurance (Singapore) Pte. Ltd. 4 Spenton Way. # 21-01. SGX Centre 2, Singapore 058807 1ef ±55 6827 7888. Fax ±65 6827 7800 10 Feg No. 200412212G GST Reg. No. 20-041271. G

Certificate of Insurance

POAD TRANSPORT ACT 1967 (MALAYSIA)

THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)

THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)

(REPUBLIC OF SINGAPORE)

THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)
OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form $M:X:\mathbb{F}$

Individual Ownership

MOTOR MAX
Comprehensive

Certificate No. A 27905086 GMX

Excess: SGD1,500
Windscreen Excess: SGD100

Index Mark and Registration Number of Vehicle

SKB4327R

2. Name of Policyholder

Joh Tong Meng Tony

3. Effective Date of the Commencement of Insurance for the purposes of the Act

09/06/**2017**

4. Date of Expiry of Insurance

08/06/2018

5 Persons or Classes of Persons entitled to drive

Coh Tong Meng Tony

Any other person provided he is do stay at the Policyholder's order or with the Policyholder's permission.

* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Meter Vehicle.

6. Limitations as to use*

Ose only for social demestic and pleasure purposes and for the Policyholder's business. The Policy does not dover use for name or leward racing pace-making reliability trial speed-besting the carriage of goods other than samples in connection with any brade of distincts or use for any purpose in connection with the Woter France

* Limitations rendered inoperative by Section 8 of the Motor Venicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

PLEASE NOTE ALL CLAIMS RELATED REPAIR MUST BE CARRIED OUT AT ANY MSIG AUTHORISED WORKSHOP LISTED IN THE ATTACHED


This Certificate is not transferable to a new owner of the venicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189)

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment. Act or Acts passed in substitution thereof.

MSIG Insurance (Singapore) Pte. Ltd.

Approved insurers

for Chief Executive Officer



















2C JALAN MAS KUNING BINGAPORE 0512

Enquire PARF/COE Rebate for Registered Vehicle

year and a summer of the summe	The state of the second st	
Vehicle Owner Particulars		
Owner ID Type	Singapore NRIC	
Owner ID	4631E	
Vehicle Details		
Vehicle No.	SKB4327R	
Vehicle to be Exported	No	
Intended De-registration Date	14 Dec 2017	
Vehicle Make	VOLKSWAGEN	-
Vehicle Model	PASSAT CC 1.8T AT 3572J7	
Primary Colour	Brown	
Manufacturing Year	2009	
Engine No.	BZB101114	
Chassis No.	WVWZZZ3CZ9E561079	
Maximum Power Output	118.0 kW (158 bhp)	
Open Market Value	\$30,445.00	
Original Registration Date	09 Jun 2009	
First Registration Date	09 Jun 2009	• •
Transfer Count	1	
Actual ARF Paid	\$30,445.00	
Intended PARF Rebate Details		:
PARF Eligibility	Yes	
PARF Eligibility Expiry Date	08 Jun 2019	AL MANY CONTRACTOR AND A
PARF Rebate Amount	\$16,744.00	W. ove
Intended COE Rebate Details		34,000
COE Expiry Date	08 Jun 2019	17,833
COE Category	B - Car (1601cc & above)	1108
COE Period(Years)	10	14, 14,
QP Paid	\$7,490.00	10/
COE Rebate Amount	\$1,111.00	
Total Rebate Amount	\$17,855.00	

The information contained herein is correct as at 14 Dec 2017

Land Transport Authority

Please read through the Privacy Statement, Terms of Use, and Disclaimer.

Please do not use the Back or Forward buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 10 and above, Chrome, Firefox, and Safari.

Copyright 2017 LTAPrivacy StatementTerms of UseDisclaimerRate the WebsiteRate this e-Service

Last updated on 19 Nov 2017 at 12:12 AM

Rasul (LKKAuto)

From:

Rasul (LKKAuto)

Sent:

Thursday, 14 December, 2017 6:34 PM

To:

Foo, John (VWG Singapore)

Cc:

Janice Lee (LKKAuto); 'Kong, Charmaine (VWG Singapore)'; Wong, Meiy (VWG

Singapore); 'Cheong, Pearlyn (VWG Singapore)'; Oh, Aik Seong (VWG Singapore)

Subject:

SKB 4327R DOA: 10/12/2017

Hi John,

As spoken, repair limit to repair this vehicle is 14K

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>Rasul@lkkauto.com</u> | fax: 6841-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Save the Earth Print only when necessary

PDI TUAS

Mister GOH TONG MENG TONY 2C JALAN MAS KUNING 128691

Phone No. Fax No. E-Mail

VAT Registration No. M20098505-2 Tax No. 199101494Z

Service Quote

Customer No. Quote No.

S0194631E

SER/QUO/1702043 QuoteDate

11/12/17

Salesperson

Page 1

THIS IS NOT AN OFFICIAL TAX INVOICE

Make Volkswagen Passeng PASSAT CC 1.8 118KW+4KF+8T2+8 160,537

Model Description

Mileage

Service Advisor

License No. SKB4327R

VIN WVWZZZ3CZ9E561079 Initial Registration

Sales Advisor

Engine Code

Labor Type

09/06/09 Engine No.

Model Code

BZB

11

101114 3572J7

	No.	Description	Qty.	UoM	Unit Price	Amount
P	B&P ALEX LABOUR	LABOUR FRT	6	UNIT	7184	3360 5,040,00
P		LABOUR REAR	_	UNIT	1638	2520 6,720.00
, P	B&P ALEX LABOUR	TRANSFER BOOT LID MECHANIS	1	UNIT	1000 1343	420 840.00
Р	B&P ALEX PAINT	SPRAY PAINT FRT	6	UNIT	26 8€	3200 4,800,00
Р		SPRAY PAINT REAR	_	UNIT	1560	2400 4800.00
Р	B&P NUMBER PLATE	B&P NUMBER PLATE FRT & REA	_	pcs	1560	PA 160.00
P		PROGRAMMING & CALIBRATION	1	Time Un	216	480.00
·		COMPULSORY TO DO AFTER AC	·		<i>3</i> C	
Р	B&P MECH	ELECT WIRING & MECH COMPO	1	Time Un		
		Nett				
		Sum Labor				23,120.00
Р	1K5827507	LOCK STRIKER	1	Pieces		\$ X35.04
Р		NAME PLATE -TSI	•	Pieces		> 254.70
P		REINFORCEMENT	•	Pieces		SUC 7 798.61
P	3C0853600A MQH	VW SIGN	1	Pieces	.57.54	127.86
		Use Predecessor 1K5853600 MQ	·			A .
Р	3C1823509H	LOCK	1	Pieces	<u>8</u> 3.	<u>хн</u> 186.31
		Use Predecessor 3C1823509G			1362	
Ρ	3C5807305	BUMPER REINFORCEMENT REA	1	Pieces		LSU \$ 567.15
		Do Not Unblock-Check Eugene Ng				
Р	3C5827469K ULM	MECHANISM	1	Pieces		1. 362.62
		Use Predecessor 3C5827469J UL				
Р	3C5827520B 9B9	REAR BOOT LOCK COVER	1	Pieces	6.87	15.27
P	3C8121283A	AIR GUIDE LH	1	Pieces	18.,34	CRA/ 3/ 40.75
		Do Not Unblock-Check Eugene Ng				

Sum carried forward

25,308.31

PD! TUAS

Mister GOH TONG MENG TONY 2C JALAN MAS KUNING 128691

Phone No. Fax No. E-Mail

VAT Registration No. M20098505-2 199101494Z Tax No.

Service Quote

Customer No.

S0194631E

Quote No. QuoteDate SER/QUO/1702043

11/12/17

Salesperson

2 Page

THIS IS NOT AN OFFICIAL TAX INVOICE

Model Description Mileage Service Advisor Make Volkswagen Passeng PASSAT CC 1.8 118KW+4KF+8T2+8 160,537 Initial Registration Sales Advisor License No. SKB4327R WVWZZZ3CZ9E561079 09/06/09 Engine No. **Model Code** Engine Code **Labor Type** 3572J7 101114 BZB

				Continued		25,308.31
	3C8121284C	AIR GUIDE RH	1	Pieces		Su 2 40.75
-	3001212040	Predecessor 3C8121284B	•	1 10003		1
Р	3C8121330B	AIR GUIDE UPPER	1	Pieces	28.58	63.52
Р	3C8805588C	LOCK CARRIER	1	Pieces	621.27	CP4 1,380.60
Ρ	3C8807183A	FR BUMPER SIDE BRACKET LH Use Predecessor 3C8807183	1	Pieces	14.60	ke /32.44
Ρ	3C8807184A	FR BUMPER SIDE BRACKET RH Predecessor 3C8807184	1	Pieces	14.60	32.44
Р	3C8807217N GRU	FRONT BUMPER Predecessor 3C8807217G GRU	1	Pieces	\$ H +¢¢	/a .
Р	3C8807248D	FRONT BUMPER FOAM	1	Pieces	78.93	175.39
Ρ	3C8807252B	FOAM INSER	1	Pieces		101.05
Р	3C8807285C 9B9	FR LICENCE PLATE HOLDER	1	Pieces	GF.95	(A) (150.99
Ρ	3C8807393B	BUMPER SIDE BRACKET LH Predecessor 3C8807393A	1	Pieces	ጋ ዚ.18 [.]	14 53.73
Ρ	3C8807394B	BUMPER SIDE BRACKET RH Predecessor 3C8807394A	1	Pieces	24.18	53.73
Р	3C8807417P GRU	REAR BUMPER Use Predecessor 3C8807417D GR	1	Pieces	9 %6.84	2,192.97
Ρ	3C8807443A 2ZZ	BUMPER MOLDING CENTRE Use Predecessor 3C8807443 2ZZ	1	Pieces	100.50	Cut 223.33
P	3C8807459A 2ZZ	BUMPER MOLDING LH Use Predecessor 3C8807459 2ZZ	1	Pieces	43.59	CPA 163.53
Ρ	3C8807460A 2ZZ	BUMPER MOLDING CENTRE Predecessor 3C8807460 2ZZ	1	Pieces	103,40	cut 229.77
Ρ	3C8807521 9B9	SPOILER	1	Pieces	5	ジンマ 340.44 大
				Sum carried for	orward	32,478.68

- BBN: - Acc.-No..:

PDI TUAS

Mister GOH TONG MENG TONY 2C JALAN MAS KUNING 128691 Phone No. Fax No. E-Mail

VAT Registration No. M20098505-2 Tax No. M20098505-2 199101494Z

Service Quote

Customer No.

S0194631E

Quote No.

SER/QUO/1702043

QuoteDate

11/12/17

Salesperson Page

3

THIS IS NOT AN OFFICIAL TAX INVOICE

Model Description Mileage Service Advisor Make Volkswagen Passeng PASSAT CC 1.8 118KW+4KF+8T2+8 160,537 Initial Registration Sales Advisor License No. SKB4327R WVWZZZ3CZ9E561079 09/06/09 Engine No. **Model Code Engine Code** Labor Type 101114 3572J7 BZB 11

				Continued		32,478.68
Ρ	3C8807651B 9B9	BUMPER LOWER SPOILER Use Predecessor 3C8807651 9B9	1	Pieces	,	dul 🕱 205.08
Р	3C8807863C	BUMPER CENTRE BRACKET Predecessor 3C8807863B	1	Pieces	4 3+tt	95.79
Р	3C8823031B	FRT BONET Use Predecessor 3C8823031A	1	Pieces	977.18	4.0
Р	3C8823301A	HINGE LH	1	Pieces	•	Sv. 📉 💢 133.15
Ρ	3C8823302A	HINGE RH	1	Pieces	Γ	133.15 133.15 102.57
Ρ	3C8823480	LATCH	1	Pieces) 🥕 102.57
		Successor 3C8823480A				-1/
Ρ	3C8827025C	REAR BOOT LID	1	Pieces	1086.67	2,414.82
		Predecessor 3C8827025B				19.
Ρ	3C8827301A	HINGE LH		Pieces	0,,0	- (' × 190.08 190.08
Ρ	3C8827302A	HINGE RH		Pieces	20.	
Ρ	3C8827705B 5AP	WETHERSTRIP	1	Pieces		147.24
		Use Predecessor 3C8827705A 5A				41 0.
Ρ	3C8853465A 041	BOOT LID TRIM (BLACK)	1	Pieces	278.7c	619.33
		Use Predecessor 3C8853465 041			617 <i>6</i> 7	204
Р	3C8853651Q GRU	FRONT RADIATOR GRILLE	1	Pieces	517.56	1,150.14
		Use Predecessor 3C8853651N GR			4	sr 🗴 240.49
Ρ	3C8853677 9B9	FR CENTER LOWER GRILLE	•	Pieces	nu ć	
Р	3C8853687A 739	NAME PLATE - PASSAT	1	Pieces	34.Ca	Nec 76.93
		Use Predecessor 3C8853687 739				80.
Ρ	3C8853687B 739	NAME PLATE - CC		Pieces	.33 88	75.28
Ρ	3C8867605H 8W4	REAR BOOT LID TRIM COVER	1	Pieces	,	fsu 🖟 228.13
		Do Not Unblock-Check Eugene Ng				

Sum carried forward

40,652.44

PDITUAS

Mister GOH TONG MENG TONY 2C JALAN MAS KUNING 128691

Phone No. Fax No. E-Mail

VAT Registration No. M20098505-2 199101494Z Tax No.

Service Quote

Customer No.

S0194631E

Quote No.

SER/QUO/1702043

QuoteDate

11/12/17

Salesperson

Page

THIS IS NOT AN OFFICIAL TAX INVOICE

Make

Model Description

Mileage

Service Advisor

Volkswagen Passeng

PASSAT CC 1.8 118KW+4KF+8T2+8

Sum Item

WVWZZZ3CZ9E561079

160,537

License No. SKB4327R

Initial Registration 09/06/09

Sales Advisor

Engine Code

BZB

Labor Type

Engine No.

Model Code

101114

3572J7

HEADLIGHT LH P 3C8941005D **HEADLIGHT RH** P 3C8941006D REAR BOOT LOCK P 4F5827505D 1PK ADHES. P D 172090A2 P N 0385494 **RIVET** NUT P N 10621301

1 Pieces 1 Pieces 1 Pieces 1 Pieces

Continued

350:10

1,222,45 🔭 1,222.45 **M** 🖊 198.63

6 Pieces

49. F3 6.84 7.70

89.38

110.52 **~~~** 1.86 17.12 سمع

8 Pieces

20,305.47

40,652.44

Sum Labor Sum Item

23,120.00 20,305.47

Total 7% GST

SGD

43,425.47

43,425.47 3,039.78

45 486. 77

Total SGD Incl. GST

46,465.25

Explanations

P = Proportionately Charged

Payment Terms

No Credit

14 90010068
14 (B) days
14/12/17 P 0930
Rosey 64 pand

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

Service Order Confirmation

SERVICE ORDER NO: 17IP3408 CUSTOMER NO .: S0194631E

CUSTOMER NAME: Mister GOH TONG MENG

TELEPHONE NO.:

ADDRESS: 2C JALAN MAS KUNING

VEH No.: SKB4327R

14/12/17 Order Date:

MODEL:

Reg Date: 09/06/09

162,265 KM: ENGINE NO: BZB VIN NO.: WVWZZZ3CZ9E561079

PASSAT CC 1.8 118KW+4KF+8T2MODEL NO.: 3572J7

SA: Wong Meiy

	No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
	Labor						/
1	B&P MECH	ELECT WIRING & MECH COMPONENT CHECK NETT	1	TŲ	280	55	126 -
2	B&P DIAG	PROGRAMMING & CALIBRATION- NETT	1	Tΰ	480	55	216 ~
3	B&P SUNDRIES	AIR CON GAS	48	TU	1.25	55	- 27
4	B&P AIRCON	VACUUM & REGAS AIRCON-NETT	1	TU	420	50	~ 210 _.
5	B&P ALEX LABOUR	LABOUR FRT	4	UNIT	840	35	2,184
6	B&P ALEX PAINT	SPRAY PAINT FRT	4	UNIT	800	35	- 2,080
7	B&P ALEX LABOUR	LABOUR REAR	3	UNIT	840	35	1,638
В	B&P ALEX PAINT	SPRAY PAINT REAR	3	UNIT	800	35	1,560
9	B&P ALEX LABOUR	TRANSFER BOOT LID MECHANISM	0.5	UNIT	840	35	273
10	B&P NUMBER PLATE	B&P NUMBER PLATE FRT & REAR	2	ST	80	35	104 8418
	item						_
11	3C8823031B	FRT BONNET	1	PCS	2,171.50	55	977.18
12	3C1823509H	LOCK	1	PCS	186.31	55	83.84 >
13	3C8807217N GRU	FRONT BUMPER	1	PCS	1,935.69	55	871.06 /
14	3C8807184A	FR BUMPER SIDE BRACKET RH	1	PCS	32.44	55	14.60
15	3C8807183A	FR BUMPER SIDE BRACKET LH	1	PCS	32.44	55	14.60
16	3C8807285C 9B9	FR LICENCE PLATE HOLDER	1	PCS	150.99	55	67.95
17	N 0385494	RIVET	6	PCS	0.31	55	0.84
18	3C8853651Q GRU	FRONT RADIATOR GRILLE	1	PCS	1,150.14	55	517.56
19	3C0853600A MQH	vw sign	1	PCS	127.86	55	57.54
20	3C8805588C	LOCK CARRIER	1	PCS	1,380.60	55	621.27 _
21	3C8827025C	REAR BOOT LID	1	PCS	2,414.82	55	1,086.67
22	3C8853465A 041	BOOT LID TRIM (BLACK)	1	PCS	619.33	55	278.70 ~
23	4F5827505D	REAR BOOT LOCK	1	PCS	198.63	55	89.38
24	3C5827520B 9B9	REAR BOOT LOCK COVER	1	PCS	15.27	55	6.87
25	3C8827705A 5AP	GASKET () New /	1	PCS	134.60	55	60.57 🤛
26	D 172090A2	1PK ADHES.	1	PCS	110.52	55	49.73 /
27	3C8853687A 739	NAME PLATE - PASSAT	1	PCS	76.93	55	34.62
28	3C8853687B 739	NAME PLATE - CC	1	PCS	75.28	55	33.88

Service Order Confirmation

SERVICE ORDER NO: 17/P3408 CUSTOMER NO.: S0194631E

CUSTOMER NAME: Mister GOH TONG MENG

TELEPHONE NO.:

ADDRESS:

2C JALAN MAS KUNING

VEH No.: SKB4327R

Order Date:

14/12/17

Reg Date:

09/06/09

· KM:

162,265

VIN NO.: MODEL:

ENGINE NO: BZB WVWZZZ3CZ9E561079 PASSAT CC 1.8 118KW+4KF+8T2-MODEL NO.: 3572J7

	No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
29	3C8807417P GRU	REAR BUMPER	1	PÇS	2,192.97	55	986.84
30	N 10621301	NUT	8	PCS	2.14	55	7.70
31	3C8807863C	BUMPER CENTRE BRACKET	1	PCS	95.79	55	43.11 /
32	3C8807393B	BUMPER SIDE BRACKET LH	1	PCS	53.73	55	24.18 /
33	3C8807394B	BUMPER SIDE BRACKET RH	1	PCS	53.73	55	24.18 /
34	3C8807443A 2ZZ	BUMPER MOLDING CENTRE	1	PCS	223.33	55	100.50 🗸
35	3C8807459A 2ZZ	BUMPER MOLDING LH	1	PCS	163.53	55	73.59 /
36	3C8807460A 2ZZ	BUMPER MOLDING CENTRE	1	PCS	229.77	55	103.40
37	3C0820411F	AC CONDENSER	1	PCS	932.95	55	419.83
38	3C8121283A	AIR GUIDE LH	1	PCS	40.75	55	18.34 /
39	3C8121330B	AIR GUIDE UPPER	1	PCS	63.52	55	28.58
40	3C8807248D	FRONT BUMPER FOAM	1	PCS	175.39	55	78.93 /
41	3C8941005D	HEADLIGHT LH	1	PCS	1,222.45	55	550.10
42	3C8945095G	TAILLIGHT OUTER LH	1	PCS	412.86	55	185.79 -
43	1K5853675J GQF	(A) TSILOGO CAR NE	1	PCS	50.40	55	22.68
44	3C8945311A 9B9	(A) TRIM (A)	1	PCS	50.49	55	22.72
44	200340011W 203	5 i, 11 iiii					

Remarks : DIRECT SETTLEMENT

DOA:

SURVEY BY RASUL

REPAIR LIMIT \$16,000

SA: Wong Meiy

Service Order Confirmation

CUSTOMER NO.	: \$0194631E								
CUSTOMER NAM	ME: Mister GOH TON	IG MENG							
TELEPHONE NO	u:								
ADDRESS:	2C JALAN MAS	KUNING							
VEH No.	: SKB432	27R							
Order Date:	14/12/17								
Reg Date:	09/06/09	KM:	162,265						
VIN NO.:	WVWZZZ3CZ9E5610	79 ENG	INE NO: BZB					SA: W	ong Meiy
MODEL:	PASSAT CC 1.8 118K	W+4KF+8T2 MO I	DEL NO.: 3572J7						
No.	<u>D</u> E	SCRIPTION			<u>oty</u>	<u>uom</u>	UNIT PRICE	DISC %	AMOUNT
						тот	AL		15,975.30
						GST	AMOUNT		1,118.27
						тот	AL AMOUNT		17,093.57
			On Behalf Of "COMPAR	4 Y"		(Certifled Goods/S	service received:	
			Authorized S	ignature				Customer	
	TUIC IC NOT A	V OFFICIAL	DECEIDT						

SERVICE ORDER NO: 17/P3408

Supplementary or Omitted List

VEHICLE NUMBER:

SKB4327R

MODEL

PASSET cc

CLAIMS DETAILS



	LABOUR DESCRIPTION			Ą	MOUNT		
			Qty	\neg	Unit	A	mount
1	AIR CON GAS		1	\$	60.00	\$	60.00
	VACUUM & REGAS AIRCON-NETT		_ 1 _	\$	420.00	\$	420.00
				\bot	<u>-</u>		
		Total		\dashv		\$	480.00

No.	Item No.	Description	Qty	Unit Pricing	<u>Discount</u>	<u>Amount</u>
1	3C0820411F	AC CONDENSER	1	\$932.95	41983	\$932.95
2	3C8945095G	TAILLIGHT OUTER LH	1	\$412.86	185.74	\$412.86
3						
						<u> </u>
			TOTAL:			\$1,345.81

Total Labour & Parts

\$1,825.81

Survey By

Page 1 of 1 Merimen e-Claims

...CLAIM SUBFOLDER...(Pending for Survey Report)

LAIM SUB	FOLDER TRACE	(ING								
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj S	ubmitted	Ins Auth'ed	Status		
Main	13 Dec 2017		13 Dec 2017 17:08 Edit Adj Rpt	S\$15,975.33 Edit Estimate	41 .	,975.33 w Rpt		Pending for Survey Report Cancel Case		
	Main	Refere	ence	Claim Detai	ls		ocuments	Show All		
	BFOLDER DET						[Created by i	nsurer]		
Insured:			JN(SHI ZHIWEN)	<u> </u>	=					
Main Claim			IENG TONY, ID:				T			
Vehicle Reg	g. No.:	SKB4327R		Date of Lo	Date of Loss:			10/12/2017 16:00 - :59		
Claim Type	:	TP / SNM17	D07046C02/2S	Policy/Cov	Policy/Cover Note No.:		DMPCSN3075731600 (Comprehensive)			
Vehicle Reg	g. No. (Insured):	SLD6682D		Policy No.	(Claimani	:):	A 27905086 QMX			
				Excess:			S\$0.00			
Repairer:		Volkswagen	Centre Singapore	e (Alexandra) 24	7 Alexand	Ira Road, 1	59934 Alexandra	- Tel: 64748288		
Handling Ir	nsurer:	China Taipin	g Insurance (Sin	gapore) Pte. Ltd	. (HQ) - `	Tel: 6389 6	111 [Handled	by Joel Goh}		
Claimant's	Insurer:	MSIG Insura	nce (Singapore)	Pte. Ltd. (HQ) -	Tel: +65	5827 7888				
Adjuster:		LKK Auto Co 22/12/2017		(HQ) - Tel: 6256	5-3561	[Handled b	y MOHD RASUL]	[Final Rpt du		
Driver/Cus	todian (Insured):	SEE CHEE MU	N(SHI ZHIWEN) (3	1 / Female), NF	IC: S8636	5402F				
Adj Asg. Re	emarks:	ESTIMATES A	S ATTACHED SELEC	CTED AS SJE						
ASSOCIA	TED MAIL RECI	IVED					View All	Compose Case Mai		
There are no mail for this case.										
ALL ASSO	CIATED TASK	s ⁼			View All	Search T	asks Create N	ew Task Complete		

Subject Handler

Due Date

No results.

Priority Type

Task Group

Completed On

Assigned By

Page 1 of 5 Merimen e-Claims

Claim Documents

*SKB4327R (SNM17D07046C02/2S) [SLD6682D] **GOH TONG MENG TONY** Dec 10 2017 4:00PM [SEE CHEE MUN(SHI ZHIWEN)] Volkswagen Centre Singapore

Uρ	load Documents	pload Photos Compose New Letter	View View in Bro	owser 🗸
Ass	essment Reports		1 per page 🔻	☑
No	Finalized On	VAC (Bukit Batok)	Thumbnail	Print
1	11/12/17 10:32	Accident Statement	1 Load HTM	
Pho	tos/Images		3 per page ✓	\square
No	Finalized On	VAC (Bukit Batok)	Thumbnail	Print
1	11/12/17 10:29	Accident Photo [Linked Accident Report Documents]	1 Load JPG	7
2	11/12/17 10:29	Accident Photo [Linked Accident Report Documents]	1 Load JPG	Z
3	11/12/17 10:29	Accident Photo [Linked Accident Report Documents]	1 Load JPG	\square
4	11/12/17 10:29	Accident Photo [Linked Accident Report Documents]	1 Load JPG	\mathbf{Z}
5	11/12/17 10:29	Accident Photo [Linked Accident Report Documents]	1 Load JPG	Z
6	11/12/17 10:29	Accident Photo [Linked Accident Report Documents]	■ Load JPG	Ø
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/03/18 09:29	General View	■ Load JPG	\square
2	14/03/18 09:29	General View	1 Load JPG	$ \mathbf{\nabla} $
3	14/03/18 09:29	General View	1 Load JPG	☑
4	14/03/18 09:29	General View	Load JPG	3
5	14/03/18 09:29	General View	1 Load JPG	V
6	14/03/18 09:29	General View	1 Load JPG	V
7	14/03/18 09:29	General View	1 Load JPG	Ø
8	14/03/18 09:29	General View	Load JPG	V
9	14/03/18 09:29	General View	Load JPG	$\overline{\mathbf{Z}}$
10	14/03/18 09:29	General View	Load JPG	$\overline{\mathbf{V}}$
11	14/03/18 09:29	General View	1 Load JPG	$\overline{\mathbf{Z}}$
12	14/03/18 09:29	General View	Load JPG	7
13	14/03/18 09:29	General View	1 Load JPG	Z
14	14/03/18 09:29	General View	■ Load JPG	4
15	14/03/18 09:29	General View	■ Load JPG	Z
16	14/03/18 09:29	General View	1 Load JPG	☑
17	14/03/18 09:29	General View	1 Load JPG	\square
18	14/03/18 09:29	General View	1 Load JPG	✓
19	14/03/18 09:29	General View	1 Load JPG	☑
20	14/03/18 09:29	General View	1 Load JPG	3
21	14/03/18 09:29	General View	1 Load JPG	Ø
22	14/03/18 09:29	General View	1 Load JPG	3
23	14/03/18 09:29	General View	1 Load JPG	Ø

25 14 26 14 27 14 28 14 29 14	14/03/18 09:29 14/03/18 09:29 14/03/18 09:29 14/03/18 09:29	General View	0	Load JPG	Y
26 14 27 14 28 14 29 14	14/03/18 09:29		_		(LXJ
27 14 28 14 29 14		General View	0	Load JPG	3
28 14 29 14		General View	0	Load JPG	<u> </u>
29 14	14/03/18 09:29	General View	0	Load JPG	Z
	14/03/18 09:29	General View	0	Load JPG	Z
20 1-	4/03/18 09:29	General View	0	Load JPG	V
31 14	14/03/18 09:29	General View	Ö	Load JPG	2
	14/03/18 09:29	General View	0	Load JPG	<u> </u>
·	14/03/18 09:29	General View	0	Load JPG	☑
 +-		General View	0	Load JPG	☑
	14/03/18 09:29	General View	0	Load JPG	2
	14/03/18 09:29		0	Load JPG	\square
	14/03/18 09:29	General View	0	Load JPG	
	14/03/18 09:29	General View	+= -		
	14/03/18 09:29	General View	0	Load JPG	
-	14/03/18 09:29	General View	0	Load JPG	
-	14/03/18 09:29	General View	0	Load JPG	7
· · · · · · · · · · · · · · · · · · ·	14/03/18 09:29	General View	0	Load JPG	<u>Z</u>
	14/03/18 09:29	General View	0	Load JPG	
	14/03/18 09:29	General View	0	Load JPG	
h+	14/03/18 09:29	General View	0	Load JPG	
45 14	14/03/18 09:29	General View	0	Load JPG	
46 14	14/03/18 09:29	General View	0	Load JPG	
47 14	14/03/18 09:29	General View	0	Load JPG	<u> </u>
48 14	4/03/18 09:29	General View	0	Load JPG	✓
49 14	14/03/18 09:29	General View	0	Load JPG	Z
50 14	14/03/18 09:29	General View	0	Load JPG	3
51 14	4/03/18 09:29	General View	0	Load JPG	Y
52 14	4/03/18 09:29	General View	0	Load JPG	Z
53 14	14/03/18 09:29	General View	0	Load JPG	Z
54 14	4/03/18 09:29	General View	0	Load JPG	7
55 14	4/03/18 09:29	General View	0	Load JPG	\square
56 14	4/03/18 09:29	General Yiew	0	Load JPG	☑
57 14	4/03/18 09:29	General View	0	Load JPG	\\ \I
58 14	4/03/18 09:29	General View	0	Load JPG	Z
59 14	4/03/18 09:29	General View	0	Load JPG	Ø
60 14	.4/03/18 09:29	General View	0	Load JPG	☑
61 14	4/03/18 09:29	General View	0	Load JPG	∡
62 14	4/03/18 09:29	General View	0	Load JPG	Z
63 14	4/03/18 09:29	General View	0	Load JPG	☑
64 14	4/03/18 09:29	General View	0	Load JPG	Ø
65 14	4/03/18 09:29	General View	0	Load JPG	Ø
66 14	14/03/18 09:29	General View	0	Load JPG	☑
67 14	.4/03/18 09:29	General View	0	Load JPG	Ø
68 14	4/03/18 09:29	General View	0	Load JPG	V
69 14	4/03/18 09:29	General View	0	Load JPG	V
70 14	4/03/18 09:29	General View	0	Load JPG	Ø
71 14	4/03/18 09:29	General View	0	Load JPG	☑
72 14	4/03/18 09:29	General View	0	Load JPG	☑
73 14	14/03/18 09:29	General View	0	Load JPG	Ø

74	14/03/18 09:29	General View		Load JPG	
75	14/03/18 09:29	General View	0	Load JPG	\mathbf{Z}
76	14/03/18 09:29	General View	0	Load JPG	\square
77	14/03/18 09:29	General View	0	Load JPG	\square
78	14/03/18 09:29	General View	0	Load JPG	\square
79	14/03/18 09:29	General View	0	Load JPG	\square
80	14/03/18 09:29	General View	0	Load JPG	\square
81	14/03/18 09:29	General View	0	Load JPG	\square
82	14/03/18 09:29	General View	0	Load JPG	Ø
83	14/03/18 09:29	General View	0	Load JPG	\square
84	14/03/18 09:29	General View	0	Load JPG	\square
85	14/03/18 09:29	General View	0	Load JPG	\square
86	14/03/18 09:29	General View	0	Load JPG	Ø
87	14/03/18 09:29	General View	0	Load JPG	\square
88	14/03/18 09:29	General View	0	Load JPG	\square
89	14/03/18 09:29	General View	0	Load JPG	Ø
90	14/03/18 09:29	General View	0	Load JPG	7
91	14/03/18 09:29	General View	0	Load JPG	Z
92	14/03/18 09:29	General View	0	Load JPG	$\overline{\mathbf{Z}}$
93	14/03/18 09:29	General View	0	Load JPG	\square
94	14/03/18 09:29	General View	0	Load JPG	\square
95	14/03/18 09:29	General View	0	Load JPG	☑
96	14/03/18 09:29	General View	0	Load JPG	\square
97	14/03/18 09:29	General View	0	Load JPG	$\overline{\mathbf{Z}}$
98	14/03/18 09:29	Reinspection Photo	0	Load JPG	\square
99	14/03/18 09:29	Reinspection Photo	0	Load JPG	Z
100	14/03/18 09:29	Reinspection Photo	0	Load JPG	\square
101	14/03/18 09:29	Reinspection Photo	0	Load JPG	$\overline{\mathbf{A}}$
102	14/03/18 09:29	Reinspection Photo	0	Load JPG	\square
103	14/03/18 09:29	Reinspection Photo	0	Load JPG	☑
104	14/03/18 09:29	Reinspection Photo	0	Load JPG	\square
105	14/03/18 09:29	Reinspection Photo	0	Load JPG	7
106	14/03/18 09:29	Reinspection Photo	0	Load JPG	\square
107	14/03/18 09:29	Reinspection Photo	0	Load JPG	\square
108	14/03/18 09:29	Reinspection Photo	0	Load JPG	\square
109	14/03/18 09:29	Reinspection Photo	0	Load JPG	\Box
110	14/03/18 09:29	Reinspection Photo	0	Load JPG	S
111	14/03/18 09:29	Reinspection Photo	0	Load JPG	☑
112	14/03/18 09:29	Reinspection Photo	0	Load JPG	☑
113	14/03/18 09:29	Reinspection Photo	0	Load JPG	Ø
114	14/03/18 09:29	Reinspection Photo	0	Load JPG	<u>Z</u>
115	14/03/18 09:29	Reinspection Photo	0	Load JPG	7
116	14/03/18 09:29	Reinspection Photo	0	Load JPG	Z
117	14/03/18 09:29	Reinspection Photo	0	Load JPG	7
118	14/03/18 09:29	Reinspection Photo	0	Load JPG	<u> </u>
119	14/03/18 09:29	Reinspection Photo	0	Load JPG	\square
120	14/03/18 09:29	Reinspection Photo	0	Load JPG	<u>Z</u>
121	14/03/18 09:29	Reinspection Photo	0	Load JPG	\square
122	14/03/18 09:29	Reinspection Photo	0	Load JPG	<u> </u>
123	14/03/18 09:29	Reinspection Photo	0	Load JPG	

Merimen e-Claims Page 4 of 5

124	14/03/18 09:29	Reinspection Photo	0	Load JPG	
125	14/03/18 09:29	Reinspection Photo	0	Load JPG	\mathbf{Z}
126	14/03/18 09:29	Reinspection Photo	0	Load JPG	✓
127	14/03/18 09:29	Reinspection Photo	0	Load JPG	V
128	14/03/18 09:29	Reinspection Photo	0	Load JPG	☑
129	14/03/18 09:29	Reinspection Photo	0	Load JPG	Z
130	14/03/18 09:29	Reinspection Photo	0	Load JPG	✓
131	14/03/18 09:29	Reinspection Photo	0	Load JPG	$\overline{\mathbf{A}}$
132	14/03/18 09:29	Reinspection Photo	1	Load JPG	 ✓
133	14/03/18 09:29	Reinspection Photo	0	Load JPG	∡
134	14/03/18 09:29	Reinspection Photo	0	Load JPG	Ø
135	14/03/18 09:29	Reinspection Photo	0	Load JPG	✓
136	14/03/18 09:29	Reinspection Photo	0	Load JPG	☑
137	14/03/18 09:29	Reinspection Photo	0	Load JPG	☑
138	14/03/18 09:29	Reinspection Photo	0	Load JPG	☑
139	14/03/18 09:29	Reinspection Photo	0	Load JPG	☑
140	14/03/18 09:29	Reinspection Photo	0	Load JPG	V
141	14/03/18 09:29	Reinspection Photo	0	Load JPG	☑
142	14/03/18 09:29	Reinspection Photo	0	Load JPG	₹
143	14/03/18 09:29	Reinspection Photo	0	Load JPG	\sqrt
144	14/03/18 09:29	Reinspection Photo	0	Load JPG	Y
145	14/03/18 09:29	Reinspection Photo	0	Load JPG	¥
146	14/03/18 09:29	Reinspection Photo	0	Load JPG	V
147	14/03/18 09:29	Reinspection Photo	0	Load JPG	✓
148	14/03/18 09:29	Reinspection Photo	0	Load JPG	✓
149	14/03/18 09:29	Reinspection Photo	0	Load JPG	¥
150	14/03/18 09:29	Reinspection Photo	0	Load JPG	\overline{\cdot}
151	14/03/18 09:29	Reinspection Photo	0	Load JPG	>
152	14/03/18 09:29	Reinspection Photo	0	Load JPG	V
	umentation		1 pe	r page 🔻	☑
	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	13/12/17 17:09	ESTIMATES		Load TIF	
2	13/12/17 17:09	OI GIA REPORT	• •	Load PDF	
No	Finalized On	VAC (Bukit Batok)		Thumbnail	Print
1	11/12/17 10:32	Sketch Plan [Linked Accident Report Documents]	0	Load TIF	
2	11/12/17 10:32	Sketch Plan #2 [Linked Accident Report Documents]	0	Load TIF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	19/03/18 09:51	Supplementary	0	Load PDF	

Linked Accident Report Documents

			View View in	Browser 🗸
Ass	essment Report	S	1 per page	7 2
No	Finalized On	VAC (Bukit Batok)	Thumbnai	I Print
1	11/12/17 10:32	Accident Statement	1 Load HTM	
	tos/Images	VAC (Bulit Patala)	3 per page	☑ ☑ I Print
No 1	Finalized On 11/12/17 10:29	VAC (Bukit Batok) Accident Photo	1 Load JPG	Z
_			Load JPG	<u> </u>
2	11/12/17 10:29	Accident Photo	Load JFG	-

Page 5 of 5 Merimen e-Claims

3	11/12/17 10:29	Accident Photo	■ Load JPG	✓
4	11/12/17 10:29	Accident Photo	Load JPG	₹
5	11/12/17 10:29	Accident Photo	1 Load JPG	₹
6	11/12/17 10:29	Accident Photo	1 Load JPG	V
Doc	cumentation		1 per page 🔻	✓
No	Finalized On	VAC (Bukit Batok)	Thumbnail	Print
1	11/12/17 10:32	Sketch Plan	1 Load TIF	
2	11/12/17 10:32	Sketch Plan #2	1 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
	^			
	~			
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd (Co.Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/CTI17023726/R1RD3E2

Date:

19/03/2018

REFERENCE

Handling Insurer:

China Taiping Insurance (Singapore) Pte. Ltd.

Policy No:

DMPCSN3075731600

Claimant Vehicle

SKB4327R

Insured Vehicle SLD6682D

Date of Loss:

10/12/2017

Nature of Claim: TP

Claim No:

SNM17D07046C02/2S

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

No:

SKB4327R

Make & Model:

VOLKSWAGEN PASSAT TSI, 1.8 (A)

Engine No:

BZB101114

Reg. Date:

09/06/2009 (Man. Year: 2009)

Chassis No: Odometer:

WVWZZZ3CZ9E561079 162118 km

Colour: **Engine Capacity:** Gold

1798 cc

Market Value/New Car Price:

N/A

Sum Insured (S\$):

Market Value/New Car Price

Yes Engine Modification:

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Pre-accident Condition:

Yes

Handbrake (Serviceable):

CONDITION OF TYRES Front Tyre Size:

235/45 R17

Rear Tyre Size:

No

235/45 R17

Front Left Side:

Pirelli 6 mm

Rear Left Side:

Pirelli 6 mm

Front Right Side:

Pirelli 6 mm

Rear Right Side:

Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,017.06	7,557.33	13,459.73	64.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	23,600.00	8,418.00	15,182.00	64.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	44,617.06	15,975.33	28,641.73	64.19
+ GST 7.00/7.00% (S\$)	3,123.19	1,118.27	2,004.92	64.19
Nett Amount (S\$)	47,740.25	17,093.60	30,646.65	64.19

INSPECTION

Date of Assignment:

13/12/2017

Date Inspected:

14/12/2017 Inspected At:

Volkswagen Centre Singapore (Alexandra)

247 Alexandra Road

Singapore 159934

Estimated Period of Repair:

15.0 days

Adjuster: MOHD RASUL

Manager: Janice Lee Si Hua

Page 2 of 5 Adjuster Report NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 19 Mar 2018)

Parts: 143 VOLKSWAGEN PASSAT TSI 1.8 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKB4327R)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LOCK STRIKER	Serviceable	35.04 FS	*-FS
2	1		*NAME PLATE - TSI	Not Necessary	54.70 FS	*-FS
3	1		*REINFORCEMENT	Serviceable	798.61 FS	*- FS
4	1		*VW SIGN	Necessary	127.86 FS	*57.54 FS
5	1		*LOCK	Bent	186.31 FS	*83.84 FS
6	1		*BUMPER REINFORCEMENT REA	Serviceable	567.15 FS	*- FS
7	1		*MECHANISM	Serviceable	362.62 FS	*-FS
8	1		*REAR BOOT LOCK COVER	Scratched	15.27 FS	*6.87 FS
9	1		*AIR GUIDE LH	Cracked	40.75 FS	*18.34 FS
10	1		*AIR GUIDE RH	Serviceable	40.75 FS	*-FS
11	1		*AIR GUIDE UPPER	Cut	63.52 FS	*28.58 FS
12	1		*LOCK CARRIER	Cracked	1,380.60 FS	*621.27 FS
13	1		*FR BUMPER SIDE BRACKET LH	Necessary	32.44 FS	*14.60 FS
14	1		*FRT BUMPER SIDE BRACKET RH	Necessary	32.44 FS	*14.60 FS
15	1		*FRONT BUMPER	Deformed	1,935.69 FS	*871.06 FS
16	1		*FRONT BUMPER FOAM	Cracked	175.39 FS	*78.93 FS
17	1		*FOAM INSER	Serviceable	101.05 FS	*-FS
18	1		*FRT LICENCE PLATE HOLDER	Cracked	150.99 FS	*67.95 FS
19	1		*BUMPER SIDE BRACKET LH	Necessary	53.73 FS	*24.18 FS
20	1		*BUMPER SIDE BRACKET RH	Necessary	53.73 FS	*24.18 FS
21	1		*REAR BUMPER	Deformed	2,192.97 FS	*986.84 FS
22	1		*BUMPER MOLDING CENTRE	Cut	223.33 FS	*100.50 FS
23	1		*BUMPER MOLDING LH	Cracked	163.53 FS	*73.59 FS
24	1		*BUMPER MOLDING CENTRE	Cut	229.77 FS	*103.40 FS
25	1		*SPOILER	Serviceable	340.44 FS	*-F\$
26	1		*BUMPER LOWER SPOILER	Serviceable	205.08 FS	*-FS
27	1		*BUMPER CENTRE BRACKET	Necessary	95.79 FS	*43.11 FS
28	1		*FRT BONET	Bent	2,171.50 FS	*977.18 FS
29	1		*HINGE LH	Serviceable	133.15 FS	*- FS
30	1		*HINGE RH	Serviceable	133.15 FS	*- FS
31	1		*LATCH	Serviceable	102.57 FS	*-F\$
32	1		*REAR BOOT LID	Bent	2,414.82 F\$	*1,086.67 FS
33	1		*HINGE LH	Serviceable	190.08 FS	*- FS
34	1		*HINGE RH	Serviceable	190.08 FS	*- FS
35	1		*WEATHERSTRIP	Serviceable	147.24 FS	*-FS
36	1		*FRONT RADIATOR GRILLE	Cracked	1,150.14 FS	*517.56 FS
37	1		*FR CENTER LOWER GRILLE	Serviceable	240.49 FS	*- FS
38	1		*NAM EPLATE - PASSAT	Necessary	76.93 FS	*34.62 FS
39	1		*NAME PLATE - CC	Necessary	75.28 FS	*33.88 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*REAR BOOT LID TRIM COVER	Serviceable	228.13 FS	*-FS
41	1		*HEADLIGHT LH	Cracked	1,222.45 FS	*550.10 FS
42	1		*HEADLIGHT RH	Serviceable	1,222.45 FS	*-FS
43	1		*REAR BOOT LOCK	Bent	198.63 FS	*89.38 FS
44	1		*1PK ADHES	Necessary	110.52 FS	*49.73 FS
45	1		*RIVET (6 PCS)	Necessary	1.86 FS	*0.84 FS
4 6	1		*NUT (8 PCS)	Necessary	17.12 FS	*7.70 FS
47	1		*GASKET	Necessary	60.57 FS	*60.57 FS
48	1		*TSI LOGO CRR	Necessary	22.68 FS	*22.68 FS
49	1		*TRIM	Cracked	22.72 FS	*22.72 FS
50	1		*AC CONDENSER	Bent	419.83 FS	*419.83 FS
51	1		*TAILLIGHT OUTER LH	Scratched	185.79 FS	*185.79 FS
52	1		*BOOT LID TRIM (BLACK)	Necessary	619.33 FS	*278.70FS
F=Fra	anchise	part. S=SpcN	ett.	Total Parts (S\$)	21,017.06	7,557.33

Report was unsubmitted during this print-out.

Adjuster Report Page 5 of 5

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our items	· · · · · · · · · · · · · · · · · · ·		
1	LABOUR FRT	New	5,040.00	2,184.00
2	LABOUR REAR	New	6,720.00	1,638.00
3	TRANSFER BOOT LID MECHANIS	New	840.00	273.00
4	SPRAY PAINT FRT	New	4,800.00	2,080.00
5	SPRAY PAINT REAR	New	4,800.00	1,560.00
6	B&P NUMBER PLATE FRT & REA	New	160.00	104.00
7	PROGRAMMING & CALIBRATION COMPULSORY TO DO AFTER AC	New	480.00	216.00
8	ELECT WIRING & MECH COMPO	New	280.00	126.00
9	AIR CON GAS	New	60.00	27.00
10	VACUUM & REGAS AIRCON	New	420.00	210.00
	Gross Labour Cost (S\$)		23,600.00	8,418.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >