

Service Order Confirmation

SERVICE ORDER NO: 17IP3408

CUSTOMER NO.: S0194631E

CUSTOMER NAME: Mister GOH TONG MENG

TELEPHONE NO.:

ADDRESS: 2C JALAN MAS KUNING

VEH No.: SKB4327R

Order Date: 14/12/17

Reg Date: 09/06/09 KM: 162,265

VIN NO.: WVWZZZ3CZ9E561079 ENGINE NO: BZB

SA: Wong MeiY

MODEL: PASSAT CC 1.8 118KW+4KF+8T2 MODEL NO.: 3572J7

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
Labor						
1	B&P MECH	1	TU	280	55	126 ✓
2	B&P DIAG	1	TU	480	55	216 ✓
3	B&P SUNDRIES	48	TU	1.25	55	27 ✓
4	B&P AIRCON	1	TU	420	50	210 ✓
5	B&P ALEX LABOUR	4	UNIT	840	35	2,184 ✓
6	B&P ALEX PAINT	4	UNIT	800	35	2,080 ✓
7	B&P ALEX LABOUR	3	UNIT	840	35	1,638 ✓
8	B&P ALEX PAINT	3	UNIT	800	35	1,560 ✓
9	B&P ALEX LABOUR	0.5	UNIT	840	35	273 ✓
10	B&P NUMBER PLATE	2	ST	80	35	104 ✓ <i>5418</i>
Item						
11	3C8823031B	1	PCS	2,171.50	55	977.18 ✓
12	3C1823509H	1	PCS	186.31	55	83.84 ✓
13	3C8807217N GRU	1	PCS	1,935.69	55	871.06 ✓
14	3C8807184A	1	PCS	32.44	55	14.60 ✓
15	3C8807183A	1	PCS	32.44	55	14.60 ✓
16	3C8807285C 9B9	1	PCS	150.99	55	67.95 ✓
17	N 0385494	6	PCS	0.31	55	0.84 ✓
18	3C8853651Q GRU	1	PCS	1,150.14	55	517.56 ✓
19	3C0853600A MQH	1	PCS	127.86	55	57.54 ✓
20	3C8805588C	1	PCS	1,380.60	55	621.27 ✓
21	3C8827025C	1	PCS	2,414.82	55	1,086.67 ✓
22	3C8853465A 041	1	PCS	619.33	55	278.70 ✓
23	4F5827505D	1	PCS	198.63	55	89.38 ✓
24	3C5827520B 9B9	1	PCS	15.27	55	6.87 ✓
25	3C8827705A 5AP	1	PCS	134.60	55	60.57 ✓
26	D 172090A2	1	PCS	110.52	55	49.73 ✓
27	3C8853687A 739	1	PCS	76.93	55	34.62 ✓
28	3C8853687B 739	1	PCS	75.28	55	33.88 ✓

Service Order Confirmation

SERVICE ORDER NO: 17IP3408

CUSTOMER NO.: S0194631E

CUSTOMER NAME: Mister GOH TONG MENG

TELEPHONE NO.:

ADDRESS: 2C JALAN MAS KUNING

VEH No.: SKB4327R

Order Date: 14/12/17

Reg Date: 09/06/09 KM: 162,265

VIN NO.: WVVZZZ3CZ9E561079 ENGINE NO: BZB

SA: Wong Mei-y

MODEL: PASSAT CC 1.8 118KW+4KF+8T2 MODEL NO.: 3572J7

No.	DESCRIPTION	QTY	UOM	UNIT PRICE	DISC %	AMOUNT
29	3C8807417P GRU REAR BUMPER	1	PCS	2,192.97	55	986.84 ✓
30	N 10621301 NUT	8	PCS	2.14	55	7.70 ✓
31	3C8807863C BUMPER CENTRE BRACKET	1	PCS	95.79	55	43.11 ✓
32	3C8807393B BUMPER SIDE BRACKET LH	1	PCS	53.73	55	24.18 ✓
33	3C8807394B BUMPER SIDE BRACKET RH	1	PCS	53.73	55	24.18 ✓
34	3C8807443A 2ZZ BUMPER MOLDING CENTRE	1	PCS	223.33	55	100.50 ✓
35	3C8807459A 2ZZ BUMPER MOLDING LH	1	PCS	163.53	55	73.59 ✓
36	3C8807460A 2ZZ BUMPER MOLDING CENTRE	1	PCS	229.77	55	103.40 ✓
37	3C0820411F AC CONDENSER	1	PCS	932.95	55	419.83 ✓
38	3C8121283A AIR GUIDE LH	1	PCS	40.75	55	18.34 ✓
39	3C8121330B AIR GUIDE UPPER	1	PCS	63.52	55	28.58 ✓
40	3C8807248D FRONT BUMPER FOAM	1	PCS	175.39	55	78.93 ✓
41	3C8941005D HEADLIGHT LH	1	PCS	1,222.45	55	550.10 ✓
42	3C8945095G TAILLIGHT OUTER LH	1	PCS	412.86	55	185.79 ✓
43	1K5853675J GQF (A) TSI LOGO CRR <i>mc</i>	1	PCS	50.40	55	22.68 ✓
44	3C8945311A 9B9 (A) TRIM <i>RA</i>	1	PCS	50.49	55	22.72 ✓

Remarks: DIRECT SETTLEMENT

DOA:

SURVEY BY RASUL

REPAIR LIMIT \$16,000

7557.33

Supplementary or Omitted List



VEHICLE NUMBER: **SKB4327R**

MODEL **PASSET cc**

CLAIMS DETAILS

	LABOUR DESCRIPTION	AMOUNT		
		Qty	Unit	Amount
1	AIR CON GAS	1	\$ 60.00	\$ 60.00
2	VACUUM & REGAS AIRCON-NETT	1	\$ 420.00	\$ 420.00
Total				\$480.00

<u>No.</u>	<u>Item No.</u>	<u>Description</u>	<u>Qty</u>	<u>Unit Pricing</u>	<u>Discount</u>	<u>Amount</u>
1	3C0820411F	AC CONDENSER	1	\$932.95	419.83	\$932.95
2	3C8945095G	TAILLIGHT OUTER LH	1	\$412.86	185.79	\$412.86
3						
TOTAL:						\$1,345.81

Total Labour & Parts

\$1,825.81

Survey By