



Torque 5 Pte Ltd

No. 8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

SUPPLEMENTARY REPORT

Vehicle No : GBD3844S

Estimation No. : E17120050

Make & Model

TOYOTA, HIACE 3.0 DX AT DIESEL TURBO 2WD DOA : 12/12/2017

5DR LGV, KDH2015015374

Year of

: 2014

Manufacture

No	Description	Qty	U/P	Amt
Section: List Items				
1	Fog lamp cover <i>the new</i>	2.00	490.00	980.00 <i>X</i>
2	Front bumper beam <i>Best</i>	1.00	320.00	320.00 <i>✓</i>
3	Front door RH <i>Repis</i>	1.00	1,790.00	1,790.00 <i>X</i>
4	Front door lettering <i>the new</i>	10.00	5.00	50.00 30 (SN)
5	Front door rubber <i>the new</i>	1.00	215.20	215.20 <i>X</i>
6	Front door hinges <i>the new</i>	2.00	150.00	300.00 <i>X</i>
7	Blower assy <i>the new</i>	1.00	725.90	725.90 <i>✓</i>
8	Cooling coil <i>the new</i>	1.00	792.00	792.00 <i>✓</i>
9	Heater assy <i>the new</i>	1.00	630.00	630.00 <i>✓</i>
10	Spare tank <i>Repeated</i>	1.00	500.00	500.00 <i>X</i>
11	Condensor <i>Repeated</i>	1.00	1,560.00	1,560.00 <i>X</i>
12	Fan cowling <i>coupled</i>	1.00	170.00	170.00 <i>✓</i>
13	Air cleaner box assy <i>coupled</i>	1.00	750.00	750.00 <i>✓</i>
14	Exhaust heat seal <i>the new</i>	1.00	0.00	0.00 <i>X</i>
15	Coolant <i>the new</i>	1.00	140.00	140.00 40 (SN)
16	Brake booster <i>the new</i>	1.00	0.00	0.00 <i>X</i>
17	Brake master pump <i>the new</i>	1.00	2,480.00	2,480.00 <i>X</i>
18	Brake fluid & bleeding <i>the new</i>	1.00	0.00	0.00 <i>X</i>
19	A/c pipe (4pcs) <i>Repeated</i>	4.00	320.00	1,280.00 <i>X</i>
20	Inter-cooler bracket <i>the new</i>	1.00	0.00	0.00 <i>X</i>
21	inter-cooler hose <i>the new</i>	1.00	0.00	0.00 <i>X</i>
22	Inter-cooler cover <i>the new</i>	1.00	0.00	0.00 <i>X</i>
23	Aircon fan assy <i>the new</i>	1.00	279.00	279.00 <i>X</i>
24	Rear tailgate outer garnish <i>Repeated</i>	1.00	279.20	279.20 <i>X</i>
25	Rear tailgate rubber <i>Repeated</i>	1.00	401.50	401.50 <i>X</i>

Continue on next page...



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

SUPPLEMENTARY REPORT

Vehicle No : GBD3844S Estimation No. : E17120050
Make & Model : TOYOTA, HIACE 3.0 DX AT DIESEL TURBO 2WD DOA : 12/12/2017
5DR LGV, KDH2015015374
Year of Manufacture : 2014

No	Description	Qty	U/P	Amt
26	Rear tailgate side stoppers (LH) <i>new</i>	1.00	112.30	112.30 X
27	Rear tailgate side stoppers (RH)	1.00	112.30	112.30 X
28	Rear tail lamp lower garnishes (LH) <i>reformed</i>	1.00	278.00	278.00 138
29	Rear tail lamp lower garnishes (RH)	1.00	278.00	278.00 138
30	Rear bumper step panel <i>Replaced</i>	1.00	415.00	415.00 X
31	Rear spare tyre carrier <i>Best</i>	1.00	401.80	401.80 281.40
32	Rear spare tyre carrier lock catch <i>new</i>	1.00	150.00	150.00 X
33	Rear side body pannel inner panel <i>Rpr</i>	1.00	1,500.00	1,500.00 X
34	Rear side body quarter glass inner seal <i>new</i>	1.00	150.00	150.00 60 (sn)
35	Front corner panel (LH) <i>Rpr</i>	1.00	820.00	820.00 X
36	Front corner panel (RH) <i>Replaced</i>	1.00	820.00	820.00 X
				Amt S\$
				18,680.20
				Discount (0.00%) S\$ 0.00
				Subtotal S\$
				18,680.20

Section: Special Nett Items

37	A/C gas (134a) <i>new</i>	1.00	150.00	150.00 20
38	Compressor oil <i>new</i>	1.00	80.00	80.00 30
39	Rear car number plate <i>changed</i>	1.00	50.00	50.00 ✓
40	Side panel quarter glass sealant <i>new</i>	1.00	80.00	80.00 50
				Amt S\$ 360.00
				Discount (0.00%) S\$ 0.00
				Subtotal S\$ 360.00

Supplementary: 1628.05

List Items Subtotal	S\$
	18,680.20
Special Nett Items Subtotal	S\$ 360.00
Total	S\$
	19,040.20