

12/03/2002

ASS: REC BY:

REF C33/CT117023735 / Sd3e2

Special Instructions:

range 2 days

mkm

Surveyor: Sebastian
Munien

ASSIGNMENT (Office)

From (Person): Jayn Tay

of

CTI

Date/Time:

14/12/17 @ 10:55am

Estimated Cost:

Bill to:

OD ~~TP~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBK 4139B

Insured:

SKH 8593E

at Workshop m/s

Eng Soon painting

Tel:

6760 6271

of 393 Woodlands Road, 677978

Policy No:

DMPCSN3110871600

Claim No:

SNM17D07054C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

9/12/2017

CA / REV / REP. / REV 24 HRS

1wp

H.O.D. Endorsement:

Date/Time: 11:15am

Person Contacted:

Vehicle ~~IN~~ OUT

Date/Time

Action/Instruction (X) Estimate

FBK 4139B - X

SKH 8593E - X

Dismantle: 21/12/2017

REF: CTI

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: F8K 4139B Yr Regn: /

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda C.C. _____Colour: White & Red. A/C: Insured / Std / NI / NASp. Reading: No Display T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: NC 42 - 1603666

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or BT

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 120/60ZR17R: 160/60ZR17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Met Zeler

Front Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. _____ D.O.I. 14/12/2017Survey held at Eng Soon

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time | Action / Instruction

Range

* Repair Estimate: \$6,800 - \$8,000

* 5 days

6/6/2018

RECEIVED 06 JUN 2018

Date/Time, File Pass to?

☐: Preli. ReportDays Of Repair: 5

1)

☐: Final ReportResurvey No. of Trip: 1Survey Fee: 190

Date/Time, File Return to?

Transportation:

2)

Add Fee: ☐: Site Insp (\$) S + RS. SI☐: Interview (\$) Photos☐: Tech. Invs (\$) Others☐: Weekend (\$)Report Format: PR

Lump Sum / I.B.I. (\$))

TOTAL

190

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Dec 2017		14 Dec 2017 10:55 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	WOO MIN HAO KENNETH, ID: S8330539H		[Created by insurer]
Main Claimant:	TO BE ADVISED		
Vehicle Reg. No.:	FBK4139B	Date of Loss:	09/12/2017 00:00 - :59
Claim Type:	TP / SNM17D07054C02	Policy/Cover Note No.:	DMPCSN3110871600 (Comprehensive) Coverage: 08/11/2016 - 21/12/2017
Vehicle Reg. No. (Insured):	SKH8593E	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Eng Soon Painting Services (HQ) 393J WOODLANDS ROAD, 677978 Woodlands - Tel: 67606271		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 26/12/2017]		
Adj Asg. Remarks:	PLEASE PROCEED TO SURVEY ON WITHOUT PREJUDICE BASIS & LET US HAVE YOUR RECOMMENDATION ON COST OF REPAIRS.		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

> [Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	FBK4139B		
Vehicle Type :	P00 - Passenger Motorcycle/Autocycle/Moped		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	HONDA		
Vehicle Model :	CB400 SUPER FOUR STD MANUAL		
Chassis No. :	NC421603666		
Propellant :	Petrol		
Engine No. :	NC42E1203673		
Engine Capacity :	399 cc		
Maximum Power Output :	-		
Maximum Laden Weight :	300 kg		
Unladen Weight :	190 kg		
Year Of Manufacture :	2015		
Original Registration Date :	24 Aug 2015		
Lifespan Expiry Date :	-		
COE Category :	D - Motorcycle		
Quota Premium :	\$6,112.00		
COE Expiry Date :	23 Aug 2025		
Road Tax Expiry Date :	23 Aug 2018		
Inspection Due Date :	23 Aug 2018		
Intended Transfer Date :	07 Jun 2018		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
The current road tax expiry is 23 Aug 2018. You may renew the road tax from 24 May 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 23 Aug 2018, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable (From 24 Aug 2018 to 23 Feb 2019)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	55.00	-	55.00
Total Amount Payable :			80.00
Amount Payable (From 24 Aug 2018 to 23 Aug 2019)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	110.00	-	110.00
Total Amount Payable :			135.00

You may print this page for reference.

OK

Print

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	14 Dec 2017		14 Dec 2017 10:55 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	WOO MIN HAO KENNETH, ID: S8330539H			
Main Claimant:	TO BE ADVISED			
Vehicle Reg. No.:	FBK4139B	Date of Loss:	09/12/2017 00:00 - :59	
Claim Type:	TP / SNM17D07054C02	Policy/Cover Note No.:	DMPCSN3110871600 (Comprehensive) Coverage: 08/11/2016 - 21/12/2017	
Vehicle Reg. No. (Insured):	SKH8593E	Policy No. (Claimant):		
		Excess:	S\$0.00	
Repairer:	Eng Soon Painting Services (HQ) 393J WOODLANDS ROAD, 677978 Woodlands - Tel: 67606271			
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Sebastian Yeang Wai Keen] ... [Final Rpt due 26/12/2017]			
Adj Asg. Remarks:	PLEASE PROCEED TO SURVEY ON WITHOUT PREJUDICE BASIS & LET US HAVE YOUR RECOMMENDATION ON COST OF REPAIRS.			

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)






































There are no mail for this case.



















































ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)















Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FBK4139B (SNM17D07054C02)
[SKH8593E]
TP
TO BE ADVISED
Dec 9 2017 12:00AM
[WOO MIN HAO KENNETH]
Eng Soon Painting Services

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images								3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	09/04/18 11:42	LKK SURVEYOR PHOTO 1			Load PDF					
2	24/05/18 11:57	Photographs of Damaged Parts			Load PDF					
3	31/05/18 17:35	General View			Load JPG <input checked="" type="checkbox"/>					
4	31/05/18 17:35	General View			Load JPG <input checked="" type="checkbox"/>					
5	31/05/18 17:35	General View			Load JPG <input checked="" type="checkbox"/>					
6	31/05/18 17:35	General View			Load JPG <input checked="" type="checkbox"/>					
7	31/05/18 17:35	General View			Load JPG <input checked="" type="checkbox"/>					
8	31/05/18 17:35	General View			Load JPG <input checked="" type="checkbox"/>					
9	31/05/18 17:35	General View			Load JPG <input checked="" type="checkbox"/>					
10	31/05/18 17:35	General View			Load JPG <input checked="" type="checkbox"/>					
11	31/05/18 17:35	General View			Load JPG <input checked="" type="checkbox"/>					
12	31/05/18 17:35	General View			Load JPG <input checked="" type="checkbox"/>					
13	31/05/18 17:35	General View			Load JPG <input checked="" type="checkbox"/>					
14	31/05/18 17:35	General View			Load JPG <input checked="" type="checkbox"/>					
15	31/05/18 17:35	General View			Load JPG <input checked="" type="checkbox"/>					
16	31/05/18 17:35	General View			Load JPG <input checked="" type="checkbox"/>					
17	31/05/18 17:35	General View			Load JPG <input checked="" type="checkbox"/>					
18	31/05/18 17:35	General View			Load JPG <input checked="" type="checkbox"/>					
19	31/05/18 17:35	General View			Load JPG <input checked="" type="checkbox"/>					
20	31/05/18 17:35	General View			Load JPG <input checked="" type="checkbox"/>					
21	31/05/18 17:35	General View			Load JPG <input checked="" type="checkbox"/>					
22	31/05/18 17:35	General View			Load JPG <input checked="" type="checkbox"/>					
23	31/05/18 17:35	General View			Load JPG <input checked="" type="checkbox"/>					
24	31/05/18 17:35	General View			Load JPG <input checked="" type="checkbox"/>					
25	31/05/18 17:35	General View			Load JPG <input checked="" type="checkbox"/>					
26	31/05/18 17:35	General View			Load JPG <input checked="" type="checkbox"/>					
27	31/05/18 17:35	General View			Load JPG <input checked="" type="checkbox"/>					
28	31/05/18 17:35	General View			Load JPG <input checked="" type="checkbox"/>					
29	31/05/18 17:35	General View			Load JPG <input checked="" type="checkbox"/>					
30	31/05/18 17:35	General View			Load JPG <input checked="" type="checkbox"/>					
31	31/05/18 17:35	General View			Load JPG <input checked="" type="checkbox"/>					
32	31/05/18 17:35	General View			Load JPG <input checked="" type="checkbox"/>					
33	31/05/18 17:35	General View			Load JPG <input checked="" type="checkbox"/>					
34	31/05/18 17:35	General View			Load JPG <input checked="" type="checkbox"/>					
35	31/05/18 17:35	General View			Load JPG <input checked="" type="checkbox"/>					
36	31/05/18 17:35	General View			Load JPG <input checked="" type="checkbox"/>					
37	31/05/18 17:35	General View			Load JPG <input checked="" type="checkbox"/>					

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	31/05/18 17:35	General View	 Load JPG	<input checked="" type="checkbox"/>
39	31/05/18 17:35	General View	 Load JPG	<input checked="" type="checkbox"/>
40	31/05/18 17:35	General View	 Load JPG	<input checked="" type="checkbox"/>
41	31/05/18 17:35	General View	 Load JPG	<input checked="" type="checkbox"/>
42	31/05/18 17:35	General View	 Load JPG	<input checked="" type="checkbox"/>
43	31/05/18 17:35	General View	 Load JPG	<input checked="" type="checkbox"/>
44	31/05/18 17:35	General View	 Load JPG	<input checked="" type="checkbox"/>
45	31/05/18 17:35	General View	 Load JPG	<input checked="" type="checkbox"/>
46	31/05/18 17:35	General View	 Load JPG	<input checked="" type="checkbox"/>
47	31/05/18 17:35	General View	 Load JPG	<input checked="" type="checkbox"/>
48	31/05/18 17:35	General View	 Load JPG	<input checked="" type="checkbox"/>
49	31/05/18 17:35	General View	 Load JPG	<input checked="" type="checkbox"/>
50	31/05/18 17:35	General View	 Load JPG	<input checked="" type="checkbox"/>
51	31/05/18 17:35	General View	 Load JPG	<input checked="" type="checkbox"/>
52	31/05/18 17:35	General View	 Load JPG	<input checked="" type="checkbox"/>
53	31/05/18 17:35	General View	 Load JPG	<input checked="" type="checkbox"/>
54	31/05/18 17:35	General View	 Load JPG	<input checked="" type="checkbox"/>
55	31/05/18 17:35	General View	 Load JPG	<input checked="" type="checkbox"/>
56	31/05/18 17:35	General View	 Load JPG	<input checked="" type="checkbox"/>
57	31/05/18 17:35	General View	 Load JPG	<input checked="" type="checkbox"/>
58	31/05/18 17:35	General View	 Load JPG	<input checked="" type="checkbox"/>
59	31/05/18 17:35	General View	 Load JPG	<input checked="" type="checkbox"/>
60	31/05/18 17:35	General View	 Load JPG	<input checked="" type="checkbox"/>
61	31/05/18 17:35	General View	 Load JPG	<input checked="" type="checkbox"/>
62	31/05/18 17:35	General View	 Load JPG	<input checked="" type="checkbox"/>
63	31/05/18 17:35	General View	 Load JPG	<input checked="" type="checkbox"/>
64	31/05/18 17:35	General View	 Load JPG	<input checked="" type="checkbox"/>
65	31/05/18 17:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	31/05/18 17:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	31/05/18 17:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	31/05/18 17:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	31/05/18 17:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	31/05/18 17:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	31/05/18 17:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	31/05/18 17:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	31/05/18 17:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	31/05/18 17:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	31/05/18 17:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	31/05/18 17:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	31/05/18 17:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	31/05/18 17:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	31/05/18 17:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	31/05/18 17:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	31/05/18 17:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	31/05/18 17:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	31/05/18 17:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	31/05/18 17:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	31/05/18 17:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	31/05/18 17:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	31/05/18 17:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	31/05/18 17:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	31/05/18 17:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	31/05/18 17:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	31/05/18 17:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	31/05/18 17:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	31/05/18 17:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	31/05/18 17:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	31/05/18 17:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	31/05/18 17:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	31/05/18 17:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	31/05/18 17:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	31/05/18 17:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	31/05/18 17:35	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	14/12/17 10:55	E-filed GIA report	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT117023735/SD3E2

Date: 07/06/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN3110871600

Claimant Vehicle
No : FBK4139BInsured Vehicle
No : SKH8593E

Date of Loss: 09/12/2017

Nature of Claim: TP

Claim
No: SNM17D07054C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBK4139B

Make & Model: HONDA CB400, 399cc Super Four STD

Engine No: NC42E1203673

Reg. Date: (Man. Year:)

Chassis No: NC421603666

Colour: White/Red

Odometer: 0 km

Engine Capacity: 399 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/60Z R17

Rear Tyre Size: 160/60Z R17

Front Left Side: Metzeler 6 mm

Rear Left Side: Metzeler 6 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 14/12/2017

Date Inspected: 14/12/2017 Inspected At:

Eng Soon Painting Services (HQ)
393J WOODLANDS ROAD
Singapore 677978

Estimated Period of Repair: 5.0 days

Adjuster: Sebastian Yeang Wai Keen

Manager: Nivitha Govindasamy

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,800.00 -\$8,000.00

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 07 Jun 2018)

Parts: N/A HONDA CB400 399cc Super Four STD (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for FBK4139B)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >