

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

12-Dec-17

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6444 C

1 pc	Rear windscreen moulding ✓	\$ 87.00
1 pc	Rear n/s fender ✓	\$ 1,205.00
1 pc	Rear n/s fender inner shield ✗	\$ 120.00
1 pc	Rear n/s wheel cover ✓	\$ 116.00
		<hr/>
		\$ 1,528.00
	Less 10%	\$ 152.80
		<hr/>
		\$ 1,375.20

S/NETT

1 set	Rear n/s fender inner shield clips ✗	\$ 28.00
1 pc	rear n/s fender sticker ✓	\$ 60.00
1 set	n/s door sticker ✓	\$ 100.00
	Sundry	\$ 50.00 20
	To check wheel alignment	\$ 80.00 60
	To dismantle and refit rear windscreen	\$ 120.00 100
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$ 180.00 50
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the rear n/s door, rear n/s rocker panel garnish	\$ 950.00 600
	To putty and spray painting on rear n/s door, n/s rocker panel garnish, rear n/s fender	\$ 800.00 500.00 720
	To apply rustproofing on the repaired and replaced panels.	\$ 200.00 50
		<hr/>
		\$ 3,743.20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

acknowledged by Repairer
Date:

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kalvin *CC*
15/12/17 1420h
4 Pcs
P/P
Behu Raintph