

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CQ/GST REG NO. 201019626G

SHB7860H - AIG**AAD1712-104***Not Authored*
11 Sep 8 2006

Vehicle No.:

SHB7860H - CANDY

Chassis No.:

KL1LA69RJB102070

Vehicle Make:

CHEVROLET

Vehicle Model:

EPICA 2.0

Date of Accident :

12.12.2017

Third Party Insurer :

AIG

PART		LIST	
1	1	Rear Bumper	\$ <i>CM</i> 1,202.00 ✓
2	1	Rear Bumper Beam	\$ <i>R</i> 239.94 X
3	1	Rear Bumper Centre Absorber	\$ <i>SL</i> 260.00 X
4	1	Rear Bumper Side Retainer RH	\$ <i>CM</i> 68.76 ✓
5	1	Rear Bumper Side Retainer LH	\$ <i>SL</i> 68.76 X
6	1	Rear Bumper Reflectors RH	\$ <i>CM</i> 119.74 ✓
7	1	Rear Bumper Reflectors LH	\$ <i>SL</i> 119.74 X
8	1	Rear Bumper Tow Hook Cover	\$ <i>SL</i> 93.00 X
9	1	Rear End Panel Outer	\$ <i>R</i> 623.76
10	1	Rear End Panel Inner Trim	\$ <i>SL</i> 263.84
11	1	Bootlid	\$ <i>R</i> 973.00
12	1	Bootlid Inner trim board	\$ <i>SL</i> 400.00
13	1	Bootlid Weatherstrip	\$ <i>SL</i> 344.28
14	1	Bootlid Lock - Top	\$ <i>R</i> 466.56
15	1	Bootlid 'CHEVROLET' Badge	\$ <i>SL</i> 120.62
16	1	Bootlid Logo	\$ <i>SL</i> 138.84
17	1	Bootlid 'EPICA LT' Badge	\$ <i>SL</i> 119.84
18	1	Bootlid Reflector Centre	\$ <i>SL</i> 217.97
19	1	Bootlid Reflector RH	\$ <i>SL</i> 128.40
20	1	Bootlid Hinge RH	\$ <i>R</i> 120.00
21	1	Bootlid Hinge LH	\$ <i>R</i> 120.00
22	1	Rear Tail Lamp RH	\$ <i>CM SL</i> 479.30
23	1	Rear Tail Lamp Panel RH	\$ <i>R</i> 359.00
24	1	Rear Exhaust Box (Muffler A-EXH,RR)	\$ <i>R</i> 1,110.00 X
25	1	Rear Fender RH	\$ <i>R</i> 1,145.00
26	1	Rear Fender Inner Trim RH	\$ <i>SL</i> 418.44

TOTAL	\$	9,720.79
10%	\$	972.08
	\$	8,748.71

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB7860H - AIG**AAD1712-104****Specical Nett**

1	1Set	Licence Plate With Holder	\$	60.00 ✓
2	1Set	Bootlid inner trim board Clip	\$	40.00 ✓
3	1Set	Rear Bumper Parking Sensor	\$	300.00 ✓
4	1Set	Rear Bumper Fastener Clip	\$	44.00 ✓
5	1Set	Rear Fender Inner Trim Clip RH	\$	30.00 ✓
6	1Set	Rear Bumper End Dust Cover Clip	\$	30.00 ✓
7	1	Rear Boot Sticker 'Trans-cab'	\$	30.00 ✓
8	1	Rear Boot Sticker '6555-3333'	\$	30.00 ✓
9	1	Rear Exhaust Mounting	\$	10.00 ✓
10	2	Rear Windscreen Sealant	\$	80.00 ✓
11	1	Rear Windscreen Inner Sponge Seal	\$	100.00 ✓
12	1	Spare Tyre	\$	180.00 ✓
13	1	Spare Wheel Rim	\$	126.74 ✓

TOTAL	\$	1,060.74
TOTAL PARTS	\$	9,809.45

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of
Parts, Adjust And Realign The Same

\$ 2,800.00 *2000*

To Check Electrical Lighting Concerned.

\$ 170.00 *200*

To Rust-Proofing Of The Affected Areas.

\$ 170.00 *✓*

Putty And Spray Painting Of The Affected
Portion.

\$ 2,700.00 *2000*

To transfer of end panel fittings and conduct
water seepage test.

\$ 170.00 *✓*

To Remove And Refit Rear W/Screen Glass To
Facilitate Bodywork Repair.

\$ 170.00 *✓*

To transfer of boot fittings and conduct water
seepage test.

\$ 170.00 *✓*

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB7860H - AIG**AAD1712-104**

To reinstall rear bumper parking sensor.	\$	170.00	<i>609</i>
To transfer of Fender fittings, attachments and perform water seepage test.	\$	<i>nn</i> 170.00	<i>X</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i> 380.00	<i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00	<i>X</i>
		\$	7,290.00
TOTAL		\$	17,099.45

Repair Days~~10 Days~~*2 days*

<u>LKK Auto Consultants</u> hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:
