

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

13-Dec-17

ESTIMATE REPAIR BILL FOR HYUNDAI I30 WAGON REGN NO: SHD 1191 J

1 pc	Front bumper	\$	811.11
1 pc	Front bumper n/s side bracket	\$	32.51
1 pc	Front n/s fender	\$	514.02
1 pc	Front n/s fender inner shield	\$	176.72
1 pc	Front n/s lower arm	\$	811.34
1 pc	Front n/s shock absorber	\$	611.56
1 pc	Front n/s tie rod end	\$	72.50
1 pc	Front n/s stabilizer link	\$	88.50
1 pc	Front n/s ball joint	\$	91.90
1 pc	Front n/s rim	\$	246.00
1 pc	Front n/s knuckle bearing	\$	385.76
			\$ 3,841.92
Less 20%			\$ 768.38
			\$ 3,073.54

S/NETT

1 set	Front bumper clips	\$	48.00
1 set	Front n/s fender inner shield clips	\$	28.00
1 pc	Front n/s fender sticker	\$	30.00

Sundry

To check for wheel alignment

To dismantle and replace the front n/s undercarriage

To labour charge for dismantle and renew the accident

damaged parts. Including to knock-out, straighten, repair
reshape of the front n/s undercarriage

Signature:
Date:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

\$ 50.00 20
\$ 60.00
\$ 250.00
\$ 700.00 400

To putty and spray painting on the front bumper, front n/s fender

\$ 400.00 360

To apply rustproofing on the repaired and replaced panels

\$ 250.00 20

Total

\$ 4,889.54

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.

Ka Lin LKK
13/12/17 1135hr
3 Rm
P R P
Befon Paint P Lto