

INS. CASE OWNER:

Lee Ching Koon
ywk

CC 3 / AIG170

23748, Swa3sw

LKK:
IDAC:

ASSIGNMENT

Surveyor:

DOI:

12/12/17

Date / Time:

12/12/17

Registered in Mccimen:

14/12/17

Pre-assign / CCU / FTE

GB6 472K



Insured Vehicle No.:

Name of Insured:

BD CRANE & ENGINEERING P/L

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

10/12/17

Is driver the owner?

(YES / ☒)

Nature of Accident:

If NO, Driver Name / Age:

Rajendran Vijayakanth

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

04998651286

Policy No.:

1700010793

Make / Model:

NISSAN CABSTAR

Place of Accident:

Jung West Ave 4

OI GIA REPORT: YES / NO: TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SHB54322



INSRS:

WSP:

Tel:

Liability:

RMKS:

FMP7



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

18/12

11/1/18

11/1/18

11/1/18

11/1/18

11/1/18

11/1/18

11/1/18

11/1/18

11/1/18

11/1/18

11/1/18

11/1/18

11/1/18

11/1/18

11/1/18

11/1/18

11/1/18

11/1/18

11/1/18

11/1/18

11/1/18

11/1/18

11/1/18

11/1/18

11/1/18

11/1/18

11/1/18

11/1/18

11/1/18

11/1/18

11/1/18

11/1/18

11/1/18

11/1/18

11/1/18

11/1/18

11/1/18

11/1/18

11/1/18

11/1/18

11/1/18

11/1/18

11/1/18

11/1/18

11/1/18

11/1/18

11/1/18

11/1/18

11/1/18

11/1/18

11/1/18

SHB54322 - 12/12/17 18001269 / 12/12/17 18001269; DOA: 21/01/18

GB6 472K - X

Spoke to OI, 85118585, agreed to settled on TP claims.
Aware of NCD issue. Will sent out letter

Group letter to OI.

File pass to typist type report
email from AIG to seek mandate

mandate approve via mer mer

RECEIVED 23 JUL 2018

RECEIVED 28 JAN 2018

PRELIMINARY ADVICE		Date/Time:	Sent By:	Confirm with:	Confirm by:
Repair Cost:	SS	() days	Reduction:	%	Email ☐ Call ☐
FINAL SETTLEMENT					
Final Liability:	%	100	(Agreed / Assessed)	BOLA S/N No.:	27
Repair Cost:	SS	12750.60			COLD
Loss of Rental (LOR):	SS	1643.52	(16 days)	X 102.72	
Loss of Use (LOU):	SS	—	(\$ x days)		
Loss of Income (LOI):	SS	—	(\$ x days)		
LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐	[Tick only one]				
GIA/LTA Search	SS	5.00			
Medical:	SS	380.62			
Disbursement:	SS	—	(e.g. Tow/ Independent)		
Legal Cost	SS	—			
Total:	SS	15770.00		Global Sum SS: 15770.00	
FINAL PAYMENT					
Payee 1:	SS	15770.00	Name 1:	SMRT Taxis Pte Ltd	
Payee 2: (Strike if N.A.)	SS		Name 2:		
Payee 3: (Strike if N.A.)	SS		Name 3:		

STAGE	DATE / PIC
Non-Reporting ltr (1st):	
Non-Reporting ltr (2nd):	
Non-Reporting ltr (Final):	
Notification ltr (if non-pickup):	
Call OI: 11/1/18 75118585	
After call ltr to OI: 12/01/18 - vic ok	
Documentation Check List:	Handler Typist
Notification ltr (if non-pickup)	☐ ☐
After call ltr to OI:	☒ ☐
Authorisation To Act:	☒ ☐
Release Voucher:	☒ ☐
Final Repair Bill:	☒ ☐
Car Rental Invoice:	☒ ☐
Towing Invoice	☐ ☐
LTA / GIA:	☒ ☐
Medical Bill:	☒ ☐
PIR:	☐ ☐
Mandate/Reject Instruction:	☒ ☐
LOD	☒ ☐
Payment Breakdown Form:	☐ ☐
Post-Repair Photos:	☐ ☐
Others:	☐ ☐

COPY SENT

- 1) Claim status: Normal/Reject/Private Settle
- 2) Report Format:
- 3) Survey fee:

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 14 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time | Action / Instruction

29/1/18 : Confirm US \$13750.00 with 14 working days.

TAX / 12/17 / 2056

LKE
AIG.(Ref - #784661
36/1)Veh No: SHB54322 Yr Regn: 1/8/2012

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Chevrolet Epica c.c. 1991Colour Maroon A/C: Insured / Std / NI / NASp. Reading 648710 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KL1LA(9KJBIS)8833

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: NI / S/Rim / STD A/Rim orTyre Size: F: 205/55R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Fallen

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 10/12/2017 D.O.I. 12/12/2017Survey held at SMARTDes. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$) S + RS. SI☐ : Interview (\$) Photos☐ : Tech. Invs (\$) Others☐ : Weekend (\$)

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC3/AIG17023748/Swa3		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 14-12-2017		
		Code : AIG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBG 472K	Veh. Inspected	SHB 5432Z	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	14/12/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	10/12/2017	Inspection Date	12/12/2017	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



SMRT Automotive Service Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592


Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB5432Z
 Ref. No : TAX/12/17/2056
 Reg. Date : 01/08/2012
 Vehicle Type : TAXI
 Make : CHEVROLET EPICA 2.0 VCDI
 Model : EPICA-2.0
 Name of Driver : TAN BOK HUA
 Type of Accident : HEAD TO REAR
 Date / Time of Accident : 10/12/2017 08:35:00 PM
 Accident Reported Date / Time : 11/12/2017 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by : Sebastian
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024093539
 Special Instruction to ARC, if any :
 GBG472K AIG 45
 BEFORE PAINT PHOTO AND AFTER PAINT PHOTO, FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL
 SURVEYOR SEBASTIAN (LKK) & Email : sebastianyeang @lkkauto.com HP:90036121
 LUMP SUM REPAIR
 *PLEASE CHECK BOTH REAR CHASSIS LH AND RH
 Prepared Date : 11/12/2017 09:16:37 AM



16.00 28/12/17 Pass

Recording Camera ☐ ☒

Radio Antenna ☐ ☒

1st witness Al Date 12-12-17

2nd witness [Signature] Date 28/12/17

E 12 F
 KM 648710

Attached
 Supplementary

Vehicle to Wega Date In: <u>13/12</u>	Towing: <u>Yes</u>
Time In: <u>1315</u>	Driver: <u>[Signature]</u>
Wega Job No: <u>14016/12</u>	
Vehicle sent to SMRT Date In: <u>28/12/17</u>	Towing: <u>[Signature]</u>
Time In: <u>1420</u>	Driver: <u>[Signature]</u>
Received by (SMRT): <u>[Signature]</u>	

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : KL1LA69RJBB138833


Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 2,704.00	2,250.00
Total Spray Painting Charges	: 4,068.00	1,800.00
Total Material Charges	: 11,156.50	9,003.01
Other Charges	: 1,950.00	690.00
TOTAL	: 19,878.50	13,743.01
Lum Sum Total	: 19,900.00	13,750.00
No. of Repair Days	: 15.00	14.00
Prepared / Adjusted By	:	SEBASTIAN (LKK)
Arc / Surveyor Sign Off Date	: 11/12/2017 11:54:41 AM	12/12/2017 02:33:23 PM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 11/12/2017 11:54:41 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No	: QN-1712-0821	Invoice No	:
Quotation Date	: 31/12	Invoice Date	:
Invoice Amount	:	Prepared Date	:

Section D - Details of Repair Estimates**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	2,704.00	2,250.00 /
Total Labour	2,704.00	2,250.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	200.00 /
TO RESPRAY BUMPER BEAM	180.00	100.00 /
TO RESPRAY REAR PANEL	180.00	100.00 /
TO RESPRAY REAR SPARE TYRE PANEL	180.00	0.00
TO RESPRAY REAR CHASSIS LH	180.00	100.00 /
TO RESPRAY REAR CHASSIS RH	180.00	100.00 /
TO RESPRAY REAR FLOOR SIDE PANEL LH	180.00	0.00
TO RESPRAY REAR FLOOR SIDE PANEL RH	180.00	100.00 /
TO RESPRAY REAR BOOT LID	378.00	100.00 /
TO RESPRAY REAR FENDER LH	378.00	200.00 /
TO RESPRAY REAR FENDER RH	378.00	200.00 /
TO RESPRAY REAR DOOR RH	378.00	200.00 /
TO RESPRAY TAIL LAMP PANEL LH	180.00	50.00 /
TO RESPRAY TAIL LAMP PANEL RH	180.00	50.00 /
TO RESPRAY ROOF TOP PANEL	378.00	200.00 /
TO RESPRAY RH REAR WHEEL HOUSE	180.00	100.00 /
Total Spray Painting & Panel Beating	4,068.00	1,800.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	30.00 /
TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	60.00 /
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	30.00 /
TO REMOVE AND REFIT WIRE HARDESS	200.00	0.00
REMOVE AND REPLACE BOTH RR EXHAUST MUFFLER	120.00	60.00 /
TO ALIGN CHASSIS	350.00	200.00 /
TO TRANSFER REAR TAILGATE MECHANISM	120.00	60.00 /
TO REMOVE / REFIT SEAT	120.00	50.00 /
TO TRANSFER DOOR MECHANISM	120.00	0.00
TO REMOVE AND REFIX REAR WINDSCREEN	120.00	100.00 /
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	30.00 /
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	50.00 /
TO REPLACE SUNDRY PARTS	100.00	20.00 /
TO WASH AND VACUUM	60.00	0.00
Total Other Costs	1,950.00	690.00

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached	
96634023	REAR	6504567	EMBLEM REAR	1	44.00	10.00	39.60	Replace	Replace	No	✓
	COMMON		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace	No	✓
	COMMON		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	No	✓
96636423	REAR		REAR BOOT ROD PULL LOCK	1	3.00	10.00	2.70	Replace	Check	No	✓
96632854	REAR	6504632	REAR BOOT WEATHERSTRIP	1	49.00	10.00	44.10	Replace	Replace	No	✓
			TRIM REAR BOOT, LH	0	125.00	10.00	0.00	Replace	Not given	No	✓
			TRIM REAR BOOT, RH	0	125.00	10.00	0.00	Replace	Not given	No	✓
94503739			CLIP, TRIM	10	1.00	10.00	9.00	Replace	Replace	No	✓
96932979			COVER BAORD SPARE TYRE	0	661.00	10.00	0.00	Replace	Not given	No	✓
			INSULATOR SHEET	2	41.48	10.00	74.66	Replace	Check	No	✓
	COMMON	4006314	SEALANT SIKAFLEX	2	37.00	0.00	74.00	Replace	Check	No	✓
96637759	REAR	6504579	TRIM REAR END PANEL	1	114.00	10.00	102.60	Replace	Replace	No	✓
96636426	REAR	6504633	REAR BOOT STRIKER	1	15.00	10.00	13.50	Replace	Replace	No	✓
96646502	COMMON		W/HARNESS TRK ROOM	1	51.74	10.00	46.57	Replace	Check	No	✓
96646491	COMMON		W/HARNESS T / LID	1	83.52	10.00	75.17	Replace	Check	No	✓
96632799	LEFT	6504637	FENDER LH REAR	1	1,191.00	10.00	1,071.90	Replace	Replace	No	✓
	COMMON		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace	No	✓
	COMMON		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	No	✓
96633557	REAR	6504575	LINER LH REAR FENDER (PROTECTOR)	0	201.00	10.00	0.00	Replace	Not given	No	✓
96632800	REAR	6504638	FENDER RH REAR	1	1,467.00	10.00	1,320.30	Replace	Replace	No	✓
	COMMON		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace	No	✓
	COMMON		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	No	✓
			LINER RH REAR FENDER (PROTECTOR)	1	65.00	10.00	58.50	Replace	Check	No	✓
	COMMON		AIR DUCT REAR	2	45.00	10.00	81.00	Replace	Check	No	✓
96635656	DOOR	6504604	PANEL RH REAR DOOR	1	1,863.00	100.00	0.00	Replace	Repair	No	✓
	COMMON		STICKER DECAL 6555 8888 (DOOR)	1	60.00	0.00	60.00	Replace	Replace	No	✓
96632652	REAR	6504619	MOLDING WINDSCREEN REAR	1	45.00	10.00	40.50	Replace	Replace	No	✓
	COMMON		SEALANT W/SCREEN	2	37.00	0.00	74.00	Replace	Replace	No	✓
96851763	REAR	6504563	LAMP RR COMBINATION LH	1	415.00	10.00	373.50	Replace	Replace	No	✓
96851764	REAR	6504511	LAMP RR COMBINATION RH	1	415.00	10.00	373.50	Replace	Replace	No	✓
			PANEL TAIL LAMP, LH	1	143.40	10.00	129.06	Replace	Replace	No	✓

3739.76

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached	
93745100	REAR	6504569	BUMPER RR	1	1,238.00	10.00	1,114.20	Replace	Replace	No	CRK
96941154	REAR	6504571	BEAM RR BUMPER IMPACT	1	1,221.00	10.00	1,098.90	Replace	Replace	No	BT
96873838	REAR		ABSORBER ENGY RR BUMPER	1	70.00	10.00	63.00	Replace	Replace	No	CRK
	REAR		BRACKET RR BUMPER SIDE LH	1	49.00	10.00	44.10	Replace	Replace	No	
96633534	REAR		BRACKET RR BUMPER SIDE RH	1	49.00	10.00	44.10	Replace	Replace	No	
96858575		6504584	REFLECTOR REFLEX RR LH	1	264.00	10.00	237.60	Replace	Replace	No	CRK
96858576	REAR	6504586	REFLECTOR REFLEX RR RH	1	264.00	10.00	237.60	Replace	Replace	No	
	REAR		SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace	No	DMG
96647117	COMMON		W/HARNESS RR BPR	1	227.34	10.00	204.61	Replace	Check	No	XX
96873820	REAR		COVER TOWING EYE RR	0	21.00	10.00	0.00	Replace	Not given	No	XX
96418400			MUFFLER A-EXH,RR	1	2,909.00	100.00	0.00	Replace	Repair	No	R
			EXHAUST PIPE MOUNTING, REAR	2	4.40	10.00	7.92	Replace	Check	No	XX
96632015	REAR	6504636	PANEL END REAR	1	255.00	10.00	229.50	Replace	Replace	No	DT
	COMMON	4006314	SEALANT SIKAFLEX	1	37.00	0.00	37.00	Replace	Replace	No	NEC
96515711			PANEL SPARE TYRE	1	2,299.00	10.00	2,069.10	Replace	Replace	No	DT
	BODY		PNL SIDE LH SPARE TYRE	1	650.00	10.00	585.00	Replace	Check	No	XX
	BODY		CHASSIS MEMBER RR LH	1	525.38	10.00	472.84	Replace	Check	No	XX
	BODY		PNL SIDE RH SPARE TYRE	1	650.00	10.00	585.00	Replace	Check	No	XX
	BODY		CHASSIS MEMBER RR RH	1	525.38	10.00	472.84	Replace	Replace	No	DT
96636630	REAR	6504631	REAR BOOT LID	1	974.00	10.00	876.60	Replace	Replace	No	DT
96636677	REAR	6504634	REAR BOOT LOCK	1	77.00	10.00	69.30	Replace	Replace	No	JM
96636502	REAR		REAR BOOT HINGE	2	92.00	10.00	165.60	Replace	Replace	No	BT
96474968	REAR		REAR BOOT SPRING GAS	2	144.00	10.00	259.20	Replace	Check	No	XX
96993921	REAR	6504578	TRIM TAIL LID	1	71.00	10.00	63.90	Replace	Check	No	XX
96851765	REAR	6504566	LAMP BACK UP LH	1	151.00	10.00	135.90	Replace	Replace	No	
96851766	REAR	6504583	LAMP BACK UP RH	1	122.00	10.00	109.80	Replace	Replace	No	CRK
96976171	REAR	6504635	REAR BOOT REFLECTOR	1	165.00	10.00	148.50	Replace	Replace	No	
96190751	REAR		LAMP LICENSE	2	56.00	10.00	100.80	Replace	Check	No	XX
	REAR		NUMBER PLATE	0	30.00	0.00	0.00	Replace	Not given	No	XX
	COMMON		NUMBER PLATE FRAME	0	12.00	0.00	0.00	Replace	Not given	No	XX
96634035	REAR	6504564	LETTERING:"CHEVR OLET"	1	29.00	10.00	26.10	Replace	Replace	No	
96634897	REAR	6504565	LETTERING:"EPICA LT"	1	28.00	10.00	25.20	Replace	Replace	No	NEC

7384.94

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
			PANEL TAIL LAMP, RH	1	143.40	10.00	129.06	Replace	Replace	No
TOTAL MATERIALS							13,945.63	11,253.76		
TOTAL MATERIALS(Discounted)							11,156.50	9,003.01		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

30107.12

$$\begin{array}{r}
 11,253.76 \\
 - 202 \\
 9003.01 \\
 + 2250.00 \\
 + 2490.00 \\
 \hline
 13743.01
 \end{array}$$

L/S \$13,750/-

Sebastian

3/1/2018

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB5432Z
 Ref. No : TAX/12/17/2056
 Reg. Date : 01/08/2012
 Vehicle Type : TAXI
 Make : CHEVROLET EPICA 2.0 VCDI
 Model : EPICA-2.0
 Name of Driver : TAN BOK HUA
 Type of Accident : HEAD TO REAR
 Date / Time of Accident : 10/12/2017 08:35:00 PM
 Accident Reported Date / Time : 11/12/2017 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024093539
 Special Instruction to ARC, if any :
 GBG472K
 Prepared Date : 11/12/2017 09:16:37 AM



Sebastian.
12/12/2017.

- Lump Sum Repair.
 - Question Mark Item Photo.
 - Photo After Paint.
 ★ Check both chassis status,
 if both beyond repair please
 do not repair.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : KL1LA69RJBB138833

Mileage

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labout Charges	: 1,859.00	0.00
Total Spray Painting Charges	: 3,150.00	0.00
Total Material Charges	: 14,637.61	14,637.61
Other Charges	: 1,950.00	0.00
TOTAL	: 21,596.61	0.00
Lum Sum Total	: 21,600.00	0.00
No. of Repair Days	: 11.00	0.00
Prepared / Adjusted By	:	8 days
Arc / Surveyor Sing Off Date	: 11/12/2017 11:54:41 AM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 11/12/2017 11:54:41 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount :

Prepared Date :

Section D - Details of Repair Estimates**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	1,859.00	0.00 1400
Total Labour	1,859.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY BUMPER BEAM	180.00	0.00 100
TO RESPRAY REAR PANEL	180.00	0.00 100
TO RESPRAY REAR SPARE TYRE PANEL	180.00	0.00
TO RESPRAY REAR CHASSIS LH	180.00	0.00
TO RESPRAY REAR CHASSIS RH	180.00	0.00 100
TO RESPRAY REAR FLOOR SIDE PANEL LH	180.00	0.00
TO RESPRAY REAR FLOOR SIDE PANEL RH	180.00	0.00
TO RESPRAY REAR BOOT LID	378.00	0.00 100
TO RESPRAY REAR FENDER LH	378.00	0.00 200
TO RESPRAY REAR FENDER RH	378.00	0.00 200
TO RESPRAY REAR DOOR RH	378.00	0.00 200
TO RESPRAY TAIL LAMP PANEL LH	180.00	0.00 50
TO RESPRAY TAIL LAMP PANEL RH	180.00	0.00 50
Total Spray Painting & Panel Beating	3,510.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00
TO REMOVE AND REFIT WIRE HARDESS	200.00	0.00
REMOVE AND REPLACE BOTH RR EXHAUST MUFFLER	120.00	0.00
TO ALIGN CHASSIS	350.00	0.00
TO TRANSFER REAR TAILGATE MECHANISM	120.00	0.00
TO REMOVE / REFIT SEAT	120.00	0.00
TO TRANSFER DOOR MECHANISM	120.00	0.00
TO REMOVE AND REFIX REAR WINDSCREEN	120.00	0.00
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	0.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0.00
TO REPLACE SUNDRY PARTS	100.00	0.00
TO WASH AND VACUUM	60.00	0.00
Total Other Costs	1,950.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
93745100	REAR	6504569	BUMPER RR	1	1,238.00	10.00	1,114.20	Replace	Replace ✓ CRK	No
96941154	REAR	6504571	BEAM RR BUMPER IMPACT	1	1,221.00	10.00	1,098.90	Replace	Replace ✓ BT	No
96873838	REAR		ABSORBER ENGY RR BUMPER	1	70.00	10.00	63.00	Replace	Replace ✓ CRK	No
	REAR		BRACKET RR BUMPER SIDE LH	1	49.00	10.00	44.10	Replace	Replace ✓ CRK	No
96633534	REAR		BRACKET RR BUMPER SIDE RH	1	49.00	10.00	44.10	Replace	Replace ✓ CRK	No
96858575		6504584	REFLECTOR REFLEX RR LH	1	264.00	10.00	237.60	Replace	Replace ✓ CRK	No
96858576	REAR	6504586	REFLECTOR REFLEX RR RH	1	264.00	10.00	237.60	Replace	Replace ✓ CRK	No
	REAR		SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace ✓ DMC	No
96647117	COMMON		W/HARNESS RR BPR	1	227.34	10.00	204.61	Replace	Replace ?	No
96873820	REAR		COVER TOWING EYE RR	1	21.00	10.00	18.90	Replace	Replace X	No
96418400			MUFFLER A-EXH,RR	1	2,909.00	10.00	2,618.10	Replace	Replace R	No
			EXHAUST PIPE MOUNTING, REAR	2	4.40	10.00	7.92	Replace	Replace ?	No
96632015	REAR	6504636	PANEL END REAR	1	255.00	10.00	229.50	Replace	Replace ✓ DT	No
	COMMON	4006314	SEALANT SIKAFLEX	1	37.00	0.00	37.00	Replace	Replace ✓ NEC	No
96515711			PANEL SPARE TYRE	1	2,299.00	10.00	2,069.10	Replace	Replace ?	No
	BODY		PNL SIDE LH SPARE TYRE	1	650.00	10.00	585.00	Replace	Replace ?	No
	BODY		CHASSIS MEMBER RR LH	1	525.38	10.00	472.84	Replace	Replace ?	No
	BODY		PNL SIDE RH SPARE TYRE	1	650.00	10.00	585.00	Replace	Replace ?	No
	BODY		CHASSIS MEMBER RR RH	1	525.38	10.00	472.84	Replace	Replace ✓ DT	No
96636630	REAR	6504631	REAR BOOT LID	1	974.00	10.00	876.60	Replace	Replace ✓ DT	No
96636677	REAR	6504634	REAR BOOT LOCK	1	77.00	10.00	69.30	Replace	Replace ✓ Jun	No
96636502	REAR		REAR BOOT HINGE	2	92.00	10.00	165.60	Replace	Replace ✓ BT	No
96474968	REAR		REAR BOOT SPRING GAS	2	144.00	10.00	259.20	Replace	Replace ?	No
96993921	REAR	6504578	TRIM TAIL LID	1	71.00	10.00	63.90	Replace	Replace ?	No
96851765	REAR	6504566	LAMP BACK UP LH	1	151.00	10.00	135.90	Replace	Replace ✓ CRK	No
96851766	REAR	6504583	LAMP BACK UP RH	1	122.00	10.00	109.80	Replace	Replace ✓ CRK	No
96976171	REAR	6504635	REAR BOOT REFLECTOR	1	165.00	10.00	148.50	Replace	Replace ✓ CRK	No
96190751	REAR		LAMP LICENSE	2	56.00	10.00	100.80	Replace	Replace ?	No
	REAR		NUMBER PLATE	1	30.00	0.00	30.00	Replace	Replace X	No
	COMMON		NUMBER PLATE FRAME	1	12.00	0.00	12.00	Replace	Replace X	No
96634035	REAR	6504564	LETTERING:"CHEVR OLET"	1	29.00	10.00	26.10	Replace	Replace ✓ NEC	No
96634897	REAR	6504565	LETTERING:"EPICA LT"	1	28.00	10.00	25.20	Replace	Replace ✓ NEC	No

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
96634023	REAR	6504567	EMBLEM REAR	1	44.00	10.00	39.60	Replace	Replace ✓ NEC	No
	COMMON		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace ✓ NEC	No
	COMMON		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace ✓ NEC	No
96636423	REAR		REAR BOOT ROD PULL LOCK	1	3.00	10.00	2.70	Replace	Replace ?	No
96632854	REAR	6504632	REAR BOOT WEATHERSTRIP	1	49.00	10.00	44.10	Replace	Replace ✓ Defect	No
			TRIM REAR BOOT, LH	1	125.00	10.00	112.50	Replace	Replace X	No
			TRIM REAR BOOT, RH	1	125.00	10.00	112.50	Replace	Replace X	No
94503739			CLIP, TRIM	10	1.00	10.00	9.00	Replace	Replace ✓ NEC	No
96932979			COVER BAORD SPARE TYRE	1	661.00	10.00	594.90	Replace	Replace X	No
			INSULATOR SHEET	2	41.48	10.00	74.66	Replace	Replace ✓ NEC	No ?
	COMMON	4006314	SEALANT SIKAFLEX	2	37.00	0.00	74.00	Replace	Replace ✓ NEC	No ?
96637759	REAR	6504579	TRIM REAR END PANEL	1	114.00	10.00	102.60	Replace	Replace ✓ Defect	No
96636426	REAR	6504633	REAR BOOT STRIKER	1	15.00	10.00	13.50	Replace	Replace ✓ BT	No
96646502	COMMON		W/HARNESS TRK ROOM	1	51.74	10.00	46.57	Replace	Replace ?	No
96646491	COMMON		W/HARNESS T / LID	1	83.52	10.00	75.17	Replace	Replace ?	No
96632799	LEFT	6504637	FENDER LH REAR	1	1,191.00	10.00	1,071.90	Replace	Replace ✓ DT	No
	COMMON		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace ✓ NEC	No
	COMMON		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace ✓ NEC	No
96633557	REAR	6504575	LINER LH REAR FENDER (PROTECTOR)	1	201.00	10.00	180.90	Replace	Replace X	No
96632800	REAR	6504638	FENDER RH REAR	1	1,467.00	10.00	1,320.30	Replace	Replace ✓ DT	No
	COMMON		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace ✓ NEC	No
	COMMON		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace ✓ NEC	No
			LINER RH REAR FENDER (PROTECTOR)	1	65.00	10.00	58.50	Replace	Replace ?	No
	COMMON		AIR DUCT REAR	2	45.00	10.00	81.00	Replace	Replace ?	No
96635656	DOOR	6504604	PANEL RH REAR DOOR	1	1,863.00	10.00	1,676.70	Replace	Replace R	No
	COMMON		STICKER DECAL 6555 8888 (DOOR)	1	60.00	0.00	60.00	Replace	Replace ✓ NEC	No
96632652	REAR	6504619	MOLDING WINDSCREEN REAR	1	45.00	10.00	40.50	Replace	Replace ✓ NEC	No
	COMMON		SEALANT W/SCREEN	2	37.00	0.00	74.00	Replace	Replace ✓ NEC	No
96851763	REAR	6504563	LAMP RR COMBINATION LH	1	415.00	10.00	373.50	Replace	Replace ✓ CRK	No
96851764	REAR	6504511	LAMP RR COMBINATION RH	1	415.00	10.00	373.50	Replace	Replace ✓ CRK	No
			PANEL TAIL LAMP, LH	1	143.40	10.00	129.06	Replace	Replace ✓ DT	No

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
			PANEL TAIL LAMP, RH	1	143.40	10.00	129.06	Replace	Replace <i>✓</i>	No
TOTAL MATERIALS							19,302.13	19,302.13		
TOTAL MATERIALS(Discounted)							14,637.61	14,637.61		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

OK



Please read through the [Privacy Statement](#), [Terms of Use](#), and [Disclaimer](#).

Please do not use the Back or Forward buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 10 and above, Chrome, Firefox, and Safari.

Copyright 2017 LTA [Privacy Statement](#) [Terms of Use](#) [Disclaimer](#) [Rate the Website](#) [Rate this e-Service](#)

Last updated on 19 Nov 2017 at 12:12 AM

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Dec 2017 Edit Reg		12 Dec 2017 00:00 Edit Adj Rpt	S\$13,750.00 Edit Estimates	S\$13,750.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	BD CRANE & ENGINEERING PTE LTD , Co. Reg. No.: A199300289D, Tel: +6585118585		
Main Claimant:	SMRT TAXIS PTE LTD , Co. Reg. No.: 198905369K		
Vehicle Reg. No.:	SHB5432Z	Date of Loss:	10/12/2017 20:00 - :59 [64 Months and 9 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 0491986512SG	Policy/Cover Note No.:	1700010793 (Comprehensive) Coverage: 26/05/2017 - 25/05/2018
Vehicle Reg. No. (Insured):	GBG472K	Policy No. (Claimant):	D-17087562MFSH
		Excess:	
Repairer:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com		
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Sebastian Yeang Wai Keen] ... [Final Rpt due 26/12/2017]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG_EXPRESS (19/07/2018): Alert - Adj Mandate Approved (S\$15779.14) - SHB5432Z - Claim Handler: Lee, Ming-...

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Letters/Correspondences				
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
29	27/02/18 13:56	General View	 Load JPG	
30	27/02/18 13:56	General View	 Load JPG	
31	27/02/18 13:56	General View	 Load JPG	
32	27/02/18 13:56	General View	 Load JPG	
33	27/02/18 13:56	General View	 Load JPG	
34	27/02/18 13:56	General View	 Load JPG	
35	27/02/18 13:56	General View	 Load JPG	
36	27/02/18 13:56	General View	 Load JPG	
37	27/02/18 13:56	General View	 Load JPG	
38	27/02/18 13:56	General View	 Load JPG	
39	27/02/18 13:56	General View	 Load JPG	
40	27/02/18 13:56	General View	 Load JPG	
41	27/02/18 13:56	General View	 Load JPG	
42	27/02/18 13:56	General View	 Load JPG	
43	27/02/18 13:56	General View	 Load JPG	
44	27/02/18 13:56	General View	 Load JPG	
45	27/02/18 13:56	General View	 Load JPG	
46	27/02/18 13:56	General View	 Load JPG	
47	27/02/18 13:56	General View	 Load JPG	
48	27/02/18 13:56	General View	 Load JPG	
49	27/02/18 13:56	General View	 Load JPG	
50	27/02/18 13:56	General View	 Load JPG	
51	27/02/18 13:56	General View	 Load JPG	
52	27/02/18 13:56	General View	 Load JPG	
53	27/02/18 13:56	General View	 Load JPG	
54	27/02/18 13:56	General View	 Load JPG	
55	27/02/18 13:56	General View	 Load JPG	
56	27/02/18 13:56	General View	 Load JPG	
57	27/02/18 13:56	General View	 Load JPG	
58	27/02/18 13:56	General View	 Load JPG	
59	27/02/18 13:57	General View	 Load JPG	
60	27/02/18 13:57	General View	 Load JPG	
61	27/02/18 13:57	General View	 Load JPG	
62	27/02/18 13:57	General View	 Load JPG	
63	27/02/18 13:57	General View	 Load JPG	
64	27/02/18 13:57	General View	 Load JPG	
65	27/02/18 13:57	General View	 Load JPG	
66	27/02/18 13:57	General View	 Load JPG	
67	27/02/18 13:57	General View	 Load JPG	
68	27/02/18 13:57	General View	 Load JPG	
69	27/02/18 13:57	General View	 Load JPG	
70	27/02/18 13:57	General View	 Load JPG	
71	27/02/18 13:57	General View	 Load JPG	
72	27/02/18 13:57	General View	 Load JPG	
73	27/02/18 13:57	General View	 Load JPG	
74	27/02/18 13:57	General View	 Load JPG	
75	27/02/18 13:57	Reinspection Photo	 Load JPG	
76	27/02/18 13:57	Reinspection Photo	Load JPG	

Letters/Correspondences				☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
77	27/02/18 13:57	Reinspection Photo	Load JPG	☒
78	27/02/18 13:57	Reinspection Photo	Load JPG	☒
79	27/02/18 13:57	Reinspection Photo	Load JPG	☒
80	27/02/18 13:57	Reinspection Photo	Load JPG	☒
81	27/02/18 13:57	Reinspection Photo	Load JPG	☒
82	27/02/18 13:57	Reinspection Photo	Load JPG	☒
83	27/02/18 13:57	Reinspection Photo	Load JPG	☒
84	27/02/18 13:57	Reinspection Photo	Load JPG	☒
85	27/02/18 13:57	Reinspection Photo	Load JPG	☒
86	27/02/18 13:57	Reinspection Photo	Load JPG	☒
87	27/02/18 13:57	Reinspection Photo	Load JPG	☒
88	27/02/18 13:57	Reinspection Photo	Load JPG	☒
89	27/02/18 13:57	Reinspection Photo	Load JPG	☒
90	27/02/18 13:57	Reinspection Photo	Load JPG	☒
91	27/02/18 13:57	Reinspection Photo	Load JPG	☒
92	27/02/18 13:57	Reinspection Photo	Load JPG	☒
93	27/02/18 13:57	Reinspection Photo	Load JPG	☒
94	27/02/18 13:57	Reinspection Photo	Load JPG	☒
95	27/02/18 13:57	Reinspection Photo	Load JPG	☒
96	27/02/18 13:57	Reinspection Photo	Load JPG	☒
97	27/02/18 13:57	Reinspection Photo	Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/12/17 14:43	TP GIA REPORT	Load PDF	
2	15/12/17 10:24	TP ESTIMATE - MARKED	Load PDF	
3	11/01/18 16:19	LETTER TO OI	Load PDF	
4	27/02/18 11:44	LTA SEARCH	Load PDF	
5	27/02/18 13:59	Pax medical claim	Load PDF	
6	27/02/18 14:07	Email to AIG to seek mandate SHB 54322.	Load PDF	
7	07/03/18 09:52	Final Bill	Load PDF	
8	24/07/18 08:59	AUTHORISATION TO ACT	Load PDF	
9	24/07/18 08:59	RELEASE VOUCHER	Load PDF	
10	24/07/18 08:59	RENTAL RECEIPT	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	GBG472K (Insd veh)	Model:	CHEVROLET EPICA 2.0 2.0DSL
	SHB5432Z (TP veh)		AT ABS D/AB 2WD 4DR TUR (A)
Date of Accident:	10/12/2017		

Global Sum Settlement	:	☒ Yes	☐ No	
Repair Estimate	: \$			30,107.12
Final Repair Cost	: \$			15,770.00
Loss of Use	: \$			days at \$0.00 per day
Rental (if any)	: \$			16 days
LTA / GIA Search Fee	: \$			
Others:	: \$			
	: \$			
Final Settlement Sum (GLOBAL SUM)	: \$			15,770.00

Is Third Party Workshop GIA Registered?		☐ YES	☒ NO	(Kindly indicate below)
A) For Non GIA Registered Workshop:		Agreed Liability _____ 100 _____ (%)		
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____		
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks _____				

Payment Instruction: Payee's Breakdown			
1)	SMRT TAXIS PTE LTD	: \$	15,770.00
2)		: \$	
3)		: \$	
4)		: \$	

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

24 Jul
2018

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG17023748/SWA3S2

Date: 24/07/2018

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700010793
Claimant Vehicle No :	SHB5432Z	Insured Vehicle No :	GBG472K
Date of Loss:	10/12/2017	Nature of Claim:	TP
		Claim No:	0491986512SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB5432Z		
Make & Model:	CHEVROLET EPICA, 2.0 2.0DSL AT ABS D/AB 2WD 4DR TUR (A)	Engine No:	Z20S1463366K
Reg. Date:	01/08/2012 (Man. Year: 2012)	Chassis No:	KL1LA69RJB138833
Colour:	Maroon	Odometer:	648710 km
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55R15	Rear Tyre Size:	205/55R15
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,385.12	11,253.76	10,131.36	47.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,722.00	4,740.00	3,982.00	45.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	30,107.12	15,993.76	14,113.36	46.88
Approved Total (Overridden) (S\$)		13,750.00		
Nett Amount (S\$)	30,107.12	13,750.00	16,357.12	54.33
+ Medical Costs (S\$)		380.62		
+ Car Rental (16.0 x S\$102.72/day) (S\$)		1,643.52		
+ Doc/Search Fee (S\$)		5.00		
Nett Liability (S\$)		15,779.14		
Global Sum Settlement (S\$)		15,770.00		

INSPECTION

Date of Assignment:	12/12/2017	
Date Inspected:	12/12/2017	Inspected At: SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	14.0 days	

Adjuster: Sebastian Yeang Wai Keen**Manager:** VIVIAN LAU PEI FENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*EMBLEM REAR (DISC 10%)	Necessary	44.00 F	*39.60 F
2	1		*REAR BOOT WEATHERSTRIP (DISC 10%)	Deformed	49.00 F	*44.10 F
3	10		*CLIP, TRIM (DISC 10%)	Necessary	10.00 F	*9.00 F
4	1		*TRIM REAR END PANEL (DISC 10%)	Deformed	114.00 F	*102.60 F
5	1		*REAR BOOT STRIKER (DISC 10%)	Bent	15.00 F	*13.50 F
6	1		*FENDER LH REAR (DISC 10%)	Dented	1,191.00 F	*1,071.90 F
7	1		*FENDER RH REAR (DISC 10%)	Dented	1,467.00 F	*1,320.30 F
8	1		*MOLDING WINDSCREEN REAR (DISC 10%)	Necessary	45.00 F	*40.50 F
9	1		*LAMP RR COMBINATION LH (DISC 10%)	Cracked	415.00 F	*373.50 F
10	1		*LAMP RR COMBINATION RH (DISC 10%)	Cracked	415.00 F	*373.50 F
11	1		*PANEL TAIL LAMP, LH (DISC 10%)	Dented	143.40 F	*129.06 F
12	1		*BUMPER RR (DISC 10%)	Cracked	1,238.00 F	*1,114.20 F
13	1		*BEAM RR BUMPER IMPACT (DISC 10%)	Bent	1,221.00 F	*1,098.90 F
14	1		*ABSORBER ENGY RR BUMPER (DISC 10%)	Cracked	70.00 F	*63.00 F
15	1		*BRACKET RR BUMPER SIDE LH (DISC 10%)	Cracked	49.00 F	*44.10 F
16	1		*BRACKET RR BUMPER SIDE RH (DISC 10%)	Cracked	49.00 F	*44.10 F
17	1		*REFLECTOR REFLEX RR LH (DISC 10%)	Cracked	264.00 F	*237.60 F
18	1		*REFLECTOR REFLEX RR RH (DISC 10%)	Cracked	264.00 F	*237.60 F
19	1		*PANEL END REAR (DISC 10%)	Dented	255.00 F	*229.50 F
20	1		*PANEL SPARE TYRE (DISC 10%)	Dented	2,299.00 F	*2,069.10 F
21	1		*CHASSIS MEMBER RR RH (DISC 10%)	Dented	525.38 F	*472.84 F
22	1		*REAR BOOT LID (DISC 10%)	Dented	974.00 F	*876.60 F
23	1		*REAR BOOT LOCK (DISC 10%)	Jammed	77.00 F	*69.30 F
24	2		*REAR BOOT HINGE (DISC 10%)	Bent	184.00 F	*165.60 F
25	1		*LAMP BACK UP LH (DISC 10%)	Cracked	151.00 F	*135.90 F
26	1		*LAMP BACK UP RH (DISC 10%)	Cracked	122.00 F	*109.80 F
27	1		*REAR BOOT REFLECTOR (DISC 10%)	Cracked	165.00 F	*148.50 F
28	1		*LETTERING: CHEVROLET (DISC 10%)	Necessary	29.00 F	*26.10 F
29	1		*LETTERING: EPICA LT (DISC 10%)	Necessary	28.00 F	*25.20 F
30	1		*PANEL TAIL LAMP, RH (DISC 10%)	Dented	143.40 F	*129.06 F
31	1		*SMRT LOGO (SN)	Necessary	7.80 F	*7.80 F
32	1		*STICKER DECAL 6555 8888 (SN)	Necessary	21.60 F	*21.60 F
33	1		*SMRT LOGO (SN)	Necessary	7.80 F	*7.80 F
34	1		*STICKER DECAL 6555 8888 (SN)	Necessary	21.60 F	*21.60 F
35	1		*SMRT LOGO (SN)	Necessary	7.80 F	*7.80 F
36	1		*STICKER DECAL 6555 8888 (SN)	Necessary	21.60 F	*21.60 F
37	1		*STICKER DECAL 6555 8888 (DOOR) (SN)	Necessary	60.00 F	*60.00 F
38	2		*SEALANT W/SCREEN (SN)	Necessary	74.00 F	*74.00 F
39	1		*SENSOR REVERSE (SN)	Damaged	180.00 F	*180.00 F
40	1		*SEALANT SIKAFLEX (SN)	Necessary	37.00 F	*37.00 F
41	1		*REAR BOOT ROD PULL LOCK	Not Necessary	3.00 F	*- F
42	1		*TRIM REAR BOOT, LH	Not Necessary	125.00 F	*- F
43	1		*TRIM REAR BOOT, RH	Not Necessary	125.00 F	*- F
44	1		*COVER BOARD SPARE TYRE	Not Necessary	661.00 F	*- F
45	2		*INSULATOR SHEET	Not Necessary	82.96 F	*- F
46	2		*SEALANT SIKAFLEX	Not Necessary	74.00 F	*- F
47	1		*W/HARNESS TRK ROOM	Not Necessary	51.74 F	*- F
48	1		*W/HARNESS / LID	Not Necessary	83.52 F	*- F
49	1		*LINER LH REAR FENDER (PROTECTOR)	Not Necessary	201.00 F	*- F
50	1		*LINER RH REAR FENDER (PROTECTOR)	Not Necessary	65.00 F	*- F
51	2		*AIR DUCT REAR	Not Necessary	90.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*W/HARNESS RR BPR	Not Necessary	227.34 F	*- F
53	1		*COVER TOWING EYE RR	Not Necessary	21.00 F	*- F
54	2		*EXHAUST PIPE MOUNTING, REAR	Not Necessary	8.80 F	*- F
55	1		*PNL SIDE LH SPARE TYRE	Not Necessary	650.00 F	*- F
56	1		*CHASSIS MEMBER RR LH	Not Necessary	525.38 F	*- F
57	1		*PNL SIDE RH SPARE TYRE	Not Necessary	650.00 F	*- F
58	2		*REAR BOOT SPRING GAS	Not Necessary	288.00 F	*- F
59	1		*TRIM TAIL LID	Not Necessary	71.00 F	*- F
60	2		*LAMP LICENCE	Not Necessary	112.00 F	*- F
61	1		*NUMBER PLATE	Not Necessary	30.00 F	*- F
62	1		*NUMBER PLATE FRAME	Not Necessary	12.00 F	*- F
63	1		*PANEL RH REAR DOOR	Repair	1,863.00 F	*- F
64	1		*MUFFLER A-EXH,RR	Repair	2,909.00 F	*- F

F=Franchise part.

Total Parts (S\$)	21,385.12	11,253.76
--------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODYWORK.	New	2,704.00	2,250.00
2	SPRAY PAINT.	New	4,068.00	1,800.00
3	TO CHECK WIRING AND SYSTEM FUNCTION.	New	80.00	30.00
4	TO APPLY RUST-PROOFING ON AFFECTED AREA.	New	200.00	60.00
5	TO TEST AND REFIX REVERSE SENSOR SYSTEM.	New	120.00	30.00
6	TO REMOVE AND REFIT WIRE HARDESS.	New	200.00	0.00
7	REMOVE AND REPLACE BOTH RR EXHAUST MUFFLER.	New	120.00	60.00
8	TO ALIGN CHASSIS.	New	350.00	200.00
9	TO TRANSFER REAR TAILGATE MECHANISM.	New	120.00	60.00
10	TO REMOVE / REFIT SEAT.	New	120.00	50.00
11	TO TRANSFER DOOR MECHANISM.	New	120.00	0.00
12	TO REMOVE AND REFIX REAR WINDSCREEN.	New	120.00	100.00
13	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE.	New	120.00	30.00
14	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	New	120.00	50.00
15	TO REPLACE SUNDRY PARTS.	New	100.00	20.00
16	TO WASH AND VACUUM.	New	60.00	0.00
Gross Labour Cost (\$\$)			8,722.00	4,740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >