

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Chong Boon Sen

Date: 15 Dec 2017

## **Preliminary Advice**

Vehicle No	: SFZ6955Y	Accident Date	: 09/12/2017
Make	: VOLKSWAGEN GOLF	Policy No.	: DMPCSN3065261700
Assignment Date	: 14/12/2017	Excess	: S\$1,000.00
Date of Inspection	: 14/12/2017	Est. Duration of Repair	: 16.00
Inspection At	: LAI HUAT (MENG KEE) MOTOR PTE LTD (SIN MING) 160 SIN MING DRIVE #04-01, SIN MING AUTOCITY SINGAPORE 575722		

### **Point of Impact / General Description of Damages**

The vehicle sustained impact / damages n/s body and o/s front portion. The undercarriage and body structure affected due to collision parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	20,901.51
Revised Amount	:S\$	18,612.59
Check Items (Estimated)	:S\$	1,869.52
Total	:S\$	20,482.11

Lump Sum Repair (ESTIMATED)	:S\$	16,400.00
-----------------------------	------	-----------

### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	42,000.00
COE / PARF Rebate	:S\$	21,033.00
Salvage Value	:S\$	
Margin for Repair	:S\$	20,967.00

### **Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :