

TRANS-CAB AUTO SERVICES PTE LTD

NO. 2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB9677H - CHINA TAIPING**AAD1712-067***Not Authored
11 Sep 8 2850*

Vehicle No.:

SHB 9677H - CANDY

Chassis No.:

KL1LA69RJBB122706

Vehicle Make:

CHEVROLET

Vehicle Model:

CHEVROLET EPICA 2.0

Date of Accident :

05.12.2017

Third Party Insurer :

CHINA TAIPING

		PART		LIST
1	1	Front Bumper	\$	<i>CM</i> 1,202.00 ✓
2	1	Front Bumper Lower Absorber	\$	<i>Pl</i> 180.00 ✓
3	1	Front Bumper Reinforcement	\$	<i>R</i> 356.00 X
4	1	Front Bumper Retainer RH	\$	<i>Pl</i> 102.00 ✓
5	1	Front Bumper Retainer LH	\$	<i>Pl</i> 102.00 X
6	1	Front Bumper Lower Grille	\$	<i>Pl</i> 78.00 ✓
7	1	Front Bumper Lower Stiffener	\$	<i>R</i> 134.37 X
8	1	Bumper Fog Lamp Cover RH	\$	<i>Pl</i> 32.40 X
9	1	Front Headlamp RH	\$	<i>CM</i> 816.00 ✓
10	1	Front Fender RH	\$	<i>R</i> 837.60 ✓
11	1	Front Fender Liner RH	\$	<i>Pl</i> 47.00
12	1	Windscreen Washer Tank - Filler Neck	\$	<i>Pl</i> 4.80
13	1	Windscreen Washer Tank	\$	<i>Pl</i> 62.00
14	1	Windscreen Washer Tank Motor	\$	<i>Pl</i> 51.00
15	1	Front Shock Absorber Assy RH	\$	<i>Sec</i> 216.17
16	1	Front Lower Arm RH	\$	<i>Pl</i> 283.00
17	1	Front Knuckle Arm RH	\$	<i>Pl</i> 230.00
18	1	Bonnet	\$	<i>R</i> 1,250.00
19	1	Bonnet Moulding	\$	<i>Pl</i> 161.97
20	1	Front Support Panel Assy	\$	<i>R</i> 1,222.32
21	1	Radiator Grille (Grille A-Rad)	\$	<i>Pl</i> 367.00
22	1	Radiator Grille Top Cover	\$	<i>Pl</i> 45.02
23	1	Front Door RH	\$	<i>R</i> 1,133.00
24	1	Front Side View Mirror RH	\$	<i>Pl</i> 939.00
TOTAL			\$	9,852.65
10%			\$	985.27
			\$	8,867.39

Special Nett

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB9677H - CHINA TAIPING**AAD1712-067**

1	1 Set Front Bumper Fastener Clip	\$	<i>nn</i> 30.00 ✓
2	1 Set Front Fender Liner Clip RH	\$	<i>nn</i> 30.00 X
3	1 Front Wheel Rim Hub Cap RH	\$	<i>sh</i> 166.30 X
4	1 Front Tyre RH	\$	<i>sh</i> 180.00 X
5	1 Front Tyre Rim RH	\$	<i>sh</i> 126.00 X
6	1 Door Sticker "Trans-cab" RH	\$	<i>nn</i> 80.00 X

TOTAL	\$	612.30
TOTAL PARTS	\$	9,479.69

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of
Parts, Adjust And Realign The Same

\$ 2,700.00 *400/*

To Rust-Proofing Of The Affected Areas.

\$ 220.00 *300/*

Putty and Spray Painting Of The Affected
Portion.

\$ 2,800.00 *400/*

To Check Electrical Lighting Concerned.

\$ 170.00 *200/*

To check steering geometry and computer wheel
alignment

\$ *nn* 220.00 X

Towing Fees.

\$ *nn* 120.00 X

To dismantle and refit front end suspension,
undercarriage parts, final checking and testing.

\$ *nn* 380.00 X

To transfer of door fittings, attachment and
perform water seepage test.

\$ *nn* 170.00 X

To Transfer Of Fender Fittings, Attachments
And Perform Water Seepage Test.

\$ *nn* 170.00 X

To transfer of tire, rim and on wheel balancing.

\$ *nn* 170.00 X

TOTAL	\$	7,120.00
Over All Total	\$	16,599.69

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB9677H - CHINA TAIPING

AAD1712-067

REPAIR DAYS

~~10 DAYS~~

2 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: