

15/5/2010

LKK:

IDAC:

INS. CASE OWNER:

Gerald

CC 4/LPC170 23759 / Uda302

ASSIGNMENT

Surveyor:

MARCUS

DOI:

14/12/17

Date / Time:

14/12/17

Pre-assign / CCU / FTE



Insured Vehicle No.:

STN 4651C

Name of Insured:

DAVID HO POH WAH

Insured Tel No.:

HP: 96494859

Excess Sec II :SS

D.O.A: 12/12/17

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

17/17/17/UP05/020273

Policy No.:

217UP05013207

Make / Model:

MERCEDES - BENZ C700

Place of Accident:

1 CAMPRESSOR
TPE TOWARDS BEDOK TOWN

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%


Final? Yes / No

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

9kw 5096P



INSRS:

WSP: Stytech Auto

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

STAGE

DATE / PIC

18/12/17 (THUR THUR)

9kw 5096P - X ; STN 4651C - X

OI rear-ended to IP.

29/1/18

File pass to typist

5/4/18

Received D.V.

RECEIVED 05 APR 2018

Non-Reporting ltr (1st):
 Non-Reporting ltr (2nd):
 Non-Reporting ltr (Final):
 Notification ltr (if non-pickup):
 Call OI:
 After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time: 15/12/17

Sent By: Shirley Heng

Charles Heng 5.26p

Confirm by:

FINALIZATION

Date/Time:

Confirm with:

Repair Cost:

S\$

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

26/3/18

Confirm with Win Stone

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.: 27

Repair Cost:

S\$

5136.00

Loss of Rental (LOR):

S\$

642.00

(6 days) x100 wgst

Loss of Use (LOU):

S\$

(\$ x days)

Loss of Income (LOI):

S\$

(\$ x days)

C- only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$

5.35

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

Total:

S\$

5783.35

Global Sum S\$:

Email

Call

FINAL PAYMENT

Date/Time:

Confirm with:

Payee 1:

S\$

5783.35

Name 1:

STYTECH AUTO PTE LTD

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

COPY SENT
5/4/18

Surrey mercus

REF:

LPC/
ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: SKW 5096P
 at Workshop m/s styletech
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 CA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 5 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

20776
 Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Date / Time Action / Instruction

L74 52839

Veh No: SKW 5096P Yr Regn: 10/15
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or CA

Make: mazda 3 C.C. 1496
 Colour: silver A/C: Insured / Std / NI / NA
 Sp. Reading: 30746 T/Radio: Insured / Std / NI / NA

Eng/No: _____
 C/No: JM6BM42A 8G032258
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 205/60R16
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front Rear
 R/Bal. 7 mm R/Bal. 7 mm
 L/Bal. 7 mm L/Bal. 7 mm
 D.O.A. 12/12/17 D.O.I. 14/12/17
 Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear
 The U/C / Chassis frame / Body Structure affected due to collision.

Repair Sum - \$4800+ (Red: \$4074.10/46%)

Date/Time: File Pass to?

☐ : Preli. Report
☐ : Final Report

1)

Date/Time: File Return to?

2)

Report Format:

Lump Sum / I.B.I: (\$ _____)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS (\$ _____)

Photos

Others

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CC4/LPC17023759/Uua3	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Date : 14-12-2017	
			Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJN 4651C	Veh. Inspected	SKW 5096P	
Policy No.	Z17VP05013207	Coverage (\$)	0.00	
Claim No.	17/17/17/VP05/020273	Excess (\$)	0.00	
Assign From		Assign Date	14/12/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer		Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	12/12/2017	Inspection Date	14/12/2017	
Survey held at	STYTECH AUTO PTE LTD 2 KAKI BUKIT AVENUE 2 #02-30 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: 17/17/17/VP05/020273
Our ref: CC4/LPC17023759/Uua3

Date: 15.12.2017

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.


SKW 5096P

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 14.12.2017 at the premises of M/s Stytech Auto Pte Ltd (Kaki Bukit) have the following to report:-

Workshop Estimate Amount	: S\$	7,548.60
Revised Estimate Amount	: S\$	5,936.50
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:
The vehicle sustained damages at the
Rear Portion



Comments/Present Status:
Damages Consistent
Estimated normal period for repairs: 5.0 days

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

Nivitha (LKK Auto)

From: ERIC WOO JUN KIAT <ericwoo@lonpac.com>
Sent: Wednesday, 13 December, 2017 4:45 PM
To: assignments@lkkauto.com
Cc: MT_Claim_SG
Subject: Our Ref: 17/17/17/VP05/020273 Accident involving SJN4651C & SKW5096P along New Upper Changi Rd on 12/12/17
Attachments: FW: SURVEY INVITATION for accident on 012/12/17 Along New Uppr Changi R.... (2.05 MB); 13122017164306.pdf

9:07 am @ 14/12/2017
vehicle in
person @ Winston
SUR @ Marcus

Dear Catherine,

Kindly refer to our attachment.

Please proceed to conduct a survey of the vehicle SKW5096P on without Prejudice Basis.

We look forward to receiving your report soon.

Thank you.

Best Regards,
Eric Woo
Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6279 9253 | Fax: (65) 6296 3767

Nivitha (LKK Auto)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Wednesday, 13 December, 2017 2:47 PM
To: ERIC WOO JUN KIAT
Cc: MT_Claim_SG
Subject: FW: SURVEY INVITATION for accident on 012/12/17 Along New Uppr Changi Road (EXIT 1), involving vehicle SKW5096P & SJN4651C.
Attachments: SKW5096P_12122017.pdf

Hi Eric,

Kindly do the needful.

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: Stytech Auto Pte Ltd [mailto:stytechent@singnet.com.sg]
Sent: Wednesday, 13 December, 2017 2:04 PM
To: GERALD POH WEE BIN
Subject: SURVEY INVITATION for accident on 012/12/17 Along New Uppr Changi Road (EXIT 1), involving vehicle SKW5096P & SJN4651C.

Dear Claims Officer

We would like to invite your surveyor to our workshop to survey our vehicle SKW5096P whom involved an accident with your insured SJN4651C.

Note: Vehicle in worshop.

Location	: 2 Kaki Bukit Ave 2 #01-02 Kaki Bukit Autohub S(417921) (enter via Kaki Bukit Road 2) Heavy Vehicle Workshops
Contact Person	: Mr. Winston Teo Hp. No. 9685 8843

Kindly reply to this email or contact me at 96858843 to confirm.

Thank You

Best Regards

Winston Teo

Hp 96858843

Stytech Auto Pte Ltd

2 Kaki Bukit Ave 2 #02-30

Kaki Bukit Autohub Singapore 417921

TEL : 64448125

Fax : 64453310

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Company
Owner ID	2077G
Vehicle Details	
Vehicle No.	SKW5096P
Vehicle to be Exported	No
Intended De-registration Date	14 Dec 2017
Vehicle Make	MAZDA
Vehicle Model	MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT
Primary Colour	Silver
Manufacturing Year	2015
Engine No.	P520327079
Chassis No.	JM6BM42A8G0322548
Maximum Power Output	88.0 kW (118 bhp)
Open Market Value	\$15,091.00
Original Registration Date	30 Oct 2015
First Registration Date	30 Oct 2015
Transfer Count	0
Actual ARF Paid	\$10,091.00
Intended PARF Rebate Details	
PARF Eligibility	Yes
PARF Eligibility Expiry Date	29 Oct 2025
PARF Rebate Amount	\$7,568.00
Intended COE Rebate Details	
COE Expiry Date	29 Oct 2025
COE Category	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years)	10
QP Paid	\$57,498.00
COE Rebate Amount	\$45,271.00
Total Rebate Amount	\$52,839.00

The information contained herein is correct as at 14 Dec 2017

OK

Skw 5096-P Mazda 3

- 1) Rear Bootlid — \$920.70 5.6500 —
- 2) " " Inner Lock — \$185.00 Tw. —
- 3) " " Inner shield clip — \$20.00 SN nr —
- 4) " " Lamp (5x) $282.00 = \$564.00$ RNX
- 5) " " 'Mazda 3' plate — \$55.10 nr —
- 6) " " 'skyactiv' plate — \$64.20 nr —
- 7) " " Emblem — \$55.40 nr —
- 8) Rear No. plate Assy — \$50.00 SN Set 405.00
- 9) Rear Bumper — \$959.80 D.S. —
- 10) " " clip — \$30.00 SN nr —
- 11) " " Reinforcement frame — \$385.00 D —
- 12) " " Retainer (2x) $32.70 = \$65.40$ Set —
- 13) " " Tow Hook Cover — \$68.00 Torn —
- 14) Rear Panel — \$784.60 Body —
- 15) " " sticker — \$45.00 RNX
- 16) " " garnish — \$277.66 RNX
- 17) " " Rubber — \$167.80 Tw. —
- 18) " " Tailamp (2x) $385.50 = \$771.00$ N/S CR 1/2
- Rear spare tyre top board — Torn —

SKW 1096-P

- 19) Rear Panel Joint Sealant - 80 SN
20) Reverse Sewer — 220 SN

in 50 S.W
shut 2005.1

Labour:-

- 1) check wiring — 80k — 30
2) Anti Rust Proofing — 100k — 60
3) Panel Beating — 650k — 600
4) Paintwork — 850k — 750
5) Interior Upholstery — 100k — 60

Not Shurt
in

2/5/14
Sdy.

14/12/14

STYTECH AUTO PTE. LTD.

2 Kaki Bukit Ave 2 #02-30
Kaki Bukit Autohub Singapore 417921
Tel: 6444 8125 Fax: 6445 3310
GST Reg. No.: 201601539K
Co. Reg. No.: 201601539K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

920.70	564.00	20.00	10.00	30.00	50.00	4096.50
185.00	45.00	40.00	30.00	60.00	40.00	1272.10
	277.60	30.00	20.00	600.00	50.00	340.00
55.10	385.50	50.00		750.00	100.00	60.00
64.20		200.00		60.00	40.00	1500.00
55.40						280.00
959.80						
385.00						
65.40				1500.00		
68.00						
784.60						

167.80
385.50

280.00

340.00

7548.60

~~7548.60~~ ✓

1272.10

60.00

4096.50

5368.60
4096.50
1272.10

400.00
340.00
60.00

1780.00
1500.00
280.00

0.00
0.00
0.00
4096.50
340.00

1500.00
5936.50 ✓

0.00
0.00
0.00
0.00
0.00

}

CHECK ITEM

0.00
0.00
0.00

Kaw 5096-P Mazda 3

- 1) Rear Bootlid — \$920.70 1.6m —
 - 2) " " " Inner Lock — \$185.00 1w. —
 - 3) " " " Inner shield clip — \$20.00 SN nr —
 - 4) " " " Lamp (2x) $282.00 = \$564.00$ nrx
 - 5) " " " 'Mazda 3' plate — \$55.10 nr —
 - 6) " " " 'skyactiv' plate — \$64.20 nr —
 - 7) " " " Emblem — \$55.40 nr —
 - 8) Rear No. plate Assy — \$50.00 SN 1st 40s.w
 - 9) Rear Bumper — \$959.80 0.5 —
 - 10) " " " clip — \$30.00 SN nr —
 - 11) " " " Refinement frame — \$385.00 2 —
 - 12) " " " Retainer (2x) $32.70 = \$65.40$ 1st —
 - 13) " " " Tow Hook Cover — \$68.00 Torn —
 - 14) Rear Panel — \$784.60 Body 20 —
 - 15) " " " Stricker — \$45.00 nrx
 - 16) " " " garnish — \$277.66 nrx
 - 17) " " " Rubber — \$167.80 1w. —
 - 18) " " " Taillamp (2x) $385.50 = \$771.00$ n/s cre 1/c
- Rear spare tyre top board — Torn —

SKW 6096-P

- 19) Rear Panel Joint Sealant - 80 SN
20) Reverse Sewer — 220 SN

in 50 S.W
Sheet 2005.

Labour:-

- 1) Check wing — 80k — 30
2) Anti Rust Proofing — 100k — 60
3) Panel Beating — 650k — 600
4) Paintwork — 850k — 750
5) Interior Upholstery — 100k — 60

Not Done
in
2/5/14
Sdy.
14/12/14

STYTECH AUTO PTE. LTD.
2 Kaki Bukit Ave 2 #02-30
Kaki Bukit Autohub Singapore 417921
Tel: 6444 8125 Fax: 6445 3310
GST Reg. No.: 201601539K
Co. Reg. No.: 201601539K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

u Yeh phb After repair Not Authorised Estimate

Vehicle: SKW 5096P

Make & Model: mazda 3

Repair Sum 4800

Year: _____

Chassis No: _____

5 day
14/1/17

	Parts / Labour	Condition	Price	recommend
	Bootlid	Badly DD	920.70	✓
	Bootlid inner lock	FW	185.00	✓
	Bootlid inner shield clips	ALL	20.00	✓
2PCS	Bootlid reflectors @ 282.00	11	564.00	X
	Bootlid mazda '3' emblem	ALL	55.10	✓
	Bootlid skyactiv emblem	ALL	64.20	✓
	Bootlid rear logo	ALL	55.40	✓
	Rear bumper	DIS	959.80	✓
	Rear bumper reinforcement	DD	385.00	✓
2PCS	Rear bumper side retainers @ 32.70	Best	65.40	✓
	Rear bumper Tow hook cover	Torn	68.00	✓
	Rear end panel 469.70	Badly DD	784.60	✓
	Rear end panel Striker	11	45.00	X
	Rear end panel top garnish	11	277.60	X
	Bootlid weatherstrip	FW	167.80	✓
2PCS	tailleups @ 915.00	W/SCRE	1830.00	INC
	Rear floor panel top board	Torn	266.00	✓
			6714.10	4597.60
				3678.08
	S. Netf			
	Rear licence plate w/holder	Best	50.00	405.✓
1set	Rear bumper clips	ALL	30.00	✓
	Rear end panel sealant	ALL	80.00	505.✓
1set	Rear reverse sensor	Shaded	220.00	2005.✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting.
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

labour

To check wiring

80.00 30

To spray anti rust proofing

100.00 - 60

labour for panel beating & replacing parts

650.00 - 600

To putty & spray painting

850.00 - 750

To Dismantle & refix upholstery

100.00 - 80

TOTAL # 8874.10

Shirley Hiew (LKK Auto)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Monday, 18 December 2017 9:13 AM
To: Shirley Hiew (LKK Auto)
Cc: MT_Claim_SG
Subject: RE: Our Ref: 17/17/17/VP05/020273 Accident involving SJN4651C & SKW5096P along New Upper Changi Rd on 12/12/17
Attachments: 18122017090919.pdf

Dear Shirley,

We attached a copy of insured's GIA report for your attention.

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]
Sent: Friday, 15 December, 2017 5:48 PM
To: MT_Claim_SG
Cc: ERIC WOO JUN KIAT; ONG LI LI; GERALD POH WEE BIN; Thin Thin (LKKAuto); Jas Khine (LKKAuto); Admin A
Subject: RE: Our Ref: 17/17/17/VP05/020273 Accident involving SJN4651C & SKW5096P along New Upper Changi Rd on 12/12/17

Your ref: 17/17/17/VP05/020273
LKK ref: CC4/LPC17023759/Uua3

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

This is a third party direct settlement case.

Enclosed revert of vehicle: SKW 5096P

Date of survey: 14/12/2017

Enclosed for your perusal is:

- TP's GIA report
- Estimated cost of repair
- Preliminary advice

We have not authorized repairs.

Kindly assist to verify validity of our insured's policy, and let us have a copy of insured's accident report for our necessary action.

Kindly take note that the case handler in-charge is Thin Thin and she can be contacted at DID: 6841 2360.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Shirley Hiew | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: ShirleyHiew@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Thursday, 14 December, 2017 9:09 AM

To: 'ERIC WOO JUN KIAT' <ericwoo@lonpac.com>; assignments <assignments@lkkauto.com>

Cc: 'MT_Claim_SG' <mt_claim@lonpac.com>; Admin A <admin-a@lkkauto.com>

Subject: RE: Our Ref: 17/17/17/VP05/020273 Accident involving SJN4651C & SKW5096P along New Upper Changi Rd on 12/12/17

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ERIC WOO JUN KIAT [<mailto:ericwoo@lonpac.com>]

Sent: Wednesday, 13 December, 2017 4:45 PM

To: assignments@lkkauto.com

Cc: MT_Claim_SG

Subject: Our Ref: 17/17/17/VP05/020273 Accident involving SJN4651C & SKW5096P along New Upper Changi Rd on 12/12/17

Dear Catherine,

Kindly refer to our attachment.

Please proceed to conduct a survey of the vehicle SKW5096P on without Prejudice Basis.

We look forward to receiving your report soon.

Thank you.

Best Regards,

Eric Woo

Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6279 9253 | Fax: (65) 6296 3767



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKW 5096P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BOOTLID	BADLY DENTED	920.70	920.70
1	BOOTLID INNER LOCK	TWISTED	185.00	185.00
1	BOOTLID INNER SHIELD CLIPS	NECESSARY	20.00	20.00
2	BOOTLID REFLECTORS @\$282.00	NOT NECESSARY	564.00	-
1	BOOTLID MAZDA "3" EMBLEM	NECESSARY	55.10	55.10
1	BOOTLID SKYACTIV EMBLEM	NECESSARY	64.20	64.20
1	BOOTLID REAR LOGO	NECESSARY	55.40	55.40
1	REAR BUMPER	DISTORTED	959.80	959.80
1	REAR BUMPER REINFORCEMENT	DENTED	385.00	385.00
2	REAR BUMPER SIDE RETAINERS @\$32.70	BENT	65.40	65.40
1	REAR BUMPER TOW HOOK COVER	TORN	68.00	68.00
1	REAR END PANEL	BADLY DENTED	784.60	469.70
1	REAR END PANEL STRIKER	NOT NECESSARY	45.00	-
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	277.60	-
1	BOOTLID WEATHERSTRIP	TWISTED	167.80	167.80
2	TAILLAMPS @\$915.00	N/S CRACKED	1,830.00	915.00
1	REAR FLOOR PANEL TOP BOARD	TORN	266.50	266.50
	LESS 20% DISCOUNT		-	-919.52
			6,714.10	3,678.08
SPECIAL NETT ITEMS				
1	REAR LICENCE PLATE W/HOLDER (SN)	BENT	50.00	40.00
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	30.00	30.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	80.00	50.00
1	SET REAR REVERSE SENSOR (SN)	SHORTED	220.00	200.00
			380.00	320.00
LABOUR				
	TO CHECK WIRING.		80.00	30.00
	TO SPRAY ANTI RUST PROOFING.		100.00	60.00
	LABOUR FOR PANEL BEATING & REPLACING PARTS.		650.00	600.00
	TO PUTTY & SPRAY PAINTING.		850.00	750.00

Report Ref No. CC4/LPC17023759/Uua3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DISMANTLE & REFIX UPHOLSTERY.		100.00	80.00
			1,780.00	1,520.00
	GRAND TOTAL		8,874.10	5,518.08
RECOMMENDED COST OF REPAIR SUM				4,800.00

Report Ref No. CC4/LPC17023759/Uua3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.