

Skw 5096-P Mazda 3

- 1) Rear Bootlid — \$920.70 1.6m —
- 2) " " Inner Lock — \$185.00 Tw. —
- 3) " " Inner shield clip — \$20.00 SN nr —
- 4) " " Lamp (2x) $282.00 = \$564.00$ nrx
- 5) " " 'Mazda 3' plate — \$55.10 nr —
- 6) " " 'skyactiv' plate — \$64.28 nr —
- 7) " " Emblem — \$55.40 nr —
- 8) Rear No. plate Assy — \$50.00 SN 40s.w
- 9) Rear Bumper — \$959.80 D.S. —
- 10) " " clip — \$30.00 SN nr —
- 11) " " Reinforcement frame — \$385.00 D —
- 12) " " Retainer (2x) $32.70 = \$65.40$ 40 —
- 13) " " Tow Hook Cover — \$68.00 Torn —
- 14) Rear Panel — \$784.60 Body 20 ✓
- 15) " " stricker — \$45.00 nrx
- 16) " " garnish — \$277.66 nrx
- 17) " " Rubber — \$167.80 Tw. ✓
- 18) " " Taillamp (2x) $385.50 = \$771.00$ nrx 1pc

Rear spare tyre top board — Torn —

SKW 5096-P

- 19) Rear Panel Joint Sealant - 80 SN
20) Reverse Sewer — 220 SN

in 50 S.W
shut 20.05.

Labour:-

- 1) Check wiring — 80k — 30
2) Anti Rust Proofing — 100k — 60
3) Panel Beating — 650k — 600
4) Paintwork — 850k — 750
5) Interior Upholstery — 100k — 60

Not Done
in
2/5/9
Sdy.
17/12/14

STYTECH AUTO PTE. LTD.
2 Kaki Bukit Ave 2 #02-30
Kaki Bukit Autohub Singapore 417021
Tel: 6444 8125 Fax: 6445 3310
GST Reg. No.: 201601539K
Co. Reg. No.: 201601539K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: