



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLL5904D

Mr Tan Eng Hwei (Chen Yinghui)

Blk 406 Bukit Batok West Avenue
#11-40
Singapore 650406

Mobile: 98355883

Vehicle & Document Information

WIP No **18870**
Reg No/Reg Date **SLL5904D / 01/03/2017**
Date In/Mileage **/ 0**
Chassis No **WDD1173422N450562**
Engine No **27091031150012**
Make/Model **MB/MB CLA 180 COUPE (C117) "FACELIFT"**
Colour/Trim **026 650 Calcit Whit/ 041 151-Leather Twi**

Account No	Terms	Date/Time Printed	CSE	Operator
CSIO0001	Cash	20/12/2017/ 14:20	VS	356 / Vincent Seah

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BPNSUN POLICY NO/ACC DATE : 2100501884 // 16.11.17 DRIVE IN/EXCESS : 16.11.17 // TP CAR NO.: FBE6003C=AXA DATE IN/DATE SURVEY: 20.12.17 // DIRECT SETTLEMENT : ZAYER-LKK				
A BPILAB USING STAR DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT			0.10	380.00
A BPILAB DISASSEMBLE AND REPLACE REAR BUMPER, REAR BOOT				960 1200.00
A BPIRES RESPRAY ON REAR BUMPER, REAR BOOT				600 1800.00
A BPILAB CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE. NETT				120.00
M RIGHT REAR LAMP COMBINATION	1.00	715.46	00.00	715.46
M RIVET	4.00	1.21	00.00	4.84
M RIGHT BRACKET	1.00	54.58	00.00	54.58
M RH TAIL PIPE COVER	1.00	279.23	00.00	279.23
M RIGHT BASIC MOUNTING FOR BUMPER	1.00	63.64	00.00	63.64
M REAR BUMPER	1.00	1091.31	00.00	1091.31
M REAR BUMPER LOWER PANEL	1.00	270.20	00.00	270.20
M RIGHT REAR LAMP COMBINATION	1.00	715.46	00.00	715.46
M REAR BOOT HANDLE MOLDING	1.00	63.70	00.00	63.70
M MERCEDES STAR	1.00	45.55	00.00	45.55
M CLA180 MODEL PLATE	1.00	80.61	00.00	80.61
M GROMMET	3.00	2.16	00.00	6.48
M TRUNK LID	1.00	1491.49	00.00	1491.49

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Rasul
Hp 90000000
3 days
20/12/17 @ 1500
Rasy bk pint

Confirmed & accepted by

• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Authorized signatory and company stamp

Nett **8,382.55**
7% GST on **8382.55** **586.78**
Total Payable **8,969.33**

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg